

## **UNSAFE ACT/ CONDITION and NEAR MISSES REPORT**

Reported By:

**Name:** John Smith

**FIN Num:** 123456

**Time & Date:** 22/02/2016

**Dept/MBU:** After Paint (APM or Medical Line)

☐

Unsafe Act

☒

Unsafe Condition

☐

Near Miss

Multiple issues (how many)

☐

**Location (where):**

BB11

**Date of incident:**

09/04/2013

**Injury type:**

Contusion/Crush/Concussion

**Sketch:**



**Name of the person involved:**

Konstantinos Zachos

**Description (what):**

The worker lay down on a duckboard in order to move under a tractor to check for possible oil leaks, but the duckboard shifted as the worker sat down and the worker fell and received a superficial cut to the head

**Recommendation/suggestion (how):**

provide a shell or cover for the issue like cover for the employee working under the tractor; quality department checked parts to spec and found that floor ducting measurements were out of spec. the company are dealing with this and we are waiting for good parts. That will prevent any force having to be used to fit lower hood.; use liquid or air with the hit - hot liquid investigated;

**Risk Resolved? Yes, with the following resolution(s):**

quality department checked parts to spec and found that floor ducting measurements were out of spec. the company are dealing with this and we are waiting for good parts. That will prevent any force having to be used to fit