



**TELIUM SDK**

# **SDK6.4.3 Release Note**

Reference: ICO-ETU-09-0535-PP

Date: 2009-10-13

From: Pascal PLASSE

To: All SDK users

## TABLE OF CONTENTS

<b>1. PURPOSE OF THE DOCUMENT .....</b>	<b>1</b>
<b>2. TERMINALS COMPATIBILITY .....</b>	<b>1</b>
<b>3. WARNINGS .....</b>	<b>1</b>
3.1 PROBLEM WITH BLUETOOTH WHEN THERE IS NO BATTERY INSIDE EFT930 BL1 .....	1
3.2 EFT930BL2 SYSTEM VERSION COME BACK IS FORBIDDEN .....	1
3.3 HANDHELD TERMINALS / BASES ASSOCIATIONS .....	1
<b>4. TELIUM SYSTEM .....</b>	<b>1</b>
4.1 THUNDER .....	1
4.2 930 BL1 BC02.....	1
4.3 930 BL2 .....	1
4.4 HANDHELD TERMINALS M31 .....	1
4.5 HANDHELD TERMINALS M39 .....	2
<b>5. TELIUM MANAGER .....</b>	<b>2</b>

## **1. PURPOSE OF THE DOCUMENT**

This document describes the evolutions since the SDK6.4.2 which is the previous version.

## **2. TERMINALS COMPATIBILITY**

This SDK is for EFT930 (m31) and EFT930 BL2 (m39) including base software.  
It is dedicated to NER and to France configurations.

## **3. WARNINGS**

### **3.1 PROBLEM WITH BLUETOOTH WHEN THERE IS NO BATTERY INSIDE EFT930 BL1**

On EFT930 BL1 and BL2, due to the Bluetooth module, there is a reset if no battery is present inside the terminal. So, the production is not possible with this SDK.

### **3.2 EFT930BL2 SYSTEM VERSION COME BACK IS FORBIDDEN**

It is not possible to come back from the EFT930 BL2 system version embedded in the SDK 6.4.2 to an older one. This come-back is blocked. It is due to a change of the time base (1 s to 125 ms)

### **3.3 HANDHELD TERMINALS / BASES ASSOCIATIONS**

- No more than 3 handheld terminals can connect on a base simultaneously;
- No more than one base for an handheld terminal;
- It is not possible to use modem or Ethernet with new bases (only COM1 and COMU are possible).

## **4. TELIUM SYSTEM**

New version of Telium System is **08.16**.

Following points are delivered in this release.

### **4.1 THUNDER**

- |      |   |
|------|---|
| 5669 | Backlight is now maximum even if the terminal is in low battery state |
| 5884 | Memory leak fixed for function RemoteListFile                         |
| 5936 | Different name defined for each Nexgen task                           |
| 5937 | A semaphore was corrupted in the Nexgen code                          |

### **4.2 930 BL1 BC02**

- |      |  |
|------|--|
| 5110 | A new Bluetooth terminal BC02 now works with an old base BC06 (some limitations described in the paragraph <b>Erreur ! Source du renvoi introuvable.</b> ) |
|------|--|

### **4.3 930 BL2**

- |      |   |
|------|---|
| 5205 | Lost of link between terminal and base fixed (Bluetooth BC06) |
| 5724 | Problem of loading of OS on Ingetrusted EFT930 fixed          |

### **4.4 HANDHELD TERMINALS M31**

5731 Management of Bluetooth BC02 and BC06 for EFT930 catalogues added

#### **4.5 HANDHELD TERMINALS M39**

5728 Corrections for EFT930 catalogues

### **5. TELIUM MANAGER**

Version of Telium Manager is **53.02** (No change since SDK6.4.2)

[END OF DOCUMENTATION]