

Référence / Reference : **ICO-ETU-0383-JRP** Révision / Revision : **A**

Titre /Title : **SDK 6.4.2 release delivery**

Programme / Subject : TELIUM SOFTWARE

Approbation de la révision / Revision Approval : <b>A</b>		
	<b>Nom</b> <i>Name</i>	<b>Fonction</b> <i>Function</i>
Etabli par : <i>Written by:</i>	JR.Poligny	Project manager
Vérifié ou Approuvé par : <i>Checked or approved by:</i>	C.Barthelemy	Export Product leader
Autorisé par : <i>Authorized by:</i>	C.Barthelemy	Export Product leader

<b>Révision</b> <i>Issue</i>	<b>Date de validité / d'application</b> <i>Validity/application date</i>	<b>Nb de pages</b> <i>Nb of pages</i>	<b>Nb de pages annexes</b> <i>Nb of appendices</i>	<b>Objet et description de la modification</b> <i>Object and description of modification</i>
A	September 2009			Release SDK 6.4.2

## **1 DESCRIPTION**

This document describes the evolutions between the SDK6.4.1 version and this SDK6.4.2 version.

## **2 TERMINALS COMPATIBILITY**

The following terminals are compatible with this SDK release:

### **2.1 TELIUM 1**

- EFT30
- EFT SMART
- EFT930
- TWIN
- UCM
- ML30
- CAD30
- SMART2
- MR40
- EFT930 BL2
  - GPRS,
  - GPRS Contactless,
  - GPRS Color,
  - GPRS Contactless Color;
  - Bluetooth,
  - Bluetooth Contactless,
  - Bluetooth Color;
  - EFT930 BCC (Bluetooth Color Contactless) is new in this release.

### **2.2 TELIUM 2**

- ICT220
- ICT250 is managed with extension cards. Only the following are currently managed (only one feature available by option):
  - Card option 1 : SCR2 (=CAM2)
  - Card option 2 : GPRS /  $\mu$ SD / Contactless
  - Card option 5 :  $\mu$ SD / 2<sup>nd</sup> RS232
- SPM

### **3 TELIUM SYSTEM**

Following points are delivered in this release.

- FT5384    Creation of ML30 “DIR” catalogue.
- FT5377    Catalogues X07 are renamed ICT2xxx

#### **3.1 TELIUM GENERIC**

- FT5310    Correction on PPP negotiation phase
- FT5463    Bug description : If key capture take time, the backlight is disabled a  
Correction during Pin Capture: the backlight is now managed as it is managed  
on other key capture.

#### **3.2 EFT 930 BL2**

- FT4818    Correction: white screen on 930BL2 at power-up is now disabled.
- FT5210    Correction: some freeze are now solved on EFT930B CC
- FT5400    Correction: on CLess wake-up. Some time, after wake-up the CLess restart  
slowly. The correction allows restarting as a normal speed.

### **4 TELIUM MANAGER**

Same Telium Manager package as on SDK 6.4.1.