

Approbation de la révision / Revision Approval : A		
	Nom <i>Name</i>	Fonction <i>Function</i>
Etabli par : <i>Written by:</i>	P. Plasse	SDK project manager
Vérifié ou Approuvé par : <i>Checked or approved by:</i>	C.Barthelemy	Export Product leader
Autorisé par : <i>Authorized by:</i>	C.Barthelemy	Export Product leader

Révision <i>Issue</i>	Date de validité / d'application <i>Validity/application date</i>	Nb de pages <i>Nb of pages</i>	Nb de pages annexes <i>Nb of appendices</i>	Objet et description de la modification <i>Object and description of modification</i>
A	June 2009			Release SDK 6.4 'Preliminary Version'

1 INTRODUCTION

THIS PACKAGE IS A PRELIMINARY VERSION; ITS VALIDATION IS CURRENTLY IN PROGRESS. IT MUST ONLY BE USED FOR DEVELOPMENT PURPOSE.

IT MUST NOT BE DELIVERED TO FINAL CLIENTS.

This document describes the content of the SDK 6.4 'preliminary version' delivery and evolutions/corrections from SDK 6.3.

2 TELIUM SYSTEM

The Telium System delivery is the pack **08.04**.

2.1 TELIUM GENERIC

FT4923	Downloading didn't work in system package 08.02
FT4946	Rarely, MicroSD was blocked on Smart2
FT4960	PP30S and P30 removed from all Mockup catalogues
FT4698	External command was lost if occurring too near of an external command
FT4705	Too long GSM disconnection
FT4791	Management of the L38 retrofit mode on EFT930S_GEM.
FT4860	Problem of uploading of SIM ID for GPRS HiLo
FT4035	Some MMC cards weren't functional
FT4390	Possibility added to download an application in system disk in debug mode
FT4891	Simulator tags
FT4425	IP stack upgraded to the last Nexgen version PPPOE added
FT4752	Check of the signature by parts
FT4772	Possibility to have a swap disk greater than 4 Mo
FT4777	Buffer overflow in the function SecurityParamInitialize.
FT4783	Convenient management of "Flash full" for Telium 1 and 2
FT4785	Problem of uninstall of the CAM
FT4811	Reboot when call to the function read_dateUsb
FT1841	Reboot on EFT930W and EFT930B when call to the function gethostbyname_r
FT3368	930s didn't go to LLT mode after F1-2-3-4 sequence
FT4088	SYSTEM flash disk size modified.
FT4451	System function added to read the list of applications (possible whatever the disk)

FT4514	Correction of the problem of SetNextWakeUp when the Booster date is protected
FT4519	Forbid multiple use of LinkPer() with the same parameter
FT4568	FS_dsklist did not operate properly
FT4670	Invalid DLL extent on start-up for UCM
FT4676	Correction of the reset on PMD request.
FT4737	Possibility to downgrade a system if the system disk size didn't change
FT4755	Reset during ADSL connexion
FT4759	Possibility to download without IP with SSL
FT4391	Ingetrust : Allow the start-up of the terminal without being stuck by LDbg

2.2 COLOR TERMINALS (930 BL2 AND ICT250)

FT4909	PMD added to the color driver
--------	-------------------------------

2.3 ICT220 / ICT250

FT4352	Management of CAM2 and SAM3 for the option card
FT4539	Management over 65535 SWI instead of 255
FT4559	Reset in the function EncryptPINdUkptDES for ICT220
FT4689	Possibility to change CAM frequency
FT4771	5 secret zones available
FT4786	Alignment constraints removed on the hardware DES
FT4510	Ethernet driver accessed to a physical address instead of a virtual one.
FT4776	Pinpad didn't work with an ICT when ZKA mode was activated
FT4807	Evolution to forbid the downgrade of BL3 system 8300640125
FT4841	SAM1 reset on ICT250
FT4557	COM2 management on ICT 220.
FT4744	Display of the repudiation of fake keys (ICT220 : BOOSTER3.DIA)
FT4746	Security configuration number added for ICT220
FT4767	Wrong flash size information.
FT4654	Use of COM2 for the GPRS driver

2.4 ICT220/250 : BOOSTER III

FT4792	PayPass driver 1.1 for PN512
--------	------------------------------

- FT4819 The function ddir didn't work in a scheme for RKI Ingetrust
- FT4854 Correction of the reset when enter in maintenance mode (due to the increase of RAM used when contactless were integrated)
- FT4869 Correction of the problem on first loading on ICT250
- FT4901 Change on the initialisation of the screen to not erase the factory parameters
- FT4906 Correction of the randomly reset during RKI key injection process for RKI Ingetrust
- FT4910 Incorrect number of parameters for sha256_finish

2.5 EFT930BL2

- FT4922 Association of a non Bluetooth terminal on a 2LS base.
- FT4795 Overconsumption for MMC option cards used with EFT930BL2
- FT4884 BC06 Bluetooth drivers added in 930BL2 catalogues (m39).
- FT4608 LDBG didn't work on 930S BL2
- FT4703 Correction of the reset (instead of shutdown) of the 930BL2 after a yellow key press
- FT4704 Function added to get the color structure address
- FT4774 P30 et PP30S systems removed from 930BL2 catalogues 930BL2 (m39).

2.6 SMART 2

- FT4747 Security configuration number added for SMART 2

2.7 CAD30

- FT1668 IRDA/ last character was sometimes not sent correctly.
- FT3855 Correction of the lost of the first byte for reception on a serial link with stream control
- FT4523 Correction of the bug on Telium Pass start up with CADTOOL

2.8 MR40

- FT4814 Correction of the problem when the terminal goes into sleep just after a swipe reading
- FT4797 Correction of the wrong swipe reading after card staying in the swipe when the terminal goes to light sleep
- FT4608 LDBG didn't work on MR40

3 TELUM MANAGER

The Telium Manager delivery is the pack **53.97**.

3.1 NEW IN THE MANAGER

3.1.1 New features

- FT4363 Customisation of the messages of the Manager:
AID name and message "Confirmation?" are not displayed anymore, blank screen instead. POS still wait for confirmation or cancel.
- FT4697 It is now possible to have a beep when a key is pressed
- FT4768 Shortcut to Bluetooth association menu
- FT4773 Only for French region :
Printing of the architecture type or message 135 in the state ticket
- FT4899 New catalogue m38 (MR40) for manager
- FT4927 API added to enable or disable from the application an external pinpad
- FT4943 Change of the color of the contactless logo background
- FT3702 Maximum number of applications becomes 32 (instead of 15) for some entry points
- FT4360 Change presence of footer, size, position of header with MANAGER.PAR
- FT4535 At start-up, the security configuration number is displayed
- FT4609 Possibility of changing header position (top or bottom) on black and white terminal.
- FT4613 Sim provider replace network name in the header
- FT4614 Selection of non-EMV application
- FT4658 Change of color by manager.par
- FT4738 Only for French domain :
Evolution on the IPDU for bulletin 8

3.1.2 Corrections

- FT4742 In the header in colour:
Management of the handset logo when calling in GSM mode
Management of the battery logo when no battery into POS.
- FT4802 When the manager was waiting for battery level > 5%, there was a dead lock with color displays if header was activated
- FT4926 There were some pixels default when printing a sequence of two bitmaps
- FT4939 Remapping of the DLL on SMART2 (problem was between DLL PPS30 and DLL entry)
- FT4769 Only for French domain :
Identification RFC1086+ frame problem
- FT4813 Manage ICT250 contactless logo position correctly

3.2 DLL SECURITY

The DLL Security is the pack 03.07.

FT4885 Deletion of a key is now possible on Telium 1 without erasing the secured area.

3.3 TCPIP

No evolution: TCPIP package delivery is the pack 03.05.

4 LINKLAYER

No evolution.

5 SCHEMES

No evolution.

6 SDK

FT4970 Bad version of trace.exe for Telium1 in the SDK

FT4806 Version of the Telium simulator is upgraded to 2.1 (source code of the simulator is now generated automatically by the SDK team). As this version is in test, this one and the old one are provided with this version. By default, it's the version 1.39.

7 TOOLS

No evolution.