


| | | | |
|--|--|--------------------|-----------------|
|  GuidedImports | INSPECTION REPORT <i>THIS DOCUMENT IS NON-NEGOTIABLE</i> | Client Name | John Smith |
| | | Report No. | 2017010100 - YK |
| | | Report Date | Jan 5th, 2020 |

| | | | |
|-------------------|------------------------|------------------|-------------------------|
| Contact: | Kai Arcinas | Contact: | John Smith |
| E-mail: | info@guidedimports.com | Location: | Ningbo, Zhejiang, China |
| Inspector: | Rico Zhu | Weather: | Sunny |

| PRODUCT DESCRIPTION | | |
|----------------------------|----------------------------------|---|
| Supplier/Vendor | XXXXXXXXXX | Product Photo  |
| Manufacturer | XXXXXXXXXX | |
| Product Name | Stainless Steel Bottle Insulator | |
| Order No. | N/A | |
| Order Quantity | 2,268 pcs (756 pcs + 1,512 pcs) | |
| Inspection Quantity | 2,268 pcs (756 pcs + 1,512 pcs) | |
| Reference Sample | No sample | |
| Inspection Type | Pre-Shipment Inspection | |

| | |
|---|---------|
| Factory cooperation during the inspection | Average |
| Factory Quality organization | Average |
| Inspector's general opinion on the factory | Average |

| Inspection Standard: ISO 2859-1(ANSI/ASQ Z1.4) | | Defects | | |
|--|-----------------------|----------|------------|------------|
| | | Critical | Major | Minor |
| Sampling Plan: Single, Normal | AQL | 0 | 2.5 | 4.0 |
| Inspection Level: II | Defects Found: | 0 | 0 | 18 |
| Sample Size: | 300 Pcs | 0 | 14 | 21 |
| Overall Inspection Conclusion | PASS | | | |

| |
|---|
| Remarks: |
| Client did not provide any artwork for reference prior to the inspection of the goods. The client will need to confirm the artwork. |