

Site Visit Report

Generated: April 27, 2025

Project Details

Project: Building Envelope Assessment - Image Caption Test

Report Number: TEST-IMG-001

Subject: Testing Improved Image and Caption Display

Site Observations and Discussions

Image Caption Display Test

This test document verifies the improved image and caption display format. The captions should now appear below the images with better styling and readability.

Key Improvements:

- *Smaller image size to fit captions better
- *Captions moved below images instead of overlapping
- *Caption styling with background box for better readability
- *Improved page break handling to keep images and captions together

The image shows a typical building envelope feature that requires assessment during site visits.

Action Items

Action Items

1. Verify that image captions appear below the images.
2. Check that captions are clearly visible and readable.
3. Confirm that page breaks are handled properly.

Site Visit Report

Generated: April 27, 2025

Site Photos

Photo 1



Close-up view of a single-ply membrane roofing system showing a mechanical fastener with a stress plate/washer centered in a cut-out access panel or repair patch, with visible seam lines and minor surface soiling around the perimeter. This demonstrates the improved caption placement below the image.