

Defect Record Sheet


A	Defect Ref No : <u>SW2-MAS3-EXT-WK004-047</u>		Date / Time : <u>16/9/2022</u>	
	Repeated defect: (Yes/ No) <u>Yes</u>			
	Type of Road /Footpath/Facilities : <u>Major</u>			
	Location / Landmark:	<u>Tuas Checkpoint</u>	<u>LP 25F</u>	
	Type of Asset:	<u>Railing</u>		
	Description:	<u>Railing-Damaged</u>		
	Quantity:	<u>5</u>		
	Measurement:	<u>2m x 3.5m</u>		
	Cause of Defect:	<u>Hit By Vehicle</u>		
	Recommendation:	<u>To Replace</u>		
	Inspected By :	<u>XXX</u>		
		<u>Name</u>	<u>Signature</u>	
	Supervised By :	<u>XXX</u>		
		<u>Name</u>	<u>Signature</u>	
Defects reported to DRC / RARL / RIA / other agencies on:				
Reported via:	Method / Agency / Date / Time:		<u>XXX</u>	
Acknowledgement:	Method / Date / Time:		<u>XXX</u>	
B	(For LTA Use)			
	Defects Verified by :			
		<u>Name</u>	<u>Signature</u>	<u>Date</u>
	Instructions:	<u></u>		
C	(For contractor's acknowledgement)			
	Acknowledged and received by:	<u>Name</u>	<u>Signature</u>	<u>Date</u>
	TR322			

Defect Record Sheet

Location & Photographs

Defect Ref No: SW2-MAS3-EXT-WK004-047

Sketch



- A** Railing-Damaged
● LP 25F

Photographs



TR322

