

Defect Record Sheet


A	Defect Ref No : <u>W-MAS2-EXT-WK080-040</u>		Date / Time : <u>04/05/2024</u>	
	Repeated defect: (Yes/ No) <u>0</u>			
	Type of Road /Footpath/Facilities : <u>Drive</u>			
	Location / Landmark: <u>Sembawang Road</u> <u>LP015D</u>			
	Type of Asset: <u>drainage</u>			
	Description: <u>Mild defect</u>			
	Quantity: <u>3</u>			
	Measurement: <u>5m x 1m</u>			
	Cause of Defect: <u>Aging</u>			
	Recommendation: <u>Repaint lines</u>			
	Inspected By : <u>Nina Ng</u>			
	Name		Signature	
	Supervised By : <u>Jane Chan</u>			
	Name		Signature	
Defects reported to DRC / RARL / RIA / other agencies on:				
Reported via: Method / Agency / Date / Time: _____				
Acknowledgement: Method / Date / Time: _____				
B	(For LTA Use)			
	Defects Verified by : _____			
	Name		Signature	
	Date			
C	Instructions: _____			
	WSO No.: _____			
	(For contractor's acknowledgement)			
C	Acknowledged and received by: _____			
	Name		Signature	
Date				
TR322				

Defect Record Sheet

Location & Photographs

Defect Ref No: SW2-MAS3-EXT-WK004-047

Sketch



- A** Railing-Damaged
● LP 25F

Photographs



TR322

