

Defect Record Sheet


A	Defect Ref No : SW2-MAS3-EXT-WK004-047		Date / Time : 16/9/2022	
	Repeated defect: (Yes/ No) Yes			
	Type of Road /Footpath/Facilities : Major			
	Location / Landmark: Tuas Checkpoint		TP 25F	
	Type of Asset: Railing			
	Description: Railing-Damaged			
	Quantity: 5			
	Measurement: 2m x 3.5m			
	Cause of Defect: Ht By Vehicle			
	Recommendation: To Replace			
Inspected By :	XXX	Signature		
Supervised By :	XXX	Signature		
<p>Defects reported to DRC / RARL / RIA / other agencies on:</p> <p>Reported via: Method / Agency / Date / Time: XXX</p> <p>Acknowledgement: Method / Date / Time: XXX</p>				
B	(For LTA Use)			
	Defects Verified by :	Name Signature Date		
	Instructions:			
	WSO No.:			
C	(For contractor's acknowledgement)			
	Acknowledged and received by:	Name Signature Date		
TR322				

Defect Record Sheet

Location & Photographs

Defect Ref No: SW2-MAS3-EXT-WK004-047

Sketch



- A** Railing-Damaged
● LP 25F

Photographs



TR322

