

Defect Record Sheet


A	Defect Ref No :	<u>SW2-MAS3-EXT-WK004-047</u>		Date / Time :	<u>16/9/2022</u>	
	Repeated defect: (Yes/ No)	<u>Yes</u>				
	Type of Road /Footpath/Facilities :	<u>Major</u>				
	Location / Landmark:	<u>Tuas Checkpoint</u>		<u>LP 25F</u>		
	Type of Asset:	<u>Railing</u>				
	Description:	<u>Railing-Damaged</u>				
	Quantity:	<u>4 Members</u>				
	Measurement:	<u>4 Members</u>				
	Cause of Defect:	<u>Hit By Vehicle</u>				
	Recommendation:	<u>To Replace</u>				
Inspected By :	<u> </u>		<u> </u>			
	Name		Signature			
Supervised By :	<u> </u>		<u> </u>			
	Name		Signature			
Defects reported to DRC / RARL / RIA / other agencies on:						
Reported via:	Method / Agency / Date / Time: <u> </u>					
Acknowledgement:	Method / Date / Time: <u> </u>					
B	(For LTA Use)					
	Defects Verified by :	<u> </u>		<u> </u>		
		Name	Signature	Date		
	Instructions:	<u> </u>				
	WSO No.:	<u> </u>				
C	(For contractor's acknowledgement)					
	Acknowledged and received by:	<u> </u>		<u> </u>		
		Name	Signature	Date		
TR322						

Defect Record Sheet

Location & Photographs

Defect Ref No: SW2-MAS3-EXT-WK004-047

Sketch



- A** Railing-Damaged
● LP 25F

Photographs



TR322

