

Moreover, they could also contribute to surface instability and present a fire risk with the potential for excessive black smoke.<sup>39</sup>



**Figure 10: Tyres at the Gamodubu Landfill**

**Recommendation:**

**The OAG recommends that the EHD should;**

- **Expedite the reclamation project to enable management of the accumulation of tyres within the landfill, in order to reduce instances of surface instability that may represent fire risks.**

---

<sup>39</sup> Guidelines for the Disposal of Waste by the Landfill, 1997