

Inspection Report



Summary

Chassis number 742628 underwent two inspections at the North location, with the initial inspection (ID: 1) taking place during the morning shift at 7:00 AM and the subsequent inspection (ID: 14) occurring during the evening shift at 8:33 PM. The component statuses revealed that the grab handle consistently failed, with only three units passing, while the tape, lights, and vents passed in both inspections. Notably, the overall status shifted from fail to pass between the two inspections, suggesting that other components not mentioned in the provided data were rectified. To ensure sustained quality, it is recommended that the next inspection (1) verifies the grab handle's functionality and (2) confirms the continued pass status of the other components.