



ALARM ADDRESS	A23.6	ALARM NO.	2086
OP. MESSAGE	COOLANT FILTER ALARM. CHANGE IMMEDIATELY !!		
Related Signal	Input: X1.3 (MV154/154APC/MV204) °		
CAUSE	<p>The chip jammed in the coolant filter °</p>  <p>Coolant filter detector</p>		
ACTION	<p>1. Push EMG. Stop °</p> <p>2. Replace filter with new one °</p>  <p>3. Cancel alarm by reset button on FANUC panel °</p>		