

ALARM ADDRESS	A16.6	ALARM NO.	2030
OP. MESSAGE	PLS. INSTALL BALANCE TOOL AND CHANGE TO MDI MODE PRESS SPCW KEY 3 SEC. FOR WARM UP.		
Related Signal			
CAUSE	Spindle stop to exceed 24 hours		
ACTION	Install balance tool and change to MDI mode to press SPCW key 3 sec.		