


ALARM ADDRESS	A3.6	ALARM NO.	1114
ALARM TEXT	NO CONFIRM. OF ATC FRONT AUTO OPEN.		
Related Signal	Input: X4.0 (MV154/154APC/MV204) ° Output: Y5.2 (MV154/154APC/MV204) °		
CAUSE	<p>MAG loading door sensor not function properly</p> 		
ACTION	<p>1.Check ATC front auto open sensor ° 2.Relay or solenoid of door switch not function.</p>		