


ALARM ADDRESS	A3.7	ALARM NO.	1115
ALARM TEXT	NO CONFIRM. OF ATC FRONT AUTO CLOSE.		
Related Signal	Input: X4.1 (MV154/154APC/MV204) ° Output: Y5.3 (MV154/154APC/MV204) °		
CAUSE	<p>MAG loading door sensor not function properly</p> 		
ACTION	<p>1.Check ATC front auto close sensor ° 2.Relay or solenoid of door switch not function.</p>		