

(36, 763)

(295, 763)

Input Address:

2111 PLUM ST,  
AURORA, IL, 60506

(307, 705)

(576, 763)

Output Address:

1234 STREET NAME HERE,  
WITH ROOM FOR SECOND LINE,  
CITY, STATE, ZIP

(36, 701)

(36, 674)

(576, 701)

(576, 674)

Roof Condition:

ROOF #	SCORE	MATERIAL	TYPE	AREA (FT <sup>2</sup> )	ESTIMATED VALUE (\$)	AGE (YRS)
1	66	Ballast	Gable	200	200	4
2	54	EPDM	Clipped Gable	1000	1000	4
3	23	TPO/PVC/SPF	Dutch Gable	14000	14000	4
4	85	Asphalt Shingle	Gambrel	300	300	4
5	85	Clay Tile	Hip	200	200	4
6	96	Metal	Mansard	1000	1000	4
7	66	Modified Bitumen	Shed	14000	14000	4
8	43	Slate	Flat	300	300	4
9	22	Wood Shingle	Other	500	500	4
10	22	Wood Shingle	Other	500	500	4

(36, 531)

(165, 515)

(176, 503)

(246, 513)

(49px)

(246, 502)

(576, 531)

(36, 502)

(36, 490)

(36, 470)

(36, 458)

(36, 449)

Total Roof Score:

12

Roof Attributes:

Insured Name: Company Name  
Company Name

Image date: 04/08/2024

(36, 389)

(36, 375)

(41, 373)

(41, 359)

(41, 345)

(41, 331)

(41, 317)

(41, 303)

(41, 289)

(8px)

(36, 279)

DETECTED DAMAGE AREA:

Water pooling: 55%

Staining: 89%

Patching: 64%

Tarp: 0%

Missing shingle: 3%

Other damage: 4%

Other damage: 4%

(36, 256)

(36, 243)

(41, 240)

(41, 226)

(41, 212)

(41, 198)

(41, 184)

(41, 170)

(8px)

(36, 160)

DETECTED EQUIPMENT:

HVAC/Cooling tower: 2

Skylight: Minimal

Solar panel: N/A

Pipeline: Detected

Other Equipment: N/A

Other Equipment: N/A

(36, 76)

(126, 76)

(36, 36)

(126, 36)

(246, 32)

THE CINCINNATI  
INSURANCE COMPANIES

DAMAGE:

EQUIPMENT:

2

1

Patching

Staining

Water pooling

Staining

Water pooling

Input Address:  
2111 PLUM ST,  
AURORA, IL, 60506

Output Address:  
1234 STREET NAME HERE,  
WITH ROOM FOR SECOND LINE,  
CITY, STATE, ZIP

Roof Condition:

ROOF #	SCORE	MATERIAL	TYPE	AREA (FT²)	ESTIMATED VALUE (\$)	AGE (YRS)
1	66	Ballast	Gable	200	200	4
2	54	EPDM	Clipped Gable	1000	1000	4
3	23	TPO/PVC/SPF	Dutch Gable	14000	14000	4
4	85	Asphalt Shingle	Gambrel	300	300	4
5	85	Clay Tile	Hip	200	200	4
6	96	Metal	Mansard	1000	1000	4
7	66	Modified Bitumen	Shed	14000	14000	4
8	43	Slate	Flat	300	300	4
9	22	Wood Shingle	Other	500	500	4
10	22	Wood Shingle	Other	500	500	4

Total Roof Score: 12

Roof Attributes:


Insured Name: Company Name  
Company Name  
Image date: 04/08/2024

DETECTED DAMAGE AREA:

- Water pooling: 55%
- Staining: 89%
- Patching: 64%
- Tarp: 0%
- Missing shingle: 3%
- Other damage: 4%
- Other damage: 4%

DETECTED EQUIPMENT:

- HVAC/Cooling tower: 2
- Skylight: Minimal
- Solar panel: N/A
- Pipeline: Detected
- Other Equipment: N/A
- Other Equipment: N/A



474px

172px