

## ***Bugs***

The first two operations were incompatible with the design specs.

The bypass operations had less priority than the invalid opcodes

The carry in was neglected even the FULL ADDER parameter was “ON”

The opcode used was the direct value not the registered one