

Inspection Report: RPT-2025-09-30-AA1080

Inspected Item:

damage_type: Crack
severity: Critical
action_required: Immediate Replacement
inspector_name: kanu
inspector_id: kanu
vendor: kanu
batch: kanu
location: kanu
rid: RID002
timestamp: 2025-09-30T09:48:31.428564
photo_filename: scaled_c79d3b25-d0d8-4f67-b084-85638d19918d443875898389264679.jpg

AI Analysis:

condition_score: 20
predicted_failure_risk: Immediate risk of failure; replacement required
vendor_score: No vendor alert

Work Order:

priority_level: Critical
action: Immediate Replacement
spare_part_sku: BOLT-M10-A
assigned_to: Jaipur Maintenance Division
status: Pending

Supervisor Approval:

Supervisor Signature: _____
Date: 2025-09-30