

Suction line connected to the compressor filling inlet

Fault

profile: The suction line is connected to the compressor filling inlet.

Cause:

To improve the hot gas defrosting.

On current appliances, a note (**Fig. 1**) is attached in front of the compressor.

Saugrohranschluß entgegen Typenschildangabe
Verdichter (Grund: Heißgasabtauung)

connection suction tube against specification on
type plate compressor (reason: hot gas defrost)

Fig. 1

Remedial

action: -

Note:

In service cases (compressor replacement), the lines must be connected identically.

Models:

Designation	Foreign designation	Index	Design
B.Pv 65.. / 84..	---	From -40	All
L.Pv 65..	L.T 21G1HC	From -40	All
L.Pv 84..	L.T 30W1HC	From -40	All
L.Pv 14..	L.T 50.2HC	From -40	All
G.Pv ..20 / ..40 / ..90	---	From -40	All
GKPv 6573	GRT21G1HC	From -40	All
GKPv 6570	---	11 to 21B	525
	---	From -40	001, 514, 924
	GRT21S1HC		137
	GPI 657(-43)		986
GKPv 1470	---	From 40	001, 514, 924
	GRT50S2HC		137
GGPv 6570	---	From 16C	924
	GNI 657(-43)	From 16B	986
	---	From -40	001, 514
GGPv 1470	---	From -40	001, 514, 924

Legal Notice

© 24.01.2017 Liebherr-Hausgeräte Lienz GmbH. All rights reserved.

No part of this documentation may be reproduced or processed, duplicated or distributed by means of electronic systems in any form whatsoever (print, photocopy or any other process) for purposes other than personal use without the written consent of Liebherr-Hausgeräte Lienz GmbH.

Liebherr-Hausgeräte Lienz GmbH reserves the right to change or amend the documentation at any time without prior notice. Liebherr-Hausgeräte Lienz GmbH assumes no liability for printing errors and ensuing damages.

Other brand or product names contained in this document are the brands of the respective holders of the rights and are hereby recognised as such.

Liebherr-Hausgeräte Lienz GmbH, Dr.-Hans-Liebherrstraße 1, 9900 Lienz, Austria, Phone +43 50809 20, E-Mail: info.lwl@liebherr.com, Internet: home.liebherr.com