



Operating noise

Fault profile: The fan in the compressor recess makes a perceptible operating noise.



To correct: The fan 9870 587 can be installed instead of the standard series fan.



The blades and the base of the original fan must be retained. The original fan's earth cable will no longer be required.

Models: All GTE and GTI models which include as standard the assembly unit 9870 621 "Complete Fan" (see Liparts).