




0



| | Index | FileName | Orientation | Width | Instance | Image |
|---|-------|-----------------|-------------|-------|----------|---|
| 0 | 0 | diagonal2.png | Diagonal | 4.46 | 1 |  A photograph of a light-colored, textured surface with a prominent diagonal crack running from the top-left towards the bottom-right. The crack is highlighted with a green outline, and a red rectangular bounding box is drawn around it. A small red label in the top-left corner of the bounding box reads "crack 0.75". |
| 1 | 1 | vertical.jpg | Vertical | 2.42 | 1 |  A photograph of a light-colored, textured surface with a vertical crack running from the top towards the bottom. The crack is highlighted with a green outline, and a red rectangular bounding box is drawn around it. A small red label in the top-left corner of the bounding box reads "crack 0.75". |
| 2 | 2 | horizontal2.jpg | Horizontal | 7.73 | 1 |  A photograph of a light-colored, textured surface with a horizontal crack running across the middle. The crack is highlighted with a green outline, and a red rectangular bounding box is drawn around it. A small red label in the top-left corner of the bounding box reads "crack 0.78". |