




2x







1x





2x











[N]







0






[N]

0





# PCB



Pin	Signal	M-Pin	Pin	Signal	M-Pin
1	Joystick X	A10	9	5V	
2	Joystick Y	A11	10	Poti Drehzahl	A9
3	Joystick Z	A12	11	Fräsmotor Start / Stop	31
4	Poti Vorschub	A8	12	Programm Start / Stop	33
5	LED		13	Encoder A	22
6			14	Encoder B	23
7	GND		15	Ok	30
8					

