


TOBOMETER HY




Quickstart Guide




INSTALLATION OF TOBOMETER HY

Open the battery compartment, unpack and insert the batteries and close the battery compartment.




POWER ON/OFF

Press the violet On/Off-button to switch TOBOMETER HY on/off.



CALIBRATION/MEASUREMENT

Press the MEAS-button to start calibration and measurement.



START CALIBRATION

Contact the sensor ball perpendicular to a surface to analyze the moisture content of the material / wall.