

Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#66, \$49	Date	2023/8/9 下午 04:15:06
Segment	1	Camera	1
Pattern	2207	Position[x, y]	14.3 [mm], 1668.9 [m], (2.0 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:25.6 ,V:19.2 [mm]
Result	-	Area	343.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#63, \$48	Date	2023/8/9 下午 04:14:59
Segment	1	Camera	1
Pattern	2193	Position[x, y]	0.1 [mm], 1658.3 [m], (12.5 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:223.2 [mm]
Result	-	Area	33.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#63, \$48	Date	2023/8/9 下午 04:14:59
Segment	1	Camera	1
Pattern	2193	Position[x, y]	0.1 [mm], 1658.0 [m], (12.9 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:516.4 [mm]
Result	-	Area	66.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#62, \$47	Date	2023/8/9 下午 04:14:58
Segment	1	Camera	1
Pattern	2192	Position[x, y]	0.1 [mm], 1657.3 [m], (13.6 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:802.0 [mm]
Result	-	Area	77.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#61, \$46	Date	2023/8/9 下午 04:14:58
Segment	1	Camera	1
Pattern	2191	Position[x, y]	0.1 [mm], 1656.9 [m], (14.0 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:144.4 [mm]
Result	-	Area	20.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#61, \$46	Date	2023/8/9 下午 04:14:58
Segment	1	Camera	1
Pattern	2191	Position[x, y]	0.1 [mm], 1656.5 [m], (14.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:579.2 [mm]
Result	-	Area	36.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#60, \$45	Date	2023/8/9 下午 04:14:57
Segment	1	Camera	1
Pattern	2190	Position[x, y]	0.1 [mm], 1655.7 [m], (15.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:46.8 [mm]
Result	-	Area	10.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#60, \$45	Date	2023/8/9 下午 04:14:57
Segment	1	Camera	1
Pattern	2190	Position[x, y]	0.1 [mm], 1656.0 [m], (14.9 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:401.2 [mm]
Result	-	Area	16.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#59, \$44	Date	2023/8/9 下午 04:14:57
Segment	1	Camera	1
Pattern	2189	Position[x, y]	0.1 [mm], 1655.4 [m], (15.5 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:12.0 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#58, \$43	Date	2023/8/9 下午 04:14:15
Segment	1	Camera	1
Pattern	2110	Position[x, y]	701.8 [mm], 1595.5 [m], (75.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:6.4 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#57, \$42	Date	2023/8/9 下午 04:14:14
Segment	1	Camera	1
Pattern	2107	Position[x, y]	701.5 [mm], 1593.4 [m], (77.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:18.8 [mm]
Result	-	Area	5.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#57, \$42	Date	2023/8/9 下午 04:14:14
Segment	1	Camera	1
Pattern	2107	Position[x, y]	569.7 [mm], 1593.4 [m], (77.5 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:31.6 [mm]
Result	-	Area	6.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#56, \$41	Date	2023/8/9 下午 04:14:13
Segment	1	Camera	1
Pattern	2106	Position[x, y]	701.5 [mm], 1592.8 [m], (78.1 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:12.0 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#56, \$41	Date	2023/8/9 下午 04:14:13
Segment	1	Camera	1
Pattern	2106	Position[x, y]	701.5 [mm], 1592.7 [m], (78.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:41.2 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#55, \$40	Date	2023/8/9 下午 04:14:11
Segment	1	Camera	1
Pattern	2101	Position[x, y]	701.5 [mm], 1589.0 [m], (81.9 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.0 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#54, \$39	Date	2023/8/9 下午 04:14:10
Segment	1	Camera	1
Pattern	2100	Position[x, y]	701.5 [mm], 1588.3 [m], (82.6 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#53, \$38	Date	2023/8/9 下午 04:14:07
Segment	1	Camera	1
Pattern	2094	Position[x, y]	701.5 [mm], 1583.8 [m], (87.1 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#52, \$37	Date	2023/8/9 下午 04:14:04
Segment	1	Camera	1
Pattern	2089	Position[x, y]	442.2 [mm], 1580.1 [m], (90.7 [m])
Type	縱向刀絲疵點	Size	H:20.5 ,V:28.4 [mm]
Result	-	Area	2.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#52, \$37	Date	2023/8/9 下午 04:14:04
Segment	1	Camera	1
Pattern	2089	Position[x, y]	739.4 [mm], 1580.1 [m], (90.8 [m])
Type	縱向刀絲疵點	Size	H:4.4 ,V:8.8 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#52, \$37	Date	2023/8/9 下午 04:14:04
Segment	1	Camera	1
Pattern	2089	Position[x, y]	97.8 [mm], 1580.1 [m], (90.8 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.6 [mm]
Result	-	Area	4.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#52, \$37	Date	2023/8/9 下午 04:14:04
Segment	1	Camera	1
Pattern	2089	Position[x, y]	731.3 [mm], 1579.7 [m], (91.1 [m])
Type	縱向刀絲疵點	Size	H:15.6 ,V:9.6 [mm]
Result	-	Area	7.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#51, \$36	Date	2023/8/9 下午 04:14:04
Segment	1	Camera	1
Pattern	2088	Position[x, y]	97.8 [mm], 1579.3 [m], (91.5 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#48, \$35	Date	2023/8/9 下午 04:13:31
Segment	1	Camera	1
Pattern	2026	Position[x, y]	242.3 [mm], 1532.7 [m], (138.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:797.2 [mm]
Result	-	Area	499.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#48, \$35	Date	2023/8/9 下午 04:13:31
Segment	1	Camera	1
Pattern	2026	Position[x, y]	567.0 [mm], 1532.6 [m], (138.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:797.6 [mm]
Result	-	Area	511.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#48, \$35	Date	2023/8/9 下午 04:13:31
Segment	1	Camera	1
Pattern	2026	Position[x, y]	375.1 [mm], 1532.6 [m], (138.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.4 ,V:609.2 [mm]
Result	-	Area	542.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#48, \$35	Date	2023/8/9 下午 04:13:31
Segment	1	Camera	1
Pattern	2026	Position[x, y]	699.8 [mm], 1532.6 [m], (138.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:609.6 [mm]
Result	-	Area	550.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#47, \$34	Date	2023/8/9 下午 04:13:30
Segment	1	Camera	1
Pattern	2025	Position[x, y]	566.8 [mm], 1532.2 [m], (138.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:322.8 [mm]
Result	-	Area	201.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#47, \$34	Date	2023/8/9 下午 04:13:30
Segment	1	Camera	1
Pattern	2025	Position[x, y]	567.0 [mm], 1531.9 [m], (139.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:654.8 [mm]
Result	-	Area	283.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#47, \$34	Date	2023/8/9 下午 04:13:30
Segment	1	Camera	1
Pattern	2025	Position[x, y]	699.8 [mm], 1531.8 [m], (139.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:626.8 [mm]
Result	-	Area	293.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#47, \$34	Date	2023/8/9 下午 04:13:30
Segment	1	Camera	1
Pattern	2025	Position[x, y]	374.9 [mm], 1531.8 [m], (139.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.4 ,V:626.4 [mm]
Result	-	Area	294.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#46, \$33	Date	2023/8/9 下午 04:13:29
Segment	1	Camera	1
Pattern	2024	Position[x, y]	700.3 [mm], 1531.5 [m], (139.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.9 ,V:163.2 [mm]
Result	-	Area	160.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#46, \$33	Date	2023/8/9 下午 04:13:29
Segment	1	Camera	1
Pattern	2024	Position[x, y]	374.9 [mm], 1531.1 [m], (139.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:643.6 [mm]
Result	-	Area	222.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#46, \$33	Date	2023/8/9 下午 04:13:29
Segment	1	Camera	1
Pattern	2024	Position[x, y]	699.8 [mm], 1531.1 [m], (139.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.9 ,V:644.0 [mm]
Result	-	Area	239.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#46, \$33	Date	2023/8/9 下午 04:13:29
Segment	1	Camera	1
Pattern	2024	Position[x, y]	567.0 [mm], 1531.2 [m], (139.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:744.0 [mm]
Result	-	Area	279.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#45, \$32	Date	2023/8/9 下午 04:13:29
Segment	1	Camera	1
Pattern	2023	Position[x, y]	567.0 [mm], 1530.3 [m], (140.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:552.4 [mm]
Result	-	Area	77.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#45, \$32	Date	2023/8/9 下午 04:13:29
Segment	1	Camera	1
Pattern	2023	Position[x, y]	242.0 [mm], 1530.6 [m], (140.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:415.6 [mm]
Result	-	Area	78.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#45, \$32	Date	2023/8/9 下午 04:13:29
Segment	1	Camera	1
Pattern	2023	Position[x, y]	699.8 [mm], 1530.7 [m], (140.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.9 ,V:239.6 [mm]
Result	-	Area	81.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#45, \$32	Date	2023/8/9 下午 04:13:29
Segment	1	Camera	1
Pattern	2023	Position[x, y]	699.8 [mm], 1530.4 [m], (140.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.6 ,V:458.4 [mm]
Result	-	Area	86.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#44, \$31	Date	2023/8/9 下午 04:13:28
Segment	1	Camera	1
Pattern	2022	Position[x, y]	375.8 [mm], 1529.6 [m], (141.3 [m])
Type	縱向刀絲疵點	Size	H:2.9 ,V:169.6 [mm]
Result	-	Area	21.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#44, \$31	Date	2023/8/9 下午 04:13:28
Segment	1	Camera	1
Pattern	2022	Position[x, y]	567.0 [mm], 1530.0 [m], (140.9 [m])
Type	縱向刀絲疵點	Size	H:0.2 ,V:147.6 [mm]
Result	-	Area	27.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#44, \$31	Date	2023/8/9 下午 04:13:28
Segment	1	Camera	1
Pattern	2022	Position[x, y]	450.1 [mm], 1529.6 [m], (141.3 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.4 [mm]
Result	-	Area	31.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#44, \$31	Date	2023/8/9 下午 04:13:28
Segment	1	Camera	1
Pattern	2022	Position[x, y]	375.1 [mm], 1529.9 [m], (141.0 [m])
Type	縱向刀絲疵點	Size	H:2.9 ,V:282.8 [mm]
Result	-	Area	34.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#41, \$30	Date	2023/8/9 下午 04:13:21
Segment	1	Camera	1
Pattern	2010	Position[x, y]	937.4 [mm], 1520.3 [m], (150.5 [m])
Type	面狀重疵點	Size	H:4.2 ,V:29.2 [mm]
Result	-	Area	65.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#41, \$30	Date	2023/8/9 下午 04:13:21
Segment	1	Camera	1
Pattern	2010	Position[x, y]	32.3 [mm], 1520.6 [m], (150.3 [m])
Type	面狀重疵點	Size	H:26.9 ,V:25.2 [mm]
Result	-	Area	142.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#41, \$30	Date	2023/8/9 下午 04:13:21
Segment	1	Camera	1
Pattern	2010	Position[x, y]	113.1 [mm], 1520.8 [m], (150.1 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.3 ,V:55.2 [mm]
Result	-	Area	275.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#41, \$30	Date	2023/8/9 下午 04:13:21
Segment	1	Camera	1
Pattern	2010	Position[x, y]	15.0 [mm], 1520.6 [m], (150.3 [m])
Type	点状疵点	Size	H:53.5 ,V:40.0 [mm]
Result	-	Area	1447.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#40, \$29	Date	2023/8/9 下午 04:13:20
Segment	1	Camera	1
Pattern	2009	Position[x, y]	32.3 [mm], 1519.8 [m], (151.0 [m])
Type	面狀重疵點	Size	H:26.9 ,V:25.2 [mm]
Result	-	Area	142.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#40, \$29	Date	2023/8/9 下午 04:13:20
Segment	1	Camera	1
Pattern	2009	Position[x, y]	100.4 [mm], 1519.6 [m], (151.3 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:115.5 ,V:27.2 [mm]
Result	-	Area	167.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#40, \$29	Date	2023/8/9 下午 04:13:20
Segment	1	Camera	1
Pattern	2009	Position[x, y]	745.0 [mm], 1519.6 [m], (151.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:173.6 ,V:28.0 [mm]
Result	-	Area	188.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#40, \$29	Date	2023/8/9 下午 04:13:20
Segment	1	Camera	1
Pattern	2009	Position[x, y]	15.0 [mm], 1519.8 [m], (151.0 [m])
Type	点状疵点	Size	H:53.7 ,V:40.0 [mm]
Result	-	Area	1447.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#39, \$28	Date	2023/8/9 下午 04:13:20
Segment	1	Camera	1
Pattern	2008	Position[x, y]	126.8 [mm], 1519.4 [m], (151.4 [m])
Type	面狀重疵點	Size	H:0.7 ,V:92.8 [mm]
Result	-	Area	68.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#39, \$28	Date	2023/8/9 下午 04:13:20
Segment	1	Camera	1
Pattern	2008	Position[x, y]	935.9 [mm], 1518.8 [m], (152.0 [m])
Type	縱向刀絲疵點橫向刀絲	Size	H:5.9 ,V:53.2 [mm]
Result	-	Area	87.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#39, \$28	Date	2023/8/9 下午 04:13:20
Segment	1	Camera	1
Pattern	2008	Position[x, y]	32.3 [mm], 1519.1 [m], (151.8 [m])
Type	面狀重疵點	Size	H:26.9 ,V:25.2 [mm]
Result	-	Area	142.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#39, \$28	Date	2023/8/9 下午 04:13:20
Segment	1	Camera	1
Pattern	2008	Position[x, y]	15.0 [mm], 1519.1 [m], (151.8 [m])
Type	点状疵点	Size	H:53.7 ,V:39.6 [mm]
Result	-	Area	1430.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#38, \$27	Date	2023/8/9 下午 04:13:19
Segment	1	Camera	1
Pattern	2007	Position[x, y]	936.4 [mm], 1518.1 [m], (152.8 [m])
Type	縱向刀絲疵點	Size	H:5.4 ,V:30.4 [mm]
Result	-	Area	87.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#38, \$27	Date	2023/8/9 下午 04:13:19
Segment	1	Camera	1
Pattern	2007	Position[x, y]	934.7 [mm], 1518.7 [m], (152.2 [m])
Type	面狀重疵點縱向刀絲疵點橫向刀絲	Size	H:9.3 ,V:122.8 [mm]
Result	-	Area	96.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#38, \$27	Date	2023/8/9 下午 04:13:19
Segment	1	Camera	1
Pattern	2007	Position[x, y]	935.7 [mm], 1518.1 [m], (152.8 [m])
Type	面状重疵点横向刀絲	Size	H:6.1 ,V:52.0 [mm]
Result	-	Area	107.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#38, \$27	Date	2023/8/9 下午 04:13:19
Segment	1	Camera	1
Pattern	2007	Position[x, y]	20.1 [mm], 1518.3 [m], (152.5 [m])
Type	点状疵点	Size	H:53.5 ,V:40.0 [mm]
Result	-	Area	1459.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#37, \$26	Date	2023/8/9 下午 04:13:19
Segment	1	Camera	1
Pattern	2006	Position[x, y]	935.9 [mm], 1517.3 [m], (153.5 [m])
Type	点状疵点	Size	H:6.8 ,V:51.2 [mm]
Result	-	Area	106.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#37, \$26	Date	2023/8/9 下午 04:13:19
Segment	1	Camera	1
Pattern	2006	Position[x, y]	934.7 [mm], 1518.1 [m], (152.8 [m])
Type	面狀重疵點縱向刀絲疵點橫向刀絲	Size	H:8.1 ,V:101.6 [mm]
Result	-	Area	107.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#37, \$26	Date	2023/8/9 下午 04:13:19
Segment	1	Camera	1
Pattern	2006	Position[x, y]	934.9 [mm], 1517.3 [m], (153.5 [m])
Type	縱向刀絲疵點橫向刀絲	Size	H:6.8 ,V:54.0 [mm]
Result	-	Area	111.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#37, \$26	Date	2023/8/9 下午 04:13:19
Segment	1	Camera	1
Pattern	2006	Position[x, y]	20.1 [mm], 1517.6 [m], (153.3 [m])
Type	点状疵点	Size	H:53.7 ,V:39.2 [mm]
Result	-	Area	1436.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#32, \$25	Date	2023/8/9 下午 04:04:50
Segment	1	Camera	1
Pattern	1713	Position[x, y]	383.2 [mm], 1293.7 [m], (377.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:30.0 ,V:809.6 [mm]
Result	-	Area	814.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#32, \$25	Date	2023/8/9 下午 04:04:50
Segment	1	Camera	1
Pattern	1713	Position[x, y]	242.5 [mm], 1293.9 [m], (377.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:3.7 ,V:809.6 [mm]
Result	-	Area	823.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#32, \$25	Date	2023/8/9 下午 04:04:50
Segment	1	Camera	1
Pattern	1713	Position[x, y]	65.0 [mm], 1293.7 [m], (377.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:18.3 ,V:442.8 [mm]
Result	-	Area	925.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#32, \$25	Date	2023/8/9 下午 04:04:50
Segment	1	Camera	1
Pattern	1713	Position[x, y]	58.7 [mm], 1294.0 [m], (376.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:697.6 [mm]
Result	-	Area	927.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#31, \$24	Date	2023/8/9 下午 04:04:49
Segment	1	Camera	1
Pattern	1712	Position[x, y]	374.6 [mm], 1293.3 [m], (377.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.6 ,V:680.8 [mm]
Result	-	Area	660.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#31, \$24	Date	2023/8/9 下午 04:04:49
Segment	1	Camera	1
Pattern	1712	Position[x, y]	229.4 [mm], 1293.1 [m], (377.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:34.9 ,V:808.0 [mm]
Result	-	Area	723.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#31, \$24	Date	2023/8/9 下午 04:04:49
Segment	1	Camera	1
Pattern	1712	Position[x, y]	58.9 [mm], 1293.3 [m], (377.6 [m])
Type	点状疵点	Size	H:4.4 ,V:680.8 [mm]
Result	-	Area	785.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#31, \$24	Date	2023/8/9 下午 04:04:49
Segment	1	Camera	1
Pattern	1712	Position[x, y]	67.2 [mm], 1293.0 [m], (377.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:31.0 ,V:808.0 [mm]
Result	-	Area	812.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#30, \$23	Date	2023/8/9 下午 04:04:49
Segment	1	Camera	1
Pattern	1711	Position[x, y]	374.9 [mm], 1292.5 [m], (378.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.4 ,V:706.0 [mm]
Result	-	Area	593.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#30, \$23	Date	2023/8/9 下午 04:04:49
Segment	1	Camera	1
Pattern	1711	Position[x, y]	229.4 [mm], 1292.3 [m], (378.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:34.4 ,V:797.2 [mm]
Result	-	Area	626.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#30, \$23	Date	2023/8/9 下午 04:04:49
Segment	1	Camera	1
Pattern	1711	Position[x, y]	66.3 [mm], 1292.2 [m], (378.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:18.6 ,V:422.8 [mm]
Result	-	Area	696.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#30, \$23	Date	2023/8/9 下午 04:04:49
Segment	1	Camera	1
Pattern	1711	Position[x, y]	58.7 [mm], 1292.5 [m], (378.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.6 ,V:706.0 [mm]
Result	-	Area	766.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#29, \$22	Date	2023/8/9 下午 04:04:48
Segment	1	Camera	1
Pattern	1710	Position[x, y]	380.0 [mm], 1291.4 [m], (379.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:13.7 ,V:423.6 [mm]
Result	-	Area	365.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#29, \$22	Date	2023/8/9 下午 04:04:48
Segment	1	Camera	1
Pattern	1710	Position[x, y]	243.0 [mm], 1291.4 [m], (379.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:442.0 [mm]
Result	-	Area	523.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#29, \$22	Date	2023/8/9 下午 04:04:48
Segment	1	Camera	1
Pattern	1710	Position[x, y]	58.9 [mm], 1291.9 [m], (379.0 [m])
Type	点状疵点	Size	H:3.9 ,V:322.8 [mm]
Result	-	Area	564.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#29, \$22	Date	2023/8/9 下午 04:04:48
Segment	1	Camera	1
Pattern	1710	Position[x, y]	66.0 [mm], 1291.4 [m], (379.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:30.8 ,V:441.6 [mm]
Result	-	Area	615.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#28, \$21	Date	2023/8/9 下午 04:04:48
Segment	1	Camera	1
Pattern	1709	Position[x, y]	64.6 [mm], 1290.5 [m], (380.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.7 ,V:87.2 [mm]
Result	-	Area	168.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#28, \$21	Date	2023/8/9 下午 04:04:48
Segment	1	Camera	1
Pattern	1709	Position[x, y]	243.0 [mm], 1290.7 [m], (380.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:463.6 [mm]
Result	-	Area	413.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#28, \$21	Date	2023/8/9 下午 04:04:48
Segment	1	Camera	1
Pattern	1709	Position[x, y]	59.2 [mm], 1291.0 [m], (379.9 [m])
Type	点状疵点	Size	H:3.9 ,V:454.8 [mm]
Result	-	Area	418.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#28, \$21	Date	2023/8/9 下午 04:04:48
Segment	1	Camera	1
Pattern	1709	Position[x, y]	64.6 [mm], 1290.6 [m], (380.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:13.4 ,V:462.8 [mm]
Result	-	Area	484.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#25, \$20	Date	2023/8/9 下午 04:04:40
Segment	1	Camera	1
Pattern	1698	Position[x, y]	460.3 [mm], 1281.5 [m], (389.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:193.8 ,V:230.8 [mm]
Result	-	Area	1182.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#25, \$20	Date	2023/8/9 下午 04:04:40
Segment	1	Camera	1
Pattern	1698	Position[x, y]	787.7 [mm], 1281.6 [m], (389.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:185.5 ,V:473.6 [mm]
Result	-	Area	1425.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#25, \$20	Date	2023/8/9 下午 04:04:40
Segment	1	Camera	1
Pattern	1698	Position[x, y]	474.2 [mm], 1281.7 [m], (389.1 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.6 ,V:556.0 [mm]
Result	-	Area	2623.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#25, \$20	Date	2023/8/9 下午 04:04:40
Segment	1	Camera	1
Pattern	1698	Position[x, y]	782.6 [mm], 1281.7 [m], (389.2 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.3 ,V:556.4 [mm]
Result	-	Area	5043.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$19	Date	2023/8/9 下午 04:04:40
Segment	1	Camera	1
Pattern	1697	Position[x, y]	464.9 [mm], 1280.9 [m], (390.0 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.8 ,V:425.6 [mm]
Result	-	Area	629.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$19	Date	2023/8/9 下午 04:04:40
Segment	1	Camera	1
Pattern	1697	Position[x, y]	804.8 [mm], 1280.8 [m], (390.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:185.5 ,V:432.4 [mm]
Result	-	Area	771.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$19	Date	2023/8/9 下午 04:04:40
Segment	1	Camera	1
Pattern	1697	Position[x, y]	789.4 [mm], 1281.3 [m], (389.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.8 ,V:709.6 [mm]
Result	-	Area	3545.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$19	Date	2023/8/9 下午 04:04:40
Segment	1	Camera	1
Pattern	1697	Position[x, y]	784.0 [mm], 1281.0 [m], (389.9 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.3 ,V:809.6 [mm]
Result	-	Area	3672.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#23, \$18	Date	2023/8/9 下午 04:04:39
Segment	1	Camera	1
Pattern	1696	Position[x, y]	755.0 [mm], 1280.1 [m], (390.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:185.3 ,V:446.4 [mm]
Result	-	Area	605.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#23, \$18	Date	2023/8/9 下午 04:04:39
Segment	1	Camera	1
Pattern	1696	Position[x, y]	461.5 [mm], 1280.2 [m], (390.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.8 ,V:602.8 [mm]
Result	-	Area	1018.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#23, \$18	Date	2023/8/9 下午 04:04:39
Segment	1	Camera	1
Pattern	1696	Position[x, y]	802.1 [mm], 1280.4 [m], (390.4 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:696.8 [mm]
Result	-	Area	2371.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#23, \$18	Date	2023/8/9 下午 04:04:39
Segment	1	Camera	1
Pattern	1696	Position[x, y]	786.7 [mm], 1280.1 [m], (390.7 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.3 ,V:811.2 [mm]
Result	-	Area	2498.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#22, \$17	Date	2023/8/9 下午 04:04:39
Segment	1	Camera	1
Pattern	1695	Position[x, y]	762.1 [mm], 1279.7 [m], (391.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:39.3 ,V:180.8 [mm]
Result	-	Area	131.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#22, \$17	Date	2023/8/9 下午 04:04:39
Segment	1	Camera	1
Pattern	1695	Position[x, y]	704.9 [mm], 1279.6 [m], (391.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:13.7 ,V:510.0 [mm]
Result	-	Area	382.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#22, \$17	Date	2023/8/9 下午 04:04:39
Segment	1	Camera	1
Pattern	1695	Position[x, y]	879.5 [mm], 1279.4 [m], (391.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:14.9 ,V:444.0 [mm]
Result	-	Area	417.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#22, \$17	Date	2023/8/9 下午 04:04:39
Segment	1	Camera	1
Pattern	1695	Position[x, y]	882.7 [mm], 1279.7 [m], (391.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:538.4 [mm]
Result	-	Area	579.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#21, \$16	Date	2023/8/9 下午 04:04:38
Segment	1	Camera	1
Pattern	1694	Position[x, y]	748.2 [mm], 1279.0 [m], (391.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:71.6 [mm]
Result	-	Area	12.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#21, \$16	Date	2023/8/9 下午 04:04:38
Segment	1	Camera	1
Pattern	1694	Position[x, y]	701.0 [mm], 1279.2 [m], (391.7 [m])
Type	点状疵点	Size	H:0.5 ,V:85.2 [mm]
Result	-	Area	20.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#21, \$16	Date	2023/8/9 下午 04:04:38
Segment	1	Camera	1
Pattern	1694	Position[x, y]	772.6 [mm], 1279.1 [m], (391.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.6 [mm]
Result	-	Area	47.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#21, \$16	Date	2023/8/9 下午 04:04:38
Segment	1	Camera	1
Pattern	1694	Position[x, y]	881.9 [mm], 1279.2 [m], (391.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:14.6 ,V:192.0 [mm]
Result	-	Area	91.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#18, \$15	Date	2023/8/9 下午 04:04:24
Segment	1	Camera	1
Pattern	1675	Position[x, y]	391.7 [mm], 1264.8 [m], (406.1 [m])
Type	点状疵点	Size	H:191.4 ,V:315.2 [mm]
Result	-	Area	755.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#18, \$15	Date	2023/8/9 下午 04:04:24
Segment	1	Camera	1
Pattern	1675	Position[x, y]	433.7 [mm], 1264.3 [m], (406.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.1 ,V:637.6 [mm]
Result	-	Area	860.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#18, \$15	Date	2023/8/9 下午 04:04:24
Segment	1	Camera	1
Pattern	1675	Position[x, y]	99.2 [mm], 1264.7 [m], (406.1 [m])
Type	点状疵点	Size	H:186.3 ,V:316.0 [mm]
Result	-	Area	2106.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#18, \$15	Date	2023/8/9 下午 04:04:24
Segment	1	Camera	1
Pattern	1675	Position[x, y]	134.6 [mm], 1264.3 [m], (406.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.0 ,V:451.2 [mm]
Result	-	Area	2152.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#17, \$14	Date	2023/8/9 下午 04:04:22
Segment	1	Camera	1
Pattern	1674	Position[x, y]	476.4 [mm], 1263.9 [m], (407.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:193.4 ,V:358.8 [mm]
Result	-	Area	1115.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#17, \$14	Date	2023/8/9 下午 04:04:22
Segment	1	Camera	1
Pattern	1674	Position[x, y]	448.1 [mm], 1263.6 [m], (407.3 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.8 ,V:470.0 [mm]
Result	-	Area	1824.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#17, \$14	Date	2023/8/9 下午 04:04:22
Segment	1	Camera	1
Pattern	1674	Position[x, y]	152.2 [mm], 1263.7 [m], (407.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:186.3 ,V:674.0 [mm]
Result	-	Area	2131.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#17, \$14	Date	2023/8/9 下午 04:04:22
Segment	1	Camera	1
Pattern	1674	Position[x, y]	129.5 [mm], 1263.6 [m], (407.3 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.8 ,V:469.6 [mm]
Result	-	Area	3355.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#16, \$13	Date	2023/8/9 下午 04:04:21
Segment	1	Camera	1
Pattern	1673	Position[x, y]	766.2 [mm], 1263.0 [m], (407.8 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:130.4 [mm]
Result	-	Area	641.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#16, \$13	Date	2023/8/9 下午 04:04:21
Segment	1	Camera	1
Pattern	1673	Position[x, y]	103.6 [mm], 1262.6 [m], (408.2 [m])
Type	点状疵点	Size	H:185.8 ,V:53.2 [mm]
Result	-	Area	738.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#16, \$13	Date	2023/8/9 下午 04:04:21
Segment	1	Camera	1
Pattern	1673	Position[x, y]	148.8 [mm], 1262.9 [m], (408.0 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.5 ,V:430.0 [mm]
Result	-	Area	3147.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範囲 : 83.6 ~ 1024.2 [mm] 宽度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	1670.9 [m]	
Segments	1 (從左側)	

Defect information

No.	#16, \$13	Date	2023/8/9 下午 04:04:21
Segment	1	Camera	1
Pattern	1673	Position[x, y]	181.7 [mm], 1263.2 [m], (407.7 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.5 ,V:707.2 [mm]
Result	—	Area	3618.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#15, \$12	Date	2023/8/9 下午 04:04:20
Segment	1	Camera	1
Pattern	1672	Position[x, y]	755.5 [mm], 1261.9 [m], (408.9 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.8 ,V:162.4 [mm]
Result	-	Area	724.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#15, \$12	Date	2023/8/9 下午 04:04:20
Segment	1	Camera	1
Pattern	1672	Position[x, y]	162.0 [mm], 1262.2 [m], (408.7 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:248.8 [mm]
Result	-	Area	758.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#15, \$12	Date	2023/8/9 下午 04:04:20
Segment	1	Camera	1
Pattern	1672	Position[x, y]	111.4 [mm], 1261.9 [m], (408.9 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.8 ,V:92.4 [mm]
Result	-	Area	848.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#15, \$12	Date	2023/8/9 下午 04:04:20
Segment	1	Camera	1
Pattern	1672	Position[x, y]	165.4 [mm], 1262.4 [m], (408.4 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:374.0 [mm]
Result	-	Area	1647.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 下午 04:04:18
Segment	1	Camera	1
Pattern	1671	Position[x, y]	752.5 [mm], 1261.7 [m], (409.1 [m])
Type	点状疵点	Size	H:74.0 ,V:169.6 [mm]
Result	-	Area	401.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 下午 04:04:18
Segment	1	Camera	1
Pattern	1671	Position[x, y]	443.2 [mm], 1261.5 [m], (409.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:192.9 ,V:23.6 [mm]
Result	-	Area	584.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 下午 04:04:18
Segment	1	Camera	1
Pattern	1671	Position[x, y]	802.6 [mm], 1261.7 [m], (409.2 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.1 ,V:351.2 [mm]
Result	-	Area	988.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 下午 04:04:18
Segment	1	Camera	1
Pattern	1671	Position[x, y]	789.7 [mm], 1261.4 [m], (409.5 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.1 ,V:776.8 [mm]
Result	-	Area	1132.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#12, \$10	Date	2023/8/9 下午 04:04:14
Segment	1	Camera	1
Pattern	1669	Position[x, y]	737.4 [mm], 1260.2 [m], (410.6 [m])
Type	点状疵点横向刀絲	Size	H:72.5 ,V:117.6 [mm]
Result	-	Area	169.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#12, \$10	Date	2023/8/9 下午 04:04:14
Segment	1	Camera	1
Pattern	1669	Position[x, y]	174.2 [mm], 1259.8 [m], (411.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:137.9 ,V:333.2 [mm]
Result	-	Area	330.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#12, \$10	Date	2023/8/9 下午 04:04:14
Segment	1	Camera	1
Pattern	1669	Position[x, y]	129.3 [mm], 1260.2 [m], (410.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:329.6 [mm]
Result	-	Area	972.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#12, \$10	Date	2023/8/9 下午 04:04:14
Segment	1	Camera	1
Pattern	1669	Position[x, y]	142.7 [mm], 1259.8 [m], (411.1 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.5 ,V:620.8 [mm]
Result	-	Area	999.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#11, \$9	Date	2023/8/9 下午 04:04:09
Segment	1	Camera	1
Pattern	1668	Position[x, y]	457.1 [mm], 1258.9 [m], (411.9 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:192.9 ,V:85.6 [mm]
Result	-	Area	435.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#11, \$9	Date	2023/8/9 下午 04:04:09
Segment	1	Camera	1
Pattern	1668	Position[x, y]	62.6 [mm], 1259.5 [mm], (411.3 [mm])
Type	点状疵点	Size	H:48.1 ,V:314.8 [mm]
Result	-	Area	489.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#11, \$9	Date	2023/8/9 下午 04:04:09
Segment	1	Camera	1
Pattern	1668	Position[x, y]	130.2 [mm], 1258.9 [m], (412.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:185.5 ,V:77.6 [mm]
Result	-	Area	503.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#11, \$9	Date	2023/8/9 下午 04:04:09
Segment	1	Camera	1
Pattern	1668	Position[x, y]	146.3 [mm], 1259.0 [m], (411.9 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.3 ,V:453.6 [mm]
Result	-	Area	632.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#9, \$8	Date	2023/8/9 下午 04:01:07
Segment	1	Camera	1
Pattern	1667	Position[x, y]	152.4 [mm], 1258.2 [m], (412.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:86.4 [mm]
Result	-	Area	319.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#9, \$8	Date	2023/8/9 下午 04:01:07
Segment	1	Camera	1
Pattern	1667	Position[x, y]	465.9 [mm], 1258.2 [m], (412.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.1 ,V:86.4 [mm]
Result	-	Area	320.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#9, \$8	Date	2023/8/9 下午 04:01:07
Segment	1	Camera	1
Pattern	1667	Position[x, y]	149.8 [mm], 1258.5 [m], (412.3 [m])
Type	点状疵点	Size	H:184.3 ,V:2.8 [mm]
Result	-	Area	420.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#9, \$8	Date	2023/8/9 下午 04:01:07
Segment	1	Camera	1
Pattern	1667	Position[x, y]	138.8 [mm], 1258.6 [m], (412.3 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.1 ,V:136.8 [mm]
Result	-	Area	445.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#8, \$7	Date	2023/8/9 下午 04:01:04
Segment	1	Camera	1
Pattern	1666	Position[x, y]	496.9 [mm], 1257.8 [m], (413.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:108.9 ,V:65.6 [mm]
Result	-	Area	117.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#8, \$7	Date	2023/8/9 下午 04:01:04
Segment	1	Camera	1
Pattern	1666	Position[x, y]	149.5 [mm], 1257.4 [m], (413.5 [m])
Type	点状疵点	Size	H:182.6 ,V:1.6 [mm]
Result	-	Area	212.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#8, \$7	Date	2023/8/9 下午 04:01:04
Segment	1	Camera	1
Pattern	1666	Position[x, y]	458.8 [mm], 1257.4 [m], (413.4 [m])
Type	点状疵点	Size	H:189.7 ,V:1.6 [mm]
Result	-	Area	262.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#8, \$7	Date	2023/8/9 下午 04:01:04
Segment	1	Camera	1
Pattern	1666	Position[x, y]	157.3 [mm], 1257.5 [m], (413.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:184.3 ,V:58.8 [mm]
Result	-	Area	293.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#7, \$6	Date	2023/8/9 下午 04:01:03
Segment	1	Camera	1
Pattern	1665	Position[x, y]	217.4 [mm], 1257.0 [m], (413.9 [m])
Type	点状疵点	Size	H:49.3 ,V:1.2 [mm]
Result	-	Area	40.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範囲 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	参照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#7, \$6	Date	2023/8/9 下午 04:01:03
Segment	1	Camera	1
Pattern	1665	Position[x, y]	504.7 [mm], 1257.0 [m], (413.8 [m])
Type	点状疵点	Size	H:72.0 ,V:1.2 [mm]
Result	-	Area	64.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#7, \$6	Date	2023/8/9 下午 04:01:03
Segment	1	Camera	1
Pattern	1665	Position[x, y]	407.1 [mm], 1257.0 [m], (413.8 [m])
Type	点状疵点	Size	H:65.9 ,V:1.2 [mm]
Result	-	Area	72.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#7, \$6	Date	2023/8/9 下午 04:01:03
Segment	1	Camera	1
Pattern	1665	Position[x, y]	148.3 [mm], 1257.0 [m], (413.9 [m])
Type	点状疵点	Size	H:77.9 ,V:1.2 [mm]
Result	-	Area	77.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	49	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#6, \$5	Date	2023/8/9 下午 03:57:54
Segment	1	Camera	1
Pattern	1345	Position[x, y]	796.7 [mm], 1016.4 [m], (654.5 [m])
Type	縱向刀絲疵點	Size	H:2.9 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#5, \$4	Date	2023/8/9 下午 03:57:38
Segment	1	Camera	1
Pattern	1317	Position[x, y]	783.1 [mm], 995.8 [m], (675.0 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:2.0 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#4, \$3	Date	2023/8/9 下午 03:53:11
Segment	1	Camera	1
Pattern	863	Position[x, y]	829.7 [mm], 654.4 [m], (1016.5 [m])
Type	縱向刀絲疵點	Size	H:3.7 ,V:1.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#3, \$2	Date	2023/8/9 下午 03:50:48
Segment	1	Camera	1
Pattern	620	Position[x, y]	798.0 [mm], 471.9 [m], (1199.0 [m])
Type	縱向刀絲疵點	Size	H:1.7 ,V:2.4 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 7

Inspected date : 2023/8/9 下午 03:44:45 ~ 2023/8/9 下午 04:15:13

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	49	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	1670.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#2, \$1	Date	2023/8/9 下午 03:45:05
Segment	1	Camera	1
Pattern	36	Position[x, y]	878.3 [mm], 33.7 [m], (1637.1 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

