

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#108, \$91	Date	2023/8/10 上午 09:15:10
Segment	1	Camera	1
Pattern	8036	Position[ x, y ]	6.2 [mm], 6043.4 [m], ( 3.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:12.5 ,V:16.4 [mm]
Result	-	Area	148.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#107, \$90	Date	2023/8/10 上午 09:14:54
Segment	1	Camera	1
Pattern	8009	Position[ x, y ]	698.1 [mm], 6022.9 [m], ( 23.6 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:14.0 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#106, \$89	Date	2023/8/10 上午 09:14:53
Segment	1	Camera	1
Pattern	8007	Position[ x, y ]	698.1 [mm], 6022.0 [m], ( 24.5 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:36.4 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#106, \$89	Date	2023/8/10 上午 09:14:53
Segment	1	Camera	1
Pattern	8007	Position[ x, y ]	566.1 [mm], 6021.6 [m], ( 24.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:48.0 [mm]
Result	-	Area	11.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#103, \$88	Date	2023/8/10 上午 09:14:28
Segment	1	Camera	1
Pattern	7965	Position[ x, y ]	564.1 [mm], 5990.6 [m], ( 56.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:251.2 [mm]
Result	-	Area	118.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#103, \$88	Date	2023/8/10 上午 09:14:28
Segment	1	Camera	1
Pattern	7965	Position[ x, y ]	697.4 [mm], 5990.2 [m], ( 56.4 [m] )
Type	点状疵点	Size	H:0.7 ,V:326.8 [mm]
Result	-	Area	126.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#103, \$88	Date	2023/8/10 上午 09:14:28
Segment	1	Camera	1
Pattern	7965	Position[ x, y ]	564.1 [mm], 5990.2 [m], ( 56.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:665.6 [mm]
Result	-	Area	163.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#103, \$88	Date	2023/8/10 上午 09:14:28
Segment	1	Camera	1
Pattern	7965	Position[ x, y ]	371.5 [mm], 5990.1 [m], ( 56.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:327.6 [mm]
Result	-	Area	167.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#102, \$87	Date	2023/8/10 上午 09:14:28
Segment	1	Camera	1
Pattern	7964	Position[ x, y ]	239.1 [mm], 5989.7 [m], ( 56.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:380.8 [mm]
Result	-	Area	112.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#102, \$87	Date	2023/8/10 上午 09:14:28
Segment	1	Camera	1
Pattern	7964	Position[ x, y ]	371.5 [mm], 5989.8 [m], ( 56.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:284.4 [mm]
Result	-	Area	128.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information ( No. 2 )


商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#102, \$87	Date	2023/8/10 上午 09:14:28
Segment	1	Camera	1
Pattern	7964	Position[ x, y ]	696.2 [mm], 5989.8 [m], ( 56.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:283.6 [mm]
Result	—	Area	128.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#102, \$87	Date	2023/8/10 上午 09:14:28
Segment	1	Camera	1
Pattern	7964	Position[ x, y ]	564.3 [mm], 5989.7 [m], ( 56.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:478.0 [mm]
Result	-	Area	153.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#101, \$86	Date	2023/8/10 上午 09:14:27
Segment	1	Camera	1
Pattern	7963	Position[ x, y ]	371.7 [mm], 5989.0 [m], ( 57.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:266.4 [mm]
Result	-	Area	126.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#101, \$86	Date	2023/8/10 上午 09:14:27
Segment	1	Camera	1
Pattern	7963	Position[ x, y ]	564.6 [mm], 5989.0 [m], ( 57.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:267.2 [mm]
Result	-	Area	134.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#101, \$86	Date	2023/8/10 上午 09:14:27
Segment	1	Camera	1
Pattern	7963	Position[ x, y ]	371.5 [mm], 5988.6 [m], ( 58.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:327.6 [mm]
Result	-	Area	156.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#101, \$86	Date	2023/8/10 上午 09:14:27
Segment	1	Camera	1
Pattern	7963	Position[ x, y ]	564.1 [mm], 5988.7 [m], ( 57.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:437.6 [mm]
Result	-	Area	157.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#100, \$85	Date	2023/8/10 上午 09:14:27
Segment	1	Camera	1
Pattern	7962	Position[ x, y ]	371.7 [mm], 5987.9 [m], ( 58.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:208.0 [mm]
Result	-	Area	42.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#100, \$85	Date	2023/8/10 上午 09:14:27
Segment	1	Camera	1
Pattern	7962	Position[ x, y ]	565.6 [mm], 5988.0 [m], ( 58.6 [m] )
Type	点状疵点	Size	H:0.5 ,V:180.4 [mm]
Result	-	Area	76.5 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#100, \$85	Date	2023/8/10 上午 09:14:27
Segment	1	Camera	1
Pattern	7962	Position[ x, y ]	371.5 [mm], 5988.3 [m], ( 58.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:295.6 [mm]
Result	-	Area	81.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#100, \$85	Date	2023/8/10 上午 09:14:27
Segment	1	Camera	1
Pattern	7962	Position[ x, y ]	565.6 [mm], 5988.3 [m], ( 58.3 [m] )
Type	点状疵点	Size	H:1.5 ,V:296.0 [mm]
Result	-	Area	140.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#99, \$84	Date	2023/8/10 上午 09:14:26
Segment	1	Camera	1
Pattern	7961	Position[ x, y ]	240.6 [mm], 5987.6 [m], ( 58.9 [m] )
Type	点状疵点	Size	H:0.5 ,V:4.0 [mm]
Result	-	Area	1.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#99, \$84	Date	2023/8/10 上午 09:14:26
Segment	1	Camera	1
Pattern	7961	Position[ x, y ]	697.6 [mm], 5987.6 [m], ( 59.0 [m] )
Type	点状疵点	Size	H:0.5 ,V:5.2 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#99, \$84	Date	2023/8/10 上午 09:14:26
Segment	1	Camera	1
Pattern	7961	Position[ x, y ]	565.6 [mm], 5987.6 [m], ( 58.9 [m] )
Type	点状疵点	Size	H:0.5 ,V:26.8 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#96, \$83	Date	2023/8/10 上午 09:14:18
Segment	1	Camera	1
Pattern	7947	Position[ x, y ]	565.6 [mm], 5976.9 [m], ( 69.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:668.4 [mm]
Result	-	Area	407.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#96, \$83	Date	2023/8/10 上午 09:14:18
Segment	1	Camera	1
Pattern	7947	Position[ x, y ]	240.6 [mm], 5976.7 [m], ( 69.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:806.4 [mm]
Result	-	Area	428.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#96, \$83	Date	2023/8/10 上午 09:14:18
Segment	1	Camera	1
Pattern	7947	Position[ x, y ]	698.1 [mm], 5976.7 [m], ( 69.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.9 ,V:681.6 [mm]
Result	-	Area	435.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#96, \$83	Date	2023/8/10 上午 09:14:18
Segment	1	Camera	1
Pattern	7947	Position[ x, y ]	373.4 [mm], 5976.7 [m], ( 69.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.6 ,V:697.2 [mm]
Result	-	Area	453.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#95, \$82	Date	2023/8/10 上午 09:14:17
Segment	1	Camera	1
Pattern	7946	Position[ x, y ]	698.4 [mm], 5976.1 [m], ( 70.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.4 ,V:504.8 [mm]
Result	-	Area	267.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information ( No. 2 )


商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#95, \$82	Date	2023/8/10 上午 09:14:17
Segment	1	Camera	1
Pattern	7946	Position[ x, y ]	565.6 [mm], 5976.0 [m], ( 70.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:808.0 [mm]
Result	—	Area	289.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



### Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information ( No. 2 )


商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#95, \$82	Date	2023/8/10 上午 09:14:17
Segment	1	Camera	1
Pattern	7946	Position[ x, y ]	373.4 [mm], 5976.1 [m], ( 70.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.6 ,V:559.2 [mm]
Result	—	Area	308.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#95, \$82	Date	2023/8/10 上午 09:14:17
Segment	1	Camera	1
Pattern	7946	Position[ x, y ]	240.6 [mm], 5976.2 [m], ( 70.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:549.6 [mm]
Result	-	Area	316.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#94, \$81	Date	2023/8/10 上午 09:14:17
Segment	1	Camera	1
Pattern	7945	Position[ x, y ]	697.9 [mm], 5975.6 [m], ( 71.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.4 ,V:101.2 [mm]
Result	-	Area	56.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#94, \$81	Date	2023/8/10 上午 09:14:17
Segment	1	Camera	1
Pattern	7945	Position[ x, y ]	698.4 [mm], 5975.2 [m], ( 71.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.7 ,V:625.2 [mm]
Result	-	Area	66.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#94, \$81	Date	2023/8/10 上午 09:14:17
Segment	1	Camera	1
Pattern	7945	Position[ x, y ]	240.6 [mm], 5975.3 [m], ( 71.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:479.2 [mm]
Result	-	Area	107.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#94, \$81	Date	2023/8/10 上午 09:14:17
Segment	1	Camera	1
Pattern	7945	Position[ x, y ]	565.6 [mm], 5975.2 [m], ( 71.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:808.0 [mm]
Result	-	Area	152.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#93, \$80	Date	2023/8/10 上午 09:14:16
Segment	1	Camera	1
Pattern	7944	Position[ x, y ]	127.8 [mm], 5974.8 [m], ( 71.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.0 [mm]
Result	-	Area	27.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#93, \$80	Date	2023/8/10 上午 09:14:16
Segment	1	Camera	1
Pattern	7944	Position[ x, y ]	770.9 [mm], 5974.4 [m], ( 72.1 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:52.8 [mm]
Result	-	Area	29.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#93, \$80	Date	2023/8/10 上午 09:14:16
Segment	1	Camera	1
Pattern	7944	Position[ x, y ]	770.9 [mm], 5974.8 [m], ( 71.8 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:97.2 [mm]
Result	-	Area	36.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#93, \$80	Date	2023/8/10 上午 09:14:16
Segment	1	Camera	1
Pattern	7944	Position[ x, y ]	448.1 [mm], 5974.8 [m], ( 71.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:96.4 [mm]
Result	-	Area	45.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#92, \$79	Date	2023/8/10 上午 09:14:15
Segment	1	Camera	1
Pattern	7943	Position[ x, y ]	746.2 [mm], 5974.0 [m], ( 72.5 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:73.6 [mm]
Result	-	Area	20.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#92, \$79	Date	2023/8/10 上午 09:14:15
Segment	1	Camera	1
Pattern	7943	Position[ x, y ]	422.7 [mm], 5973.6 [m], ( 72.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:73.6 [mm]
Result	-	Area	23.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#92, \$79	Date	2023/8/10 上午 09:14:15
Segment	1	Camera	1
Pattern	7943	Position[ x, y ]	448.4 [mm], 5973.6 [m], ( 72.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.0 [mm]
Result	-	Area	26.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#92, \$79	Date	2023/8/10 上午 09:14:15
Segment	1	Camera	1
Pattern	7943	Position[ x, y ]	770.9 [mm], 5974.0 [m], ( 72.5 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:96.8 [mm]
Result	-	Area	35.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#89, \$78	Date	2023/8/10 上午 09:14:08
Segment	1	Camera	1
Pattern	7930	Position[ x, y ]	126.4 [mm], 5964.3 [m], ( 82.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:98.0 [mm]
Result	-	Area	135.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#89, \$78	Date	2023/8/10 上午 09:14:08
Segment	1	Camera	1
Pattern	7930	Position[ x, y ]	447.2 [mm], 5963.9 [m], ( 82.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:98.0 [mm]
Result	-	Area	135.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#89, \$78	Date	2023/8/10 上午 09:14:08
Segment	1	Camera	1
Pattern	7930	Position[ x, y ]	769.4 [mm], 5964.3 [m], ( 82.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:98.0 [mm]
Result	-	Area	138.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#89, \$78	Date	2023/8/10 上午 09:14:08
Segment	1	Camera	1
Pattern	7930	Position[ x, y ]	447.2 [mm], 5964.3 [m], ( 82.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:97.6 [mm]
Result	-	Area	148.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#88, \$77	Date	2023/8/10 上午 09:14:07
Segment	1	Camera	1
Pattern	7929	Position[ x, y ]	769.4 [mm], 5963.5 [m], ( 83.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:98.0 [mm]
Result	-	Area	112.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#88, \$77	Date	2023/8/10 上午 09:14:07
Segment	1	Camera	1
Pattern	7929	Position[ x, y ]	126.4 [mm], 5963.5 [m], ( 83.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:98.0 [mm]
Result	-	Area	114.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#88, \$77	Date	2023/8/10 上午 09:14:07
Segment	1	Camera	1
Pattern	7929	Position[ x, y ]	447.2 [mm], 5963.1 [m], ( 83.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:97.6 [mm]
Result	-	Area	125.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#88, \$77	Date	2023/8/10 上午 09:14:07
Segment	1	Camera	1
Pattern	7929	Position[ x, y ]	447.2 [mm], 5963.5 [m], ( 83.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:98.0 [mm]
Result	-	Area	136.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#87, \$76	Date	2023/8/10 上午 09:14:07
Segment	1	Camera	1
Pattern	7928	Position[ x, y ]	447.4 [mm], 5962.4 [m], ( 84.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	70.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#87, \$76	Date	2023/8/10 上午 09:14:07
Segment	1	Camera	1
Pattern	7928	Position[ x, y ]	126.4 [mm], 5962.4 [m], ( 84.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	72.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#87, \$76	Date	2023/8/10 上午 09:14:07
Segment	1	Camera	1
Pattern	7928	Position[ x, y ]	126.4 [mm], 5962.8 [m], ( 83.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.6 [mm]
Result	-	Area	72.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#87, \$76	Date	2023/8/10 上午 09:14:07
Segment	1	Camera	1
Pattern	7928	Position[ x, y ]	447.2 [mm], 5962.8 [m], ( 83.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	84.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#86, \$75	Date	2023/8/10 上午 09:14:06
Segment	1	Camera	1
Pattern	7927	Position[ x, y ]	769.7 [mm], 5962.0 [m], ( 84.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:96.4 [mm]
Result	-	Area	23.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#86, \$75	Date	2023/8/10 上午 09:14:06
Segment	1	Camera	1
Pattern	7927	Position[ x, y ]	446.9 [mm], 5961.6 [m], ( 84.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.0 [mm]
Result	-	Area	42.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#86, \$75	Date	2023/8/10 上午 09:14:06
Segment	1	Camera	1
Pattern	7927	Position[ x, y ]	126.6 [mm], 5962.0 [m], ( 84.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.6 [mm]
Result	-	Area	52.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#86, \$75	Date	2023/8/10 上午 09:14:06
Segment	1	Camera	1
Pattern	7927	Position[ x, y ]	447.4 [mm], 5962.0 [m], ( 84.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.2 [mm]
Result	-	Area	56.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#85, \$74	Date	2023/8/10 上午 09:14:06
Segment	1	Camera	1
Pattern	7926	Position[ x, y ]	126.1 [mm], 5961.2 [m], ( 85.3 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:27.6 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#85, \$74	Date	2023/8/10 上午 09:14:06
Segment	1	Camera	1
Pattern	7926	Position[ x, y ]	446.9 [mm], 5961.3 [m], ( 85.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:24.0 [mm]
Result	-	Area	6.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#82, \$73	Date	2023/8/10 上午 09:13:57
Segment	1	Camera	1
Pattern	7912	Position[ x, y ]	697.9 [mm], 5950.7 [m], ( 95.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.9 ,V:454.0 [mm]
Result	-	Area	480.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3



## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#82, \$73	Date	2023/8/10 上午 09:13:57
Segment	1	Camera	1
Pattern	7912	Position[ x, y ]	565.1 [mm], 5950.7 [m], ( 95.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:664.4 [mm]
Result	-	Area	483.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#82, \$73	Date	2023/8/10 上午 09:13:57
Segment	1	Camera	1
Pattern	7912	Position[ x, y ]	240.1 [mm], 5950.7 [m], ( 95.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:664.8 [mm]
Result	-	Area	496.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information ( No. 2 )


商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#82, \$73	Date	2023/8/10 上午 09:13:57
Segment	1	Camera	1
Pattern	7912	Position[ x, y ]	372.9 [mm], 5950.7 [m], ( 95.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:454.8 [mm]
Result	—	Area	539.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



### Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information ( No. 2 )


商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#81, \$72	Date	2023/8/10 上午 09:13:57
Segment	1	Camera	1
Pattern	7911	Position[ x, y ]	565.1 [mm], 5949.9 [m], ( 96.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:433.6 [mm]
Result	—	Area	214.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#81, \$72	Date	2023/8/10 上午 09:13:57
Segment	1	Camera	1
Pattern	7911	Position[ x, y ]	697.6 [mm], 5950.0 [m], ( 96.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.6 ,V:436.0 [mm]
Result	-	Area	278.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#81, \$72	Date	2023/8/10 上午 09:13:57
Segment	1	Camera	1
Pattern	7911	Position[ x, y ]	373.2 [mm], 5950.0 [m], ( 96.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:436.8 [mm]
Result	-	Area	289.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#81, \$72	Date	2023/8/10 上午 09:13:57
Segment	1	Camera	1
Pattern	7911	Position[ x, y ]	240.1 [mm], 5949.9 [m], ( 96.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:451.2 [mm]
Result	-	Area	303.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#80, \$71	Date	2023/8/10 上午 09:13:56
Segment	1	Camera	1
Pattern	7910	Position[ x, y ]	239.9 [mm], 5948.9 [m], ( 97.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:474.8 [mm]
Result	-	Area	64.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#80, \$71	Date	2023/8/10 上午 09:13:56
Segment	1	Camera	1
Pattern	7910	Position[ x, y ]	770.2 [mm], 5948.9 [m], ( 97.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:98.0 [mm]
Result	-	Area	69.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



G M G M



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#80, \$71	Date	2023/8/10 上午 09:13:56
Segment	1	Camera	1
Pattern	7910	Position[ x, y ]	447.6 [mm], 5948.9 [m], ( 97.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	88.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#80, \$71	Date	2023/8/10 上午 09:13:56
Segment	1	Camera	1
Pattern	7910	Position[ x, y ]	127.1 [mm], 5948.9 [m], ( 97.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	89.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#79, \$70	Date	2023/8/10 上午 09:13:56
Segment	1	Camera	1
Pattern	7909	Position[ x, y ]	127.1 [mm], 5948.5 [m], ( 98.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.6 [mm]
Result	-	Area	42.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#79, \$70	Date	2023/8/10 上午 09:13:56
Segment	1	Camera	1
Pattern	7909	Position[ x, y ]	447.6 [mm], 5948.1 [m], ( 98.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:98.0 [mm]
Result	-	Area	47.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#79, \$70	Date	2023/8/10 上午 09:13:56
Segment	1	Camera	1
Pattern	7909	Position[ x, y ]	770.6 [mm], 5948.5 [m], ( 98.0 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:97.2 [mm]
Result	-	Area	51.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#79, \$70	Date	2023/8/10 上午 09:13:56
Segment	1	Camera	1
Pattern	7909	Position[ x, y ]	447.9 [mm], 5948.5 [m], ( 98.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.6 [mm]
Result	-	Area	59.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#78, \$69	Date	2023/8/10 上午 09:13:55
Segment	1	Camera	1
Pattern	7908	Position[ x, y ]	745.7 [mm], 5947.4 [m], ( 99.2 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:73.2 [mm]
Result	-	Area	18.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#78, \$69	Date	2023/8/10 上午 09:13:55
Segment	1	Camera	1
Pattern	7908	Position[ x, y ]	127.3 [mm], 5947.4 [m], ( 99.2 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:84.4 [mm]
Result	-	Area	20.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#78, \$69	Date	2023/8/10 上午 09:13:55
Segment	1	Camera	1
Pattern	7908	Position[ x, y ]	422.5 [mm], 5947.7 [m], ( 98.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:74.4 [mm]
Result	-	Area	24.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#78, \$69	Date	2023/8/10 上午 09:13:55
Segment	1	Camera	1
Pattern	7908	Position[ x, y ]	448.1 [mm], 5947.8 [m], ( 98.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.0 [mm]
Result	-	Area	42.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#75, \$68	Date	2023/8/10 上午 09:13:42
Segment	1	Camera	1
Pattern	7886	Position[ x, y ]	779.9 [mm], 5930.8 [m], ( 115.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:187.3 ,V:464.0 [mm]
Result	-	Area	2272.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#75, \$68	Date	2023/8/10 上午 09:13:42
Segment	1	Camera	1
Pattern	7886	Position[ x, y ]	462.0 [mm], 5930.9 [m], ( 115.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:257.8 ,V:806.4 [mm]
Result	-	Area	6207.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#75, \$68	Date	2023/8/10 上午 09:13:42
Segment	1	Camera	1
Pattern	7886	Position[ x, y ]	132.9 [mm], 5930.9 [m], ( 115.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.5 ,V:477.6 [mm]
Result	-	Area	7035.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#75, \$68	Date	2023/8/10 上午 09:13:42
Segment	1	Camera	1
Pattern	7886	Position[ x, y ]	765.5 [mm], 5930.9 [m], ( 115.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:188.0 ,V:478.4 [mm]
Result	-	Area	7381.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#74, \$67	Date	2023/8/10 上午 09:13:42
Segment	1	Camera	1
Pattern	7885	Position[ x, y ]	463.8 [mm], 5929.9 [m], ( 116.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:195.6 ,V:121.2 [mm]
Result	-	Area	2177.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#74, \$67	Date	2023/8/10 上午 09:13:42
Segment	1	Camera	1
Pattern	7885	Position[ x, y ]	128.8 [mm], 5930.2 [m], ( 116.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.3 ,V:804.8 [mm]
Result	-	Area	6777.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#74, \$67	Date	2023/8/10 上午 09:13:42
Segment	1	Camera	1
Pattern	7885	Position[ x, y ]	453.0 [mm], 5930.1 [m], ( 116.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:198.2 ,V:804.8 [mm]
Result	-	Area	7136.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#74, \$67	Date	2023/8/10 上午 09:13:42
Segment	1	Camera	1
Pattern	7885	Position[ x, y ]	769.2 [mm], 5930.1 [m], ( 116.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.3 ,V:541.6 [mm]
Result	-	Area	7368.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#73, \$66	Date	2023/8/10 上午 09:13:41
Segment	1	Camera	1
Pattern	7884	Position[ x, y ]	778.7 [mm], 5929.3 [m], ( 117.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:186.3 ,V:455.2 [mm]
Result	-	Area	1945.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#73, \$66	Date	2023/8/10 上午 09:13:41
Segment	1	Camera	1
Pattern	7884	Position[ x, y ]	770.2 [mm], 5929.4 [m], ( 117.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.0 ,V:547.6 [mm]
Result	-	Area	6080.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#73, \$66	Date	2023/8/10 上午 09:13:41
Segment	1	Camera	1
Pattern	7884	Position[ x, y ]	136.9 [mm], 5929.4 [m], ( 117.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.3 ,V:546.8 [mm]
Result	-	Area	6143.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#73, \$66	Date	2023/8/10 上午 09:13:41
Segment	1	Camera	1
Pattern	7884	Position[ x, y ]	455.0 [mm], 5929.4 [m], ( 117.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:196.0 ,V:547.2 [mm]
Result	-	Area	6789.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$65	Date	2023/8/10 上午 09:13:40
Segment	1	Camera	1
Pattern	7883	Position[ x, y ]	773.3 [mm], 5928.5 [m], ( 118.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:186.0 ,V:346.0 [mm]
Result	-	Area	1968.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$65	Date	2023/8/10 上午 09:13:40
Segment	1	Camera	1
Pattern	7883	Position[ x, y ]	137.1 [mm], 5928.6 [m], ( 117.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.5 ,V:564.0 [mm]
Result	-	Area	6199.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$65	Date	2023/8/10 上午 09:13:40
Segment	1	Camera	1
Pattern	7883	Position[ x, y ]	772.1 [mm], 5928.7 [m], ( 117.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.8 ,V:712.4 [mm]
Result	-	Area	6572.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$65	Date	2023/8/10 上午 09:13:40
Segment	1	Camera	1
Pattern	7883	Position[ x, y ]	450.3 [mm], 5928.7 [m], ( 117.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:240.5 ,V:768.8 [mm]
Result	-	Area	6683.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#71, \$64	Date	2023/8/10 上午 09:13:40
Segment	1	Camera	1
Pattern	7882	Position[ x, y ]	471.8 [mm], 5927.7 [m], ( 118.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:195.1 ,V:352.0 [mm]
Result	-	Area	2505.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#71, \$64	Date	2023/8/10 上午 09:13:40
Segment	1	Camera	1
Pattern	7882	Position[ x, y ]	131.0 [mm], 5927.9 [m], ( 118.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.3 ,V:591.6 [mm]
Result	-	Area	5816.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#71, \$64	Date	2023/8/10 上午 09:13:40
Segment	1	Camera	1
Pattern	7882	Position[ x, y ]	767.7 [mm], 5927.9 [m], ( 118.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.5 ,V:592.4 [mm]
Result	-	Area	6192.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#71, \$64	Date	2023/8/10 上午 09:13:40
Segment	1	Camera	1
Pattern	7882	Position[ x, y ]	450.1 [mm], 5927.9 [m], ( 118.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:195.6 ,V:712.8 [mm]
Result	-	Area	6219.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#68, \$63	Date	2023/8/10 上午 09:13:30
Segment	1	Camera	1
Pattern	7866	Position[ x, y ]	879.5 [mm], 5914.9 [m], ( 131.7 [m] )
Type	点状疵点	Size	H:1.7 ,V:274.4 [mm]
Result	-	Area	214.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#68, \$63	Date	2023/8/10 上午 09:13:30
Segment	1	Camera	1
Pattern	7866	Position[ x, y ]	699.1 [mm], 5915.0 [m], ( 131.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:11.7 ,V:513.6 [mm]
Result	-	Area	567.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#68, \$63	Date	2023/8/10 上午 09:13:30
Segment	1	Camera	1
Pattern	7866	Position[ x, y ]	699.8 [mm], 5914.7 [m], ( 131.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.2 ,V:740.0 [mm]
Result	-	Area	638.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#68, \$63	Date	2023/8/10 上午 09:13:30
Segment	1	Camera	1
Pattern	7866	Position[ x, y ]	631.5 [mm], 5914.7 [m], ( 131.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.0 ,V:708.4 [mm]
Result	-	Area	1047.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#67, \$62	Date	2023/8/10 上午 09:13:29
Segment	1	Camera	1
Pattern	7865	Position[ x, y ]	110.0 [mm], 5913.9 [m], ( 132.6 [m] )
Type	縱向刀絲疵點	Size	H:52.5 ,V:180.0 [mm]
Result	-	Area	68.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#67, \$62	Date	2023/8/10 上午 09:13:29
Segment	1	Camera	1
Pattern	7865	Position[ x, y ]	426.6 [mm], 5914.0 [m], ( 132.6 [m] )
Type	縱向刀絲疵點	Size	H:68.1 ,V:183.2 [mm]
Result	-	Area	70.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#67, \$62	Date	2023/8/10 上午 09:13:29
Segment	1	Camera	1
Pattern	7865	Position[ x, y ]	749.2 [mm], 5914.0 [m], ( 132.6 [m] )
Type	面狀重疵點縱向刀絲疵點	Size	H:65.9 ,V:180.4 [mm]
Result	-	Area	81.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#67, \$62	Date	2023/8/10 上午 09:13:29
Segment	1	Camera	1
Pattern	7865	Position[ x, y ]	767.5 [mm], 5914.4 [m], ( 132.2 [m] )
Type	面狀重疵點	Size	H:1.0 ,V:94.4 [mm]
Result	-	Area	86.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#66, \$61	Date	2023/8/10 上午 09:13:28
Segment	1	Camera	1
Pattern	7864	Position[ x, y ]	931.0 [mm], 5913.7 [m], ( 132.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:9.0 ,V:6.8 [mm]
Result	-	Area	16.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#66, \$61	Date	2023/8/10 上午 09:13:28
Segment	1	Camera	1
Pattern	7864	Position[ x, y ]	756.2 [mm], 5913.2 [m], ( 133.4 [m] )
Type	縱向刀絲疵點	Size	H:39.6 ,V:179.6 [mm]
Result	-	Area	27.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#66, \$61	Date	2023/8/10 上午 09:13:28
Segment	1	Camera	1
Pattern	7864	Position[ x, y ]	115.1 [mm], 5913.2 [m], ( 133.4 [m] )
Type	縱向刀絲疵點	Size	H:38.8 ,V:180.8 [mm]
Result	-	Area	68.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#66, \$61	Date	2023/8/10 上午 09:13:28
Segment	1	Camera	1
Pattern	7864	Position[ x, y ]	430.8 [mm], 5913.2 [m], ( 133.3 [m] )
Type	縱向刀絲疵點	Size	H:41.0 ,V:180.4 [mm]
Result	-	Area	69.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#65, \$60	Date	2023/8/10 上午 09:13:28
Segment	1	Camera	1
Pattern	7863	Position[ x, y ]	93.6 [mm], 5912.5 [m], ( 134.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:22.5 ,V:156.4 [mm]
Result	-	Area	27.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#65, \$60	Date	2023/8/10 上午 09:13:28
Segment	1	Camera	1
Pattern	7863	Position[ x, y ]	768.4 [mm], 5912.5 [m], ( 134.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.6 [mm]
Result	-	Area	69.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#65, \$60	Date	2023/8/10 上午 09:13:28
Segment	1	Camera	1
Pattern	7863	Position[ x, y ]	116.6 [mm], 5912.5 [m], ( 134.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:38.8 ,V:152.4 [mm]
Result	-	Area	89.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#65, \$60	Date	2023/8/10 上午 09:13:28
Segment	1	Camera	1
Pattern	7863	Position[ x, y ]	444.0 [mm], 5912.5 [m], ( 134.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:15.4 ,V:180.0 [mm]
Result	-	Area	96.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#64, \$59	Date	2023/8/10 上午 09:13:27
Segment	1	Camera	1
Pattern	7862	Position[ x, y ]	445.9 [mm], 5911.8 [m], ( 134.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:81.6 [mm]
Result	-	Area	24.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#64, \$59	Date	2023/8/10 上午 09:13:27
Segment	1	Camera	1
Pattern	7862	Position[ x, y ]	768.7 [mm], 5912.2 [m], ( 134.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:96.8 [mm]
Result	-	Area	24.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#64, \$59	Date	2023/8/10 上午 09:13:27
Segment	1	Camera	1
Pattern	7862	Position[ x, y ]	446.4 [mm], 5912.2 [m], ( 134.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.6 [mm]
Result	-	Area	53.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#64, \$59	Date	2023/8/10 上午 09:13:27
Segment	1	Camera	1
Pattern	7862	Position[ x, y ]	125.6 [mm], 5912.2 [m], ( 134.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.2 [mm]
Result	-	Area	69.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#61, \$58	Date	2023/8/10 上午 09:12:58
Segment	1	Camera	1
Pattern	7812	Position[ x, y ]	446.9 [mm], 5874.2 [m], ( 172.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.8 [mm]
Result	-	Area	46.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#61, \$58	Date	2023/8/10 上午 09:12:58
Segment	1	Camera	1
Pattern	7812	Position[ x, y ]	447.4 [mm], 5874.6 [m], ( 172.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:96.8 [mm]
Result	-	Area	46.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#61, \$58	Date	2023/8/10 上午 09:12:58
Segment	1	Camera	1
Pattern	7812	Position[ x, y ]	126.6 [mm], 5874.2 [m], ( 172.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:97.6 [mm]
Result	-	Area	68.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#61, \$58	Date	2023/8/10 上午 09:12:58
Segment	1	Camera	1
Pattern	7812	Position[ x, y ]	126.6 [mm], 5874.6 [m], ( 172.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:97.2 [mm]
Result	-	Area	69.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#60, \$57	Date	2023/8/10 上午 09:12:57
Segment	1	Camera	1
Pattern	7811	Position[ x, y ]	446.9 [mm], 5873.5 [m], ( 173.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:97.2 [mm]
Result	-	Area	45.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#60, \$57	Date	2023/8/10 上午 09:12:57
Segment	1	Camera	1
Pattern	7811	Position[ x, y ]	446.9 [mm], 5873.8 [m], ( 172.7 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:97.2 [mm]
Result	-	Area	46.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#60, \$57	Date	2023/8/10 上午 09:12:57
Segment	1	Camera	1
Pattern	7811	Position[ x, y ]	126.1 [mm], 5873.5 [m], ( 173.1 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:97.6 [mm]
Result	-	Area	69.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#60, \$57	Date	2023/8/10 上午 09:12:57
Segment	1	Camera	1
Pattern	7811	Position[ x, y ]	126.6 [mm], 5873.8 [m], ( 172.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:97.2 [mm]
Result	-	Area	70.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#59, \$56	Date	2023/8/10 上午 09:12:57
Segment	1	Camera	1
Pattern	7810	Position[ x, y ]	446.9 [mm], 5872.7 [m], ( 173.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:67.6 [mm]
Result	-	Area	18.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#59, \$56	Date	2023/8/10 上午 09:12:57
Segment	1	Camera	1
Pattern	7810	Position[ x, y ]	126.4 [mm], 5872.7 [m], ( 173.8 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:97.2 [mm]
Result	-	Area	27.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#59, \$56	Date	2023/8/10 上午 09:12:57
Segment	1	Camera	1
Pattern	7810	Position[ x, y ]	446.9 [mm], 5873.1 [m], ( 173.5 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.4 [mm]
Result	-	Area	42.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#59, \$56	Date	2023/8/10 上午 09:12:57
Segment	1	Camera	1
Pattern	7810	Position[ x, y ]	126.4 [mm], 5873.1 [m], ( 173.5 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:97.2 [mm]
Result	-	Area	47.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#58, \$55	Date	2023/8/10 上午 09:12:56
Segment	1	Camera	1
Pattern	7809	Position[ x, y ]	446.9 [mm], 5872.0 [m], ( 174.6 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:22.8 [mm]
Result	-	Area	5.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#58, \$55	Date	2023/8/10 上午 09:12:56
Segment	1	Camera	1
Pattern	7809	Position[ x, y ]	446.9 [mm], 5872.3 [m], ( 174.2 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:50.4 [mm]
Result	-	Area	13.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image




G

M

G

M



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#57, \$54	Date	2023/8/10 上午 09:12:56
Segment	1	Camera	1
Pattern	7808	Position[ x, y ]	937.1 [mm], 5871.0 [m], ( 175.6 [m] )
Type	点状疵点	Size	H:0.5 ,V:5.6 [mm]
Result	-	Area	1.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#57, \$54	Date	2023/8/10 上午 09:12:56
Segment	1	Camera	1
Pattern	7808	Position[ x, y ]	446.9 [mm], 5871.6 [m], ( 175.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:25.2 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#56, \$53	Date	2023/8/10 上午 09:12:54
Segment	1	Camera	1
Pattern	7806	Position[ x, y ]	937.1 [mm], 5869.5 [m], ( 177.1 [m] )
Type	点状疵点	Size	H:0.5 ,V:6.4 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#55, \$52	Date	2023/8/10 上午 09:12:54
Segment	1	Camera	1
Pattern	7805	Position[ x, y ]	937.1 [mm], 5868.7 [m], ( 177.8 [m] )
Type	点状疵点	Size	H:0.5 ,V:5.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#54, \$51	Date	2023/8/10 上午 09:12:53
Segment	1	Camera	1
Pattern	7804	Position[ x, y ]	937.1 [mm], 5868.0 [m], ( 178.6 [m] )
Type	点状疵点	Size	H:0.5 ,V:6.4 [mm]
Result	-	Area	1.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#53, \$50	Date	2023/8/10 上午 09:12:53
Segment	1	Camera	1
Pattern	7803	Position[ x, y ]	937.1 [mm], 5867.2 [m], ( 179.3 [m] )
Type	点状疵点	Size	H:0.5 ,V:3.2 [mm]
Result	-	Area	1.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#50, \$49	Date	2023/8/10 上午 09:12:41
Segment	1	Camera	1
Pattern	7783	Position[ x, y ]	936.9 [mm], 5852.8 [m], ( 193.7 [m] )
Type	点状疵点	Size	H:1.5 ,V:25.6 [mm]
Result	-	Area	4.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#50, \$49	Date	2023/8/10 上午 09:12:41
Segment	1	Camera	1
Pattern	7783	Position[ x, y ]	409.1 [mm], 5852.3 [m], ( 194.3 [m] )
Type	縱向刀絲疵點	Size	H:8.3 ,V:31.6 [mm]
Result	-	Area	4.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#50, \$49	Date	2023/8/10 上午 09:12:41
Segment	1	Camera	1
Pattern	7783	Position[ x, y ]	732.6 [mm], 5852.3 [m], ( 194.3 [m] )
Type	縱向刀絲疵點	Size	H:8.1 ,V:31.6 [mm]
Result	-	Area	4.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#50, \$49	Date	2023/8/10 上午 09:12:41
Segment	1	Camera	1
Pattern	7783	Position[ x, y ]	551.6 [mm], 5852.6 [m], ( 194.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:13.2 [mm]
Result	-	Area	4.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#49, \$48	Date	2023/8/10 上午 09:12:40
Segment	1	Camera	1
Pattern	7782	Position[ x, y ]	721.3 [mm], 5851.5 [m], ( 195.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.4 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#49, \$48	Date	2023/8/10 上午 09:12:40
Segment	1	Camera	1
Pattern	7782	Position[ x, y ]	721.3 [mm], 5851.9 [m], ( 194.6 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#49, \$48	Date	2023/8/10 上午 09:12:40
Segment	1	Camera	1
Pattern	7782	Position[ x, y ]	736.5 [mm], 5851.9 [m], ( 194.6 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image



Reference image



Shape image




G

M

G

M



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#49, \$48	Date	2023/8/10 上午 09:12:40
Segment	1	Camera	1
Pattern	7782	Position[ x, y ]	736.5 [mm], 5851.5 [m], ( 195.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#48, \$47	Date	2023/8/10 上午 09:12:40
Segment	1	Camera	1
Pattern	7781	Position[ x, y ]	736.5 [mm], 5850.8 [m], ( 195.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#48, \$47	Date	2023/8/10 上午 09:12:40
Segment	1	Camera	1
Pattern	7781	Position[ x, y ]	937.1 [mm], 5850.7 [m], ( 195.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:14.0 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3



## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#48, \$47	Date	2023/8/10 上午 09:12:40
Segment	1	Camera	1
Pattern	7781	Position[ x, y ]	721.3 [mm], 5850.8 [m], ( 195.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.4 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#48, \$47	Date	2023/8/10 上午 09:12:40
Segment	1	Camera	1
Pattern	7781	Position[ x, y ]	721.3 [mm], 5851.2 [m], ( 195.4 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#47, \$46	Date	2023/8/10 上午 09:12:39
Segment	1	Camera	1
Pattern	7780	Position[ x, y ]	91.7 [mm], 5850.1 [m], ( 196.5 [m] )
Type	縱向刀絲疵點	Size	H:7.8 ,V:30.4 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#47, \$46	Date	2023/8/10 上午 09:12:39
Segment	1	Camera	1
Pattern	7780	Position[ x, y ]	724.7 [mm], 5850.1 [m], ( 196.5 [m] )
Type	縱向刀絲疵點	Size	H:8.1 ,V:55.2 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#47, \$46	Date	2023/8/10 上午 09:12:39
Segment	1	Camera	1
Pattern	7780	Position[ x, y ]	721.3 [mm], 5850.4 [m], ( 196.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#46, \$45	Date	2023/8/10 上午 09:12:39
Segment	1	Camera	1
Pattern	7779	Position[ x, y ]	721.3 [mm], 5849.3 [m], ( 197.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:6.4 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#46, \$45	Date	2023/8/10 上午 09:12:39
Segment	1	Camera	1
Pattern	7779	Position[ x, y ]	721.3 [mm], 5849.7 [m], ( 196.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.4 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image



Reference image



Shape image




G

M

G

M





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#45, \$44	Date	2023/8/10 上午 09:12:29
Segment	1	Camera	1
Pattern	7762	Position[ x, y ]	408.1 [mm], 5836.8 [m], ( 209.8 [m] )
Type	点状疵点	Size	H:0.5 ,V:2.4 [mm]
Result	-	Area	1.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#45, \$44	Date	2023/8/10 上午 09:12:29
Segment	1	Camera	1
Pattern	7762	Position[ x, y ]	389.3 [mm], 5836.4 [m], ( 210.1 [m] )
Type	点状疵点	Size	H:0.7 ,V:4.0 [mm]
Result	-	Area	1.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#45, \$44	Date	2023/8/10 上午 09:12:29
Segment	1	Camera	1
Pattern	7762	Position[ x, y ]	933.0 [mm], 5836.4 [m], ( 210.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:5.9 ,V:37.6 [mm]
Result	-	Area	18.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#44, \$43	Date	2023/8/10 上午 09:12:28
Segment	1	Camera	1
Pattern	7761	Position[ x, y ]	857.1 [mm], 5836.1 [m], ( 210.5 [m] )
Type	点状疵点	Size	H:1.5 ,V:22.0 [mm]
Result	-	Area	16.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#44, \$43	Date	2023/8/10 上午 09:12:28
Segment	1	Camera	1
Pattern	7761	Position[ x, y ]	851.9 [mm], 5835.9 [m], ( 210.7 [m] )
Type	点状疵点	Size	H:5.6 ,V:133.2 [mm]
Result	-	Area	19.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#44, \$43	Date	2023/8/10 上午 09:12:28
Segment	1	Camera	1
Pattern	7761	Position[ x, y ]	862.7 [mm], 5836.3 [m], ( 210.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:5.4 ,V:104.4 [mm]
Result	-	Area	42.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#44, \$43	Date	2023/8/10 上午 09:12:28
Segment	1	Camera	1
Pattern	7761	Position[ x, y ]	855.6 [mm], 5836.0 [m], ( 210.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.5 ,V:352.4 [mm]
Result	-	Area	146.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#43, \$42	Date	2023/8/10 上午 09:12:28
Segment	1	Camera	1
Pattern	7760	Position[ x, y ]	841.2 [mm], 5835.2 [m], ( 211.3 [m] )
Type	点状疵点	Size	H:2.7 ,V:4.8 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#43, \$42	Date	2023/8/10 上午 09:12:28
Segment	1	Camera	1
Pattern	7760	Position[ x, y ]	840.0 [mm], 5835.5 [m], ( 211.0 [m] )
Type	点状疵点	Size	H:9.0 ,V:5.2 [mm]
Result	-	Area	4.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#43, \$42	Date	2023/8/10 上午 09:12:28
Segment	1	Camera	1
Pattern	7760	Position[ x, y ]	856.1 [mm], 5835.5 [m], ( 211.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:22.9 ,V:78.8 [mm]
Result	-	Area	7.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#43, \$42	Date	2023/8/10 上午 09:12:28
Segment	1	Camera	1
Pattern	7760	Position[ x, y ]	935.9 [mm], 5835.5 [m], ( 211.0 [m] )
Type	点状疵点	Size	H:2.0 ,V:6.4 [mm]
Result	-	Area	8.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#42, \$41	Date	2023/8/10 上午 09:05:21
Segment	1	Camera	1
Pattern	7030	Position[ x, y ]	14.3 [mm], 5286.9 [m], ( 759.7 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:2.4 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#41, \$40	Date	2023/8/10 上午 08:29:57
Segment	1	Camera	1
Pattern	3398	Position[ x, y ]	876.4 [mm], 2558.2 [m], ( 3488.4 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:6.0 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#40, \$39	Date	2023/8/10 上午 08:26:07
Segment	1	Camera	1
Pattern	3005	Position[ x, y ]	352.4 [mm], 2262.9 [m], ( 3783.7 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#39, \$38	Date	2023/8/10 上午 08:23:35
Segment	1	Camera	1
Pattern	2744	Position[ x, y ]	917.9 [mm], 2067.5 [m], ( 3979.1 [m] )
Type	縱向刀絲疵點	Size	H:2.7 ,V:1.2 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#38, \$37	Date	2023/8/10 上午 08:06:59
Segment	1	Camera	1
Pattern	1044	Position[ x, y ]	877.1 [mm], 790.6 [mm], ( 5256.0 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:2.4 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#37, \$36	Date	2023/8/10 上午 08:05:27
Segment	1	Camera	1
Pattern	887	Position[ x, y ]	717.9 [mm], 672.7 [m], ( 5373.9 [m] )
Type	縱向刀絲疵點	Size	H:1.5 ,V:3.2 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#36, \$35	Date	2023/8/10 上午 07:59:16
Segment	1	Camera	1
Pattern	260	Position[ x, y ]	10.6 [mm], 202.1 [m], ( 5844.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:21.7 ,V:19.2 [mm]
Result	-	Area	276.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#35, \$34	Date	2023/8/10 上午 07:58:17
Segment	1	Camera	1
Pattern	160	Position[ x, y ]	809.7 [mm], 126.9 [m], ( 5919.7 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#34, \$33	Date	2023/8/10 上午 07:57:49
Segment	1	Camera	1
Pattern	113	Position[ x, y ]	809.9 [mm], 91.2 [m], ( 5955.4 [m] )
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image




G

M

G

M



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#33, \$32	Date	2023/8/10 上午 07:57:47
Segment	1	Camera	1
Pattern	109	Position[ x, y ]	809.5 [mm], 88.3 [m], ( 5958.2 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#32, \$31	Date	2023/8/10 上午 07:57:44
Segment	1	Camera	1
Pattern	105	Position[ x, y ]	809.2 [mm], 85.5 [m], ( 5961.1 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#31, \$30	Date	2023/8/10 上午 07:57:43
Segment	1	Camera	1
Pattern	103	Position[ x, y ]	809.5 [mm], 84.1 [m], ( 5962.5 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#30, \$29	Date	2023/8/10 上午 07:57:37
Segment	1	Camera	1
Pattern	93	Position[ x, y ]	809.5 [mm], 76.9 [m], ( 5969.7 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#29, \$28	Date	2023/8/10 上午 07:57:37
Segment	1	Camera	1
Pattern	92	Position[ x, y ]	809.7 [mm], 75.5 [m], ( 5971.1 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#28, \$27	Date	2023/8/10 上午 07:57:35
Segment	1	Camera	1
Pattern	90	Position[ x, y ]	809.7 [mm], 74.0 [m], ( 5972.5 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information ( No. 2 )




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

Defect information

No.	#27, \$26	Date	2023/8/10 上午 07:57:34
Segment	1	Camera	1
Pattern	88	Position[ x, y ]	809.9 [mm], 72.6 [m], ( 5974.0 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

Defect information

No.	#26, \$25	Date	2023/8/10 上午 07:57:32
Segment	1	Camera	1
Pattern	84	Position[ x, y ]	810.2 [mm], 69.7 [m], ( 5976.8 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#25, \$24	Date	2023/8/10 上午 07:57:31
Segment	1	Camera	1
Pattern	82	Position[ x, y ]	810.2 [mm], 68.3 [m], ( 5978.2 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#24, \$23	Date	2023/8/10 上午 07:57:27
Segment	1	Camera	1
Pattern	76	Position[ x, y ]	809.7 [mm], 64.0 [m], ( 5982.5 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#23, \$22	Date	2023/8/10 上午 07:57:25
Segment	1	Camera	1
Pattern	72	Position[ x, y ]	810.2 [mm], 61.2 [m], ( 5985.4 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#22, \$21	Date	2023/8/10 上午 07:57:24
Segment	1	Camera	1
Pattern	71	Position[ x, y ]	810.4 [mm], 59.7 [m], ( 5986.8 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$20	Date	2023/8/10 上午 07:57:18
Segment	1	Camera	1
Pattern	61	Position[ x, y ]	810.4 [mm], 52.5 [m], ( 5994.0 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#20, \$19	Date	2023/8/10 上午 07:57:17
Segment	1	Camera	1
Pattern	59	Position[ x, y ]	810.4 [mm], 51.1 [m], ( 5995.4 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#19, \$18	Date	2023/8/10 上午 07:57:16
Segment	1	Camera	1
Pattern	57	Position[ x, y ]	810.4 [mm], 49.7 [m], ( 5996.9 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm]  寬度 : 937.7 [mm] 参照更新 : 無更新/無更新
Web length	6046.6 [m]	
Segments	1 ( 從左側 )	

### Defect information

No.	#18, \$17	Date	2023/8/10 上午 07:57:15
Segment	1	Camera	1
Pattern	55	Position[ x, y ]	810.2 [mm], 48.2 [m], ( 5998.3 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	—	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		





# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#17, \$16	Date	2023/8/10 上午 07:57:12
Segment	1	Camera	1
Pattern	51	Position[ x, y ]	810.2 [mm], 45.4 [m], ( 6001.2 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#16, \$15	Date	2023/8/10 上午 07:57:12
Segment	1	Camera	1
Pattern	50	Position[ x, y ]	810.2 [mm], 43.9 [m], ( 6002.6 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

Defect information

No.	#15, \$14	Date	2023/8/10 上午 07:57:09
Segment	1	Camera	1
Pattern	46	Position[ x, y ]	810.4 [mm], 41.1 [m], ( 6005.5 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#14, \$13	Date	2023/8/10 上午 07:57:08
Segment	1	Camera	1
Pattern	44	Position[ x, y ]	810.4 [mm], 39.6 [m], ( 6006.9 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#13, \$12	Date	2023/8/10 上午 07:57:07
Segment	1	Camera	1
Pattern	42	Position[ x, y ]	810.2 [mm], 38.2 [m], ( 6008.4 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#12, \$11	Date	2023/8/10 上午 07:57:06
Segment	1	Camera	1
Pattern	40	Position[ x, y ]	810.4 [mm], 36.8 [m], ( 6009.8 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#11, \$10	Date	2023/8/10 上午 07:57:05
Segment	1	Camera	1
Pattern	38	Position[ x, y ]	810.4 [mm], 35.3 [m], ( 6011.2 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#10, \$9	Date	2023/8/10 上午 07:57:00
Segment	1	Camera	1
Pattern	30	Position[ x, y ]	810.4 [mm], 29.6 [m], ( 6017.0 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#9, \$8	Date	2023/8/10 上午 07:56:59
Segment	1	Camera	1
Pattern	28	Position[ x, y ]	810.2 [mm], 28.1 [m], ( 6018.4 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#8, \$7	Date	2023/8/10 上午 07:56:58
Segment	1	Camera	1
Pattern	27	Position[ x, y ]	810.4 [mm], 26.7 [m], ( 6019.8 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#7, \$6	Date	2023/8/10 上午 07:56:55
Segment	1	Camera	1
Pattern	21	Position[ x, y ]	810.2 [mm], 22.4 [m], ( 6024.2 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#6, \$5	Date	2023/8/10 上午 07:56:53
Segment	1	Camera	1
Pattern	19	Position[ x, y ]	809.9 [mm], 21.0 [m], ( 6025.6 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#5, \$4	Date	2023/8/10 上午 07:56:52
Segment	1	Camera	1
Pattern	17	Position[ x, y ]	809.9 [mm], 19.5 [m], ( 6027.0 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	91	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6046.6 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#4, \$3	Date	2023/8/10 上午 07:56:49
Segment	1	Camera	1
Pattern	11	Position[ x, y ]	810.2 [mm], 15.2 [m], ( 6031.4 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:2.0 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#3, \$2	Date	2023/8/10 上午 07:56:46
Segment	1	Camera	1
Pattern	7	Position[ x, y ]	810.4 [mm], 12.3 [m], ( 6034.2 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 2

Inspected date : 2023/8/10 上午 07:56:43 ~ 2023/8/10 上午 09:15:18

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	91	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6046.6 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#2, \$1	Date	2023/8/10 上午 07:56:44
Segment	1	Camera	1
Pattern	4	Position[ x, y ]	810.2 [mm], 9.5 [m], ( 6037.1 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
