

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>	
Segments	1 (從左側)		

Defect information

No.	#161, \$148	Date	2023/8/9 上午 11:34:57
Segment	1	Camera	1
Pattern	7282	Position[x, y]	8.2 [mm], 5506.5 [m], (1.9 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:16.6 ,V:16.8 [mm]
Result	-	Area	206.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#160, \$147	Date	2023/8/9 上午 11:33:57
Segment	1	Camera	1
Pattern	7180	Position[x, y]	181.7 [mm], 5430.5 [m], (77.9 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#159, \$146	Date	2023/8/9 上午 11:33:56
Segment	1	Camera	1
Pattern	7179	Position[x, y]	181.7 [mm], 5429.1 [m], (79.3 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#158, \$145	Date	2023/8/9 上午 11:33:55
Segment	1	Camera	1
Pattern	7177	Position[x, y]	181.7 [mm], 5427.7 [m], (80.7 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#157, \$144	Date	2023/8/9 上午 11:33:32
Segment	1	Camera	1
Pattern	7139	Position[x, y]	182.0 [mm], 5399.3 [m], (109.1 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#156, \$143	Date	2023/8/9 上午 11:33:28
Segment	1	Camera	1
Pattern	7131	Position[x, y]	181.7 [mm], 5393.6 [m], (114.7 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#155, \$142	Date	2023/8/9 上午 11:33:26
Segment	1	Camera	1
Pattern	7128	Position[x, y]	182.0 [mm], 5390.8 [m], (117.6 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#154, \$141	Date	2023/8/9 上午 11:33:24
Segment	1	Camera	1
Pattern	7124	Position[x, y]	168.3 [mm], 5388.2 [m], (120.2 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#153, \$140	Date	2023/8/9 上午 11:33:17
Segment	1	Camera	1
Pattern	7113	Position[x, y]	167.8 [mm], 5379.6 [m], (128.7 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#152, \$139	Date	2023/8/9 上午 11:33:16
Segment	1	Camera	1
Pattern	7111	Position[x, y]	168.1 [mm], 5378.2 [m], (130.2 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#151, \$138	Date	2023/8/9 上午 11:33:15
Segment	1	Camera	1
Pattern	7109	Position[x, y]	167.8 [mm], 5376.8 [m], (131.6 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#150, \$137	Date	2023/8/9 上午 11:33:09
Segment	1	Camera	1
Pattern	7099	Position[x, y]	181.7 [mm], 5369.5 [m], (138.9 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#149, \$136	Date	2023/8/9 上午 11:33:08
Segment	1	Camera	1
Pattern	7097	Position[x, y]	168.1 [mm], 5368.3 [m], (140.1 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#148, \$135	Date	2023/8/9 上午 11:33:06
Segment	1	Camera	1
Pattern	7095	Position[x, y]	181.7 [mm], 5366.6 [m], (141.8 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#147, \$134	Date	2023/8/9 上午 11:33:03
Segment	1	Camera	1
Pattern	7090	Position[x, y]	182.2 [mm], 5362.4 [m], (146.0 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#146, \$133	Date	2023/8/9 上午 11:33:02
Segment	1	Camera	1
Pattern	7088	Position[x, y]	168.3 [mm], 5361.1 [m], (147.2 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#146, \$133	Date	2023/8/9 上午 11:33:02
Segment	1	Camera	1
Pattern	7088	Position[x, y]	182.2 [mm], 5360.9 [m], (147.4 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#145, \$132	Date	2023/8/9 上午 11:33:00
Segment	1	Camera	1
Pattern	7084	Position[x, y]	168.3 [mm], 5358.3 [m], (150.1 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#144, \$131	Date	2023/8/9 上午 11:32:58
Segment	1	Camera	1
Pattern	7080	Position[x, y]	182.2 [mm], 5355.2 [m], (153.1 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#143, \$130	Date	2023/8/9 上午 11:32:57
Segment	1	Camera	1
Pattern	7079	Position[x, y]	168.3 [mm], 5354.0 [m], (154.4 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#142, \$129	Date	2023/8/9 上午 11:32:56
Segment	1	Camera	1
Pattern	7077	Position[x, y]	168.3 [mm], 5352.6 [m], (155.8 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#141, \$128	Date	2023/8/9 上午 11:32:55
Segment	1	Camera	1
Pattern	7076	Position[x, y]	182.5 [mm], 5352.4 [m], (156.0 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#140, \$127	Date	2023/8/9 上午 11:32:54
Segment	1	Camera	1
Pattern	7074	Position[x, y]	182.2 [mm], 5351.0 [m], (157.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#139, \$126	Date	2023/8/9 上午 11:32:51
Segment	1	Camera	1
Pattern	7069	Position[x, y]	168.6 [mm], 5346.9 [m], (161.5 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#138, \$125	Date	2023/8/9 上午 11:32:50
Segment	1	Camera	1
Pattern	7067	Position[x, y]	168.6 [mm], 5345.5 [m], (162.9 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#137, \$124	Date	2023/8/9 上午 11:32:46
Segment	1	Camera	1
Pattern	7060	Position[x, y]	168.1 [mm], 5339.8 [m], (168.6 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.2 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#136, \$123	Date	2023/8/9 上午 11:32:45
Segment	1	Camera	1
Pattern	7059	Position[x, y]	181.7 [mm], 5339.6 [m], (168.8 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.8 [mm]
Result	-	Area	4.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#135, \$122	Date	2023/8/9 上午 11:32:45
Segment	1	Camera	1
Pattern	7058	Position[x, y]	167.8 [mm], 5338.3 [m], (170.0 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#134, \$121	Date	2023/8/9 上午 11:32:44
Segment	1	Camera	1
Pattern	7057	Position[x, y]	182.0 [mm], 5338.1 [m], (170.2 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#133, \$120	Date	2023/8/9 上午 11:32:43
Segment	1	Camera	1
Pattern	7056	Position[x, y]	167.8 [mm], 5336.9 [m], (171.5 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#132, \$119	Date	2023/8/9 上午 11:32:40
Segment	1	Camera	1
Pattern	7050	Position[x, y]	182.2 [mm], 5332.4 [m], (175.9 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#131, \$118	Date	2023/8/9 上午 11:32:39
Segment	1	Camera	1
Pattern	7048	Position[x, y]	182.2 [mm], 5331.0 [m], (177.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#130, \$117	Date	2023/8/9 上午 11:32:37
Segment	1	Camera	1
Pattern	7046	Position[x, y]	182.2 [mm], 5329.6 [m], (178.8 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#129, \$116	Date	2023/8/9 上午 11:32:35
Segment	1	Camera	1
Pattern	7041	Position[x, y]	167.8 [mm], 5325.5 [m], (182.9 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#128, \$115	Date	2023/8/9 上午 11:32:34
Segment	1	Camera	1
Pattern	7040	Position[x, y]	182.0 [mm], 5325.3 [m], (183.1 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#127, \$114	Date	2023/8/9 上午 11:32:33
Segment	1	Camera	1
Pattern	7038	Position[x, y]	181.7 [mm], 5323.9 [m], (184.5 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#126, \$113	Date	2023/8/9 上午 11:32:32
Segment	1	Camera	1
Pattern	7037	Position[x, y]	168.1 [mm], 5322.7 [m], (185.7 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#125, \$112	Date	2023/8/9 上午 11:32:32
Segment	1	Camera	1
Pattern	7036	Position[x, y]	182.0 [mm], 5322.5 [m], (185.9 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#124, \$111	Date	2023/8/9 上午 11:32:31
Segment	1	Camera	1
Pattern	7035	Position[x, y]	182.0 [mm], 5321.0 [m], (187.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#123, \$110	Date	2023/8/9 上午 11:32:30
Segment	1	Camera	1
Pattern	7033	Position[x, y]	168.1 [mm], 5319.8 [m], (188.6 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#122, \$109	Date	2023/8/9 上午 11:32:29
Segment	1	Camera	1
Pattern	7031	Position[x, y]	167.8 [mm], 5318.4 [m], (190.0 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#122, \$109	Date	2023/8/9 上午 11:32:29
Segment	1	Camera	1
Pattern	7031	Position[x, y]	182.2 [mm], 5318.2 [m], (190.2 [m])
Type	縱向刀絲疵點	Size	H:2.7 ,V:1.6 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#121, \$108	Date	2023/8/9 上午 11:32:26
Segment	1	Camera	1
Pattern	7027	Position[x, y]	182.0 [mm], 5315.3 [m], (193.1 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#120, \$107	Date	2023/8/9 上午 11:32:25
Segment	1	Camera	1
Pattern	7025	Position[x, y]	181.7 [mm], 5313.9 [m], (194.5 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#120, \$107	Date	2023/8/9 上午 11:32:25
Segment	1	Camera	1
Pattern	7025	Position[x, y]	168.1 [mm], 5314.1 [m], (194.3 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#119, \$106	Date	2023/8/9 上午 11:32:24
Segment	1	Camera	1
Pattern	7023	Position[x, y]	168.1 [mm], 5312.7 [m], (195.7 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#119, \$106	Date	2023/8/9 上午 11:32:24
Segment	1	Camera	1
Pattern	7023	Position[x, y]	182.0 [mm], 5312.5 [m], (195.9 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#118, \$105	Date	2023/8/9 上午 11:32:23
Segment	1	Camera	1
Pattern	7021	Position[x, y]	168.1 [mm], 5311.2 [m], (197.2 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#117, \$104	Date	2023/8/9 上午 11:32:21
Segment	1	Camera	1
Pattern	7019	Position[x, y]	182.2 [mm], 5309.6 [m], (198.8 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image

G	M	G	M

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#116, \$103	Date	2023/8/9 上午 11:32:20
Segment	1	Camera	1
Pattern	7017	Position[x, y]	182.0 [mm], 5308.2 [m], (200.2 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#115, \$102	Date	2023/8/9 上午 11:32:20
Segment	1	Camera	1
Pattern	7016	Position[x, y]	168.3 [mm], 5306.9 [m], (201.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#114, \$101	Date	2023/8/9 上午 11:32:19
Segment	1	Camera	1
Pattern	7015	Position[x, y]	182.2 [mm], 5306.7 [m], (201.7 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#113, \$100	Date	2023/8/9 上午 11:32:16
Segment	1	Camera	1
Pattern	7010	Position[x, y]	182.5 [mm], 5302.4 [m], (205.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	5.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#112, \$99	Date	2023/8/9 上午 11:32:15
Segment	1	Camera	1
Pattern	7008	Position[x, y]	182.2 [mm], 5301.0 [m], (207.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.2 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#111, \$98	Date	2023/8/9 上午 11:32:14
Segment	1	Camera	1
Pattern	7006	Position[x, y]	182.7 [mm], 5299.6 [m], (208.8 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#110, \$97	Date	2023/8/9 上午 11:32:11
Segment	1	Camera	1
Pattern	7002	Position[x, y]	168.6 [mm], 5296.9 [m], (211.5 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範囲 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	参照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#109, \$96	Date	2023/8/9 上午 11:32:10
Segment	1	Camera	1
Pattern	6999	Position[x, y]	168.3 [mm], 5294.1 [m], (214.3 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.2 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#108, \$95	Date	2023/8/9 上午 11:32:09
Segment	1	Camera	1
Pattern	6998	Position[x, y]	182.2 [mm], 5293.9 [m], (214.5 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.2 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#107, \$94	Date	2023/8/9 上午 11:32:08
Segment	1	Camera	1
Pattern	6996	Position[x, y]	182.5 [mm], 5292.4 [m], (216.0 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#106, \$93	Date	2023/8/9 上午 11:32:07
Segment	1	Camera	1
Pattern	6995	Position[x, y]	168.3 [mm], 5291.2 [m], (217.2 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#105, \$92	Date	2023/8/9 上午 11:32:06
Segment	1	Camera	1
Pattern	6993	Position[x, y]	182.0 [mm], 5289.6 [m], (218.8 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#104, \$91	Date	2023/8/9 上午 11:32:05
Segment	1	Camera	1
Pattern	6991	Position[x, y]	168.1 [mm], 5288.3 [m], (220.0 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.2 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#103, \$90	Date	2023/8/9 上午 11:32:04
Segment	1	Camera	1
Pattern	6989	Position[x, y]	182.2 [mm], 5286.7 [m], (221.7 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#102, \$89	Date	2023/8/9 上午 11:32:03
Segment	1	Camera	1
Pattern	6987	Position[x, y]	182.2 [mm], 5285.3 [m], (223.1 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#101, \$88	Date	2023/8/9 上午 11:32:01
Segment	1	Camera	1
Pattern	6985	Position[x, y]	168.1 [mm], 5284.0 [m], (224.3 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#100, \$87	Date	2023/8/9 上午 11:32:00
Segment	1	Camera	1
Pattern	6983	Position[x, y]	167.8 [mm], 5282.6 [m], (225.8 [m])
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#99, \$86	Date	2023/8/9 上午 11:31:59
Segment	1	Camera	1
Pattern	6981	Position[x, y]	167.8 [mm], 5281.2 [m], (227.2 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#98, \$85	Date	2023/8/9 上午 11:31:58
Segment	1	Camera	1
Pattern	6980	Position[x, y]	168.1 [mm], 5279.7 [m], (228.6 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#97, \$84	Date	2023/8/9 上午 11:31:58
Segment	1	Camera	1
Pattern	6979	Position[x, y]	182.2 [mm], 5279.5 [m], (228.8 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#96, \$83	Date	2023/8/9 上午 11:31:57
Segment	1	Camera	1
Pattern	6978	Position[x, y]	167.8 [mm], 5278.3 [m], (230.1 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#95, \$82	Date	2023/8/9 上午 11:31:57
Segment	1	Camera	1
Pattern	6977	Position[x, y]	182.2 [mm], 5278.1 [m], (230.3 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#94, \$81	Date	2023/8/9 上午 11:31:55
Segment	1	Camera	1
Pattern	6975	Position[x, y]	182.2 [mm], 5276.7 [m], (231.7 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	4.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#93, \$80	Date	2023/8/9 上午 11:31:55
Segment	1	Camera	1
Pattern	6974	Position[x, y]	168.1 [mm], 5275.4 [m], (232.9 [m])
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#93, \$80	Date	2023/8/9 上午 11:31:55
Segment	1	Camera	1
Pattern	6974	Position[x, y]	182.2 [mm], 5275.2 [m], (233.1 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#92, \$79	Date	2023/8/9 上午 11:31:54
Segment	1	Camera	1
Pattern	6972	Position[x, y]	167.8 [mm], 5274.0 [m], (234.4 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#92, \$79	Date	2023/8/9 上午 11:31:54
Segment	1	Camera	1
Pattern	6972	Position[x, y]	182.2 [mm], 5273.8 [m], (234.6 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#91, \$78	Date	2023/8/9 上午 11:31:52
Segment	1	Camera	1
Pattern	6970	Position[x, y]	168.1 [mm], 5272.6 [m], (235.8 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#90, \$77	Date	2023/8/9 上午 11:31:51
Segment	1	Camera	1
Pattern	6968	Position[x, y]	182.2 [mm], 5270.9 [m], (237.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#89, \$76	Date	2023/8/9 上午 11:31:50
Segment	1	Camera	1
Pattern	6966	Position[x, y]	168.1 [mm], 5269.7 [m], (238.7 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#89, \$76	Date	2023/8/9 上午 11:31:50
Segment	1	Camera	1
Pattern	6966	Position[x, y]	182.0 [mm], 5269.5 [m], (238.9 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#88, \$75	Date	2023/8/9 上午 11:31:49
Segment	1	Camera	1
Pattern	6964	Position[x, y]	167.8 [mm], 5268.3 [m], (240.1 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#88, \$75	Date	2023/8/9 上午 11:31:49
Segment	1	Camera	1
Pattern	6964	Position[x, y]	182.2 [mm], 5268.1 [m], (240.3 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#87, \$74	Date	2023/8/9 上午 11:31:48
Segment	1	Camera	1
Pattern	6962	Position[x, y]	167.8 [mm], 5266.8 [m], (241.5 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#86, \$73	Date	2023/8/9 上午 11:31:47
Segment	1	Camera	1
Pattern	6960	Position[x, y]	168.1 [mm], 5265.4 [m], (243.0 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#85, \$72	Date	2023/8/9 上午 11:31:46
Segment	1	Camera	1
Pattern	6959	Position[x, y]	168.1 [mm], 5264.0 [m], (244.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#84, \$71	Date	2023/8/9 上午 11:31:45
Segment	1	Camera	1
Pattern	6958	Position[x, y]	182.0 [mm], 5263.8 [m], (244.6 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	148	検査範囲 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	参照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#83, \$70	Date	2023/8/9 上午 11:31:44
Segment	1	Camera	1
Pattern	6955	Position[x, y]	168.1 [mm], 5261.1 [m], (247.3 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#82, \$69	Date	2023/8/9 上午 11:31:43
Segment	1	Camera	1
Pattern	6954	Position[x, y]	182.2 [mm], 5260.9 [m], (247.5 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:2.0 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#81, \$68	Date	2023/8/9 上午 11:31:42
Segment	1	Camera	1
Pattern	6953	Position[x, y]	182.5 [mm], 5259.5 [m], (248.9 [m])
Type	点状疵点	Size	H:1.2 ,V:1.2 [mm]
Result	-	Area	1.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#81, \$68	Date	2023/8/9 上午 11:31:42
Segment	1	Camera	1
Pattern	6953	Position[x, y]	168.3 [mm], 5259.7 [m], (248.7 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#81, \$68	Date	2023/8/9 上午 11:31:42
Segment	1	Camera	1
Pattern	6953	Position[x, y]	182.2 [mm], 5259.5 [m], (248.9 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#80, \$67	Date	2023/8/9 上午 11:31:41
Segment	1	Camera	1
Pattern	6951	Position[x, y]	168.3 [mm], 5258.2 [m], (250.2 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#79, \$66	Date	2023/8/9 上午 11:31:39
Segment	1	Camera	1
Pattern	6947	Position[x, y]	182.2 [mm], 5255.2 [m], (253.2 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#79, \$66	Date	2023/8/9 上午 11:31:39
Segment	1	Camera	1
Pattern	6947	Position[x, y]	168.1 [mm], 5255.4 [m], (253.0 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#78, \$65	Date	2023/8/9 上午 11:31:38
Segment	1	Camera	1
Pattern	6945	Position[x, y]	168.1 [mm], 5253.9 [m], (254.5 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#78, \$65	Date	2023/8/9 上午 11:31:38
Segment	1	Camera	1
Pattern	6945	Position[x, y]	182.5 [mm], 5253.7 [m], (254.7 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#77, \$64	Date	2023/8/9 上午 11:31:37
Segment	1	Camera	1
Pattern	6943	Position[x, y]	182.5 [mm], 5252.3 [m], (256.1 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#76, \$63	Date	2023/8/9 上午 11:31:35
Segment	1	Camera	1
Pattern	6941	Position[x, y]	168.1 [mm], 5251.1 [m], (257.3 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#76, \$63	Date	2023/8/9 上午 11:31:35
Segment	1	Camera	1
Pattern	6941	Position[x, y]	182.7 [mm], 5250.9 [m], (257.5 [m])
Type	縱向刀絲疵點	Size	H:3.2 ,V:2.0 [mm]
Result	-	Area	4.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#75, \$62	Date	2023/8/9 上午 11:31:34
Segment	1	Camera	1
Pattern	6939	Position[x, y]	168.1 [mm], 5249.6 [m], (258.8 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#75, \$62	Date	2023/8/9 上午 11:31:34
Segment	1	Camera	1
Pattern	6939	Position[x, y]	182.5 [mm], 5249.4 [m], (259.0 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#74, \$61	Date	2023/8/9 上午 11:31:33
Segment	1	Camera	1
Pattern	6937	Position[x, y]	168.1 [mm], 5248.2 [m], (260.2 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#73, \$60	Date	2023/8/9 上午 11:31:32
Segment	1	Camera	1
Pattern	6935	Position[x, y]	182.0 [mm], 5246.5 [m], (261.8 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#72, \$59	Date	2023/8/9 上午 11:31:31
Segment	1	Camera	1
Pattern	6933	Position[x, y]	181.7 [mm], 5245.1 [m], (263.3 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範囲 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	参照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#71, \$58	Date	2023/8/9 上午 11:31:30
Segment	1	Camera	1
Pattern	6932	Position[x, y]	167.6 [mm], 5243.9 [m], (264.5 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#70, \$57	Date	2023/8/9 上午 11:31:29
Segment	1	Camera	1
Pattern	6930	Position[x, y]	167.6 [mm], 5242.4 [m], (265.9 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	4.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#69, \$56	Date	2023/8/9 上午 11:31:28
Segment	1	Camera	1
Pattern	6928	Position[x, y]	167.8 [mm], 5241.0 [m], (267.4 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#69, \$56	Date	2023/8/9 上午 11:31:28
Segment	1	Camera	1
Pattern	6928	Position[x, y]	182.0 [mm], 5240.8 [m], (267.6 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#68, \$55	Date	2023/8/9 上午 11:31:26
Segment	1	Camera	1
Pattern	6926	Position[x, y]	167.8 [mm], 5239.6 [m], (268.8 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#67, \$54	Date	2023/8/9 上午 11:31:25
Segment	1	Camera	1
Pattern	6924	Position[x, y]	182.5 [mm], 5237.9 [m], (270.5 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	5.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#66, \$53	Date	2023/8/9 上午 11:31:24
Segment	1	Camera	1
Pattern	6922	Position[x, y]	182.2 [mm], 5236.5 [m], (271.9 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#65, \$52	Date	2023/8/9 上午 11:31:23
Segment	1	Camera	1
Pattern	6920	Position[x, y]	168.1 [mm], 5235.3 [m], (273.1 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#65, \$52	Date	2023/8/9 上午 11:31:23
Segment	1	Camera	1
Pattern	6920	Position[x, y]	182.5 [mm], 5235.0 [m], (273.3 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#64, \$51	Date	2023/8/9 上午 11:31:22
Segment	1	Camera	1
Pattern	6918	Position[x, y]	168.1 [mm], 5233.8 [m], (274.6 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#63, \$50	Date	2023/8/9 上午 11:31:21
Segment	1	Camera	1
Pattern	6916	Position[x, y]	182.2 [mm], 5232.2 [m], (276.2 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#63, \$50	Date	2023/8/9 上午 11:31:21
Segment	1	Camera	1
Pattern	6916	Position[x, y]	168.1 [mm], 5232.4 [m], (276.0 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#62, \$49	Date	2023/8/9 上午 11:31:19
Segment	1	Camera	1
Pattern	6914	Position[x, y]	168.3 [mm], 5230.9 [m], (277.5 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	4.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#61, \$48	Date	2023/8/9 上午 11:31:18
Segment	1	Camera	1
Pattern	6912	Position[x, y]	182.2 [mm], 5229.3 [m], (279.1 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#60, \$47	Date	2023/8/9 上午 11:31:17
Segment	1	Camera	1
Pattern	6910	Position[x, y]	182.2 [mm], 5227.9 [m], (280.5 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:2.0 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#59, \$46	Date	2023/8/9 上午 11:31:16
Segment	1	Camera	1
Pattern	6909	Position[x, y]	167.6 [mm], 5226.6 [m], (281.8 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#58, \$45	Date	2023/8/9 上午 11:31:16
Segment	1	Camera	1
Pattern	6908	Position[x, y]	182.2 [mm], 5226.4 [m], (282.0 [m])
Type	縱向刀絲疵點	Size	H:2.7 ,V:1.6 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#57, \$44	Date	2023/8/9 上午 11:31:15
Segment	1	Camera	1
Pattern	6907	Position[x, y]	167.8 [mm], 5225.2 [m], (283.2 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#56, \$43	Date	2023/8/9 上午 11:31:14
Segment	1	Camera	1
Pattern	6905	Position[x, y]	182.0 [mm], 5223.5 [m], (284.8 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#56, \$43	Date	2023/8/9 上午 11:31:14
Segment	1	Camera	1
Pattern	6905	Position[x, y]	167.8 [mm], 5223.7 [m], (284.6 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#55, \$42	Date	2023/8/9 上午 11:31:13
Segment	1	Camera	1
Pattern	6903	Position[x, y]	167.8 [mm], 5222.3 [m], (286.1 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#54, \$41	Date	2023/8/9 上午 11:31:12
Segment	1	Camera	1
Pattern	6901	Position[x, y]	182.2 [mm], 5220.7 [m], (287.7 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	4.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#53, \$40	Date	2023/8/9 上午 11:31:10
Segment	1	Camera	1
Pattern	6899	Position[x, y]	182.5 [mm], 5219.2 [m], (289.2 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#52, \$39	Date	2023/8/9 上午 11:31:09
Segment	1	Camera	1
Pattern	6897	Position[x, y]	167.8 [mm], 5218.0 [m], (290.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.4 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#51, \$38	Date	2023/8/9 上午 11:31:08
Segment	1	Camera	1
Pattern	6895	Position[x, y]	182.2 [mm], 5216.3 [m], (292.0 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#51, \$38	Date	2023/8/9 上午 11:31:08
Segment	1	Camera	1
Pattern	6895	Position[x, y]	168.1 [mm], 5216.5 [m], (291.8 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#50, \$37	Date	2023/8/9 上午 11:31:07
Segment	1	Camera	1
Pattern	6893	Position[x, y]	168.1 [mm], 5215.1 [m], (293.3 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#50, \$37	Date	2023/8/9 上午 11:31:07
Segment	1	Camera	1
Pattern	6893	Position[x, y]	182.5 [mm], 5214.9 [m], (293.5 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	5.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#49, \$36	Date	2023/8/9 上午 11:31:06
Segment	1	Camera	1
Pattern	6891	Position[x, y]	168.1 [mm], 5213.7 [m], (294.7 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範囲 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	参照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#49, \$36	Date	2023/8/9 上午 11:31:06
Segment	1	Camera	1
Pattern	6891	Position[x, y]	182.5 [mm], 5213.5 [m], (294.9 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#46, \$35	Date	2023/8/9 上午 11:31:04
Segment	1	Camera	1
Pattern	6888	Position[x, y]	168.1 [mm], 5210.8 [m], (297.6 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#45, \$34	Date	2023/8/9 上午 11:31:03
Segment	1	Camera	1
Pattern	6887	Position[x, y]	182.5 [mm], 5210.6 [m], (297.8 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.8 [mm]
Result	-	Area	5.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#44, \$33	Date	2023/8/9 上午 11:31:03
Segment	1	Camera	1
Pattern	6886	Position[x, y]	168.1 [mm], 5209.3 [m], (299.0 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#43, \$32	Date	2023/8/9 上午 11:31:02
Segment	1	Camera	1
Pattern	6885	Position[x, y]	182.5 [mm], 5209.1 [m], (299.2 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image

G	M	G	M

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#42, \$31	Date	2023/8/9 上午 11:31:02
Segment	1	Camera	1
Pattern	6884	Position[x, y]	168.3 [mm], 5207.9 [m], (300.5 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image

G	M	G	M

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#42, \$31	Date	2023/8/9 上午 11:31:02
Segment	1	Camera	1
Pattern	6884	Position[x, y]	182.7 [mm], 5207.7 [m], (300.7 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#41, \$30	Date	2023/8/9 上午 11:31:00
Segment	1	Camera	1
Pattern	6882	Position[x, y]	168.1 [mm], 5206.5 [m], (301.9 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#40, \$29	Date	2023/8/9 上午 11:30:58
Segment	1	Camera	1
Pattern	6878	Position[x, y]	168.1 [mm], 5203.6 [m], (304.8 [m])
Type	縱向刀絲疵點	Size	H:1.7 ,V:2.0 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#40, \$29	Date	2023/8/9 上午 11:30:58
Segment	1	Camera	1
Pattern	6878	Position[x, y]	182.5 [mm], 5203.4 [m], (305.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:2.8 [mm]
Result	-	Area	5.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#39, \$28	Date	2023/8/9 上午 11:30:57
Segment	1	Camera	1
Pattern	6876	Position[x, y]	168.1 [mm], 5202.1 [m], (306.3 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.4 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#36, \$27	Date	2023/8/9 上午 11:30:49
Segment	1	Camera	1
Pattern	6863	Position[x, y]	566.8 [mm], 5191.9 [m], (316.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:25.2 [mm]
Result	-	Area	11.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#36, \$27	Date	2023/8/9 上午 11:30:49
Segment	1	Camera	1
Pattern	6863	Position[x, y]	698.8 [mm], 5192.4 [m], (316.0 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:210.0 [mm]
Result	-	Area	15.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#36, \$27	Date	2023/8/9 上午 11:30:49
Segment	1	Camera	1
Pattern	6863	Position[x, y]	698.8 [mm], 5192.1 [m], (316.3 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:137.2 [mm]
Result	-	Area	20.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#36, \$27	Date	2023/8/9 上午 11:30:49
Segment	1	Camera	1
Pattern	6863	Position[x, y]	566.8 [mm], 5192.1 [m], (316.3 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:307.2 [mm]
Result	-	Area	71.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#35, \$26	Date	2023/8/9 上午 11:30:49
Segment	1	Camera	1
Pattern	6862	Position[x, y]	882.4 [mm], 5191.4 [m], (317.0 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:43.6 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#35, \$26	Date	2023/8/9 上午 11:30:49
Segment	1	Camera	1
Pattern	6862	Position[x, y]	698.8 [mm], 5191.7 [m], (316.7 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:38.8 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#35, \$26	Date	2023/8/9 上午 11:30:49
Segment	1	Camera	1
Pattern	6862	Position[x, y]	182.2 [mm], 5191.8 [m], (316.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:3.4 ,V:2.8 [mm]
Result	-	Area	5.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#35, \$26	Date	2023/8/9 上午 11:30:49
Segment	1	Camera	1
Pattern	6862	Position[x, y]	566.8 [mm], 5191.4 [m], (317.0 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:300.0 [mm]
Result	-	Area	36.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#34, \$25	Date	2023/8/9 上午 11:30:48
Segment	1	Camera	1
Pattern	6861	Position[x, y]	167.8 [mm], 5190.6 [m], (317.8 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:2.0 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#34, \$25	Date	2023/8/9 上午 11:30:48
Segment	1	Camera	1
Pattern	6861	Position[x, y]	566.8 [mm], 5190.6 [m], (317.8 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:214.0 [mm]
Result	-	Area	47.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#33, \$24	Date	2023/8/9 上午 11:30:47
Segment	1	Camera	1
Pattern	6860	Position[x, y]	882.4 [mm], 5189.7 [m], (318.7 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:10.8 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#33, \$24	Date	2023/8/9 上午 11:30:47
Segment	1	Camera	1
Pattern	6860	Position[x, y]	566.8 [mm], 5189.7 [m], (318.7 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:26.8 [mm]
Result	-	Area	7.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#32, \$23	Date	2023/8/9 上午 11:30:47
Segment	1	Camera	1
Pattern	6859	Position[x, y]	167.8 [mm], 5189.2 [m], (319.2 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.0 [mm]
Result	-	Area	3.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#32, \$23	Date	2023/8/9 上午 11:30:47
Segment	1	Camera	1
Pattern	6859	Position[x, y]	182.5 [mm], 5189.0 [m], (319.4 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.8 [mm]
Result	-	Area	4.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#31, \$22	Date	2023/8/9 上午 11:30:46
Segment	1	Camera	1
Pattern	6857	Position[x, y]	167.8 [mm], 5187.7 [m], (320.7 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#31, \$22	Date	2023/8/9 上午 11:30:46
Segment	1	Camera	1
Pattern	6857	Position[x, y]	182.2 [mm], 5187.5 [m], (320.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:3.2 [mm]
Result	-	Area	7.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#28, \$21	Date	2023/8/9 上午 11:30:37
Segment	1	Camera	1
Pattern	6843	Position[x, y]	133.4 [mm], 5177.0 [m], (331.4 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.8 ,V:138.8 [mm]
Result	-	Area	2313.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#28, \$21	Date	2023/8/9 上午 11:30:37
Segment	1	Camera	1
Pattern	6843	Position[x, y]	773.1 [mm], 5177.3 [m], (331.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:184.3 ,V:38.4 [mm]
Result	-	Area	2368.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#28, \$21	Date	2023/8/9 上午 11:30:37
Segment	1	Camera	1
Pattern	6843	Position[x, y]	458.8 [mm], 5177.0 [m], (331.4 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.6 ,V:132.0 [mm]
Result	-	Area	2426.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#28, \$21	Date	2023/8/9 上午 11:30:37
Segment	1	Camera	1
Pattern	6843	Position[x, y]	771.8 [mm], 5177.4 [m], (331.0 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:111.6 [mm]
Result	-	Area	2446.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#27, \$20	Date	2023/8/9 上午 11:30:37
Segment	1	Camera	1
Pattern	6842	Position[x, y]	133.4 [mm], 5176.3 [m], (332.1 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.8 ,V:138.4 [mm]
Result	-	Area	2054.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#27, \$20	Date	2023/8/9 上午 11:30:37
Segment	1	Camera	1
Pattern	6842	Position[x, y]	768.7 [mm], 5176.7 [m], (331.7 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:111.2 [mm]
Result	-	Area	2149.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#27, \$20	Date	2023/8/9 上午 11:30:37
Segment	1	Camera	1
Pattern	6842	Position[x, y]	126.6 [mm], 5176.6 [m], (331.8 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:37.6 [mm]
Result	-	Area	2232.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#27, \$20	Date	2023/8/9 上午 11:30:37
Segment	1	Camera	1
Pattern	6842	Position[x, y]	448.3 [mm], 5176.6 [m], (331.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:193.6 ,V:167.6 [mm]
Result	-	Area	2329.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#26, \$19	Date	2023/8/9 上午 11:30:36
Segment	1	Camera	1
Pattern	6841	Position[x, y]	443.0 [mm], 5175.4 [m], (333.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:193.6 ,V:50.4 [mm]
Result	-	Area	2289.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#26, \$19	Date	2023/8/9 上午 11:30:36
Segment	1	Camera	1
Pattern	6841	Position[x, y]	471.5 [mm], 5175.5 [m], (332.9 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.8 ,V:86.8 [mm]
Result	-	Area	2363.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#26, \$19	Date	2023/8/9 上午 11:30:36
Segment	1	Camera	1
Pattern	6841	Position[x, y]	428.3 [mm], 5175.8 [m], (332.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:193.6 ,V:38.0 [mm]
Result	-	Area	2371.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#26, \$19	Date	2023/8/9 上午 11:30:36
Segment	1	Camera	1
Pattern	6841	Position[x, y]	473.3 [mm], 5175.9 [m], (332.5 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.4 ,V:130.8 [mm]
Result	-	Area	2504.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#25, \$18	Date	2023/8/9 上午 11:30:36
Segment	1	Camera	1
Pattern	6840	Position[x, y]	781.8 [mm], 5174.8 [m], (333.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.8 ,V:138.8 [mm]
Result	-	Area	2208.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#25, \$18	Date	2023/8/9 上午 11:30:36
Segment	1	Camera	1
Pattern	6840	Position[x, y]	467.1 [mm], 5174.8 [m], (333.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.8 ,V:104.4 [mm]
Result	-	Area	2309.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#25, \$18	Date	2023/8/9 上午 11:30:36
Segment	1	Camera	1
Pattern	6840	Position[x, y]	122.9 [mm], 5175.1 [m], (333.3 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:118.4 [mm]
Result	-	Area	2375.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#25, \$18	Date	2023/8/9 上午 11:30:36
Segment	1	Camera	1
Pattern	6840	Position[x, y]	457.4 [mm], 5175.1 [m], (333.3 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.1 ,V:151.2 [mm]
Result	-	Area	2496.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$17	Date	2023/8/9 上午 11:30:35
Segment	1	Camera	1
Pattern	6839	Position[x, y]	792.6 [mm], 5174.0 [m], (334.4 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.3 ,V:138.0 [mm]
Result	-	Area	2184.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$17	Date	2023/8/9 上午 11:30:35
Segment	1	Camera	1
Pattern	6839	Position[x, y]	754.7 [mm], 5173.9 [m], (334.4 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.1 ,V:81.2 [mm]
Result	-	Area	2196.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$17	Date	2023/8/9 上午 11:30:35
Segment	1	Camera	1
Pattern	6839	Position[x, y]	452.0 [mm], 5174.4 [m], (334.0 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.1 ,V:238.0 [mm]
Result	-	Area	2255.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$17	Date	2023/8/9 上午 11:30:35
Segment	1	Camera	1
Pattern	6839	Position[x, y]	434.4 [mm], 5174.0 [m], (334.4 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.1 ,V:131.6 [mm]
Result	-	Area	2325.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#21, \$16	Date	2023/8/9 上午 11:30:18
Segment	1	Camera	1
Pattern	6810	Position[x, y]	59.7 [mm], 5152.0 [m], (356.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.7 ,V:424.4 [mm]
Result	-	Area	531.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#21, \$16	Date	2023/8/9 上午 11:30:18
Segment	1	Camera	1
Pattern	6810	Position[x, y]	59.4 [mm], 5152.3 [m], (356.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.2 ,V:606.4 [mm]
Result	-	Area	548.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#21, \$16	Date	2023/8/9 上午 11:30:18
Segment	1	Camera	1
Pattern	6810	Position[x, y]	360.9 [mm], 5152.4 [m], (356.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:89.1 ,V:382.0 [mm]
Result	-	Area	1203.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#21, \$16	Date	2023/8/9 上午 11:30:18
Segment	1	Camera	1
Pattern	6810	Position[x, y]	590.9 [mm], 5152.2 [m], (356.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:65.2 ,V:806.4 [mm]
Result	-	Area	5914.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#20, \$15	Date	2023/8/9 上午 11:30:17
Segment	1	Camera	1
Pattern	6809	Position[x, y]	238.4 [mm], 5151.1 [m], (357.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:58.8 ,V:200.4 [mm]
Result	-	Area	218.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#20, \$15	Date	2023/8/9 上午 11:30:17
Segment	1	Camera	1
Pattern	6809	Position[x, y]	62.6 [mm], 5151.6 [m], (356.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.5 ,V:314.0 [mm]
Result	-	Area	342.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#20, \$15	Date	2023/8/9 上午 11:30:17
Segment	1	Camera	1
Pattern	6809	Position[x, y]	145.1 [mm], 5151.3 [m], (357.1 [m])
Type	面状重疵点縱向刀絲疵點	Size	H:112.5 ,V:278.0 [mm]
Result	-	Area	354.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#20, \$15	Date	2023/8/9 上午 11:30:17
Segment	1	Camera	1
Pattern	6809	Position[x, y]	561.9 [mm], 5151.3 [m], (357.1 [m])
Type	面状重疵点縱向刀絲疵點	Size	H:41.7 ,V:450.8 [mm]
Result	-	Area	575.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#19, \$14	Date	2023/8/9 上午 11:30:16
Segment	1	Camera	1
Pattern	6808	Position[x, y]	415.9 [mm], 5150.5 [m], (357.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:74.7 ,V:383.2 [mm]
Result	-	Area	276.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#19, \$14	Date	2023/8/9 上午 11:30:16
Segment	1	Camera	1
Pattern	6808	Position[x, y]	58.2 [mm], 5150.5 [m], (357.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:12.0 ,V:416.0 [mm]
Result	-	Area	491.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#19, \$14	Date	2023/8/9 上午 11:30:16
Segment	1	Camera	1
Pattern	6808	Position[x, y]	60.4 [mm], 5150.9 [m], (357.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.2 ,V:328.4 [mm]
Result	-	Area	516.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#19, \$14	Date	2023/8/9 上午 11:30:16
Segment	1	Camera	1
Pattern	6808	Position[x, y]	355.6 [mm], 5150.8 [m], (357.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:161.1 ,V:423.2 [mm]
Result	-	Area	1977.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#18, \$13	Date	2023/8/9 上午 11:30:16
Segment	1	Camera	1
Pattern	6807	Position[x, y]	58.5 [mm], 5149.9 [m], (358.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.0 ,V:144.0 [mm]
Result	-	Area	127.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#18, \$13	Date	2023/8/9 上午 11:30:16
Segment	1	Camera	1
Pattern	6807	Position[x, y]	497.9 [mm], 5149.6 [m], (358.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.0 ,V:180.0 [mm]
Result	-	Area	213.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#18, \$13	Date	2023/8/9 上午 11:30:16
Segment	1	Camera	1
Pattern	6807	Position[x, y]	483.0 [mm], 5150.0 [m], (358.4 [m])
Type	面狀重疵点	Size	H:7.6 ,V:40.4 [mm]
Result	-	Area	252.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#18, \$13	Date	2023/8/9 上午 11:30:16
Segment	1	Camera	1
Pattern	6807	Position[x, y]	63.3 [mm], 5150.1 [m], (358.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.7 ,V:326.8 [mm]
Result	-	Area	464.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#17, \$12	Date	2023/8/9 上午 11:30:15
Segment	1	Camera	1
Pattern	6806	Position[x, y]	118.8 [mm], 5149.0 [m], (359.4 [m])
Type	面状重疵点縱向刀絲疵點	Size	H:28.1 ,V:180.4 [mm]
Result	-	Area	115.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#17, \$12	Date	2023/8/9 上午 11:30:15
Segment	1	Camera	1
Pattern	6806	Position[x, y]	532.6 [mm], 5149.0 [m], (359.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:46.6 ,V:224.8 [mm]
Result	-	Area	191.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#17, \$12	Date	2023/8/9 上午 11:30:15
Segment	1	Camera	1
Pattern	6806	Position[x, y]	456.4 [mm], 5148.9 [m], (359.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:29.8 ,V:213.2 [mm]
Result	-	Area	232.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#17, \$12	Date	2023/8/9 上午 11:30:15
Segment	1	Camera	1
Pattern	6806	Position[x, y]	437.4 [mm], 5149.0 [m], (359.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:81.8 ,V:460.0 [mm]
Result	-	Area	610.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 上午 11:30:06
Segment	1	Camera	1
Pattern	6791	Position[x, y]	646.1 [mm], 5137.5 [m], (370.9 [m])
Type	面狀重疵點	Size	H:3.2 ,V:229.2 [mm]
Result	-	Area	280.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 上午 11:30:06
Segment	1	Camera	1
Pattern	6791	Position[x, y]	780.6 [mm], 5137.6 [m], (370.7 [m])
Type	面狀重疵點	Size	H:14.2 ,V:40.8 [mm]
Result	-	Area	313.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 上午 11:30:06
Segment	1	Camera	1
Pattern	6791	Position[x, y]	645.4 [mm], 5137.6 [m], (370.7 [m])
Type	面狀重疵點	Size	H:5.1 ,V:644.0 [mm]
Result	-	Area	630.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 上午 11:30:06
Segment	1	Camera	1
Pattern	6791	Position[x, y]	767.9 [mm], 5137.6 [m], (370.7 [m])
Type	点状疵点	Size	H:145.5 ,V:46.4 [mm]
Result	-	Area	1072.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#13, \$10	Date	2023/8/9 上午 11:30:05
Segment	1	Camera	1
Pattern	6790	Position[x, y]	768.2 [mm], 5136.7 [m], (371.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:6.3 ,V:129.2 [mm]
Result	-	Area	198.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#13, \$10	Date	2023/8/9 上午 11:30:05
Segment	1	Camera	1
Pattern	6790	Position[x, y]	699.8 [mm], 5137.0 [m], (371.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.0 ,V:270.0 [mm]
Result	-	Area	316.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#13, \$10	Date	2023/8/9 上午 11:30:05
Segment	1	Camera	1
Pattern	6790	Position[x, y]	880.2 [mm], 5136.7 [m], (371.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:676.4 [mm]
Result	-	Area	501.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#13, \$10	Date	2023/8/9 上午 11:30:05
Segment	1	Camera	1
Pattern	6790	Position[x, y]	618.3 [mm], 5136.6 [m], (371.8 [m])
Type	縱向刀絲疵點	Size	H:4.4 ,V:367.6 [mm]
Result	-	Area	599.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#12, \$9	Date	2023/8/9 上午 11:30:05
Segment	1	Camera	1
Pattern	6789	Position[x, y]	932.2 [mm], 5136.1 [m], (372.3 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:6.1 ,V:102.0 [mm]
Result	-	Area	50.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#12, \$9	Date	2023/8/9 上午 11:30:05
Segment	1	Camera	1
Pattern	6789	Position[x, y]	705.7 [mm], 5136.1 [m], (372.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:32.2 ,V:98.4 [mm]
Result	-	Area	50.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#12, \$9	Date	2023/8/9 上午 11:30:05
Segment	1	Camera	1
Pattern	6789	Position[x, y]	757.7 [mm], 5135.9 [m], (372.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:40.5 ,V:180.0 [mm]
Result	-	Area	94.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#12, \$9	Date	2023/8/9 上午 11:30:05
Segment	1	Camera	1
Pattern	6789	Position[x, y]	698.8 [mm], 5136.3 [m], (372.1 [m])
Type	点状疵点	Size	H:21.0 ,V:329.6 [mm]
Result	-	Area	570.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#11, \$8	Date	2023/8/9 上午 11:30:04
Segment	1	Camera	1
Pattern	6788	Position[x, y]	938.1 [mm], 5135.3 [m], (373.1 [m])
Type	点状疵点	Size	H:1.5 ,V:10.8 [mm]
Result	-	Area	12.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#11, \$8	Date	2023/8/9 上午 11:30:04
Segment	1	Camera	1
Pattern	6788	Position[x, y]	933.7 [mm], 5135.3 [m], (373.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.2 ,V:53.2 [mm]
Result	-	Area	13.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#11, \$8	Date	2023/8/9 上午 11:30:04
Segment	1	Camera	1
Pattern	6788	Position[x, y]	732.5 [mm], 5135.4 [m], (372.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:13.4 ,V:10.4 [mm]
Result	-	Area	13.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#11, \$8	Date	2023/8/9 上午 11:30:04
Segment	1	Camera	1
Pattern	6788	Position[x, y]	708.4 [mm], 5135.4 [m], (372.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:12.4 [mm]
Result	-	Area	14.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#10, \$7	Date	2023/8/9 上午 11:30:04
Segment	1	Camera	1
Pattern	6787	Position[x, y]	845.1 [mm], 5135.0 [m], (373.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:11.6 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#9, \$6	Date	2023/8/9 上午 11:08:29
Segment	1	Camera	1
Pattern	4602	Position[x, y]	878.3 [mm], 3492.9 [m], (2015.5 [m])
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#7, \$4	Date	2023/8/9 上午 11:08:12
Segment	1	Camera	1
Pattern	4573	Position[x, y]	810.4 [mm], 3471.5 [m], (2036.9 [m])
Type	縱向刀絲疵點	Size	H:2.4 ,V:4.0 [mm]
Result	-	Area	5.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#6, \$3	Date	2023/8/9 上午 11:04:14
Segment	1	Camera	1
Pattern	4172	Position[x, y]	792.8 [mm], 3170.0 [m], (2338.4 [m])
Type	縱向刀絲疵點	Size	H:1.5 ,V:4.4 [mm]
Result	-	Area	3.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#5, \$2	Date	2023/8/9 上午 11:00:53
Segment	1	Camera	1
Pattern	3833	Position[x, y]	545.3 [mm], 2915.4 [m], (2593.0 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:42.8 [mm]
Result	-	Area	46.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#4, \$1	Date	2023/8/9 上午 10:34:25
Segment	1	Camera	1
Pattern	1152	Position[x, y]	355.6 [mm], 901.4 [m], (4607.0 [m])
Type	縱向刀絲疵點橫向刀絲	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/9 上午 10:22:39 ~ 2023/8/9 上午 11:35:04

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	148	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5508.4 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#8, \$5	Date	2023/8/9 上午 11:08:28
Segment	1	Camera	1
Pattern	4601	Position[x, y]	849.0 [mm], 3492.6 [m], (2015.8 [m])
Type	縱向刀絲疵點	Size	H:1.7 ,V:2.0 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image



Reference image



Shape image

