

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#77, \$68	Date	2023/8/9 下午 03:44:38
Segment	1	Camera	1
Pattern	8160	Position[ x, y ]	12.8 [mm], 6138.9 [m], ( 1.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:25.9 ,V:21.6 [mm]
Result	-	Area	339.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#74, \$67	Date	2023/8/9 下午 03:43:44
Segment	1	Camera	1
Pattern	8069	Position[ x, y ]	802.4 [mm], 6070.5 [m], ( 70.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.5 ,V:422.0 [mm]
Result	-	Area	1793.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#74, \$67	Date	2023/8/9 下午 03:43:44
Segment	1	Camera	1
Pattern	8069	Position[ x, y ]	834.3 [mm], 6070.6 [m], ( 70.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:186.5 ,V:708.4 [mm]
Result	-	Area	1991.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#74, \$67	Date	2023/8/9 下午 03:43:44
Segment	1	Camera	1
Pattern	8069	Position[ x, y ]	488.9 [mm], 6070.5 [m], ( 70.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:195.8 ,V:421.6 [mm]
Result	-	Area	2476.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#74, \$67	Date	2023/8/9 下午 03:43:44
Segment	1	Camera	1
Pattern	8069	Position[ x, y ]	155.9 [mm], 6070.5 [m], ( 70.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.5 ,V:517.2 [mm]
Result	-	Area	2517.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#73, \$66	Date	2023/8/9 下午 03:43:44
Segment	1	Camera	1
Pattern	8068	Position[ x, y ]	792.8 [mm], 6069.8 [m], ( 70.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.8 ,V:437.2 [mm]
Result	-	Area	1969.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#73, \$66	Date	2023/8/9 下午 03:43:44
Segment	1	Camera	1
Pattern	8068	Position[ x, y ]	162.7 [mm], 6069.8 [m], ( 70.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.8 ,V:705.6 [mm]
Result	-	Area	2197.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#73, \$66	Date	2023/8/9 下午 03:43:44
Segment	1	Camera	1
Pattern	8068	Position[ x, y ]	479.8 [mm], 6069.8 [m], ( 70.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:196.3 ,V:479.2 [mm]
Result	-	Area	2561.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#73, \$66	Date	2023/8/9 下午 03:43:44
Segment	1	Camera	1
Pattern	8068	Position[ x, y ]	152.9 [mm], 6069.7 [m], ( 70.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.7 ,V:808.0 [mm]
Result	-	Area	2607.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$65	Date	2023/8/9 下午 03:43:43
Segment	1	Camera	1
Pattern	8067	Position[ x, y ]	403.2 [mm], 6068.8 [m], ( 71.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:195.3 ,V:78.8 [mm]
Result	-	Area	1296.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$65	Date	2023/8/9 下午 03:43:43
Segment	1	Camera	1
Pattern	8067	Position[ x, y ]	787.0 [mm], 6069.0 [m], ( 71.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.8 ,V:497.2 [mm]
Result	-	Area	2350.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$65	Date	2023/8/9 下午 03:43:43
Segment	1	Camera	1
Pattern	8067	Position[ x, y ]	140.2 [mm], 6069.0 [m], ( 71.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.7 ,V:456.0 [mm]
Result	-	Area	3040.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$65	Date	2023/8/9 下午 03:43:43
Segment	1	Camera	1
Pattern	8067	Position[ x, y ]	473.3 [mm], 6069.0 [m], ( 71.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:196.3 ,V:808.0 [mm]
Result	-	Area	3723.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#71, \$64	Date	2023/8/9 下午 03:43:43
Segment	1	Camera	1
Pattern	8066	Position[ x, y ]	836.3 [mm], 6068.3 [m], ( 72.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.5 ,V:708.8 [mm]
Result	-	Area	2153.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#71, \$64	Date	2023/8/9 下午 03:43:43
Segment	1	Camera	1
Pattern	8066	Position[ x, y ]	162.2 [mm], 6068.3 [m], ( 72.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.5 ,V:517.2 [mm]
Result	-	Area	2518.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#71, \$64	Date	2023/8/9 下午 03:43:43
Segment	1	Camera	1
Pattern	8066	Position[ x, y ]	478.1 [mm], 6068.3 [m], ( 72.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:195.8 ,V:421.6 [mm]
Result	-	Area	2615.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#71, \$64	Date	2023/8/9 下午 03:43:43
Segment	1	Camera	1
Pattern	8066	Position[ x, y ]	477.4 [mm], 6068.3 [m], ( 72.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:196.0 ,V:709.2 [mm]
Result	-	Area	3651.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#70, \$63	Date	2023/8/9 下午 03:43:42
Segment	1	Camera	1
Pattern	8065	Position[ x, y ]	482.8 [mm], 6067.5 [m], ( 73.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:195.6 ,V:434.0 [mm]
Result	-	Area	969.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#70, \$63	Date	2023/8/9 下午 03:43:42
Segment	1	Camera	1
Pattern	8065	Position[ x, y ]	798.4 [mm], 6067.5 [m], ( 73.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.8 ,V:480.4 [mm]
Result	-	Area	2085.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#70, \$63	Date	2023/8/9 下午 03:43:42
Segment	1	Camera	1
Pattern	8065	Position[ x, y ]	147.6 [mm], 6067.5 [m], ( 73.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.7 ,V:479.2 [mm]
Result	-	Area	2742.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#70, \$63	Date	2023/8/9 下午 03:43:42
Segment	1	Camera	1
Pattern	8065	Position[ x, y ]	483.3 [mm], 6067.5 [m], ( 73.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:196.3 ,V:438.0 [mm]
Result	-	Area	2932.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#68, \$62	Date	2023/8/9 下午 03:41:41
Segment	1	Camera	1
Pattern	7880	Position[ x, y ]	149.5 [mm], 5927.4 [m], ( 213.3 [m] )
Type	点状疵点	Size	H:184.6 ,V:3.2 [mm]
Result	-	Area	454.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#68, \$62	Date	2023/8/9 下午 03:41:41
Segment	1	Camera	1
Pattern	7880	Position[ x, y ]	463.2 [mm], 5927.4 [m], ( 213.3 [m] )
Type	点状疵点	Size	H:193.4 ,V:2.8 [mm]
Result	-	Area	466.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#68, \$62	Date	2023/8/9 下午 03:41:41
Segment	1	Camera	1
Pattern	7880	Position[ x, y ]	494.0 [mm], 5927.4 [m], ( 213.3 [m] )
Type	点状疵点横向刀絲	Size	H:193.1 ,V:48.8 [mm]
Result	-	Area	470.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#68, \$62	Date	2023/8/9 下午 03:41:41
Segment	1	Camera	1
Pattern	7880	Position[ x, y ]	126.1 [mm], 5927.3 [m], ( 213.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.1 ,V:108.0 [mm]
Result	-	Area	474.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#66, \$61	Date	2023/8/9 下午 03:41:24
Segment	1	Camera	1
Pattern	7879	Position[ x, y ]	469.1 [mm], 5926.3 [m], ( 214.4 [m] )
Type	点状疵点	Size	H:193.4 ,V:2.4 [mm]
Result	-	Area	364.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#66, \$61	Date	2023/8/9 下午 03:41:24
Segment	1	Camera	1
Pattern	7879	Position[ x, y ]	783.8 [mm], 5926.2 [m], ( 214.4 [m] )
Type	点状疵点	Size	H:184.1 ,V:2.4 [mm]
Result	-	Area	377.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#66, \$61	Date	2023/8/9 下午 03:41:24
Segment	1	Camera	1
Pattern	7879	Position[ x, y ]	460.8 [mm], 5926.2 [m], ( 214.4 [m] )
Type	点状疵点	Size	H:193.1 ,V:2.8 [mm]
Result	-	Area	405.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#66, \$61	Date	2023/8/9 下午 03:41:24
Segment	1	Camera	1
Pattern	7879	Position[ x, y ]	149.0 [mm], 5926.2 [m], ( 214.4 [m] )
Type	点状疵点	Size	H:184.3 ,V:2.8 [mm]
Result	-	Area	439.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#65, \$60	Date	2023/8/9 下午 03:41:22
Segment	1	Camera	1
Pattern	7878	Position[ x, y ]	464.2 [mm], 5925.9 [m], ( 214.8 [m] )
Type	点状疵点	Size	H:193.1 ,V:1.6 [mm]
Result	-	Area	275.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#65, \$60	Date	2023/8/9 下午 03:41:22
Segment	1	Camera	1
Pattern	7878	Position[ x, y ]	468.1 [mm], 5925.5 [m], ( 215.1 [m] )
Type	点状疵点	Size	H:193.4 ,V:2.0 [mm]
Result	-	Area	277.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#65, \$60	Date	2023/8/9 下午 03:41:22
Segment	1	Camera	1
Pattern	7878	Position[ x, y ]	468.9 [mm], 5925.9 [m], ( 214.8 [m] )
Type	点状疵点	Size	H:192.6 ,V:2.0 [mm]
Result	-	Area	291.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#65, \$60	Date	2023/8/9 下午 03:41:22
Segment	1	Camera	1
Pattern	7878	Position[ x, y ]	148.8 [mm], 5925.9 [m], ( 214.8 [m] )
Type	点状疵点	Size	H:184.6 ,V:1.6 [mm]
Result	-	Area	292.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#64, \$59	Date	2023/8/9 下午 03:41:21
Segment	1	Camera	1
Pattern	7877	Position[ x, y ]	74.3 [mm], 5925.4 [m], ( 215.2 [m] )
Type	点状疵点	Size	H:10.5 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#61, \$58	Date	2023/8/9 下午 03:41:07
Segment	1	Camera	1
Pattern	7854	Position[ x, y ]	403.7 [mm], 5907.6 [m], ( 233.1 [m] )
Type	点状疵点	Size	H:20.0 ,V:12.4 [mm]
Result	-	Area	184.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#61, \$58	Date	2023/8/9 下午 03:41:07
Segment	1	Camera	1
Pattern	7854	Position[ x, y ]	727.6 [mm], 5907.9 [m], ( 232.7 [m] )
Type	点状疵点	Size	H:19.3 ,V:12.4 [mm]
Result	-	Area	185.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#61, \$58	Date	2023/8/9 下午 03:41:07
Segment	1	Camera	1
Pattern	7854	Position[ x, y ]	86.0 [mm], 5907.6 [m], ( 233.1 [m] )
Type	点状疵点	Size	H:19.0 ,V:13.2 [mm]
Result	-	Area	189.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#61, \$58	Date	2023/8/9 下午 03:41:07
Segment	1	Camera	1
Pattern	7854	Position[ x, y ]	58.5 [mm], 5907.7 [m], ( 232.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:15.6 ,V:538.4 [mm]
Result	-	Area	446.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#60, \$57	Date	2023/8/9 下午 03:41:06
Segment	1	Camera	1
Pattern	7853	Position[ x, y ]	727.6 [mm], 5907.2 [m], ( 233.5 [m] )
Type	点状疵点	Size	H:19.3 ,V:12.8 [mm]
Result	-	Area	191.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#60, \$57	Date	2023/8/9 下午 03:41:06
Segment	1	Camera	1
Pattern	7853	Position[ x, y ]	239.1 [mm], 5906.9 [m], ( 233.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:16.4 ,V:607.2 [mm]
Result	-	Area	218.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#60, \$57	Date	2023/8/9 下午 03:41:06
Segment	1	Camera	1
Pattern	7853	Position[ x, y ]	56.7 [mm], 5906.9 [m], ( 233.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.2 ,V:346.8 [mm]
Result	-	Area	281.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#60, \$57	Date	2023/8/9 下午 03:41:06
Segment	1	Camera	1
Pattern	7853	Position[ x, y ]	58.7 [mm], 5907.2 [m], ( 233.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:11.0 ,V:454.8 [mm]
Result	-	Area	433.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#59, \$56	Date	2023/8/9 下午 03:41:06
Segment	1	Camera	1
Pattern	7852	Position[ x, y ]	86.0 [mm], 5906.1 [m], ( 234.6 [m] )
Type	点状疵点	Size	H:19.0 ,V:13.6 [mm]
Result	-	Area	196.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#59, \$56	Date	2023/8/9 下午 03:41:06
Segment	1	Camera	1
Pattern	7852	Position[ x, y ]	238.9 [mm], 5906.2 [m], ( 234.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:16.1 ,V:654.8 [mm]
Result	-	Area	262.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#59, \$56	Date	2023/8/9 下午 03:41:06
Segment	1	Camera	1
Pattern	7852	Position[ x, y ]	58.0 [mm], 5906.4 [m], ( 234.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:11.2 ,V:808.0 [mm]
Result	-	Area	294.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#59, \$56	Date	2023/8/9 下午 03:41:06
Segment	1	Camera	1
Pattern	7852	Position[ x, y ]	374.4 [mm], 5906.3 [m], ( 234.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:11.7 ,V:650.8 [mm]
Result	-	Area	401.7 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#58, \$55	Date	2023/8/9 下午 03:41:05
Segment	1	Camera	1
Pattern	7851	Position[ x, y ]	421.7 [mm], 5905.3 [m], ( 235.4 [m] )
Type	点状疵点	Size	H:194.8 ,V:247.2 [mm]
Result	-	Area	641.4 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#58, \$55	Date	2023/8/9 下午 03:41:05
Segment	1	Camera	1
Pattern	7851	Position[ x, y ]	195.2 [mm], 5905.3 [m], ( 235.3 [m] )
Type	点状疵点	Size	H:186.0 ,V:247.6 [mm]
Result	-	Area	667.3 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#58, \$55	Date	2023/8/9 下午 03:41:05
Segment	1	Camera	1
Pattern	7851	Position[ x, y ]	462.5 [mm], 5905.5 [m], ( 235.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:195.6 ,V:790.0 [mm]
Result	-	Area	1113.0 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#58, \$55	Date	2023/8/9 下午 03:41:05
Segment	1	Camera	1
Pattern	7851	Position[ x, y ]	118.0 [mm], 5905.5 [m], ( 235.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:187.0 ,V:789.6 [mm]
Result	-	Area	1599.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#57, \$54	Date	2023/8/9 下午 03:41:04
Segment	1	Camera	1
Pattern	7850	Position[ x, y ]	78.5 [mm], 5905.0 [m], ( 235.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:187.3 ,V:709.2 [mm]
Result	-	Area	1869.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#57, \$54	Date	2023/8/9 下午 03:41:04
Segment	1	Camera	1
Pattern	7850	Position[ x, y ]	425.6 [mm], 5904.6 [m], ( 236.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:195.8 ,V:804.0 [mm]
Result	-	Area	1963.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#57, \$54	Date	2023/8/9 下午 03:41:04
Segment	1	Camera	1
Pattern	7850	Position[ x, y ]	454.2 [mm], 5905.0 [m], ( 235.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:195.6 ,V:709.2 [mm]
Result	-	Area	1989.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#57, \$54	Date	2023/8/9 下午 03:41:04
Segment	1	Camera	1
Pattern	7850	Position[ x, y ]	121.2 [mm], 5904.8 [m], ( 235.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:187.3 ,V:805.6 [mm]
Result	-	Area	2145.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


Defect information

No.	#55, \$53	Date	2023/8/9 下午 03:40:14
Segment	1	Camera	1
Pattern	7782	Position[ x, y ]	153.9 [mm], 5852.6 [m], ( 288.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.1 ,V:92.8 [mm]
Result	-	Area	257.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#55, \$53	Date	2023/8/9 下午 03:40:14
Segment	1	Camera	1
Pattern	7782	Position[ x, y ]	467.6 [mm], 5852.6 [m], ( 288.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:189.9 ,V:38.8 [mm]
Result	-	Area	263.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


Defect information

No.	#55, \$53	Date	2023/8/9 下午 03:40:14
Segment	1	Camera	1
Pattern	7782	Position[ x, y ]	765.2 [mm], 5852.2 [m], ( 288.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:183.8 ,V:138.4 [mm]
Result	-	Area	400.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#55, \$53	Date	2023/8/9 下午 03:40:14
Segment	1	Camera	1
Pattern	7782	Position[ x, y ]	767.0 [mm], 5852.6 [m], ( 288.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:183.8 ,V:130.4 [mm]
Result	-	Area	469.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#54, \$52	Date	2023/8/9 下午 03:40:10
Segment	1	Camera	1
Pattern	7781	Position[ x, y ]	442.7 [mm], 5851.5 [m], ( 289.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.1 ,V:50.8 [mm]
Result	-	Area	599.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#54, \$52	Date	2023/8/9 下午 03:40:10
Segment	1	Camera	1
Pattern	7781	Position[ x, y ]	468.9 [mm], 5851.4 [m], ( 289.2 [m] )
Type	点状疵点横向刀絲	Size	H:193.1 ,V:49.2 [mm]
Result	-	Area	609.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#54, \$52	Date	2023/8/9 下午 03:40:10
Segment	1	Camera	1
Pattern	7781	Position[ x, y ]	131.2 [mm], 5851.5 [m], ( 289.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.3 ,V:60.0 [mm]
Result	-	Area	610.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#54, \$52	Date	2023/8/9 下午 03:40:10
Segment	1	Camera	1
Pattern	7781	Position[ x, y ]	153.7 [mm], 5851.4 [m], ( 289.2 [m] )
Type	点状疵点横向刀絲	Size	H:184.3 ,V:49.6 [mm]
Result	-	Area	613.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#52, \$51	Date	2023/8/9 下午 03:36:31
Segment	1	Camera	1
Pattern	7780	Position[ x, y ]	468.4 [mm], 5850.7 [m], ( 290.0 [m] )
Type	点状疵点	Size	H:192.9 ,V:2.0 [mm]
Result	-	Area	319.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#52, \$51	Date	2023/8/9 下午 03:36:31
Segment	1	Camera	1
Pattern	7780	Position[ x, y ]	146.1 [mm], 5850.7 [m], ( 290.0 [m] )
Type	点状疵点	Size	H:184.3 ,V:2.0 [mm]
Result	-	Area	319.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#52, \$51	Date	2023/8/9 下午 03:36:31
Segment	1	Camera	1
Pattern	7780	Position[ x, y ]	740.8 [mm], 5851.1 [m], ( 289.6 [m] )
Type	点状疵点横向刀絲	Size	H:183.8 ,V:85.6 [mm]
Result	-	Area	333.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#52, \$51	Date	2023/8/9 下午 03:36:31
Segment	1	Camera	1
Pattern	7780	Position[ x, y ]	172.2 [mm], 5850.7 [m], ( 289.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:184.3 ,V:59.2 [mm]
Result	-	Area	341.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#51, \$50	Date	2023/8/9 下午 03:36:29
Segment	1	Camera	1
Pattern	7779	Position[ x, y ]	134.4 [mm], 5850.0 [m], ( 290.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:173.3 ,V:88.4 [mm]
Result	-	Area	142.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#51, \$50	Date	2023/8/9 下午 03:36:29
Segment	1	Camera	1
Pattern	7779	Position[ x, y ]	793.3 [mm], 5849.9 [m], ( 290.7 [m] )
Type	点状疵点	Size	H:183.8 ,V:2.0 [mm]
Result	-	Area	272.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#51, \$50	Date	2023/8/9 下午 03:36:29
Segment	1	Camera	1
Pattern	7779	Position[ x, y ]	155.6 [mm], 5849.9 [m], ( 290.7 [m] )
Type	点状疵点	Size	H:184.1 ,V:2.0 [mm]
Result	-	Area	318.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#51, \$50	Date	2023/8/9 下午 03:36:29
Segment	1	Camera	1
Pattern	7779	Position[ x, y ]	473.0 [mm], 5849.9 [m], ( 290.7 [m] )
Type	点状疵点	Size	H:192.9 ,V:2.0 [mm]
Result	-	Area	333.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#50, \$49	Date	2023/8/9 下午 03:36:28
Segment	1	Camera	1
Pattern	7778	Position[ x, y ]	729.4 [mm], 5849.8 [m], ( 290.9 [m] )
Type	点状疵点	Size	H:43.0 ,V:24.0 [mm]
Result	-	Area	18.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#50, \$49	Date	2023/8/9 下午 03:36:28
Segment	1	Camera	1
Pattern	7778	Position[ x, y ]	84.3 [mm], 5849.8 [m], ( 290.9 [m] )
Type	点状疵点	Size	H:43.0 ,V:41.2 [mm]
Result	-	Area	21.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#50, \$49	Date	2023/8/9 下午 03:36:28
Segment	1	Camera	1
Pattern	7778	Position[ x, y ]	760.4 [mm], 5849.3 [m], ( 291.3 [m] )
Type	点状疵点	Size	H:24.4 ,V:1.2 [mm]
Result	-	Area	27.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#50, \$49	Date	2023/8/9 下午 03:36:28
Segment	1	Camera	1
Pattern	7778	Position[ x, y ]	116.3 [mm], 5849.3 [m], ( 291.3 [m] )
Type	点状疵点	Size	H:23.7 ,V:1.6 [mm]
Result	-	Area	28.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#49, \$48	Date	2023/8/9 下午 03:35:21
Segment	1	Camera	1
Pattern	7665	Position[ x, y ]	789.9 [mm], 5764.7 [m], ( 376.0 [m] )
Type	縱向刀絲疵點	Size	H:2.4 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範囲 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	参照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#48, \$47	Date	2023/8/9 下午 03:35:20
Segment	1	Camera	1
Pattern	7663	Position[ x, y ]	793.6 [mm], 5763.2 [m], ( 377.5 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:3.2 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#47, \$46	Date	2023/8/9 下午 03:31:46
Segment	1	Camera	1
Pattern	7299	Position[ x, y ]	349.7 [mm], 5489.7 [m], ( 650.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:58.8 [mm]
Result	-	Area	87.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#46, \$45	Date	2023/8/9 下午 03:30:21
Segment	1	Camera	1
Pattern	7154	Position[ x, y ]	862.4 [mm], 5380.8 [m], ( 759.9 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:2.0 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	68	検査範囲 : 83.6 ~ 1024.2 [mm]  宽度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6140.6 [m]	
Segments	1 ( 從左側 )	

## Defect information

No.	#45, \$44	Date	2023/8/9 下午 03:25:09
Segment	1	Camera	1
Pattern	6623	Position[ x, y ]	769.1 [mm], 4982.0 [m], ( 1158.6 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:2.0 [mm]
Result	—	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#44, \$43	Date	2023/8/9 下午 03:16:36
Segment	1	Camera	1
Pattern	5750	Position[ x, y ]	913.2 [mm], 4326.3 [m], ( 1814.4 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:24.4 [mm]
Result	-	Area	11.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#43, \$42	Date	2023/8/9 下午 03:11:35
Segment	1	Camera	1
Pattern	5237	Position[ x, y ]	790.6 [mm], 3940.8 [m], ( 2199.9 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#42, \$41	Date	2023/8/9 下午 03:08:03
Segment	1	Camera	1
Pattern	4876	Position[ x, y ]	807.0 [mm], 3669.1 [m], ( 2471.5 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:17.2 [mm]
Result	-	Area	20.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#41, \$40	Date	2023/8/9 下午 03:07:45
Segment	1	Camera	1
Pattern	4846	Position[ x, y ]	936.6 [mm], 3647.0 [m], ( 2493.7 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:21.2 [mm]
Result	-	Area	22.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#40, \$39	Date	2023/8/9 下午 03:03:49
Segment	1	Camera	1
Pattern	4444	Position[ x, y ]	675.2 [mm], 3344.8 [m], ( 2795.9 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:51.2 [mm]
Result	-	Area	73.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#39, \$38	Date	2023/8/9 下午 02:56:20
Segment	1	Camera	1
Pattern	3680	Position[ x, y ]	317.2 [mm], 2770.8 [m], ( 3369.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:80.8 [mm]
Result	-	Area	120.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#38, \$37	Date	2023/8/9 下午 02:55:57
Segment	1	Camera	1
Pattern	3641	Position[ x, y ]	819.9 [mm], 2741.3 [m], ( 3399.3 [m] )
Type	縱向刀絲疵點	Size	H:2.4 ,V:62.0 [mm]
Result	-	Area	20.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





### Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	68	検査範囲 : 83.6 ~ 1024.2 [mm]  宽度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6140.6 [m]	
Segments	1 ( 從左側 )	

## Defect information

No.	#37, \$36	Date	2023/8/9 下午 02:55:56
Segment	1	Camera	1
Pattern	3640	Position[ x, y ]	820.9 [mm], 2741.3 [m], ( 3399.4 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:30.4 [mm]
Result	—	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#36, \$35	Date	2023/8/9 下午 02:54:57
Segment	1	Camera	1
Pattern	3539	Position[ x, y ]	785.8 [mm], 2664.7 [m], ( 3476.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:22.4 [mm]
Result	-	Area	48.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#35, \$34	Date	2023/8/9 下午 02:52:38
Segment	1	Camera	1
Pattern	3303	Position[ x, y ]	780.6 [mm], 2487.4 [m], ( 3653.3 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:29.2 [mm]
Result	-	Area	29.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#34, \$33	Date	2023/8/9 下午 02:51:30
Segment	1	Camera	1
Pattern	3188	Position[ x, y ]	852.4 [mm], 2401.3 [m], ( 3739.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:8.1 ,V:10.8 [mm]
Result	-	Area	27.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#33, \$32	Date	2023/8/9 下午 02:49:55
Segment	1	Camera	1
Pattern	3026	Position[ x, y ]	878.8 [mm], 2280.0 [m], ( 3860.7 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:12.8 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#32, \$31	Date	2023/8/9 下午 02:49:02
Segment	1	Camera	1
Pattern	2936	Position[ x, y ]	192.7 [mm], 2211.9 [m], ( 3928.8 [m] )
Type	縱向刀絲疵點	Size	H:1.5 ,V:4.0 [mm]
Result	-	Area	2.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#31, \$30	Date	2023/8/9 下午 02:47:17
Segment	1	Camera	1
Pattern	2759	Position[ x, y ]	904.2 [mm], 2078.9 [m], ( 4061.8 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:4.4 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#30, \$29	Date	2023/8/9 下午 02:46:23
Segment	1	Camera	1
Pattern	2666	Position[ x, y ]	598.5 [mm], 2008.9 [m], ( 4131.7 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:51.2 [mm]
Result	-	Area	39.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#29, \$28	Date	2023/8/9 下午 02:46:11
Segment	1	Camera	1
Pattern	2647	Position[ x, y ]	786.7 [mm], 1995.0 [m], ( 4145.7 [m] )
Type	縱向刀絲疵點	Size	H:3.7 ,V:2.8 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#28, \$27	Date	2023/8/9 下午 02:45:04
Segment	1	Camera	1
Pattern	2533	Position[ x, y ]	284.8 [mm], 1909.1 [m], ( 4231.6 [m] )
Type	縱向刀絲疵點	Size	H:2.9 ,V:203.6 [mm]
Result	-	Area	251.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範囲 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	参照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#27, \$26	Date	2023/8/9 下午 02:42:41
Segment	1	Camera	1
Pattern	2290	Position[ x, y ]	478.4 [mm], 1726.5 [m], ( 4414.2 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:37.2 [mm]
Result	-	Area	30.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#26, \$25	Date	2023/8/9 下午 02:41:02
Segment	1	Camera	1
Pattern	2122	Position[ x, y ]	835.6 [mm], 1600.5 [m], ( 4540.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:45.6 [mm]
Result	-	Area	93.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#25, \$24	Date	2023/8/9 下午 02:40:41
Segment	1	Camera	1
Pattern	2086	Position[ x, y ]	513.3 [mm], 1573.4 [m], ( 4567.2 [m] )
Type	縱向刀絲疵點	Size	H:2.9 ,V:42.8 [mm]
Result	-	Area	60.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#24, \$23	Date	2023/8/9 下午 02:40:13
Segment	1	Camera	1
Pattern	2039	Position[ x, y ]	573.3 [mm], 1537.8 [m], ( 4602.8 [m] )
Type	縱向刀絲疵點	Size	H:4.6 ,V:215.6 [mm]
Result	-	Area	230.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#23, \$22	Date	2023/8/9 下午 02:40:13
Segment	1	Camera	1
Pattern	2038	Position[ x, y ]	571.4 [mm], 1537.6 [m], ( 4603.0 [m] )
Type	縱向刀絲疵點	Size	H:4.6 ,V:277.2 [mm]
Result	-	Area	364.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#22, \$21	Date	2023/8/9 下午 02:40:04
Segment	1	Camera	1
Pattern	2023	Position[ x, y ]	886.1 [mm], 1526.0 [m], ( 4614.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:22.4 [mm]
Result	-	Area	54.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#21, \$20	Date	2023/8/9 下午 02:40:01
Segment	1	Camera	1
Pattern	2019	Position[ x, y ]	123.6 [mm], 1522.8 [m], ( 4617.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.4 ,V:45.2 [mm]
Result	-	Area	130.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



G M G M



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#20, \$19	Date	2023/8/9 下午 02:38:28
Segment	1	Camera	1
Pattern	1860	Position[ x, y ]	662.9 [mm], 1403.4 [m], ( 4737.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:12.4 [mm]
Result	-	Area	18.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#19, \$18	Date	2023/8/9 下午 02:36:54
Segment	1	Camera	1
Pattern	1701	Position[ x, y ]	813.3 [mm], 1284.5 [m], ( 4856.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.2 ,V:8.0 [mm]
Result	-	Area	20.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#18, \$17	Date	2023/8/9 下午 02:36:07
Segment	1	Camera	1
Pattern	1621	Position[ x, y ]	240.8 [mm], 1223.7 [m], ( 4916.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.7 ,V:70.4 [mm]
Result	-	Area	97.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#17, \$16	Date	2023/8/9 下午 02:31:41
Segment	1	Camera	1
Pattern	1169	Position[ x, y ]	784.3 [mm], 884.7 [m], ( 5255.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:2.4 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#16, \$15	Date	2023/8/9 下午 02:31:07
Segment	1	Camera	1
Pattern	1111	Position[ x, y ]	58.7 [mm], 841.0 [m], ( 5299.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:42.0 [mm]
Result	-	Area	89.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#15, \$14	Date	2023/8/9 下午 02:29:51
Segment	1	Camera	1
Pattern	982	Position[ x, y ]	304.8 [mm], 744.0 [m], ( 5396.7 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:29.2 [mm]
Result	-	Area	6.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#14, \$13	Date	2023/8/9 下午 02:29:30
Segment	1	Camera	1
Pattern	946	Position[ x, y ]	279.2 [mm], 717.4 [m], ( 5423.2 [m] )
Type	縱向刀絲疵點	Size	H:2.4 ,V:61.6 [mm]
Result	-	Area	77.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


Defect information

No.	#13, \$12	Date	2023/8/9 下午 02:29:27
Segment	1	Camera	1
Pattern	941	Position[ x, y ]	401.7 [mm], 713.4 [m], ( 5427.3 [m] )
Type	縱向刀絲疵點	Size	H:2.9 ,V:44.8 [mm]
Result	-	Area	81.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#12, \$11	Date	2023/8/9 下午 02:28:15
Segment	1	Camera	1
Pattern	820	Position[ x, y ]	83.1 [mm], 622.2 [m], ( 5518.5 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:10.4 [mm]
Result	-	Area	7.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#11, \$10	Date	2023/8/9 下午 02:27:11
Segment	1	Camera	1
Pattern	711	Position[ x, y ]	314.3 [mm], 540.3 [m], ( 5600.4 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:15.2 [mm]
Result	-	Area	19.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#10, \$9	Date	2023/8/9 下午 02:26:39
Segment	1	Camera	1
Pattern	656	Position[ x, y ]	736.4 [mm], 499.4 [m], ( 5641.3 [m] )
Type	縱向刀絲疵點	Size	H:3.2 ,V:2.0 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information ( No. 2 )




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

Defect information

No.	#9, \$8	Date	2023/8/9 下午 02:26:36
Segment	1	Camera	1
Pattern	652	Position[ x, y ]	842.1 [mm], 496.5 [m], ( 5644.2 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:4.8 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#8, \$7	Date	2023/8/9 下午 02:24:36
Segment	1	Camera	1
Pattern	450	Position[ x, y ]	9.6 [mm], 344.5 [m], ( 5796.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.2 ,V:169.6 [mm]
Result	-	Area	339.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#7, \$6	Date	2023/8/9 下午 02:23:16
Segment	1	Camera	1
Pattern	317	Position[ x, y ]	875.6 [mm], 244.9 [m], ( 5895.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.7 ,V:4.8 [mm]
Result	-	Area	8.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#6, \$5	Date	2023/8/9 下午 02:22:06
Segment	1	Camera	1
Pattern	199	Position[ x, y ]	64.1 [mm], 155.8 [m], ( 5984.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:12.8 [mm]
Result	-	Area	22.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#5, \$4	Date	2023/8/9 下午 02:22:03
Segment	1	Camera	1
Pattern	195	Position[ x, y ]	810.7 [mm], 153.2 [m], ( 5987.4 [m] )
Type	縱向刀絲疵點	Size	H:2.4 ,V:2.4 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#4, \$3	Date	2023/8/9 下午 02:20:57
Segment	1	Camera	1
Pattern	83	Position[ x, y ]	568.7 [mm], 68.7 [m], ( 6072.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:40.4 [mm]
Result	-	Area	10.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#4, \$3	Date	2023/8/9 下午 02:20:57
Segment	1	Camera	1
Pattern	83	Position[ x, y ]	884.4 [mm], 68.7 [m], ( 6072.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:40.4 [mm]
Result	-	Area	11.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


Defect information

No.	#4, \$3	Date	2023/8/9 下午 02:20:57
Segment	1	Camera	1
Pattern	83	Position[ x, y ]	700.8 [mm], 68.7 [m], ( 6072.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:40.4 [mm]
Result	-	Area	12.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


Defect information

No.	#3, \$2	Date	2023/8/9 下午 02:20:56
Segment	1	Camera	1
Pattern	82	Position[ x, y ]	700.8 [mm], 68.3 [m], ( 6072.4 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:26.0 [mm]
Result	-	Area	3.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


Defect information

No.	#3, \$2	Date	2023/8/9 下午 02:20:56
Segment	1	Camera	1
Pattern	82	Position[ x, y ]	884.4 [mm], 68.6 [m], ( 6072.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:110.4 [mm]
Result	-	Area	26.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#3, \$2	Date	2023/8/9 下午 02:20:56
Segment	1	Camera	1
Pattern	82	Position[ x, y ]	700.8 [mm], 68.6 [m], ( 6072.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:141.2 [mm]
Result	-	Area	32.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#3, \$2	Date	2023/8/9 下午 02:20:56
Segment	1	Camera	1
Pattern	82	Position[ x, y ]	568.7 [mm], 68.5 [m], ( 6072.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:304.4 [mm]
Result	-	Area	77.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 6

Inspected date : 2023/8/9 下午 02:20:08 ~ 2023/8/9 下午 03:44:45

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	68	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6140.6 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#2, \$1	Date	2023/8/9 下午 02:20:22
Segment	1	Camera	1
Pattern	25	Position[ x, y ]	457.9 [mm], 25.2 [m], ( 6115.5 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:37.2 [mm]
Result	-	Area	55.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
