

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#47, \$36	Date	2023/8/10 下午 12:12:01
Segment	1	Camera	1
Pattern	7872	Position[ x, y ]	10.6 [mm], 5892.5 [m], ( 1.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:21.0 ,V:18.0 [mm]
Result	-	Area	268.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#44, \$35	Date	2023/8/10 下午 12:11:39
Segment	1	Camera	1
Pattern	7835	Position[ x, y ]	399.1 [mm], 5864.4 [m], ( 29.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.4 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#44, \$35	Date	2023/8/10 下午 12:11:39
Segment	1	Camera	1
Pattern	7835	Position[ x, y ]	412.5 [mm], 5864.8 [m], ( 29.5 [m] )
Type	縱向刀絲疵點	Size	H:4.4 ,V:9.2 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#44, \$35	Date	2023/8/10 下午 12:11:39
Segment	1	Camera	1
Pattern	7835	Position[ x, y ]	738.9 [mm], 5864.4 [m], ( 29.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#44, \$35	Date	2023/8/10 下午 12:11:39
Segment	1	Camera	1
Pattern	7835	Position[ x, y ]	414.7 [mm], 5864.4 [m], ( 29.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.6 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#43, \$34	Date	2023/8/10 下午 12:11:38
Segment	1	Camera	1
Pattern	7834	Position[ x, y ]	739.1 [mm], 5864.1 [m], ( 30.2 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)


商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#43, \$34	Date	2023/8/10 下午 12:11:38
Segment	1	Camera	1
Pattern	7834	Position[ x, y ]	412.5 [mm], 5864.1 [m], ( 30.2 [m] )
Type	縱向刀絲疵點	Size	H:4.4 ,V:9.2 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#43, \$34	Date	2023/8/10 下午 12:11:38
Segment	1	Camera	1
Pattern	7834	Position[ x, y ]	414.7 [mm], 5863.7 [m], ( 30.6 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.6 [mm]
Result	-	Area	4.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#43, \$34	Date	2023/8/10 下午 12:11:38
Segment	1	Camera	1
Pattern	7834	Position[ x, y ]	738.9 [mm], 5863.7 [m], ( 30.6 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:9.6 [mm]
Result	-	Area	4.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#42, \$33	Date	2023/8/10 下午 12:11:38
Segment	1	Camera	1
Pattern	7833	Position[ x, y ]	399.1 [mm], 5862.9 [m], ( 31.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.4 [mm]
Result	-	Area	2.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#42, \$33	Date	2023/8/10 下午 12:11:38
Segment	1	Camera	1
Pattern	7833	Position[ x, y ]	414.7 [mm], 5862.9 [m], ( 31.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#42, \$33	Date	2023/8/10 下午 12:11:38
Segment	1	Camera	1
Pattern	7833	Position[ x, y ]	412.5 [mm], 5863.3 [m], ( 31.0 [m] )
Type	縱向刀絲疵點	Size	H:4.4 ,V:9.6 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#42, \$33	Date	2023/8/10 下午 12:11:38
Segment	1	Camera	1
Pattern	7833	Position[ x, y ]	738.9 [mm], 5862.9 [m], ( 31.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#41, \$32	Date	2023/8/10 下午 12:11:37
Segment	1	Camera	1
Pattern	7832	Position[ x, y ]	739.1 [mm], 5862.6 [m], ( 31.7 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#41, \$32	Date	2023/8/10 下午 12:11:37
Segment	1	Camera	1
Pattern	7832	Position[ x, y ]	95.1 [mm], 5862.6 [m], ( 31.7 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)


商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#41, \$32	Date	2023/8/10 下午 12:11:37
Segment	1	Camera	1
Pattern	7832	Position[ x, y ]	412.5 [mm], 5862.6 [m], ( 31.7 [m] )
Type	縱向刀絲疵點	Size	H:4.4 ,V:9.2 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#41, \$32	Date	2023/8/10 下午 12:11:37
Segment	1	Camera	1
Pattern	7832	Position[ x, y ]	738.9 [mm], 5862.2 [m], ( 32.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)


商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#40, \$31	Date	2023/8/10 下午 12:11:37
Segment	1	Camera	1
Pattern	7831	Position[ x, y ]	401.5 [mm], 5861.8 [m], ( 32.5 [m] )
Type	縱向刀絲疵點	Size	H:8.3 ,V:28.0 [mm]
Result	-	Area	2.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)


商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#40, \$31	Date	2023/8/10 下午 12:11:37
Segment	1	Camera	1
Pattern	7831	Position[ x, y ]	95.1 [mm], 5861.8 [m], ( 32.5 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	2.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#40, \$31	Date	2023/8/10 下午 12:11:37
Segment	1	Camera	1
Pattern	7831	Position[ x, y ]	738.9 [mm], 5861.4 [m], ( 32.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#37, \$30	Date	2023/8/10 下午 12:11:21
Segment	1	Camera	1
Pattern	7805	Position[ x, y ]	241.3 [mm], 5842.4 [m], ( 51.8 [m] )
Type	点状疵点	Size	H:1.7 ,V:146.4 [mm]
Result	-	Area	158.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#37, \$30	Date	2023/8/10 下午 12:11:21
Segment	1	Camera	1
Pattern	7805	Position[ x, y ]	372.7 [mm], 5842.1 [m], ( 52.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:327.2 [mm]
Result	-	Area	256.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#37, \$30	Date	2023/8/10 下午 12:11:21
Segment	1	Camera	1
Pattern	7805	Position[ x, y ]	566.1 [mm], 5842.0 [m], ( 52.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:393.2 [mm]
Result	-	Area	276.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#37, \$30	Date	2023/8/10 下午 12:11:21
Segment	1	Camera	1
Pattern	7805	Position[ x, y ]	237.2 [mm], 5842.0 [m], ( 52.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:14.6 ,V:463.6 [mm]
Result	-	Area	358.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#36, \$29	Date	2023/8/10 下午 12:11:21
Segment	1	Camera	1
Pattern	7804	Position[ x, y ]	373.7 [mm], 5841.7 [m], ( 52.6 [m] )
Type	点状疵点	Size	H:1.7 ,V:176.0 [mm]
Result	-	Area	133.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#36, \$29	Date	2023/8/10 下午 12:11:21
Segment	1	Camera	1
Pattern	7804	Position[ x, y ]	698.6 [mm], 5841.6 [m], ( 52.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:306.0 [mm]
Result	-	Area	145.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#36, \$29	Date	2023/8/10 下午 12:11:21
Segment	1	Camera	1
Pattern	7804	Position[ x, y ]	240.6 [mm], 5841.6 [m], ( 52.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:15.4 ,V:326.4 [mm]
Result	-	Area	172.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#36, \$29	Date	2023/8/10 下午 12:11:21
Segment	1	Camera	1
Pattern	7804	Position[ x, y ]	565.8 [mm], 5841.4 [m], ( 52.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:328.4 [mm]
Result	-	Area	196.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#35, \$28	Date	2023/8/10 下午 12:11:20
Segment	1	Camera	1
Pattern	7803	Position[ x, y ]	566.1 [mm], 5840.6 [m], ( 53.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:118.0 [mm]
Result	-	Area	82.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#35, \$28	Date	2023/8/10 下午 12:11:20
Segment	1	Camera	1
Pattern	7803	Position[ x, y ]	240.9 [mm], 5840.6 [m], ( 53.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:118.8 [mm]
Result	-	Area	84.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#35, \$28	Date	2023/8/10 下午 12:11:20
Segment	1	Camera	1
Pattern	7803	Position[ x, y ]	236.2 [mm], 5841.0 [m], ( 53.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:14.9 ,V:169.6 [mm]
Result	-	Area	85.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#35, \$28	Date	2023/8/10 下午 12:11:20
Segment	1	Camera	1
Pattern	7803	Position[ x, y ]	240.6 [mm], 5840.8 [m], ( 53.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:263.2 [mm]
Result	-	Area	86.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#34, \$27	Date	2023/8/10 下午 12:11:20
Segment	1	Camera	1
Pattern	7802	Position[ x, y ]	567.5 [mm], 5840.2 [m], ( 54.1 [m] )
Type	点状疵点	Size	H:1.5 ,V:132.8 [mm]
Result	-	Area	37.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#34, \$27	Date	2023/8/10 下午 12:11:20
Segment	1	Camera	1
Pattern	7802	Position[ x, y ]	240.6 [mm], 5840.1 [m], ( 54.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:311.2 [mm]
Result	-	Area	50.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#34, \$27	Date	2023/8/10 下午 12:11:20
Segment	1	Camera	1
Pattern	7802	Position[ x, y ]	699.8 [mm], 5840.0 [m], ( 54.3 [m] )
Type	点状疵点	Size	H:0.5 ,V:118.8 [mm]
Result	-	Area	50.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#34, \$27	Date	2023/8/10 下午 12:11:20
Segment	1	Camera	1
Pattern	7802	Position[ x, y ]	699.8 [mm], 5840.2 [m], ( 54.1 [m] )
Type	点状疵点	Size	H:1.5 ,V:131.6 [mm]
Result	-	Area	63.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#33, \$26	Date	2023/8/10 下午 12:11:19
Segment	1	Camera	1
Pattern	7801	Position[ x, y ]	422.3 [mm], 5839.1 [m], ( 55.1 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:5.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#33, \$26	Date	2023/8/10 下午 12:11:19
Segment	1	Camera	1
Pattern	7801	Position[ x, y ]	126.4 [mm], 5839.2 [m], ( 55.1 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:95.2 [mm]
Result	-	Area	28.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#33, \$26	Date	2023/8/10 下午 12:11:19
Segment	1	Camera	1
Pattern	7801	Position[ x, y ]	448.1 [mm], 5839.2 [m], ( 55.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.4 [mm]
Result	-	Area	46.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#30, \$25	Date	2023/8/10 下午 12:10:48
Segment	1	Camera	1
Pattern	7748	Position[ x, y ]	565.6 [mm], 5799.5 [m], ( 94.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:297.6 [mm]
Result	-	Area	111.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#30, \$25	Date	2023/8/10 下午 12:10:48
Segment	1	Camera	1
Pattern	7748	Position[ x, y ]	239.9 [mm], 5799.6 [m], ( 94.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:328.0 [mm]
Result	-	Area	113.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#30, \$25	Date	2023/8/10 下午 12:10:48
Segment	1	Camera	1
Pattern	7748	Position[ x, y ]	697.9 [mm], 5799.5 [m], ( 94.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:478.4 [mm]
Result	-	Area	125.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#30, \$25	Date	2023/8/10 下午 12:10:48
Segment	1	Camera	1
Pattern	7748	Position[ x, y ]	372.4 [mm], 5799.5 [m], ( 94.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.9 ,V:311.2 [mm]
Result	-	Area	136.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#29, \$24	Date	2023/8/10 下午 12:10:47
Segment	1	Camera	1
Pattern	7747	Position[ x, y ]	698.6 [mm], 5798.9 [m], ( 95.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:121.6 [mm]
Result	-	Area	56.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#29, \$24	Date	2023/8/10 下午 12:10:47
Segment	1	Camera	1
Pattern	7747	Position[ x, y ]	372.9 [mm], 5799.3 [m], ( 95.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:101.2 [mm]
Result	-	Area	65.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#29, \$24	Date	2023/8/10 下午 12:10:47
Segment	1	Camera	1
Pattern	7747	Position[ x, y ]	372.9 [mm], 5799.0 [m], ( 95.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.7 ,V:143.6 [mm]
Result	-	Area	68.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#29, \$24	Date	2023/8/10 下午 12:10:47
Segment	1	Camera	1
Pattern	7747	Position[ x, y ]	698.4 [mm], 5799.3 [m], ( 95.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.7 ,V:101.2 [mm]
Result	-	Area	71.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#28, \$23	Date	2023/8/10 下午 12:10:47
Segment	1	Camera	1
Pattern	7746	Position[ x, y ]	126.1 [mm], 5798.4 [m], ( 95.8 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:15.2 [mm]
Result	-	Area	8.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#28, \$23	Date	2023/8/10 下午 12:10:47
Segment	1	Camera	1
Pattern	7746	Position[ x, y ]	447.6 [mm], 5798.4 [m], ( 95.8 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:58.8 [mm]
Result	-	Area	13.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#28, \$23	Date	2023/8/10 下午 12:10:47
Segment	1	Camera	1
Pattern	7746	Position[ x, y ]	447.9 [mm], 5798.1 [m], ( 96.2 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:96.8 [mm]
Result	-	Area	33.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#28, \$23	Date	2023/8/10 下午 12:10:47
Segment	1	Camera	1
Pattern	7746	Position[ x, y ]	126.6 [mm], 5798.1 [m], ( 96.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:97.2 [mm]
Result	-	Area	51.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#27, \$22	Date	2023/8/10 下午 12:10:46
Segment	1	Camera	1
Pattern	7745	Position[ x, y ]	746.2 [mm], 5797.3 [m], ( 97.0 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:11.2 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#27, \$22	Date	2023/8/10 下午 12:10:46
Segment	1	Camera	1
Pattern	7745	Position[ x, y ]	126.4 [mm], 5797.3 [m], ( 96.9 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:73.2 [mm]
Result	-	Area	17.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#27, \$22	Date	2023/8/10 下午 12:10:46
Segment	1	Camera	1
Pattern	7745	Position[ x, y ]	447.9 [mm], 5797.3 [m], ( 96.9 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:96.4 [mm]
Result	-	Area	27.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#26, \$21	Date	2023/8/10 下午 12:10:46
Segment	1	Camera	1
Pattern	7744	Position[ x, y ]	126.4 [mm], 5797.0 [m], ( 97.3 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:25.2 [mm]
Result	-	Area	13.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#26, \$21	Date	2023/8/10 下午 12:10:46
Segment	1	Camera	1
Pattern	7744	Position[ x, y ]	447.9 [mm], 5797.0 [m], ( 97.3 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:31.6 [mm]
Result	-	Area	14.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#26, \$21	Date	2023/8/10 下午 12:10:46
Segment	1	Camera	1
Pattern	7744	Position[ x, y ]	126.6 [mm], 5796.6 [m], ( 97.7 [m] )
Type	縱向刀絲疵點	Size	H:1.0 ,V:89.2 [mm]
Result	-	Area	18.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#26, \$21	Date	2023/8/10 下午 12:10:46
Segment	1	Camera	1
Pattern	7744	Position[ x, y ]	448.1 [mm], 5796.6 [m], ( 97.7 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.4 [mm]
Result	-	Area	31.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#23, \$20	Date	2023/8/10 下午 12:10:39
Segment	1	Camera	1
Pattern	7733	Position[ x, y ]	358.3 [mm], 5788.7 [m], ( 105.5 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:48.8 ,V:90.8 [mm]
Result	-	Area	197.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#23, \$20	Date	2023/8/10 下午 12:10:39
Segment	1	Camera	1
Pattern	7733	Position[ x, y ]	699.6 [mm], 5788.8 [m], ( 105.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:36.6 ,V:258.8 [mm]
Result	-	Area	223.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#23, \$20	Date	2023/8/10 下午 12:10:39
Segment	1	Camera	1
Pattern	7733	Position[ x, y ]	881.5 [mm], 5788.3 [m], ( 106.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:327.6 [mm]
Result	-	Area	224.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#23, \$20	Date	2023/8/10 下午 12:10:39
Segment	1	Camera	1
Pattern	7733	Position[ x, y ]	697.9 [mm], 5788.5 [m], ( 105.8 [m] )
Type	点状疵点	Size	H:3.4 ,V:171.2 [mm]
Result	-	Area	248.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	36	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	参照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#22, \$19	Date	2023/8/10 下午 12:10:39
Segment	1	Camera	1
Pattern	7732	Position[ x, y ]	106.6 [mm], 5787.6 [m], ( 106.7 [m] )
Type	縱向刀絲疵點	Size	H:53.5 ,V:178.8 [mm]
Result	-	Area	33.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#22, \$19	Date	2023/8/10 下午 12:10:39
Segment	1	Camera	1
Pattern	7732	Position[ x, y ]	770.4 [mm], 5788.0 [m], ( 106.3 [m] )
Type	面狀重疵点	Size	H:1.0 ,V:93.2 [mm]
Result	-	Area	65.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#22, \$19	Date	2023/8/10 下午 12:10:39
Segment	1	Camera	1
Pattern	7732	Position[ x, y ]	433.0 [mm], 5787.6 [m], ( 106.7 [m] )
Type	縱向刀絲疵點	Size	H:46.1 ,V:179.2 [mm]
Result	-	Area	70.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#22, \$19	Date	2023/8/10 下午 12:10:39
Segment	1	Camera	1
Pattern	7732	Position[ x, y ]	759.2 [mm], 5787.6 [m], ( 106.7 [m] )
Type	面狀重疵點縱向刀絲疵點	Size	H:40.5 ,V:179.2 [mm]
Result	-	Area	86.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#21, \$18	Date	2023/8/10 下午 12:10:38
Segment	1	Camera	1
Pattern	7731	Position[ x, y ]	933.5 [mm], 5787.3 [m], ( 107.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:7.6 ,V:7.2 [mm]
Result	-	Area	15.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$18	Date	2023/8/10 下午 12:10:38
Segment	1	Camera	1
Pattern	7731	Position[ x, y ]	759.4 [mm], 5786.8 [m], ( 107.5 [m] )
Type	縱向刀絲疵點	Size	H:39.6 ,V:177.6 [mm]
Result	-	Area	38.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$18	Date	2023/8/10 下午 12:10:38
Segment	1	Camera	1
Pattern	7731	Position[ x, y ]	434.9 [mm], 5786.8 [m], ( 107.5 [m] )
Type	縱向刀絲疵點	Size	H:41.0 ,V:178.0 [mm]
Result	-	Area	52.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$18	Date	2023/8/10 下午 12:10:38
Segment	1	Camera	1
Pattern	7731	Position[ x, y ]	108.0 [mm], 5786.8 [m], ( 107.5 [m] )
Type	縱向刀絲疵點	Size	H:54.2 ,V:179.2 [mm]
Result	-	Area	59.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$17	Date	2023/8/10 下午 12:10:38
Segment	1	Camera	1
Pattern	7730	Position[ x, y ]	420.8 [mm], 5786.4 [m], ( 107.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:21.0 ,V:89.2 [mm]
Result	-	Area	8.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$17	Date	2023/8/10 下午 12:10:38
Segment	1	Camera	1
Pattern	7730	Position[ x, y ]	448.4 [mm], 5786.5 [m], ( 107.7 [m] )
Type	点状疵点	Size	H:1.0 ,V:25.6 [mm]
Result	-	Area	9.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$17	Date	2023/8/10 下午 12:10:38
Segment	1	Camera	1
Pattern	7730	Position[ x, y ]	447.4 [mm], 5786.1 [m], ( 108.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.0 [mm]
Result	-	Area	30.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$17	Date	2023/8/10 下午 12:10:38
Segment	1	Camera	1
Pattern	7730	Position[ x, y ]	125.9 [mm], 5786.1 [m], ( 108.1 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:96.0 [mm]
Result	-	Area	33.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#19, \$16	Date	2023/8/10 下午 12:10:37
Segment	1	Camera	1
Pattern	7729	Position[ x, y ]	447.4 [mm], 5785.8 [m], ( 108.5 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:51.2 [mm]
Result	-	Area	13.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#19, \$16	Date	2023/8/10 下午 12:10:37
Segment	1	Camera	1
Pattern	7729	Position[ x, y ]	125.9 [mm], 5785.8 [m], ( 108.5 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:95.2 [mm]
Result	-	Area	17.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#18, \$15	Date	2023/8/10 上午 11:44:21
Segment	1	Camera	1
Pattern	5037	Position[ x, y ]	900.5 [mm], 3773.6 [m], ( 2120.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:2.9 ,V:2.0 [mm]
Result	-	Area	5.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#17, \$14	Date	2023/8/10 上午 11:44:21
Segment	1	Camera	1
Pattern	5036	Position[ x, y ]	654.9 [mm], 3773.6 [m], ( 2120.7 [m] )
Type	縱向刀絲疵點	Size	H:2.7 ,V:2.0 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#16, \$13	Date	2023/8/10 上午 11:03:11
Segment	1	Camera	1
Pattern	818	Position[ x, y ]	754.3 [mm], 620.8 [m], ( 5273.5 [m] )
Type	点状疵点	Size	H:17.1 ,V:0.8 [mm]
Result	-	Area	11.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#16, \$13	Date	2023/8/10 上午 11:03:11
Segment	1	Camera	1
Pattern	818	Position[ x, y ]	115.1 [mm], 620.8 [m], ( 5273.5 [m] )
Type	点状疵点	Size	H:22.7 ,V:0.8 [mm]
Result	-	Area	17.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#15, \$12	Date	2023/8/10 上午 11:03:10
Segment	1	Camera	1
Pattern	817	Position[ x, y ]	13.8 [mm], 619.5 [m], ( 5274.7 [m] )
Type	点状疵点	Size	H:27.3 ,V:9.6 [mm]
Result	-	Area	72.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#15, \$12	Date	2023/8/10 上午 11:03:10
Segment	1	Camera	1
Pattern	817	Position[ x, y ]	326.6 [mm], 619.5 [m], ( 5274.7 [m] )
Type	点状疵点	Size	H:30.8 ,V:9.6 [mm]
Result	-	Area	82.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#15, \$12	Date	2023/8/10 上午 11:03:10
Segment	1	Camera	1
Pattern	817	Position[ x, y ]	431.8 [mm], 619.5 [m], ( 5274.7 [m] )
Type	点状疵点	Size	H:134.8 ,V:1.6 [mm]
Result	-	Area	104.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image




G

M

G

M



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#15, \$12	Date	2023/8/10 上午 11:03:10
Segment	1	Camera	1
Pattern	817	Position[ x, y ]	141.0 [mm], 619.5 [m], ( 5274.7 [m] )
Type	点状疵点	Size	H:178.5 ,V:1.6 [mm]
Result	-	Area	180.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#14, \$11	Date	2023/8/10 上午 11:03:09
Segment	1	Camera	1
Pattern	815	Position[ x, y ]	12.8 [mm], 618.0 [m], ( 5276.2 [m] )
Type	点状疵点	Size	H:27.3 ,V:9.2 [mm]
Result	-	Area	55.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#14, \$11	Date	2023/8/10 上午 11:03:09
Segment	1	Camera	1
Pattern	815	Position[ x, y ]	326.1 [mm], 618.0 [m], ( 5276.2 [m] )
Type	点状疵点	Size	H:30.0 ,V:9.2 [mm]
Result	-	Area	60.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#14, \$11	Date	2023/8/10 上午 11:03:09
Segment	1	Camera	1
Pattern	815	Position[ x, y ]	456.2 [mm], 618.0 [m], ( 5276.2 [m] )
Type	点状疵点	Size	H:89.4 ,V:1.2 [mm]
Result	-	Area	64.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#14, \$11	Date	2023/8/10 上午 11:03:09
Segment	1	Camera	1
Pattern	815	Position[ x, y ]	123.4 [mm], 618.0 [m], ( 5276.2 [m] )
Type	点状疵点	Size	H:138.7 ,V:1.2 [mm]
Result	-	Area	108.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#13, \$10	Date	2023/8/10 上午 11:03:09
Segment	1	Camera	1
Pattern	814	Position[ x, y ]	112.4 [mm], 617.4 [m], ( 5276.8 [m] )
Type	点状疵点	Size	H:20.8 ,V:0.8 [mm]
Result	-	Area	10.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#13, \$10	Date	2023/8/10 上午 11:03:09
Segment	1	Camera	1
Pattern	814	Position[ x, y ]	401.7 [mm], 617.9 [m], ( 5276.4 [m] )
Type	点状疵点	Size	H:51.5 ,V:0.8 [mm]
Result	-	Area	16.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#13, \$10	Date	2023/8/10 上午 11:03:09
Segment	1	Camera	1
Pattern	814	Position[ x, y ]	112.4 [mm], 617.9 [m], ( 5276.4 [m] )
Type	点状疵点	Size	H:27.3 ,V:0.8 [mm]
Result	-	Area	17.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#13, \$10	Date	2023/8/10 上午 11:03:09
Segment	1	Camera	1
Pattern	814	Position[ x, y ]	758.2 [mm], 617.4 [m], ( 5276.8 [m] )
Type	点状疵点	Size	H:22.9 ,V:0.8 [mm]
Result	-	Area	18.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#12, \$9	Date	2023/8/10 上午 11:03:01
Segment	1	Camera	1
Pattern	801	Position[ x, y ]	379.3 [mm], 607.6 [m], ( 5286.7 [m] )
Type	点状疵点	Size	H:12.0 ,V:0.8 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#12, \$9	Date	2023/8/10 上午 11:03:01
Segment	1	Camera	1
Pattern	801	Position[ x, y ]	184.2 [mm], 607.6 [m], ( 5286.7 [m] )
Type	点状疵点	Size	H:21.0 ,V:0.8 [mm]
Result	-	Area	10.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#12, \$9	Date	2023/8/10 上午 11:03:01
Segment	1	Camera	1
Pattern	801	Position[ x, y ]	181.0 [mm], 607.5 [m], ( 5286.8 [m] )
Type	点状疵点	Size	H:29.1 ,V:0.8 [mm]
Result	-	Area	14.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#12, \$9	Date	2023/8/10 上午 11:03:01
Segment	1	Camera	1
Pattern	801	Position[ x, y ]	88.5 [mm], 607.6 [m], ( 5286.7 [m] )
Type	点状疵点	Size	H:72.3 ,V:1.6 [mm]
Result	-	Area	71.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#11, \$8	Date	2023/8/10 上午 11:03:00
Segment	1	Camera	1
Pattern	800	Position[ x, y ]	121.5 [mm], 607.3 [m], ( 5287.0 [m] )
Type	点状疵点	Size	H:1.0 ,V:1.2 [mm]
Result	-	Area	1.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#11, \$8	Date	2023/8/10 上午 11:03:00
Segment	1	Camera	1
Pattern	800	Position[ x, y ]	434.7 [mm], 607.3 [m], ( 5287.0 [m] )
Type	点状疵点	Size	H:24.7 ,V:1.2 [mm]
Result	-	Area	21.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#11, \$8	Date	2023/8/10 上午 11:03:00
Segment	1	Camera	1
Pattern	800	Position[ x, y ]	757.5 [mm], 607.3 [m], ( 5287.0 [m] )
Type	点状疵点	Size	H:23.2 ,V:1.2 [mm]
Result	-	Area	22.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#10, \$7	Date	2023/8/10 上午 11:02:26
Segment	1	Camera	1
Pattern	742	Position[ x, y ]	435.2 [mm], 563.7 [m], ( 5330.6 [m] )
Type	点状疵点	Size	H:24.2 ,V:0.8 [mm]
Result	-	Area	11.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#10, \$7	Date	2023/8/10 上午 11:02:26
Segment	1	Camera	1
Pattern	742	Position[ x, y ]	114.4 [mm], 563.7 [m], ( 5330.6 [m] )
Type	点状疵点	Size	H:22.7 ,V:0.8 [mm]
Result	-	Area	17.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#7, \$6	Date	2023/8/10 上午 11:00:29
Segment	1	Camera	1
Pattern	542	Position[ x, y ]	564.6 [mm], 413.0 [m], ( 5481.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:132.0 [mm]
Result	-	Area	66.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#7, \$6	Date	2023/8/10 上午 11:00:29
Segment	1	Camera	1
Pattern	542	Position[ x, y ]	696.4 [mm], 413.1 [m], ( 5481.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:289.6 [mm]
Result	-	Area	83.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#7, \$6	Date	2023/8/10 上午 11:00:29
Segment	1	Camera	1
Pattern	542	Position[ x, y ]	373.2 [mm], 413.1 [m], ( 5481.1 [m] )
Type	点状疵点	Size	H:1.5 ,V:183.6 [mm]
Result	-	Area	86.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#7, \$6	Date	2023/8/10 上午 11:00:29
Segment	1	Camera	1
Pattern	542	Position[ x, y ]	564.3 [mm], 413.2 [m], ( 5481.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:329.2 [mm]
Result	-	Area	169.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#6, \$5	Date	2023/8/10 上午 11:00:29
Segment	1	Camera	1
Pattern	541	Position[ x, y ]	373.2 [mm], 412.8 [m], ( 5481.5 [m] )
Type	点状疵点	Size	H:1.5 ,V:288.4 [mm]
Result	-	Area	94.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#6, \$5	Date	2023/8/10 上午 11:00:29
Segment	1	Camera	1
Pattern	541	Position[ x, y ]	564.3 [mm], 412.5 [m], ( 5481.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:176.0 [mm]
Result	-	Area	98.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#6, \$5	Date	2023/8/10 上午 11:00:29
Segment	1	Camera	1
Pattern	541	Position[ x, y ]	564.3 [mm], 412.8 [m], ( 5481.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:289.2 [mm]
Result	-	Area	118.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#6, \$5	Date	2023/8/10 上午 11:00:29
Segment	1	Camera	1
Pattern	541	Position[ x, y ]	696.2 [mm], 412.8 [m], ( 5481.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:356.4 [mm]
Result	-	Area	144.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#5, \$4	Date	2023/8/10 上午 11:00:28
Segment	1	Camera	1
Pattern	540	Position[ x, y ]	373.2 [mm], 411.6 [m], ( 5482.6 [m] )
Type	点状疵点	Size	H:1.5 ,V:185.2 [mm]
Result	-	Area	90.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#5, \$4	Date	2023/8/10 上午 11:00:28
Segment	1	Camera	1
Pattern	540	Position[ x, y ]	564.3 [mm], 411.7 [m], ( 5482.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:253.2 [mm]
Result	-	Area	96.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#5, \$4	Date	2023/8/10 上午 11:00:28
Segment	1	Camera	1
Pattern	540	Position[ x, y ]	564.3 [mm], 412.0 [m], ( 5482.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:272.0 [mm]
Result	-	Area	115.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#5, \$4	Date	2023/8/10 上午 11:00:28
Segment	1	Camera	1
Pattern	540	Position[ x, y ]	696.2 [mm], 412.1 [m], ( 5482.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:270.4 [mm]
Result	-	Area	127.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/10 上午 11:00:28
Segment	1	Camera	1
Pattern	539	Position[ x, y ]	697.9 [mm], 411.2 [m], ( 5483.1 [m] )
Type	点状疵点	Size	H:0.5 ,V:100.0 [mm]
Result	-	Area	40.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/10 上午 11:00:28
Segment	1	Camera	1
Pattern	539	Position[ x, y ]	566.1 [mm], 410.9 [m], ( 5483.4 [m] )
Type	点状疵点	Size	H:1.5 ,V:99.6 [mm]
Result	-	Area	45.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/10 上午 11:00:28
Segment	1	Camera	1
Pattern	539	Position[ x, y ]	565.8 [mm], 411.1 [m], ( 5483.2 [m] )
Type	点状疵点	Size	H:1.5 ,V:107.6 [mm]
Result	-	Area	51.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/10 上午 11:00:28
Segment	1	Camera	1
Pattern	539	Position[ x, y ]	373.2 [mm], 410.9 [m], ( 5483.4 [m] )
Type	点状疵点	Size	H:0.5 ,V:149.6 [mm]
Result	-	Area	58.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#3, \$2	Date	2023/8/10 上午 11:00:27
Segment	1	Camera	1
Pattern	538	Position[ x, y ]	566.1 [mm], 410.5 [m], ( 5483.8 [m] )
Type	点状疵点	Size	H:0.5 ,V:44.4 [mm]
Result	-	Area	5.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#3, \$2	Date	2023/8/10 上午 11:00:27
Segment	1	Camera	1
Pattern	538	Position[ x, y ]	373.2 [mm], 410.7 [m], ( 5483.6 [m] )
Type	点状疵点	Size	H:0.5 ,V:78.0 [mm]
Result	-	Area	14.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#3, \$2	Date	2023/8/10 上午 11:00:27
Segment	1	Camera	1
Pattern	538	Position[ x, y ]	697.9 [mm], 410.7 [m], ( 5483.6 [m] )
Type	点状疵点	Size	H:0.7 ,V:80.0 [mm]
Result	-	Area	20.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#3, \$2	Date	2023/8/10 上午 11:00:27
Segment	1	Camera	1
Pattern	538	Position[ x, y ]	566.1 [mm], 410.6 [m], ( 5483.6 [m] )
Type	点状疵点	Size	H:1.5 ,V:155.2 [mm]
Result	-	Area	37.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/10 上午 10:55:13 ~ 2023/8/10 下午 12:12:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	36	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	5894.3 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#2, \$1	Date	2023/8/10 上午 10:57:00
Segment	1	Camera	1
Pattern	184	Position[ x, y ]	737.4 [mm], 144.9 [m], ( 5749.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:2.4 [mm]
Result	-	Area	5.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image



Reference image



Shape image

