

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#35, \$26	Date	2023/8/9 下午 12:59:21
Segment	1	Camera	1
Pattern	7645	Position[x, y]	12.6 [mm], 5748.0 [m], (1.9 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:24.9 ,V:18.8 [mm]
Result	-	Area	316.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#32, \$25	Date	2023/8/9 下午 12:58:34
Segment	1	Camera	1
Pattern	7568	Position[x, y]	443.2 [mm], 5690.3 [m], (59.6 [m])
Type	縱向刀絲疵點	Size	H:36.9 ,V:180.0 [mm]
Result	-	Area	70.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#32, \$25	Date	2023/8/9 下午 12:58:34
Segment	1	Camera	1
Pattern	7568	Position[x, y]	759.9 [mm], 5690.3 [m], (59.6 [m])
Type	縱向刀絲疵點	Size	H:61.0 ,V:180.4 [mm]
Result	-	Area	76.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#32, \$25	Date	2023/8/9 下午 12:58:34
Segment	1	Camera	1
Pattern	7568	Position[x, y]	372.4 [mm], 5690.6 [m], (59.2 [m])
Type	点状疵点	Size	H:1.7 ,V:96.0 [mm]
Result	-	Area	77.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#32, \$25	Date	2023/8/9 下午 12:58:34
Segment	1	Camera	1
Pattern	7568	Position[x, y]	870.0 [mm], 5690.3 [m], (59.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:26.1 ,V:218.4 [mm]
Result	-	Area	92.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#31, \$24	Date	2023/8/9 下午 12:58:34
Segment	1	Camera	1
Pattern	7567	Position[x, y]	766.7 [mm], 5689.5 [m], (60.3 [m])
Type	縱向刀絲疵點	Size	H:35.9 ,V:181.2 [mm]
Result	-	Area	79.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#31, \$24	Date	2023/8/9 下午 12:58:34
Segment	1	Camera	1
Pattern	7567	Position[x, y]	874.4 [mm], 5689.6 [m], (60.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:26.4 ,V:372.0 [mm]
Result	-	Area	90.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#31, \$24	Date	2023/8/9 下午 12:58:34
Segment	1	Camera	1
Pattern	7567	Position[x, y]	555.0 [mm], 5689.6 [m], (60.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:28.1 ,V:380.4 [mm]
Result	-	Area	90.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#31, \$24	Date	2023/8/9 下午 12:58:34
Segment	1	Camera	1
Pattern	7567	Position[x, y]	703.5 [mm], 5689.6 [m], (60.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:27.3 ,V:392.8 [mm]
Result	-	Area	114.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#30, \$23	Date	2023/8/9 下午 12:58:33
Segment	1	Camera	1
Pattern	7566	Position[x, y]	373.9 [mm], 5688.8 [m], (61.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:3.9 ,V:208.4 [mm]
Result	-	Area	109.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#30, \$23	Date	2023/8/9 下午 12:58:33
Segment	1	Camera	1
Pattern	7566	Position[x, y]	555.3 [mm], 5688.8 [m], (61.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:28.3 ,V:446.0 [mm]
Result	-	Area	136.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#30, \$23	Date	2023/8/9 下午 12:58:33
Segment	1	Camera	1
Pattern	7566	Position[x, y]	871.2 [mm], 5688.8 [m], (61.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:26.6 ,V:446.4 [mm]
Result	-	Area	166.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#30, \$23	Date	2023/8/9 下午 12:58:33
Segment	1	Camera	1
Pattern	7566	Position[x, y]	698.6 [mm], 5688.8 [m], (61.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.2 ,V:324.8 [mm]
Result	-	Area	169.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#29, \$22	Date	2023/8/9 下午 12:58:33
Segment	1	Camera	1
Pattern	7565	Position[x, y]	444.2 [mm], 5688.0 [m], (61.8 [m])
Type	縱向刀絲疵點	Size	H:37.1 ,V:180.4 [mm]
Result	-	Area	94.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#29, \$22	Date	2023/8/9 下午 12:58:33
Segment	1	Camera	1
Pattern	7565	Position[x, y]	764.0 [mm], 5688.0 [m], (61.8 [m])
Type	縱向刀絲疵點	Size	H:35.6 ,V:180.4 [mm]
Result	-	Area	95.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#29, \$22	Date	2023/8/9 下午 12:58:33
Segment	1	Camera	1
Pattern	7565	Position[x, y]	870.7 [mm], 5688.0 [m], (61.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:26.1 ,V:361.6 [mm]
Result	-	Area	108.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#29, \$22	Date	2023/8/9 下午 12:58:33
Segment	1	Camera	1
Pattern	7565	Position[x, y]	554.3 [mm], 5688.1 [m], (61.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:28.1 ,V:418.4 [mm]
Result	-	Area	146.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#28, \$21	Date	2023/8/9 下午 12:58:32
Segment	1	Camera	1
Pattern	7564	Position[x, y]	765.0 [mm], 5687.3 [m], (62.6 [m])
Type	縱向刀絲疵點	Size	H:35.9 ,V:180.8 [mm]
Result	-	Area	95.8 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#28, \$21	Date	2023/8/9 下午 12:58:32
Segment	1	Camera	1
Pattern	7564	Position[x, y]	698.3 [mm], 5687.3 [m], (62.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:4.4 ,V:430.8 [mm]
Result	-	Area	163.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#28, \$21	Date	2023/8/9 下午 12:58:32
Segment	1	Camera	1
Pattern	7564	Position[x, y]	554.5 [mm], 5687.3 [m], (62.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:28.1 ,V:430.4 [mm]
Result	-	Area	178.7 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#28, \$21	Date	2023/8/9 下午 12:58:32
Segment	1	Camera	1
Pattern	7564	Position[x, y]	871.0 [mm], 5687.3 [m], (62.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:26.6 ,V:431.2 [mm]
Result	-	Area	230.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#26, \$20	Date	2023/8/9 下午 12:53:10
Segment	1	Camera	1
Pattern	7425	Position[x, y]	459.8 [mm], 5581.3 [m], (168.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:192.6 ,V:79.2 [mm]
Result	-	Area	269.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#26, \$20	Date	2023/8/9 下午 12:53:10
Segment	1	Camera	1
Pattern	7425	Position[x, y]	117.3 [mm], 5581.3 [m], (168.6 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.1 ,V:112.8 [mm]
Result	-	Area	289.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#26, \$20	Date	2023/8/9 下午 12:53:10
Segment	1	Camera	1
Pattern	7425	Position[x, y]	747.7 [mm], 5581.6 [m], (168.2 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.1 ,V:85.2 [mm]
Result	-	Area	359.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#26, \$20	Date	2023/8/9 下午 12:53:10
Segment	1	Camera	1
Pattern	7425	Position[x, y]	133.4 [mm], 5581.6 [m], (168.2 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.1 ,V:159.2 [mm]
Result	-	Area	379.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$19	Date	2023/8/9 下午 12:48:41
Segment	1	Camera	1
Pattern	7424	Position[x, y]	217.1 [mm], 5580.5 [m], (169.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:47.4 ,V:41.6 [mm]
Result	-	Area	54.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$19	Date	2023/8/9 下午 12:48:41
Segment	1	Camera	1
Pattern	7424	Position[x, y]	464.5 [mm], 5580.5 [m], (169.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:82.0 ,V:48.0 [mm]
Result	-	Area	56.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#24, \$19	Date	2023/8/9 下午 12:48:41
Segment	1	Camera	1
Pattern	7424	Position[x, y]	538.2 [mm], 5580.5 [m], (169.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:59.3 ,V:41.2 [mm]
Result	-	Area	65.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#24, \$19	Date	2023/8/9 下午 12:48:41
Segment	1	Camera	1
Pattern	7424	Position[x, y]	125.6 [mm], 5580.4 [m], (169.4 [m])
Type	点状疵点	Size	H:108.2 ,V:1.6 [mm]
Result	-	Area	123.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#23, \$18	Date	2023/8/9 下午 12:42:44
Segment	1	Camera	1
Pattern	6836	Position[x, y]	178.3 [mm], 5139.2 [m], (610.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:4.8 [mm]
Result	-	Area	7.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#22, \$17	Date	2023/8/9 下午 12:35:53
Segment	1	Camera	1
Pattern	6155	Position[x, y]	482.0 [mm], 4628.0 [m], (1121.9 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:4.8 [mm]
Result	-	Area	5.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#21, \$16	Date	2023/8/9 下午 12:35:53
Segment	1	Camera	1
Pattern	6154	Position[x, y]	482.0 [mm], 4627.4 [m], (1122.5 [m])
Type	縱向刀絲疵點	Size	H:1.7 ,V:2.4 [mm]
Result	-	Area	2.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#20, \$15	Date	2023/8/9 下午 12:28:40
Segment	1	Camera	1
Pattern	5437	Position[x, y]	831.4 [mm], 4088.4 [m], (1661.4 [m])
Type	縱向刀絲疵點	Size	H:2.9 ,V:94.8 [mm]
Result	-	Area	101.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#19, \$14	Date	2023/8/9 下午 12:25:50
Segment	1	Camera	1
Pattern	5155	Position[x, y]	879.3 [mm], 3876.9 [m], (1872.9 [m])
Type	縱向刀絲疵點	Size	H:1.7 ,V:2.4 [mm]
Result	-	Area	2.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#16, \$13	Date	2023/8/9 下午 12:20:43
Segment	1	Camera	1
Pattern	4635	Position[x, y]	375.3 [mm], 3486.4 [m], (2263.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:648.0 [mm]
Result	-	Area	79.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#16, \$13	Date	2023/8/9 下午 12:20:43
Segment	1	Camera	1
Pattern	4635	Position[x, y]	568.2 [mm], 3486.4 [m], (2263.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:794.0 [mm]
Result	-	Area	86.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#16, \$13	Date	2023/8/9 下午 12:20:43
Segment	1	Camera	1
Pattern	4635	Position[x, y]	700.1 [mm], 3486.4 [m], (2263.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:648.0 [mm]
Result	-	Area	107.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#16, \$13	Date	2023/8/9 下午 12:20:43
Segment	1	Camera	1
Pattern	4635	Position[x, y]	243.0 [mm], 3486.4 [m], (2263.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:793.6 [mm]
Result	-	Area	115.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#15, \$12	Date	2023/8/9 下午 12:20:42
Segment	1	Camera	1
Pattern	4634	Position[x, y]	243.0 [mm], 3485.6 [m], (2264.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:808.0 [mm]
Result	-	Area	116.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#15, \$12	Date	2023/8/9 下午 12:20:42
Segment	1	Camera	1
Pattern	4634	Position[x, y]	700.1 [mm], 3485.6 [m], (2264.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:623.6 [mm]
Result	-	Area	119.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範囲 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#15, \$12	Date	2023/8/9 下午 12:20:42
Segment	1	Camera	1
Pattern	4634	Position[x, y]	883.9 [mm], 3485.6 [m], (2264.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:808.0 [mm]
Result	-	Area	119.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#15, \$12	Date	2023/8/9 下午 12:20:42
Segment	1	Camera	1
Pattern	4634	Position[x, y]	568.0 [mm], 3485.6 [m], (2264.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:808.0 [mm]
Result	-	Area	149.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#14, \$11	Date	2023/8/9 下午 12:20:42
Segment	1	Camera	1
Pattern	4633	Position[x, y]	883.9 [mm], 3484.9 [m], (2265.0 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:808.0 [mm]
Result	-	Area	116.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#14, \$11	Date	2023/8/9 下午 12:20:42
Segment	1	Camera	1
Pattern	4633	Position[x, y]	243.0 [mm], 3484.9 [m], (2265.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:808.0 [mm]
Result	-	Area	118.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#14, \$11	Date	2023/8/9 下午 12:20:42
Segment	1	Camera	1
Pattern	4633	Position[x, y]	700.1 [mm], 3484.8 [m], (2265.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:641.2 [mm]
Result	-	Area	122.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#14, \$11	Date	2023/8/9 下午 12:20:42
Segment	1	Camera	1
Pattern	4633	Position[x, y]	568.0 [mm], 3484.9 [m], (2265.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:808.0 [mm]
Result	-	Area	147.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#13, \$10	Date	2023/8/9 下午 12:20:41
Segment	1	Camera	1
Pattern	4632	Position[x, y]	375.1 [mm], 3484.4 [m], (2265.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:495.2 [mm]
Result	-	Area	111.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#13, \$10	Date	2023/8/9 下午 12:20:41
Segment	1	Camera	1
Pattern	4632	Position[x, y]	243.0 [mm], 3484.2 [m], (2265.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:793.2 [mm]
Result	-	Area	117.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#13, \$10	Date	2023/8/9 下午 12:20:41
Segment	1	Camera	1
Pattern	4632	Position[x, y]	883.9 [mm], 3484.3 [m], (2265.6 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:602.8 [mm]
Result	-	Area	119.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#13, \$10	Date	2023/8/9 下午 12:20:41
Segment	1	Camera	1
Pattern	4632	Position[x, y]	568.0 [mm], 3484.1 [m], (2265.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:793.6 [mm]
Result	-	Area	152.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#12, \$9	Date	2023/8/9 下午 12:20:40
Segment	1	Camera	1
Pattern	4631	Position[x, y]	375.3 [mm], 3483.6 [m], (2266.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:143.6 [mm]
Result	-	Area	35.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#12, \$9	Date	2023/8/9 下午 12:20:40
Segment	1	Camera	1
Pattern	4631	Position[x, y]	700.1 [mm], 3483.7 [m], (2266.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:326.4 [mm]
Result	-	Area	64.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#12, \$9	Date	2023/8/9 下午 12:20:40
Segment	1	Camera	1
Pattern	4631	Position[x, y]	243.0 [mm], 3483.7 [m], (2266.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:483.6 [mm]
Result	-	Area	91.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#12, \$9	Date	2023/8/9 下午 12:20:40
Segment	1	Camera	1
Pattern	4631	Position[x, y]	568.2 [mm], 3483.6 [m], (2266.3 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:426.8 [mm]
Result	-	Area	108.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#9, \$8	Date	2023/8/9 下午 12:20:33
Segment	1	Camera	1
Pattern	4618	Position[x, y]	92.9 [mm], 3473.5 [m], (2276.4 [m])
Type	縱向刀絲疵點	Size	H:8.5 ,V:58.8 [mm]
Result	-	Area	7.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#9, \$8	Date	2023/8/9 下午 12:20:33
Segment	1	Camera	1
Pattern	4618	Position[x, y]	96.1 [mm], 3473.8 [m], (2276.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:13.2 [mm]
Result	-	Area	7.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#9, \$8	Date	2023/8/9 下午 12:20:33
Segment	1	Camera	1
Pattern	4618	Position[x, y]	225.0 [mm], 3473.5 [m], (2276.4 [m])
Type	縱向刀絲疵點	Size	H:12.9 ,V:45.2 [mm]
Result	-	Area	8.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#9, \$8	Date	2023/8/9 下午 12:20:33
Segment	1	Camera	1
Pattern	4618	Position[x, y]	939.8 [mm], 3473.7 [m], (2276.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:14.4 [mm]
Result	-	Area	8.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#8, \$7	Date	2023/8/9 下午 12:20:32
Segment	1	Camera	1
Pattern	4617	Position[x, y]	415.1 [mm], 3473.1 [m], (2276.8 [m])
Type	縱向刀絲疵點	Size	H:2.7 ,V:13.2 [mm]
Result	-	Area	6.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#8, \$7	Date	2023/8/9 下午 12:20:32
Segment	1	Camera	1
Pattern	4617	Position[x, y]	735.0 [mm], 3472.7 [m], (2277.1 [m])
Type	縱向刀絲疵點	Size	H:8.5 ,V:58.4 [mm]
Result	-	Area	6.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#8, \$7	Date	2023/8/9 下午 12:20:32
Segment	1	Camera	1
Pattern	4617	Position[x, y]	738.6 [mm], 3473.1 [m], (2276.8 [m])
Type	縱向刀絲疵點	Size	H:0.7 ,V:9.6 [mm]
Result	-	Area	7.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#8, \$7	Date	2023/8/9 下午 12:20:32
Segment	1	Camera	1
Pattern	4617	Position[x, y]	939.6 [mm], 3473.0 [m], (2276.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:14.4 [mm]
Result	-	Area	8.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#7, \$6	Date	2023/8/9 下午 12:20:32
Segment	1	Camera	1
Pattern	4616	Position[x, y]	738.6 [mm], 3472.3 [m], (2277.5 [m])
Type	縱向刀絲疵點	Size	H:0.7 ,V:9.6 [mm]
Result	-	Area	4.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#7, \$6	Date	2023/8/9 下午 12:20:32
Segment	1	Camera	1
Pattern	4616	Position[x, y]	92.6 [mm], 3471.9 [m], (2277.9 [m])
Type	縱向刀絲疵點	Size	H:8.1 ,V:32.0 [mm]
Result	-	Area	4.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#7, \$6	Date	2023/8/9 下午 12:20:32
Segment	1	Camera	1
Pattern	4616	Position[x, y]	728.6 [mm], 3472.0 [m], (2277.9 [m])
Type	縱向刀絲疵點	Size	H:8.3 ,V:56.4 [mm]
Result	-	Area	5.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#7, \$6	Date	2023/8/9 下午 12:20:32
Segment	1	Camera	1
Pattern	4616	Position[x, y]	939.3 [mm], 3472.2 [m], (2277.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.6 ,V:14.4 [mm]
Result	-	Area	6.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#6, \$5	Date	2023/8/9 下午 12:20:31
Segment	1	Camera	1
Pattern	4615	Position[x, y]	939.6 [mm], 3471.5 [m], (2278.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:14.0 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#6, \$5	Date	2023/8/9 下午 12:20:31
Segment	1	Camera	1
Pattern	4615	Position[x, y]	723.5 [mm], 3471.6 [m], (2278.3 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.4 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#6, \$5	Date	2023/8/9 下午 12:20:31
Segment	1	Camera	1
Pattern	4615	Position[x, y]	734.7 [mm], 3471.6 [m], (2278.3 [m])
Type	縱向刀絲疵點	Size	H:8.1 ,V:31.2 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#6, \$5	Date	2023/8/9 下午 12:20:31
Segment	1	Camera	1
Pattern	4615	Position[x, y]	738.6 [mm], 3471.2 [m], (2278.7 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#5, \$4	Date	2023/8/9 下午 12:20:30
Segment	1	Camera	1
Pattern	4614	Position[x, y]	735.7 [mm], 3470.4 [m], (2279.4 [m])
Type	縱向刀絲疵點	Size	H:8.1 ,V:55.6 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#5, \$4	Date	2023/8/9 下午 12:20:30
Segment	1	Camera	1
Pattern	4614	Position[x, y]	734.7 [mm], 3470.8 [m], (2279.0 [m])
Type	縱向刀絲疵點	Size	H:8.1 ,V:53.6 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#4, \$3	Date	2023/8/9 下午 12:20:20
Segment	1	Camera	1
Pattern	4596	Position[x, y]	730.3 [mm], 3456.9 [m], (2292.9 [m])
Type	縱向刀絲疵點	Size	H:11.5 ,V:8.8 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#4, \$3	Date	2023/8/9 下午 12:20:20
Segment	1	Camera	1
Pattern	4596	Position[x, y]	400.7 [mm], 3457.3 [m], (2292.6 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.6 [mm]
Result	-	Area	3.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#4, \$3	Date	2023/8/9 下午 12:20:20
Segment	1	Camera	1
Pattern	4596	Position[x, y]	939.3 [mm], 3457.2 [m], (2292.7 [m])
Type	点状疵点	Size	H:0.5 ,V:10.8 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	

Defect information

No.	#4, \$3	Date	2023/8/9 下午 12:20:20
Segment	1	Camera	1
Pattern	4596	Position[x, y]	725.0 [mm], 3457.3 [m], (2292.6 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	3.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#3, \$2	Date	2023/8/9 下午 12:20:19
Segment	1	Camera	1
Pattern	4595	Position[x, y]	939.3 [mm], 3456.4 [m], (2293.4 [m])
Type	点状疵点	Size	H:0.5 ,V:4.4 [mm]
Result	-	Area	1.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#3, \$2	Date	2023/8/9 下午 12:20:19
Segment	1	Camera	1
Pattern	4595	Position[x, y]	727.6 [mm], 3456.6 [m], (2293.3 [m])
Type	縱向刀絲疵點	Size	H:11.5 ,V:8.4 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 4

Inspected date : 2023/8/9 上午 11:35:04 ~ 2023/8/9 下午 12:59:28

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	26	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	5749.9 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 (從左側)	


Defect information

No.	#2, \$1	Date	2023/8/9 上午 11:43:19
Segment	1	Camera	1
Pattern	838	Position[x, y]	392.7 [mm], 636.0 [m], (5113.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:2.0 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image



Reference image



Shape image

