

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#82, \$59	Date	2023/8/10 上午 10:55:05
Segment	1	Camera	1
Pattern	8270	Position[ x, y ]	5.0 [mm], 6221.8 [m], ( 2.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:10.7 ,V:16.4 [mm]
Result	-	Area	122.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#79, \$58	Date	2023/8/10 上午 10:53:50
Segment	1	Camera	1
Pattern	8141	Position[ x, y ]	203.5 [mm], 6125.0 [m], ( 99.1 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:14.0 [mm]
Result	-	Area	8.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#79, \$58	Date	2023/8/10 上午 10:53:50
Segment	1	Camera	1
Pattern	8141	Position[ x, y ]	527.7 [mm], 6124.7 [m], ( 99.5 [m] )
Type	縱向刀絲疵點	Size	H:5.6 ,V:14.4 [mm]
Result	-	Area	8.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#79, \$58	Date	2023/8/10 上午 10:53:50
Segment	1	Camera	1
Pattern	8141	Position[ x, y ]	707.2 [mm], 6124.6 [m], ( 99.5 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:14.0 [mm]
Result	-	Area	8.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#79, \$58	Date	2023/8/10 上午 10:53:50
Segment	1	Camera	1
Pattern	8141	Position[ x, y ]	203.7 [mm], 6124.7 [m], ( 99.5 [m] )
Type	縱向刀絲疵點	Size	H:5.6 ,V:14.0 [mm]
Result	-	Area	8.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#78, \$57	Date	2023/8/10 上午 10:53:49
Segment	1	Camera	1
Pattern	8140	Position[ x, y ]	526.7 [mm], 6123.9 [m], ( 100.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:14.0 [mm]
Result	-	Area	5.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#78, \$57	Date	2023/8/10 上午 10:53:49
Segment	1	Camera	1
Pattern	8140	Position[ x, y ]	202.5 [mm], 6124.3 [m], ( 99.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:13.2 [mm]
Result	-	Area	6.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#78, \$57	Date	2023/8/10 上午 10:53:49
Segment	1	Camera	1
Pattern	8140	Position[ x, y ]	202.5 [mm], 6123.9 [m], ( 100.3 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:13.6 [mm]
Result	-	Area	6.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)


商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#78, \$57	Date	2023/8/10 上午 10:53:49
Segment	1	Camera	1
Pattern	8140	Position[ x, y ]	706.7 [mm], 6124.3 [m], ( 99.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:14.0 [mm]
Result	-	Area	6.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#77, \$56	Date	2023/8/10 上午 10:53:48
Segment	1	Camera	1
Pattern	8139	Position[ x, y ]	528.2 [mm], 6123.5 [m], ( 100.6 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:13.6 [mm]
Result	-	Area	6.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)


商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#77, \$56	Date	2023/8/10 上午 10:53:48
Segment	1	Camera	1
Pattern	8139	Position[ x, y ]	383.2 [mm], 6123.5 [m], ( 100.7 [m] )
Type	縱向刀絲疵點	Size	H:5.6 ,V:13.6 [mm]
Result	-	Area	6.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#77, \$56	Date	2023/8/10 上午 10:53:48
Segment	1	Camera	1
Pattern	8139	Position[ x, y ]	383.2 [mm], 6123.1 [m], ( 101.0 [m] )
Type	縱向刀絲疵點	Size	H:5.6 ,V:14.0 [mm]
Result	-	Area	6.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#77, \$56	Date	2023/8/10 上午 10:53:48
Segment	1	Camera	1
Pattern	8139	Position[ x, y ]	527.7 [mm], 6123.2 [m], ( 101.0 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:14.0 [mm]
Result	-	Area	7.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#76, \$55	Date	2023/8/10 上午 10:53:48
Segment	1	Camera	1
Pattern	8138	Position[ x, y ]	706.9 [mm], 6122.4 [m], ( 101.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:13.2 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#76, \$55	Date	2023/8/10 上午 10:53:48
Segment	1	Camera	1
Pattern	8138	Position[ x, y ]	526.7 [mm], 6122.4 [m], ( 101.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:13.6 [mm]
Result	-	Area	4.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#76, \$55	Date	2023/8/10 上午 10:53:48
Segment	1	Camera	1
Pattern	8138	Position[ x, y ]	383.4 [mm], 6122.8 [m], ( 101.4 [m] )
Type	縱向刀絲疵點	Size	H:5.6 ,V:13.6 [mm]
Result	-	Area	5.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#76, \$55	Date	2023/8/10 上午 10:53:48
Segment	1	Camera	1
Pattern	8138	Position[ x, y ]	528.0 [mm], 6122.8 [m], ( 101.4 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:13.2 [mm]
Result	-	Area	5.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#75, \$54	Date	2023/8/10 上午 10:53:47
Segment	1	Camera	1
Pattern	8137	Position[ x, y ]	937.4 [mm], 6122.3 [m], ( 101.9 [m] )
Type	点状疵点	Size	H:1.2 ,V:4.0 [mm]
Result	-	Area	1.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#72, \$53	Date	2023/8/10 上午 10:53:37
Segment	1	Camera	1
Pattern	8119	Position[ x, y ]	696.2 [mm], 6108.2 [m], ( 116.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:102.8 [mm]
Result	-	Area	119.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$53	Date	2023/8/10 上午 10:53:37
Segment	1	Camera	1
Pattern	8119	Position[ x, y ]	551.9 [mm], 6108.2 [m], ( 116.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:32.5 ,V:245.6 [mm]
Result	-	Area	119.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$53	Date	2023/8/10 上午 10:53:37
Segment	1	Camera	1
Pattern	8119	Position[ x, y ]	695.9 [mm], 6108.3 [m], ( 115.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:198.4 [mm]
Result	-	Area	120.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#72, \$53	Date	2023/8/10 上午 10:53:37
Segment	1	Camera	1
Pattern	8119	Position[ x, y ]	371.0 [mm], 6108.3 [m], ( 115.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:194.4 [mm]
Result	-	Area	122.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#71, \$52	Date	2023/8/10 上午 10:53:36
Segment	1	Camera	1
Pattern	8118	Position[ x, y ]	229.4 [mm], 6107.6 [m], ( 116.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:26.6 ,V:132.4 [mm]
Result	-	Area	127.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#71, \$52	Date	2023/8/10 上午 10:53:36
Segment	1	Camera	1
Pattern	8118	Position[ x, y ]	371.0 [mm], 6107.5 [m], ( 116.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:195.6 [mm]
Result	-	Area	145.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#71, \$52	Date	2023/8/10 上午 10:53:36
Segment	1	Camera	1
Pattern	8118	Position[ x, y ]	695.9 [mm], 6107.5 [m], ( 116.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:199.2 [mm]
Result	-	Area	155.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#71, \$52	Date	2023/8/10 上午 10:53:36
Segment	1	Camera	1
Pattern	8118	Position[ x, y ]	559.0 [mm], 6107.6 [m], ( 116.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:14.9 ,V:398.0 [mm]
Result	-	Area	247.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#70, \$51	Date	2023/8/10 上午 10:53:35
Segment	1	Camera	1
Pattern	8117	Position[ x, y ]	565.3 [mm], 6107.2 [m], ( 117.0 [m] )
Type	点状疵点	Size	H:1.7 ,V:203.2 [mm]
Result	-	Area	101.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#70, \$51	Date	2023/8/10 上午 10:53:35
Segment	1	Camera	1
Pattern	8117	Position[ x, y ]	371.0 [mm], 6106.8 [m], ( 117.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:176.0 [mm]
Result	-	Area	102.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#70, \$51	Date	2023/8/10 上午 10:53:35
Segment	1	Camera	1
Pattern	8117	Position[ x, y ]	697.2 [mm], 6107.0 [m], ( 117.2 [m] )
Type	点状疵点	Size	H:1.7 ,V:120.4 [mm]
Result	-	Area	114.0 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#70, \$51	Date	2023/8/10 上午 10:53:35
Segment	1	Camera	1
Pattern	8117	Position[ x, y ]	697.2 [mm], 6107.2 [m], ( 117.0 [m] )
Type	点状疵点	Size	H:1.7 ,V:142.8 [mm]
Result	-	Area	114.4 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#69, \$50	Date	2023/8/10 上午 10:53:35
Segment	1	Camera	1
Pattern	8116	Position[ x, y ]	696.4 [mm], 6106.0 [m], ( 118.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:162.8 [mm]
Result	-	Area	54.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#69, \$50	Date	2023/8/10 上午 10:53:35
Segment	1	Camera	1
Pattern	8116	Position[ x, y ]	565.3 [mm], 6106.3 [m], ( 117.9 [m] )
Type	点状疵点	Size	H:1.5 ,V:83.2 [mm]
Result	-	Area	59.3 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#69, \$50	Date	2023/8/10 上午 10:53:35
Segment	1	Camera	1
Pattern	8116	Position[ x, y ]	697.6 [mm], 6106.4 [m], ( 117.7 [m] )
Type	点状疵点	Size	H:1.5 ,V:125.2 [mm]
Result	-	Area	69.2 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#69, \$50	Date	2023/8/10 上午 10:53:35
Segment	1	Camera	1
Pattern	8116	Position[ x, y ]	565.3 [mm], 6106.4 [m], ( 117.7 [m] )
Type	点状疵点	Size	H:1.5 ,V:126.4 [mm]
Result	-	Area	86.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#68, \$49	Date	2023/8/10 上午 10:53:34
Segment	1	Camera	1
Pattern	8115	Position[ x, y ]	565.6 [mm], 6105.7 [m], ( 118.5 [m] )
Type	点状疵点	Size	H:0.5 ,V:108.0 [mm]
Result	-	Area	27.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#68, \$49	Date	2023/8/10 上午 10:53:34
Segment	1	Camera	1
Pattern	8115	Position[ x, y ]	697.6 [mm], 6105.5 [m], ( 118.7 [m] )
Type	点状疵点	Size	H:0.5 ,V:99.6 [mm]
Result	-	Area	27.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#68, \$49	Date	2023/8/10 上午 10:53:34
Segment	1	Camera	1
Pattern	8115	Position[ x, y ]	565.6 [mm], 6105.8 [m], ( 118.3 [m] )
Type	点状疵点	Size	H:0.5 ,V:101.2 [mm]
Result	-	Area	30.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#68, \$49	Date	2023/8/10 上午 10:53:34
Segment	1	Camera	1
Pattern	8115	Position[ x, y ]	697.6 [mm], 6105.7 [m], ( 118.5 [m] )
Type	点状疵点	Size	H:0.5 ,V:106.8 [mm]
Result	-	Area	37.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#65, \$48	Date	2023/8/10 上午 10:53:26
Segment	1	Camera	1
Pattern	8101	Position[ x, y ]	240.1 [mm], 6094.8 [m], ( 129.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:179.2 [mm]
Result	-	Area	134.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#65, \$48	Date	2023/8/10 上午 10:53:26
Segment	1	Camera	1
Pattern	8101	Position[ x, y ]	565.6 [mm], 6094.8 [m], ( 129.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:390.8 [mm]
Result	-	Area	173.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#65, \$48	Date	2023/8/10 上午 10:53:26
Segment	1	Camera	1
Pattern	8101	Position[ x, y ]	881.2 [mm], 6094.9 [m], ( 129.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:497.2 [mm]
Result	-	Area	185.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#65, \$48	Date	2023/8/10 上午 10:53:26
Segment	1	Camera	1
Pattern	8101	Position[ x, y ]	702.3 [mm], 6094.8 [m], ( 129.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:13.2 ,V:498.0 [mm]
Result	-	Area	212.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#64, \$47	Date	2023/8/10 上午 10:53:26
Segment	1	Camera	1
Pattern	8100	Position[ x, y ]	881.2 [mm], 6094.2 [m], ( 130.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:546.8 [mm]
Result	-	Area	94.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#64, \$47	Date	2023/8/10 上午 10:53:26
Segment	1	Camera	1
Pattern	8100	Position[ x, y ]	701.6 [mm], 6094.0 [m], ( 130.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.9 ,V:279.6 [mm]
Result	-	Area	96.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#64, \$47	Date	2023/8/10 上午 10:53:26
Segment	1	Camera	1
Pattern	8100	Position[ x, y ]	697.4 [mm], 6094.3 [m], ( 129.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:348.4 [mm]
Result	-	Area	113.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#64, \$47	Date	2023/8/10 上午 10:53:26
Segment	1	Camera	1
Pattern	8100	Position[ x, y ]	565.3 [mm], 6094.2 [m], ( 130.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:806.4 [mm]
Result	-	Area	170.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#63, \$46	Date	2023/8/10 上午 10:53:25
Segment	1	Camera	1
Pattern	8099	Position[ x, y ]	880.8 [mm], 6093.7 [m], ( 130.5 [m] )
Type	点状疵点	Size	H:1.5 ,V:124.8 [mm]
Result	-	Area	49.4 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#63, \$46	Date	2023/8/10 上午 10:53:25
Segment	1	Camera	1
Pattern	8099	Position[ x, y ]	697.4 [mm], 6093.5 [m], ( 130.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:500.4 [mm]
Result	-	Area	61.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#63, \$46	Date	2023/8/10 上午 10:53:25
Segment	1	Camera	1
Pattern	8099	Position[ x, y ]	881.2 [mm], 6093.4 [m], ( 130.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:500.0 [mm]
Result	-	Area	83.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#63, \$46	Date	2023/8/10 上午 10:53:25
Segment	1	Camera	1
Pattern	8099	Position[ x, y ]	565.3 [mm], 6093.5 [m], ( 130.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:502.8 [mm]
Result	-	Area	88.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#62, \$45	Date	2023/8/10 上午 10:53:24
Segment	1	Camera	1
Pattern	8098	Position[ x, y ]	697.4 [mm], 6092.4 [m], ( 131.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:50.4 [mm]
Result	-	Area	18.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#62, \$45	Date	2023/8/10 上午 10:53:24
Segment	1	Camera	1
Pattern	8098	Position[ x, y ]	697.2 [mm], 6093.1 [m], ( 131.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:50.8 [mm]
Result	-	Area	22.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#62, \$45	Date	2023/8/10 上午 10:53:24
Segment	1	Camera	1
Pattern	8098	Position[ x, y ]	881.2 [mm], 6092.7 [m], ( 131.5 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:193.2 [mm]
Result	-	Area	25.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#62, \$45	Date	2023/8/10 上午 10:53:24
Segment	1	Camera	1
Pattern	8098	Position[ x, y ]	881.2 [mm], 6093.1 [m], ( 131.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:202.4 [mm]
Result	-	Area	39.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#61, \$44	Date	2023/8/10 上午 10:53:24
Segment	1	Camera	1
Pattern	8097	Position[ x, y ]	697.4 [mm], 6092.4 [m], ( 131.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:50.0 [mm]
Result	-	Area	18.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#58, \$43	Date	2023/8/10 上午 10:52:59
Segment	1	Camera	1
Pattern	8055	Position[ x, y ]	752.8 [mm], 6060.5 [m], ( 163.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:186.5 ,V:651.6 [mm]
Result	-	Area	1755.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#58, \$43	Date	2023/8/10 上午 10:52:59
Segment	1	Camera	1
Pattern	8055	Position[ x, y ]	126.6 [mm], 6060.4 [m], ( 163.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.0 ,V:530.8 [mm]
Result	-	Area	2165.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#58, \$43	Date	2023/8/10 上午 10:52:59
Segment	1	Camera	1
Pattern	8055	Position[ x, y ]	430.1 [mm], 6060.4 [m], ( 163.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:261.5 ,V:808.0 [mm]
Result	-	Area	2357.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#58, \$43	Date	2023/8/10 上午 10:52:59
Segment	1	Camera	1
Pattern	8055	Position[ x, y ]	762.1 [mm], 6060.3 [m], ( 163.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.3 ,V:532.4 [mm]
Result	-	Area	2383.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	59	検査範囲 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	参照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

### Defect information

No.	#57, \$42	Date	2023/8/10 上午 10:52:59
Segment	1	Camera	1
Pattern	8054	Position[ x, y ]	478.9 [mm], 6060.0 [m], ( 164.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:366.2 ,V:122.0 [mm]
Result	—	Area	2078.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#57, \$42	Date	2023/8/10 上午 10:52:59
Segment	1	Camera	1
Pattern	8054	Position[ x, y ]	64.6 [mm], 6060.0 [m], ( 164.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:128.4 ,V:260.4 [mm]
Result	-	Area	2115.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#57, \$42	Date	2023/8/10 上午 10:52:59
Segment	1	Camera	1
Pattern	8054	Position[ x, y ]	751.1 [mm], 6059.5 [m], ( 164.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:187.3 ,V:506.0 [mm]
Result	-	Area	2172.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#57, \$42	Date	2023/8/10 上午 10:52:59
Segment	1	Camera	1
Pattern	8054	Position[ x, y ]	417.9 [mm], 6059.6 [m], ( 164.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:202.9 ,V:808.0 [mm]
Result	-	Area	2175.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#56, \$41	Date	2023/8/10 上午 10:52:58
Segment	1	Camera	1
Pattern	8053	Position[ x, y ]	695.2 [mm], 6059.1 [m], ( 165.0 [m] )
Type	点状疵点	Size	H:4.4 ,V:668.4 [mm]
Result	-	Area	719.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#56, \$41	Date	2023/8/10 上午 10:52:58
Segment	1	Camera	1
Pattern	8053	Position[ x, y ]	867.8 [mm], 6058.9 [m], ( 165.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:34.4 ,V:811.2 [mm]
Result	-	Area	739.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#56, \$41	Date	2023/8/10 上午 10:52:58
Segment	1	Camera	1
Pattern	8053	Position[ x, y ]	563.1 [mm], 6058.8 [m], ( 165.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.2 ,V:473.6 [mm]
Result	-	Area	739.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#56, \$41	Date	2023/8/10 上午 10:52:58
Segment	1	Camera	1
Pattern	8053	Position[ x, y ]	698.4 [mm], 6058.8 [m], ( 165.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:13.7 ,V:727.2 [mm]
Result	-	Area	803.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#55, \$40	Date	2023/8/10 上午 10:52:57
Segment	1	Camera	1
Pattern	8052	Position[ x, y ]	563.1 [mm], 6058.2 [m], ( 166.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:808.0 [mm]
Result	-	Area	722.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#55, \$40	Date	2023/8/10 上午 10:52:57
Segment	1	Camera	1
Pattern	8052	Position[ x, y ]	399.1 [mm], 6058.1 [m], ( 166.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:79.8 ,V:807.6 [mm]
Result	-	Area	777.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#55, \$40	Date	2023/8/10 上午 10:52:57
Segment	1	Camera	1
Pattern	8052	Position[ x, y ]	712.5 [mm], 6058.5 [m], ( 165.7 [m] )
Type	点状疵点横向刀絲	Size	H:72.5 ,V:275.6 [mm]
Result	-	Area	902.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#55, \$40	Date	2023/8/10 上午 10:52:57
Segment	1	Camera	1
Pattern	8052	Position[ x, y ]	714.0 [mm], 6058.1 [m], ( 166.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:64.0 ,V:407.2 [mm]
Result	-	Area	995.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#54, \$39	Date	2023/8/10 上午 10:52:57
Segment	1	Camera	1
Pattern	8051	Position[ x, y ]	696.2 [mm], 6057.6 [m], ( 166.6 [m] )
Type	点状疵点	Size	H:46.4 ,V:626.8 [mm]
Result	-	Area	612.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#54, \$39	Date	2023/8/10 上午 10:52:57
Segment	1	Camera	1
Pattern	8051	Position[ x, y ]	563.1 [mm], 6057.3 [m], ( 166.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.2 ,V:511.2 [mm]
Result	-	Area	629.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#54, \$39	Date	2023/8/10 上午 10:52:57
Segment	1	Camera	1
Pattern	8051	Position[ x, y ]	865.9 [mm], 6057.3 [m], ( 166.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:34.4 ,V:512.0 [mm]
Result	-	Area	658.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#54, \$39	Date	2023/8/10 上午 10:52:57
Segment	1	Camera	1
Pattern	8051	Position[ x, y ]	698.4 [mm], 6057.3 [m], ( 166.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:13.2 ,V:705.2 [mm]
Result	-	Area	738.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#51, \$38	Date	2023/8/10 上午 10:52:47
Segment	1	Camera	1
Pattern	8036	Position[ x, y ]	805.6 [mm], 6045.2 [m], ( 179.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:184.1 ,V:40.8 [mm]
Result	-	Area	394.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#51, \$38	Date	2023/8/10 上午 10:52:47
Segment	1	Camera	1
Pattern	8036	Position[ x, y ]	438.6 [mm], 6045.2 [m], ( 179.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:193.4 ,V:106.0 [mm]
Result	-	Area	424.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#51, \$38	Date	2023/8/10 上午 10:52:47
Segment	1	Camera	1
Pattern	8036	Position[ x, y ]	488.2 [mm], 6045.2 [m], ( 179.0 [m] )
Type	点状疵点横向刀絲	Size	H:193.1 ,V:48.4 [mm]
Result	-	Area	434.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#51, \$38	Date	2023/8/10 上午 10:52:47
Segment	1	Camera	1
Pattern	8036	Position[ x, y ]	759.9 [mm], 6045.2 [m], ( 178.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:134.4 [mm]
Result	-	Area	440.2 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#50, \$37	Date	2023/8/10 上午 10:52:47
Segment	1	Camera	1
Pattern	8035	Position[ x, y ]	748.7 [mm], 6044.8 [m], ( 179.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:184.1 ,V:61.2 [mm]
Result	-	Area	304.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#50, \$37	Date	2023/8/10 上午 10:52:47
Segment	1	Camera	1
Pattern	8035	Position[ x, y ]	151.3 [mm], 6044.8 [m], ( 179.3 [m] )
Type	点状疵点	Size	H:184.6 ,V:2.0 [mm]
Result	-	Area	305.8 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#50, \$37	Date	2023/8/10 上午 10:52:47
Segment	1	Camera	1
Pattern	8035	Position[ x, y ]	734.0 [mm], 6044.9 [m], ( 179.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:184.1 ,V:88.0 [mm]
Result	-	Area	316.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#50, \$37	Date	2023/8/10 上午 10:52:47
Segment	1	Camera	1
Pattern	8035	Position[ x, y ]	473.3 [mm], 6044.8 [m], ( 179.3 [m] )
Type	点状疵点	Size	H:193.4 ,V:2.0 [mm]
Result	-	Area	329.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#49, \$36	Date	2023/8/10 上午 10:52:46
Segment	1	Camera	1
Pattern	8034	Position[ x, y ]	806.8 [mm], 6044.0 [m], ( 180.1 [m] )
Type	点状疵点	Size	H:143.3 ,V:1.6 [mm]
Result	-	Area	146.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#49, \$36	Date	2023/8/10 上午 10:52:46
Segment	1	Camera	1
Pattern	8034	Position[ x, y ]	148.1 [mm], 6044.1 [m], ( 180.1 [m] )
Type	点状疵点	Size	H:183.1 ,V:1.2 [mm]
Result	-	Area	219.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#49, \$36	Date	2023/8/10 上午 10:52:46
Segment	1	Camera	1
Pattern	8034	Position[ x, y ]	409.6 [mm], 6044.1 [m], ( 180.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:192.6 ,V:88.0 [mm]
Result	-	Area	278.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#49, \$36	Date	2023/8/10 上午 10:52:46
Segment	1	Camera	1
Pattern	8034	Position[ x, y ]	728.2 [mm], 6044.1 [m], ( 180.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:184.1 ,V:88.8 [mm]
Result	-	Area	335.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#48, \$35	Date	2023/8/10 上午 10:52:46
Segment	1	Camera	1
Pattern	8033	Position[ x, y ]	937.1 [mm], 6042.9 [m], ( 181.3 [m] )
Type	点状疵点	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#48, \$35	Date	2023/8/10 上午 10:52:46
Segment	1	Camera	1
Pattern	8033	Position[ x, y ]	715.0 [mm], 6043.4 [m], ( 180.8 [m] )
Type	縱向刀絲疵點	Size	H:15.9 ,V:5.6 [mm]
Result	-	Area	3.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#48, \$35	Date	2023/8/10 上午 10:52:46
Segment	1	Camera	1
Pattern	8033	Position[ x, y ]	936.9 [mm], 6043.5 [m], ( 180.7 [m] )
Type	点状疵点	Size	H:1.7 ,V:25.6 [mm]
Result	-	Area	8.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#47, \$34	Date	2023/8/10 上午 10:52:45
Segment	1	Camera	1
Pattern	8032	Position[ x, y ]	936.9 [mm], 6042.8 [m], ( 181.4 [m] )
Type	点状疵点	Size	H:1.5 ,V:6.0 [mm]
Result	-	Area	4.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#46, \$33	Date	2023/8/10 上午 10:52:42
Segment	1	Camera	1
Pattern	8027	Position[ x, y ]	566.3 [mm], 6038.7 [m], ( 185.5 [m] )
Type	点状疵点	Size	H:0.5 ,V:16.8 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#46, \$33	Date	2023/8/10 上午 10:52:42
Segment	1	Camera	1
Pattern	8027	Position[ x, y ]	699.1 [mm], 6038.5 [m], ( 185.7 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:10.0 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#46, \$33	Date	2023/8/10 上午 10:52:42
Segment	1	Camera	1
Pattern	8027	Position[ x, y ]	698.6 [mm], 6038.7 [m], ( 185.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:34.0 [mm]
Result	-	Area	15.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#46, \$33	Date	2023/8/10 上午 10:52:42
Segment	1	Camera	1
Pattern	8027	Position[ x, y ]	699.1 [mm], 6038.3 [m], ( 185.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:38.8 [mm]
Result	-	Area	18.0 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#45, \$32	Date	2023/8/10 上午 10:52:41
Segment	1	Camera	1
Pattern	8026	Position[ x, y ]	241.8 [mm], 6037.7 [m], ( 186.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:339.6 [mm]
Result	-	Area	164.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#45, \$32	Date	2023/8/10 上午 10:52:41
Segment	1	Camera	1
Pattern	8026	Position[ x, y ]	373.9 [mm], 6037.6 [m], ( 186.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.2 ,V:322.0 [mm]
Result	-	Area	177.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#45, \$32	Date	2023/8/10 上午 10:52:41
Segment	1	Camera	1
Pattern	8026	Position[ x, y ]	567.0 [mm], 6037.8 [m], ( 186.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:579.6 [mm]
Result	-	Area	191.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#45, \$32	Date	2023/8/10 上午 10:52:41
Segment	1	Camera	1
Pattern	8026	Position[ x, y ]	699.1 [mm], 6037.7 [m], ( 186.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:4.2 ,V:363.6 [mm]
Result	-	Area	195.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#42, \$31	Date	2023/8/10 上午 10:52:34
Segment	1	Camera	1
Pattern	8017	Position[ x, y ]	441.3 [mm], 6030.2 [m], ( 194.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.8 ,V:174.0 [mm]
Result	-	Area	1943.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#42, \$31	Date	2023/8/10 上午 10:52:34
Segment	1	Camera	1
Pattern	8017	Position[ x, y ]	745.3 [mm], 6030.5 [m], ( 193.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.3 ,V:68.4 [mm]
Result	-	Area	1968.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#42, \$31	Date	2023/8/10 上午 10:52:34
Segment	1	Camera	1
Pattern	8017	Position[ x, y ]	791.4 [mm], 6030.6 [m], ( 193.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:184.3 ,V:107.2 [mm]
Result	-	Area	2024.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#42, \$31	Date	2023/8/10 上午 10:52:34
Segment	1	Camera	1
Pattern	8017	Position[ x, y ]	445.9 [mm], 6030.6 [m], ( 193.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.6 ,V:225.2 [mm]
Result	-	Area	2100.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#41, \$30	Date	2023/8/10 上午 10:52:33
Segment	1	Camera	1
Pattern	8016	Position[ x, y ]	137.1 [mm], 6029.5 [m], ( 194.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.0 ,V:107.2 [mm]
Result	-	Area	1560.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#41, \$30	Date	2023/8/10 上午 10:52:33
Segment	1	Camera	1
Pattern	8016	Position[ x, y ]	762.1 [mm], 6029.8 [m], ( 194.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.3 ,V:36.0 [mm]
Result	-	Area	1596.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#41, \$30	Date	2023/8/10 上午 10:52:33
Segment	1	Camera	1
Pattern	8016	Position[ x, y ]	118.1 [mm], 6029.8 [m], ( 194.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.8 ,V:36.4 [mm]
Result	-	Area	1631.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#41, \$30	Date	2023/8/10 上午 10:52:33
Segment	1	Camera	1
Pattern	8016	Position[ x, y ]	141.5 [mm], 6029.9 [m], ( 194.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:185.1 ,V:128.8 [mm]
Result	-	Area	1686.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#40, \$29	Date	2023/8/10 上午 10:52:33
Segment	1	Camera	1
Pattern	8015	Position[ x, y ]	466.9 [mm], 6029.1 [m], ( 195.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.8 ,V:125.2 [mm]
Result	-	Area	1158.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#40, \$29	Date	2023/8/10 上午 10:52:33
Segment	1	Camera	1
Pattern	8015	Position[ x, y ]	136.6 [mm], 6028.7 [m], ( 195.5 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.3 ,V:170.8 [mm]
Result	-	Area	1248.0 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#40, \$29	Date	2023/8/10 上午 10:52:33
Segment	1	Camera	1
Pattern	8015	Position[ x, y ]	768.7 [mm], 6029.0 [m], ( 195.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:72.8 [mm]
Result	-	Area	1356.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#40, \$29	Date	2023/8/10 上午 10:52:33
Segment	1	Camera	1
Pattern	8015	Position[ x, y ]	119.5 [mm], 6029.0 [m], ( 195.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:184.8 ,V:34.8 [mm]
Result	-	Area	1379.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#39, \$28	Date	2023/8/10 上午 10:52:32
Segment	1	Camera	1
Pattern	8014	Position[ x, y ]	445.4 [mm], 6027.9 [m], ( 196.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.8 ,V:152.8 [mm]
Result	-	Area	1037.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#39, \$28	Date	2023/8/10 上午 10:52:32
Segment	1	Camera	1
Pattern	8014	Position[ x, y ]	147.1 [mm], 6028.3 [m], ( 195.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.1 ,V:199.6 [mm]
Result	-	Area	1166.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#39, \$28	Date	2023/8/10 上午 10:52:32
Segment	1	Camera	1
Pattern	8014	Position[ x, y ]	451.6 [mm], 6028.4 [m], ( 195.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.6 ,V:129.6 [mm]
Result	-	Area	1220.2 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#39, \$28	Date	2023/8/10 上午 10:52:32
Segment	1	Camera	1
Pattern	8014	Position[ x, y ]	434.0 [mm], 6028.3 [m], ( 195.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.1 ,V:77.2 [mm]
Result	-	Area	1220.7 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#38, \$27	Date	2023/8/10 上午 10:52:31
Segment	1	Camera	1
Pattern	8013	Position[ x, y ]	454.7 [mm], 6027.2 [m], ( 197.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.8 ,V:140.0 [mm]
Result	-	Area	717.4 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#38, \$27	Date	2023/8/10 上午 10:52:31
Segment	1	Camera	1
Pattern	8013	Position[ x, y ]	765.5 [mm], 6027.6 [m], ( 196.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.3 ,V:37.6 [mm]
Result	-	Area	862.4 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#38, \$27	Date	2023/8/10 上午 10:52:31
Segment	1	Camera	1
Pattern	8013	Position[ x, y ]	772.8 [mm], 6027.5 [m], ( 196.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:116.0 [mm]
Result	-	Area	885.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#38, \$27	Date	2023/8/10 上午 10:52:31
Segment	1	Camera	1
Pattern	8013	Position[ x, y ]	436.7 [mm], 6027.5 [m], ( 196.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.8 ,V:116.0 [mm]
Result	-	Area	923.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#36, \$26	Date	2023/8/10 上午 10:43:16
Segment	1	Camera	1
Pattern	7899	Position[ x, y ]	473.3 [mm], 5940.9 [m], ( 283.3 [m] )
Type	点状疵点	Size	H:193.1 ,V:2.0 [mm]
Result	-	Area	361.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#36, \$26	Date	2023/8/10 上午 10:43:16
Segment	1	Camera	1
Pattern	7899	Position[ x, y ]	464.5 [mm], 5941.0 [m], ( 283.2 [m] )
Type	点状疵点	Size	H:193.4 ,V:2.0 [mm]
Result	-	Area	363.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#36, \$26	Date	2023/8/10 上午 10:43:16
Segment	1	Camera	1
Pattern	7899	Position[ x, y ]	148.6 [mm], 5940.9 [m], ( 283.3 [m] )
Type	点状疵点	Size	H:184.6 ,V:2.0 [mm]
Result	-	Area	366.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#36, \$26	Date	2023/8/10 上午 10:43:16
Segment	1	Camera	1
Pattern	7899	Position[ x, y ]	123.9 [mm], 5941.0 [m], ( 283.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:184.6 ,V:64.0 [mm]
Result	-	Area	371.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#34, \$25	Date	2023/8/10 上午 10:39:36
Segment	1	Camera	1
Pattern	7898	Position[ x, y ]	468.6 [mm], 5940.2 [m], ( 284.0 [m] )
Type	点状疵点	Size	H:193.1 ,V:1.6 [mm]
Result	-	Area	306.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#34, \$25	Date	2023/8/10 上午 10:39:36
Segment	1	Camera	1
Pattern	7898	Position[ x, y ]	152.0 [mm], 5940.2 [m], ( 284.0 [m] )
Type	点状疵点	Size	H:184.6 ,V:2.0 [mm]
Result	-	Area	309.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#34, \$25	Date	2023/8/10 上午 10:39:36
Segment	1	Camera	1
Pattern	7898	Position[ x, y ]	471.6 [mm], 5940.2 [m], ( 283.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.4 ,V:68.8 [mm]
Result	-	Area	353.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#34, \$25	Date	2023/8/10 上午 10:39:36
Segment	1	Camera	1
Pattern	7898	Position[ x, y ]	137.6 [mm], 5940.2 [m], ( 283.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:79.2 [mm]
Result	-	Area	353.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#33, \$24	Date	2023/8/10 上午 10:39:34
Segment	1	Camera	1
Pattern	7897	Position[ x, y ]	96.1 [mm], 5939.8 [m], ( 284.4 [m] )
Type	点状疵点	Size	H:61.3 ,V:1.2 [mm]
Result	-	Area	57.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#33, \$24	Date	2023/8/10 上午 10:39:34
Segment	1	Camera	1
Pattern	7897	Position[ x, y ]	539.0 [mm], 5939.8 [m], ( 284.4 [m] )
Type	点状疵点	Size	H:51.3 ,V:1.2 [mm]
Result	-	Area	60.8 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#33, \$24	Date	2023/8/10 上午 10:39:34
Segment	1	Camera	1
Pattern	7897	Position[ x, y ]	446.4 [mm], 5939.8 [m], ( 284.4 [m] )
Type	点状疵点	Size	H:105.7 ,V:1.2 [mm]
Result	-	Area	113.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#33, \$24	Date	2023/8/10 上午 10:39:34
Segment	1	Camera	1
Pattern	7897	Position[ x, y ]	180.6 [mm], 5939.8 [m], ( 284.4 [m] )
Type	点状疵点	Size	H:126.0 ,V:1.6 [mm]
Result	-	Area	167.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#30, \$23	Date	2023/8/10 上午 10:39:00
Segment	1	Camera	1
Pattern	7841	Position[ x, y ]	707.4 [mm], 5897.7 [m], ( 326.5 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:13.6 [mm]
Result	-	Area	4.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#30, \$23	Date	2023/8/10 上午 10:39:00
Segment	1	Camera	1
Pattern	7841	Position[ x, y ]	203.3 [mm], 5897.8 [m], ( 326.4 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:12.0 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#30, \$23	Date	2023/8/10 上午 10:39:00
Segment	1	Camera	1
Pattern	7841	Position[ x, y ]	203.5 [mm], 5897.4 [m], ( 326.8 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:10.4 [mm]
Result	-	Area	4.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#30, \$23	Date	2023/8/10 上午 10:39:00
Segment	1	Camera	1
Pattern	7841	Position[ x, y ]	528.2 [mm], 5897.4 [m], ( 326.8 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:13.2 [mm]
Result	-	Area	5.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#29, \$22	Date	2023/8/10 上午 10:38:59
Segment	1	Camera	1
Pattern	7840	Position[ x, y ]	405.9 [mm], 5897.0 [m], ( 327.2 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:7.2 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3



## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#29, \$22	Date	2023/8/10 上午 10:38:59
Segment	1	Camera	1
Pattern	7840	Position[ x, y ]	844.9 [mm], 5896.6 [m], ( 327.6 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:12.8 [mm]
Result	-	Area	3.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#29, \$22	Date	2023/8/10 上午 10:38:59
Segment	1	Camera	1
Pattern	7840	Position[ x, y ]	225.7 [mm], 5896.6 [m], ( 327.6 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:7.6 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#29, \$22	Date	2023/8/10 上午 10:38:59
Segment	1	Camera	1
Pattern	7840	Position[ x, y ]	528.2 [mm], 5896.6 [m], ( 327.6 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:13.6 [mm]
Result	-	Area	5.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#28, \$21	Date	2023/8/10 上午 10:38:58
Segment	1	Camera	1
Pattern	7839	Position[ x, y ]	528.5 [mm], 5895.9 [m], ( 328.3 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:7.2 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#28, \$21	Date	2023/8/10 上午 10:38:58
Segment	1	Camera	1
Pattern	7839	Position[ x, y ]	225.7 [mm], 5895.9 [m], ( 328.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:7.6 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#27, \$20	Date	2023/8/10 上午 10:38:58
Segment	1	Camera	1
Pattern	7838	Position[ x, y ]	225.7 [mm], 5895.1 [m], ( 329.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:7.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#26, \$19	Date	2023/8/10 上午 10:38:57
Segment	1	Camera	1
Pattern	7837	Position[ x, y ]	225.7 [mm], 5894.4 [m], ( 329.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:6.4 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#23, \$18	Date	2023/8/10 上午 10:38:19
Segment	1	Camera	1
Pattern	7772	Position[ x, y ]	464.0 [mm], 5845.6 [m], ( 378.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:194.6 ,V:114.0 [mm]
Result	-	Area	589.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#23, \$18	Date	2023/8/10 上午 10:38:19
Segment	1	Camera	1
Pattern	7772	Position[ x, y ]	757.0 [mm], 5845.7 [m], ( 378.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.8 ,V:224.0 [mm]
Result	-	Area	604.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#23, \$18	Date	2023/8/10 上午 10:38:19
Segment	1	Camera	1
Pattern	7772	Position[ x, y ]	117.8 [mm], 5845.8 [m], ( 378.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:187.0 ,V:395.2 [mm]
Result	-	Area	774.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#23, \$18	Date	2023/8/10 上午 10:38:19
Segment	1	Camera	1
Pattern	7772	Position[ x, y ]	437.9 [mm], 5845.8 [m], ( 378.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:195.6 ,V:458.8 [mm]
Result	-	Area	1425.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#22, \$17	Date	2023/8/10 上午 10:38:19
Segment	1	Camera	1
Pattern	7771	Position[ x, y ]	444.7 [mm], 5844.9 [m], ( 379.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:195.1 ,V:262.4 [mm]
Result	-	Area	604.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#22, \$17	Date	2023/8/10 上午 10:38:19
Segment	1	Camera	1
Pattern	7771	Position[ x, y ]	122.2 [mm], 5845.0 [m], ( 379.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.8 ,V:448.0 [mm]
Result	-	Area	627.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#22, \$17	Date	2023/8/10 上午 10:38:19
Segment	1	Camera	1
Pattern	7771	Position[ x, y ]	786.3 [mm], 5845.3 [m], ( 378.9 [m] )
Type	点状疵点横向刀絲	Size	H:185.3 ,V:167.6 [mm]
Result	-	Area	644.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#22, \$17	Date	2023/8/10 上午 10:38:19
Segment	1	Camera	1
Pattern	7771	Position[ x, y ]	451.3 [mm], 5845.0 [m], ( 379.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:195.3 ,V:552.4 [mm]
Result	-	Area	1418.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#21, \$16	Date	2023/8/10 上午 10:38:18
Segment	1	Camera	1
Pattern	7770	Position[ x, y ]	434.9 [mm], 5844.6 [m], ( 379.6 [m] )
Type	点状疵点横向刀絲	Size	H:194.6 ,V:294.8 [mm]
Result	-	Area	774.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#21, \$16	Date	2023/8/10 上午 10:38:18
Segment	1	Camera	1
Pattern	7770	Position[ x, y ]	743.5 [mm], 5844.4 [m], ( 379.8 [m] )
Type	点状疵点	Size	H:185.3 ,V:145.6 [mm]
Result	-	Area	984.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#21, \$16	Date	2023/8/10 上午 10:38:18
Segment	1	Camera	1
Pattern	7770	Position[ x, y ]	400.5 [mm], 5844.4 [m], ( 379.8 [m] )
Type	点状疵点	Size	H:66.7 ,V:30.0 [mm]
Result	-	Area	1072.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$16	Date	2023/8/10 上午 10:38:18
Segment	1	Camera	1
Pattern	7770	Position[ x, y ]	94.1 [mm], 5844.4 [m], ( 379.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:68.8 ,V:53.2 [mm]
Result	-	Area	1146.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$15	Date	2023/8/10 上午 10:38:18
Segment	1	Camera	1
Pattern	7769	Position[ x, y ]	370.5 [mm], 5843.4 [m], ( 380.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:110.0 [mm]
Result	-	Area	46.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$15	Date	2023/8/10 上午 10:38:18
Segment	1	Camera	1
Pattern	7769	Position[ x, y ]	932.3 [mm], 5843.4 [m], ( 380.8 [m] )
Type	点状疵点	Size	H:4.6 ,V:15.2 [mm]
Result	-	Area	49.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$15	Date	2023/8/10 上午 10:38:18
Segment	1	Camera	1
Pattern	7769	Position[ x, y ]	933.2 [mm], 5843.4 [m], ( 380.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:6.8 ,V:56.4 [mm]
Result	-	Area	121.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#20, \$15	Date	2023/8/10 上午 10:38:18
Segment	1	Camera	1
Pattern	7769	Position[ x, y ]	30.2 [mm], 5843.3 [m], ( 380.8 [m] )
Type	縱向刀絲疵點橫向刀絲	Size	H:68.1 ,V:48.8 [mm]
Result	-	Area	403.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#19, \$14	Date	2023/8/10 上午 10:38:17
Segment	1	Camera	1
Pattern	7768	Position[ x, y ]	933.2 [mm], 5842.6 [m], ( 381.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:6.8 ,V:56.4 [mm]
Result	-	Area	120.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#19, \$14	Date	2023/8/10 上午 10:38:17
Segment	1	Camera	1
Pattern	7768	Position[ x, y ]	86.6 [mm], 5843.2 [m], ( 380.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:91.8 ,V:172.8 [mm]
Result	-	Area	3964.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#19, \$14	Date	2023/8/10 上午 10:38:17
Segment	1	Camera	1
Pattern	7768	Position[ x, y ]	747.2 [mm], 5843.2 [m], ( 381.0 [m] )
Type	点状疵点横向刀絲	Size	H:71.3 ,V:95.2 [mm]
Result	-	Area	4146.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#19, \$14	Date	2023/8/10 上午 10:38:17
Segment	1	Camera	1
Pattern	7768	Position[ x, y ]	410.3 [mm], 5843.2 [m], ( 381.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:83.3 ,V:95.2 [mm]
Result	-	Area	4256.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#16, \$13	Date	2023/8/10 上午 10:38:12
Segment	1	Camera	1
Pattern	7761	Position[ x, y ]	502.8 [mm], 5836.9 [m], ( 387.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.8 ,V:166.0 [mm]
Result	-	Area	3289.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#16, \$13	Date	2023/8/10 上午 10:38:12
Segment	1	Camera	1
Pattern	7761	Position[ x, y ]	470.6 [mm], 5836.6 [m], ( 387.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:193.8 ,V:136.8 [mm]
Result	-	Area	3419.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#16, \$13	Date	2023/8/10 上午 10:38:12
Segment	1	Camera	1
Pattern	7761	Position[ x, y ]	454.7 [mm], 5836.6 [m], ( 387.5 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.6 ,V:169.2 [mm]
Result	-	Area	3455.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#16, \$13	Date	2023/8/10 上午 10:38:12
Segment	1	Camera	1
Pattern	7761	Position[ x, y ]	794.3 [mm], 5836.6 [m], ( 387.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:206.8 [mm]
Result	-	Area	3588.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#15, \$12	Date	2023/8/10 上午 10:38:12
Segment	1	Camera	1
Pattern	7760	Position[ x, y ]	463.8 [mm], 5835.9 [m], ( 388.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.8 ,V:257.2 [mm]
Result	-	Area	3465.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#15, \$12	Date	2023/8/10 上午 10:38:12
Segment	1	Camera	1
Pattern	7760	Position[ x, y ]	488.9 [mm], 5836.2 [m], ( 388.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:192.9 ,V:123.2 [mm]
Result	-	Area	3471.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#15, \$12	Date	2023/8/10 上午 10:38:12
Segment	1	Camera	1
Pattern	7760	Position[ x, y ]	776.7 [mm], 5835.9 [m], ( 388.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:169.2 [mm]
Result	-	Area	3566.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#15, \$12	Date	2023/8/10 上午 10:38:12
Segment	1	Camera	1
Pattern	7760	Position[ x, y ]	140.8 [mm], 5835.9 [m], ( 388.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.0 ,V:176.0 [mm]
Result	-	Area	3617.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#14, \$11	Date	2023/8/10 上午 10:38:11
Segment	1	Camera	1
Pattern	7759	Position[ x, y ]	429.8 [mm], 5835.1 [m], ( 389.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:193.6 ,V:118.0 [mm]
Result	-	Area	3542.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#14, \$11	Date	2023/8/10 上午 10:38:11
Segment	1	Camera	1
Pattern	7759	Position[ x, y ]	447.2 [mm], 5835.1 [m], ( 389.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.6 ,V:168.8 [mm]
Result	-	Area	3553.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#14, \$11	Date	2023/8/10 上午 10:38:11
Segment	1	Camera	1
Pattern	7759	Position[ x, y ]	771.1 [mm], 5835.1 [m], ( 389.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:176.0 [mm]
Result	-	Area	3689.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#14, \$11	Date	2023/8/10 上午 10:38:11
Segment	1	Camera	1
Pattern	7759	Position[ x, y ]	129.5 [mm], 5835.1 [m], ( 389.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.3 ,V:131.6 [mm]
Result	-	Area	3702.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#13, \$10	Date	2023/8/10 上午 10:38:11
Segment	1	Camera	1
Pattern	7758	Position[ x, y ]	463.0 [mm], 5834.3 [m], ( 389.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:193.6 ,V:178.4 [mm]
Result	-	Area	3446.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#13, \$10	Date	2023/8/10 上午 10:38:11
Segment	1	Camera	1
Pattern	7758	Position[ x, y ]	154.2 [mm], 5834.4 [m], ( 389.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.0 ,V:206.8 [mm]
Result	-	Area	3519.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#13, \$10	Date	2023/8/10 上午 10:38:11
Segment	1	Camera	1
Pattern	7758	Position[ x, y ]	786.5 [mm], 5834.4 [m], ( 389.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:288.4 [mm]
Result	-	Area	3531.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#13, \$10	Date	2023/8/10 上午 10:38:11
Segment	1	Camera	1
Pattern	7758	Position[ x, y ]	450.8 [mm], 5834.4 [m], ( 389.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.6 ,V:131.6 [mm]
Result	-	Area	3819.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#12, \$9	Date	2023/8/10 上午 10:38:10
Segment	1	Camera	1
Pattern	7757	Position[ x, y ]	158.3 [mm], 5833.6 [m], ( 390.5 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:186.0 ,V:207.6 [mm]
Result	-	Area	3446.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

ID information ( No. 2 )




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

Defect information

No.	#12, \$9	Date	2023/8/10 上午 10:38:10
Segment	1	Camera	1
Pattern	7757	Position[ x, y ]	793.8 [mm], 5833.6 [m], ( 390.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:162.8 [mm]
Result	-	Area	3476.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

ID information ( No. 2 )




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

Defect information

No.	#12, \$9	Date	2023/8/10 上午 10:38:10
Segment	1	Camera	1
Pattern	7757	Position[ x, y ]	507.5 [mm], 5833.9 [m], ( 390.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:193.6 ,V:79.6 [mm]
Result	-	Area	3647.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#12, \$9	Date	2023/8/10 上午 10:38:10
Segment	1	Camera	1
Pattern	7757	Position[ x, y ]	462.8 [mm], 5833.6 [m], ( 390.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.6 ,V:260.8 [mm]
Result	-	Area	3676.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#10, \$8	Date	2023/8/10 上午 10:36:05
Segment	1	Camera	1
Pattern	7724	Position[ x, y ]	487.2 [mm], 5804.6 [m], ( 419.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:194.8 ,V:185.2 [mm]
Result	-	Area	9617.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#10, \$8	Date	2023/8/10 上午 10:36:05
Segment	1	Camera	1
Pattern	7724	Position[ x, y ]	776.5 [mm], 5804.8 [m], ( 419.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:195.8 ,V:559.2 [mm]
Result	-	Area	43430.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#10, \$8	Date	2023/8/10 上午 10:36:05
Segment	1	Camera	1
Pattern	7724	Position[ x, y ]	139.1 [mm], 5804.7 [m], ( 419.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:199.0 ,V:558.0 [mm]
Result	-	Area	44577.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#10, \$8	Date	2023/8/10 上午 10:36:05
Segment	1	Camera	1
Pattern	7724	Position[ x, y ]	455.0 [mm], 5804.8 [m], ( 419.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:206.8 ,V:558.8 [mm]
Result	-	Area	46562.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#8, \$7	Date	2023/8/10 上午 10:30:38
Segment	1	Camera	1
Pattern	7722	Position[ x, y ]	468.4 [mm], 5803.9 [m], ( 420.2 [m] )
Type	点状疵点	Size	H:192.9 ,V:1.6 [mm]
Result	-	Area	306.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#8, \$7	Date	2023/8/10 上午 10:30:38
Segment	1	Camera	1
Pattern	7722	Position[ x, y ]	475.7 [mm], 5804.0 [m], ( 420.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:192.9 ,V:79.6 [mm]
Result	-	Area	356.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#8, \$7	Date	2023/8/10 上午 10:30:38
Segment	1	Camera	1
Pattern	7722	Position[ x, y ]	146.6 [mm], 5804.0 [m], ( 420.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.3 ,V:112.8 [mm]
Result	-	Area	362.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#8, \$7	Date	2023/8/10 上午 10:30:38
Segment	1	Camera	1
Pattern	7722	Position[ x, y ]	447.6 [mm], 5804.4 [m], ( 419.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:193.1 ,V:85.2 [mm]
Result	-	Area	416.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#7, \$6	Date	2023/8/10 上午 10:30:36
Segment	1	Camera	1
Pattern	7721	Position[ x, y ]	768.0 [mm], 5803.6 [m], ( 420.6 [m] )
Type	点状疵点	Size	H:150.9 ,V:1.2 [mm]
Result	-	Area	164.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#7, \$6	Date	2023/8/10 上午 10:30:36
Segment	1	Camera	1
Pattern	7721	Position[ x, y ]	149.5 [mm], 5803.2 [m], ( 420.9 [m] )
Type	点状疵点	Size	H:184.1 ,V:1.6 [mm]
Result	-	Area	231.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#7, \$6	Date	2023/8/10 上午 10:30:36
Segment	1	Camera	1
Pattern	7721	Position[ x, y ]	466.2 [mm], 5803.6 [m], ( 420.6 [m] )
Type	点状疵点	Size	H:191.4 ,V:1.6 [mm]
Result	-	Area	252.0 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#7, \$6	Date	2023/8/10 上午 10:30:36
Segment	1	Camera	1
Pattern	7721	Position[ x, y ]	149.8 [mm], 5803.6 [m], ( 420.6 [m] )
Type	点状疵点	Size	H:183.6 ,V:2.0 [mm]
Result	-	Area	280.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#6, \$5	Date	2023/8/10 上午 10:30:34
Segment	1	Camera	1
Pattern	7720	Position[ x, y ]	757.7 [mm], 5803.0 [m], ( 421.2 [m] )
Type	点状疵点	Size	H:23.4 ,V:0.8 [mm]
Result	-	Area	18.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#6, \$5	Date	2023/8/10 上午 10:30:34
Segment	1	Camera	1
Pattern	7720	Position[ x, y ]	114.9 [mm], 5803.0 [m], ( 421.2 [m] )
Type	点状疵点	Size	H:24.2 ,V:1.2 [mm]
Result	-	Area	27.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#6, \$5	Date	2023/8/10 上午 10:30:34
Segment	1	Camera	1
Pattern	7720	Position[ x, y ]	434.9 [mm], 5803.0 [m], ( 421.2 [m] )
Type	点状疵点	Size	H:25.1 ,V:1.6 [mm]
Result	-	Area	29.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#5, \$4	Date	2023/8/10 上午 10:13:32
Segment	1	Camera	1
Pattern	5973	Position[ x, y ]	929.1 [mm], 4491.3 [m], ( 1732.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:2.4 [mm]
Result	-	Area	4.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/10 上午 09:45:30
Segment	1	Camera	1
Pattern	3098	Position[ x, y ]	883.4 [mm], 2332.0 [m], ( 3892.1 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:28.8 [mm]
Result	-	Area	14.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	59	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#3, \$2	Date	2023/8/10 上午 09:24:14
Segment	1	Camera	1
Pattern	918	Position[ x, y ]	933.7 [mm], 695.8 [m], ( 5528.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:2.4 [mm]
Result	-	Area	5.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 3

Inspected date : 2023/8/10 上午 09:15:18 ~ 2023/8/10 上午 10:55:13

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	59	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6224.2 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#2, \$1	Date	2023/8/10 上午 09:19:26
Segment	1	Camera	1
Pattern	425	Position[ x, y ]	394.2 [mm], 325.5 [m], ( 5898.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:2.9 ,V:2.4 [mm]
Result	-	Area	5.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image



Reference image



Shape image

