

Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#51, \$38	Date	2023/8/10 下午 01:31:10
Segment	1	Camera	1
Pattern	8109	Position[x, y]	3.6 [mm], 6063.3 [m], (3.0 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:7.6 ,V:15.6 [mm]
Result	-	Area	71.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#48, \$37	Date	2023/8/10 下午 01:30:38
Segment	1	Camera	1
Pattern	8055	Position[x, y]	700.1 [mm], 6023.0 [m], (43.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:307.2 [mm]
Result	-	Area	68.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#48, \$37	Date	2023/8/10 下午 01:30:38
Segment	1	Camera	1
Pattern	8055	Position[x, y]	700.3 [mm], 6023.4 [m], (43.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:387.6 [mm]
Result	-	Area	68.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#48, \$37	Date	2023/8/10 下午 01:30:38
Segment	1	Camera	1
Pattern	8055	Position[x, y]	374.6 [mm], 6023.3 [m], (43.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:491.2 [mm]
Result	-	Area	79.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#48, \$37	Date	2023/8/10 下午 01:30:38
Segment	1	Camera	1
Pattern	8055	Position[x, y]	567.8 [mm], 6023.2 [m], (43.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:803.2 [mm]
Result	-	Area	80.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#47, \$36	Date	2023/8/10 下午 01:30:38
Segment	1	Camera	1
Pattern	8054	Position[x, y]	700.1 [mm], 6022.7 [m], (43.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:346.8 [mm]
Result	-	Area	68.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#47, \$36	Date	2023/8/10 下午 01:30:38
Segment	1	Camera	1
Pattern	8054	Position[x, y]	700.1 [mm], 6022.3 [m], (44.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:320.4 [mm]
Result	-	Area	68.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#47, \$36	Date	2023/8/10 下午 01:30:38
Segment	1	Camera	1
Pattern	8054	Position[x, y]	374.6 [mm], 6022.4 [m], (44.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:465.2 [mm]
Result	-	Area	79.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#47, \$36	Date	2023/8/10 下午 01:30:38
Segment	1	Camera	1
Pattern	8054	Position[x, y]	567.8 [mm], 6022.5 [m], (43.9 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:803.2 [mm]
Result	-	Area	80.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#46, \$35	Date	2023/8/10 下午 01:30:37
Segment	1	Camera	1
Pattern	8053	Position[x, y]	700.3 [mm], 6022.2 [m], (44.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:62.4 [mm]
Result	-	Area	30.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#46, \$35	Date	2023/8/10 下午 01:30:37
Segment	1	Camera	1
Pattern	8053	Position[x, y]	700.3 [mm], 6022.0 [m], (44.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:347.2 [mm]
Result	-	Area	67.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image




Reference image



Shape image



G M G M



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#46, \$35	Date	2023/8/10 下午 01:30:37
Segment	1	Camera	1
Pattern	8053	Position[x, y]	700.1 [mm], 6021.6 [m], (44.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:341.2 [mm]
Result	-	Area	68.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#46, \$35	Date	2023/8/10 下午 01:30:37
Segment	1	Camera	1
Pattern	8053	Position[x, y]	567.8 [mm], 6021.7 [m], (44.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:744.8 [mm]
Result	-	Area	80.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#45, \$34	Date	2023/8/10 下午 01:30:36
Segment	1	Camera	1
Pattern	8052	Position[x, y]	700.1 [mm], 6021.4 [m], (45.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:126.0 [mm]
Result	-	Area	39.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#45, \$34	Date	2023/8/10 下午 01:30:36
Segment	1	Camera	1
Pattern	8052	Position[x, y]	700.3 [mm], 6021.1 [m], (45.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:261.2 [mm]
Result	-	Area	53.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#45, \$34	Date	2023/8/10 下午 01:30:36
Segment	1	Camera	1
Pattern	8052	Position[x, y]	568.0 [mm], 6020.8 [m], (45.6 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:415.2 [mm]
Result	-	Area	65.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#45, \$34	Date	2023/8/10 下午 01:30:36
Segment	1	Camera	1
Pattern	8052	Position[x, y]	700.3 [mm], 6020.9 [m], (45.5 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:318.4 [mm]
Result	-	Area	67.8 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#44, \$33	Date	2023/8/10 下午 01:30:36
Segment	1	Camera	1
Pattern	8051	Position[x, y]	700.3 [mm], 6020.5 [m], (45.8 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:38.0 [mm]
Result	-	Area	4.0 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	参照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#44, \$33	Date	2023/8/10 下午 01:30:36
Segment	1	Camera	1
Pattern	8051	Position[x, y]	568.0 [mm], 6020.7 [m], (45.7 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:34.8 [mm]
Result	-	Area	8.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#44, \$33	Date	2023/8/10 下午 01:30:36
Segment	1	Camera	1
Pattern	8051	Position[x, y]	700.3 [mm], 6020.7 [m], (45.7 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:68.8 [mm]
Result	-	Area	13.2 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#44, \$33	Date	2023/8/10 下午 01:30:36
Segment	1	Camera	1
Pattern	8051	Position[x, y]	700.3 [mm], 6020.3 [m], (46.1 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:95.2 [mm]
Result	-	Area	13.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#41, \$32	Date	2023/8/10 下午 01:30:28
Segment	1	Camera	1
Pattern	8038	Position[x, y]	373.2 [mm], 6010.9 [m], (55.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:257.6 [mm]
Result	-	Area	62.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#41, \$32	Date	2023/8/10 下午 01:30:28
Segment	1	Camera	1
Pattern	8038	Position[x, y]	698.9 [mm], 6010.9 [m], (55.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:256.4 [mm]
Result	-	Area	85.1 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#41, \$32	Date	2023/8/10 下午 01:30:28
Segment	1	Camera	1
Pattern	8038	Position[x, y]	567.5 [mm], 6010.5 [m], (55.8 [m])
Type	点状疵点	Size	H:1.5 ,V:298.0 [mm]
Result	-	Area	105.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image




Reference image



Shape image



G M G M



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#41, \$32	Date	2023/8/10 下午 01:30:28
Segment	1	Camera	1
Pattern	8038	Position[x, y]	699.8 [mm], 6010.5 [m], (55.9 [m])
Type	点状疵点	Size	H:1.5 ,V:325.6 [mm]
Result	-	Area	154.9 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#40, \$31	Date	2023/8/10 下午 01:30:28
Segment	1	Camera	1
Pattern	8037	Position[x, y]	372.7 [mm], 6009.7 [m], (56.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:393.6 [mm]
Result	-	Area	89.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#40, \$31	Date	2023/8/10 下午 01:30:28
Segment	1	Camera	1
Pattern	8037	Position[x, y]	698.1 [mm], 6010.1 [m], (56.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:286.8 [mm]
Result	-	Area	114.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#40, \$31	Date	2023/8/10 下午 01:30:28
Segment	1	Camera	1
Pattern	8037	Position[x, y]	698.1 [mm], 6009.8 [m], (56.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:404.8 [mm]
Result	-	Area	158.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#40, \$31	Date	2023/8/10 下午 01:30:28
Segment	1	Camera	1
Pattern	8037	Position[x, y]	565.8 [mm], 6009.8 [m], (56.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:327.6 [mm]
Result	-	Area	184.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#39, \$30	Date	2023/8/10 下午 01:30:27
Segment	1	Camera	1
Pattern	8036	Position[x, y]	567.3 [mm], 6008.8 [m], (57.6 [m])
Type	点状疵点	Size	H:1.5 ,V:116.8 [mm]
Result	-	Area	69.2 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#39, \$30	Date	2023/8/10 下午 01:30:27
Segment	1	Camera	1
Pattern	8036	Position[x, y]	372.7 [mm], 6009.0 [m], (57.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:394.0 [mm]
Result	-	Area	85.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#39, \$30	Date	2023/8/10 下午 01:30:27
Segment	1	Camera	1
Pattern	8036	Position[x, y]	698.1 [mm], 6009.0 [m], (57.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:556.0 [mm]
Result	-	Area	163.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#39, \$30	Date	2023/8/10 下午 01:30:27
Segment	1	Camera	1
Pattern	8036	Position[x, y]	565.8 [mm], 6009.0 [m], (57.4 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:650.0 [mm]
Result	-	Area	220.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#38, \$29	Date	2023/8/10 下午 01:30:26
Segment	1	Camera	1
Pattern	8035	Position[x, y]	567.3 [mm], 6008.7 [m], (57.7 [m])
Type	点状疵点	Size	H:1.5 ,V:149.2 [mm]
Result	-	Area	73.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#38, \$29	Date	2023/8/10 下午 01:30:26
Segment	1	Camera	1
Pattern	8035	Position[x, y]	372.9 [mm], 6008.3 [m], (58.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:325.6 [mm]
Result	-	Area	81.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#38, \$29	Date	2023/8/10 下午 01:30:26
Segment	1	Camera	1
Pattern	8035	Position[x, y]	567.5 [mm], 6008.3 [m], (58.1 [m])
Type	点状疵点	Size	H:1.5 ,V:327.6 [mm]
Result	-	Area	120.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#38, \$29	Date	2023/8/10 下午 01:30:26
Segment	1	Camera	1
Pattern	8035	Position[x, y]	699.8 [mm], 6008.3 [m], (58.1 [m])
Type	点状疵点	Size	H:0.5 ,V:325.2 [mm]
Result	-	Area	126.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#37, \$28	Date	2023/8/10 下午 01:30:26
Segment	1	Camera	1
Pattern	8034	Position[x, y]	699.8 [mm], 6007.9 [m], (58.5 [m])
Type	点状疵点	Size	H:0.5 ,V:4.0 [mm]
Result	-	Area	1.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#37, \$28	Date	2023/8/10 下午 01:30:26
Segment	1	Camera	1
Pattern	8034	Position[x, y]	699.8 [mm], 6008.0 [m], (58.4 [m])
Type	点状疵点	Size	H:0.5 ,V:16.4 [mm]
Result	-	Area	5.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#37, \$28	Date	2023/8/10 下午 01:30:26
Segment	1	Camera	1
Pattern	8034	Position[x, y]	699.8 [mm], 6007.8 [m], (58.6 [m])
Type	点状疵点	Size	H:0.5 ,V:19.6 [mm]
Result	-	Area	5.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#34, \$27	Date	2023/8/10 下午 01:30:18
Segment	1	Camera	1
Pattern	8021	Position[x, y]	376.1 [mm], 5997.8 [m], (68.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:13.2 ,V:803.2 [mm]
Result	-	Area	437.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#34, \$27	Date	2023/8/10 下午 01:30:18
Segment	1	Camera	1
Pattern	8021	Position[x, y]	567.5 [mm], 5997.8 [m], (68.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:803.2 [mm]
Result	-	Area	444.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#34, \$27	Date	2023/8/10 下午 01:30:18
Segment	1	Camera	1
Pattern	8021	Position[x, y]	700.6 [mm], 5997.8 [m], (68.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:743.2 [mm]
Result	-	Area	460.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#34, \$27	Date	2023/8/10 下午 01:30:18
Segment	1	Camera	1
Pattern	8021	Position[x, y]	241.8 [mm], 5997.8 [m], (68.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:803.2 [mm]
Result	-	Area	463.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#33, \$26	Date	2023/8/10 下午 01:30:18
Segment	1	Camera	1
Pattern	8020	Position[x, y]	241.8 [mm], 5997.1 [m], (69.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:790.4 [mm]
Result	-	Area	326.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#33, \$26	Date	2023/8/10 下午 01:30:18
Segment	1	Camera	1
Pattern	8020	Position[x, y]	567.0 [mm], 5997.5 [m], (68.9 [m])
Type	点状疵点	Size	H:2.0 ,V:284.4 [mm]
Result	-	Area	344.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#33, \$26	Date	2023/8/10 下午 01:30:18
Segment	1	Camera	1
Pattern	8020	Position[x, y]	567.5 [mm], 5997.1 [m], (69.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:803.2 [mm]
Result	-	Area	350.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#33, \$26	Date	2023/8/10 下午 01:30:18
Segment	1	Camera	1
Pattern	8020	Position[x, y]	374.6 [mm], 5997.1 [m], (69.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:803.2 [mm]
Result	-	Area	359.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#32, \$25	Date	2023/8/10 下午 01:30:17
Segment	1	Camera	1
Pattern	8019	Position[x, y]	241.8 [mm], 5996.4 [m], (70.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:484.0 [mm]
Result	-	Area	177.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#32, \$25	Date	2023/8/10 下午 01:30:17
Segment	1	Camera	1
Pattern	8019	Position[x, y]	883.7 [mm], 5996.4 [m], (70.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:788.4 [mm]
Result	-	Area	205.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#32, \$25	Date	2023/8/10 下午 01:30:17
Segment	1	Camera	1
Pattern	8019	Position[x, y]	700.1 [mm], 5996.4 [m], (70.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:5.1 ,V:803.2 [mm]
Result	-	Area	220.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#32, \$25	Date	2023/8/10 下午 01:30:17
Segment	1	Camera	1
Pattern	8019	Position[x, y]	567.3 [mm], 5996.3 [m], (70.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:803.2 [mm]
Result	-	Area	234.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#31, \$24	Date	2023/8/10 下午 01:30:16
Segment	1	Camera	1
Pattern	8018	Position[x, y]	567.0 [mm], 5995.6 [m], (70.8 [m])
Type	点状疵点	Size	H:0.5 ,V:325.6 [mm]
Result	-	Area	78.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#31, \$24	Date	2023/8/10 下午 01:30:16
Segment	1	Camera	1
Pattern	8018	Position[x, y]	883.7 [mm], 5995.7 [m], (70.7 [m])
Type	縱向刀絲疵點	Size	H:0.7 ,V:803.2 [mm]
Result	-	Area	126.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#31, \$24	Date	2023/8/10 下午 01:30:16
Segment	1	Camera	1
Pattern	8018	Position[x, y]	699.6 [mm], 5995.6 [m], (70.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:803.2 [mm]
Result	-	Area	138.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#31, \$24	Date	2023/8/10 下午 01:30:16
Segment	1	Camera	1
Pattern	8018	Position[x, y]	567.3 [mm], 5995.7 [m], (70.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:803.2 [mm]
Result	-	Area	140.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#30, \$23	Date	2023/8/10 下午 01:30:16
Segment	1	Camera	1
Pattern	8017	Position[x, y]	883.7 [mm], 5995.2 [m], (71.1 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:135.6 [mm]
Result	-	Area	24.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#30, \$23	Date	2023/8/10 下午 01:30:16
Segment	1	Camera	1
Pattern	8017	Position[x, y]	567.5 [mm], 5995.2 [m], (71.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:211.2 [mm]
Result	-	Area	49.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#30, \$23	Date	2023/8/10 下午 01:30:16
Segment	1	Camera	1
Pattern	8017	Position[x, y]	883.7 [mm], 5995.0 [m], (71.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:437.2 [mm]
Result	-	Area	81.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#30, \$23	Date	2023/8/10 下午 01:30:16
Segment	1	Camera	1
Pattern	8017	Position[x, y]	567.5 [mm], 5994.9 [m], (71.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:408.0 [mm]
Result	-	Area	96.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#27, \$22	Date	2023/8/10 下午 01:29:45
Segment	1	Camera	1
Pattern	7965	Position[x, y]	232.6 [mm], 5955.8 [m], (110.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:3.4 ,V:44.0 [mm]
Result	-	Area	69.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#27, \$22	Date	2023/8/10 下午 01:29:45
Segment	1	Camera	1
Pattern	7965	Position[x, y]	4.5 [mm], 5955.8 [m], (110.6 [m])
Type	縱向刀絲疵點	Size	H:9.8 ,V:156.0 [mm]
Result	-	Area	82.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#27, \$22	Date	2023/8/10 下午 01:29:45
Segment	1	Camera	1
Pattern	7965	Position[x, y]	798.0 [mm], 5955.8 [m], (110.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:13.9 ,V:43.6 [mm]
Result	-	Area	94.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#27, \$22	Date	2023/8/10 下午 01:29:45
Segment	1	Camera	1
Pattern	7965	Position[x, y]	898.3 [mm], 5956.3 [m], (110.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:6.8 ,V:311.2 [mm]
Result	-	Area	269.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#26, \$21	Date	2023/8/10 下午 01:29:45
Segment	1	Camera	1
Pattern	7964	Position[x, y]	62.1 [mm], 5955.1 [m], (111.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:39.6 ,V:398.0 [mm]
Result	-	Area	251.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#26, \$21	Date	2023/8/10 下午 01:29:45
Segment	1	Camera	1
Pattern	7964	Position[x, y]	905.2 [mm], 5955.1 [m], (111.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:69.3 ,V:328.8 [mm]
Result	-	Area	517.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#26, \$21	Date	2023/8/10 下午 01:29:45
Segment	1	Camera	1
Pattern	7964	Position[x, y]	96.8 [mm], 5955.1 [m], (111.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:25.9 ,V:174.0 [mm]
Result	-	Area	580.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#26, \$21	Date	2023/8/10 下午 01:29:45
Segment	1	Camera	1
Pattern	7964	Position[x, y]	260.1 [mm], 5955.1 [m], (111.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:41.7 ,V:336.8 [mm]
Result	-	Area	634.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#25, \$20	Date	2023/8/10 下午 01:29:44
Segment	1	Camera	1
Pattern	7963	Position[x, y]	704.2 [mm], 5954.3 [m], (112.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:25.9 ,V:436.4 [mm]
Result	-	Area	522.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#25, \$20	Date	2023/8/10 下午 01:29:44
Segment	1	Camera	1
Pattern	7963	Position[x, y]	257.9 [mm], 5954.3 [m], (112.1 [m])
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:68.1 ,V:203.2 [mm]
Result	-	Area	536.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#25, \$20	Date	2023/8/10 下午 01:29:44
Segment	1	Camera	1
Pattern	7963	Position[x, y]	782.1 [mm], 5954.7 [m], (111.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:35.6 ,V:66.4 [mm]
Result	-	Area	560.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#25, \$20	Date	2023/8/10 下午 01:29:44
Segment	1	Camera	1
Pattern	7963	Position[x, y]	266.2 [mm], 5954.6 [m], (111.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:42.2 ,V:700.4 [mm]
Result	-	Area	731.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#24, \$19	Date	2023/8/10 下午 01:29:44
Segment	1	Camera	1
Pattern	7962	Position[x, y]	636.4 [mm], 5954.2 [m], (112.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:19.0 ,V:42.4 [mm]
Result	-	Area	91.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#24, \$19	Date	2023/8/10 下午 01:29:44
Segment	1	Camera	1
Pattern	7962	Position[x, y]	698.4 [mm], 5954.2 [m], (112.2 [m])
Type	点状疵点	Size	H:4.9 ,V:112.8 [mm]
Result	-	Area	95.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#24, \$19	Date	2023/8/10 下午 01:29:44
Segment	1	Camera	1
Pattern	7962	Position[x, y]	300.2 [mm], 5954.2 [m], (112.2 [m])
Type	点状疵点縱向刀絲疵點	Size	H:53.5 ,V:60.4 [mm]
Result	-	Area	106.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#24, \$19	Date	2023/8/10 下午 01:29:44
Segment	1	Camera	1
Pattern	7962	Position[x, y]	378.3 [mm], 5953.8 [m], (112.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:18.3 ,V:459.2 [mm]
Result	-	Area	267.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#23, \$18	Date	2023/8/10 下午 01:29:43
Segment	1	Camera	1
Pattern	7961	Position[x, y]	422.0 [mm], 5953.3 [m], (113.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:21.2 ,V:115.2 [mm]
Result	-	Area	9.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#23, \$18	Date	2023/8/10 下午 01:29:43
Segment	1	Camera	1
Pattern	7961	Position[x, y]	770.4 [mm], 5953.0 [m], (113.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:95.6 [mm]
Result	-	Area	24.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#23, \$18	Date	2023/8/10 下午 01:29:43
Segment	1	Camera	1
Pattern	7961	Position[x, y]	447.4 [mm], 5953.0 [m], (113.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.0 [mm]
Result	-	Area	35.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#23, \$18	Date	2023/8/10 下午 01:29:43
Segment	1	Camera	1
Pattern	7961	Position[x, y]	448.1 [mm], 5953.4 [m], (113.0 [m])
Type	点状疵点	Size	H:1.2 ,V:95.2 [mm]
Result	-	Area	43.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#22, \$17	Date	2023/8/10 下午 01:29:42
Segment	1	Camera	1
Pattern	7959	Position[x, y]	934.2 [mm], 5951.3 [m], (115.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:11.2 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#21, \$16	Date	2023/8/10 下午 01:29:41
Segment	1	Camera	1
Pattern	7958	Position[x, y]	399.8 [mm], 5951.0 [m], (115.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.6 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#21, \$16	Date	2023/8/10 下午 01:29:41
Segment	1	Camera	1
Pattern	7958	Position[x, y]	729.9 [mm], 5951.0 [m], (115.4 [m])
Type	縱向刀絲疵點	Size	H:11.7 ,V:9.6 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	参照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#21, \$16	Date	2023/8/10 下午 01:29:41
Segment	1	Camera	1
Pattern	7958	Position[x, y]	383.9 [mm], 5951.0 [m], (115.4 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:11.2 [mm]
Result	-	Area	3.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#21, \$16	Date	2023/8/10 下午 01:29:41
Segment	1	Camera	1
Pattern	7958	Position[x, y]	399.8 [mm], 5950.6 [m], (115.7 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.8 [mm]
Result	-	Area	4.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#18, \$15	Date	2023/8/10 下午 01:28:42
Segment	1	Camera	1
Pattern	7856	Position[x, y]	240.1 [mm], 5874.5 [m], (191.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:287.6 [mm]
Result	-	Area	62.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#18, \$15	Date	2023/8/10 下午 01:28:42
Segment	1	Camera	1
Pattern	7856	Position[x, y]	372.7 [mm], 5874.6 [m], (191.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:325.6 [mm]
Result	-	Area	92.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#18, \$15	Date	2023/8/10 下午 01:28:42
Segment	1	Camera	1
Pattern	7856	Position[x, y]	698.1 [mm], 5874.5 [m], (191.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:402.4 [mm]
Result	-	Area	95.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#18, \$15	Date	2023/8/10 下午 01:28:42
Segment	1	Camera	1
Pattern	7856	Position[x, y]	565.8 [mm], 5874.6 [m], (191.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:508.0 [mm]
Result	-	Area	105.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#17, \$14	Date	2023/8/10 下午 01:28:41
Segment	1	Camera	1
Pattern	7855	Position[x, y]	698.1 [mm], 5873.9 [m], (192.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:311.2 [mm]
Result	-	Area	63.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#17, \$14	Date	2023/8/10 下午 01:28:41
Segment	1	Camera	1
Pattern	7855	Position[x, y]	372.9 [mm], 5873.7 [m], (192.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:104.8 [mm]
Result	-	Area	63.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#17, \$14	Date	2023/8/10 下午 01:28:41
Segment	1	Camera	1
Pattern	7855	Position[x, y]	565.8 [mm], 5873.9 [m], (192.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:327.6 [mm]
Result	-	Area	65.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#17, \$14	Date	2023/8/10 下午 01:28:41
Segment	1	Camera	1
Pattern	7855	Position[x, y]	372.7 [mm], 5873.9 [m], (192.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:237.6 [mm]
Result	-	Area	84.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#16, \$13	Date	2023/8/10 下午 01:28:41
Segment	1	Camera	1
Pattern	7854	Position[x, y]	240.1 [mm], 5873.1 [m], (193.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:399.2 [mm]
Result	-	Area	95.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#16, \$13	Date	2023/8/10 下午 01:28:41
Segment	1	Camera	1
Pattern	7854	Position[x, y]	698.1 [mm], 5873.1 [m], (193.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:403.6 [mm]
Result	-	Area	110.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#16, \$13	Date	2023/8/10 下午 01:28:41
Segment	1	Camera	1
Pattern	7854	Position[x, y]	565.8 [mm], 5873.1 [m], (193.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:508.4 [mm]
Result	-	Area	127.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#16, \$13	Date	2023/8/10 下午 01:28:41
Segment	1	Camera	1
Pattern	7854	Position[x, y]	372.4 [mm], 5873.1 [m], (193.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:326.8 [mm]
Result	-	Area	166.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#15, \$12	Date	2023/8/10 下午 01:28:40
Segment	1	Camera	1
Pattern	7853	Position[x, y]	374.2 [mm], 5872.6 [m], (193.8 [m])
Type	点状疵点	Size	H:1.5 ,V:96.8 [mm]
Result	-	Area	44.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#15, \$12	Date	2023/8/10 下午 01:28:40
Segment	1	Camera	1
Pattern	7853	Position[x, y]	372.9 [mm], 5872.7 [m], (193.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:101.2 [mm]
Result	-	Area	50.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#15, \$12	Date	2023/8/10 下午 01:28:40
Segment	1	Camera	1
Pattern	7853	Position[x, y]	372.7 [mm], 5872.3 [m], (194.1 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:325.6 [mm]
Result	-	Area	80.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#15, \$12	Date	2023/8/10 下午 01:28:40
Segment	1	Camera	1
Pattern	7853	Position[x, y]	565.8 [mm], 5872.3 [m], (194.0 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:434.0 [mm]
Result	-	Area	99.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#14, \$11	Date	2023/8/10 下午 01:28:39
Segment	1	Camera	1
Pattern	7852	Position[x, y]	567.5 [mm], 5871.9 [m], (194.5 [m])
Type	点状疵点	Size	H:0.5 ,V:18.0 [mm]
Result	-	Area	3.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#14, \$11	Date	2023/8/10 下午 01:28:39
Segment	1	Camera	1
Pattern	7852	Position[x, y]	567.5 [mm], 5872.1 [m], (194.3 [m])
Type	点状疵点	Size	H:0.5 ,V:50.0 [mm]
Result	-	Area	11.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#14, \$11	Date	2023/8/10 下午 01:28:39
Segment	1	Camera	1
Pattern	7852	Position[x, y]	374.2 [mm], 5872.1 [m], (194.3 [m])
Type	点状疵点	Size	H:0.5 ,V:50.0 [mm]
Result	-	Area	12.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#14, \$11	Date	2023/8/10 下午 01:28:39
Segment	1	Camera	1
Pattern	7852	Position[x, y]	699.8 [mm], 5871.7 [m], (194.7 [m])
Type	点状疵点	Size	H:0.5 ,V:58.4 [mm]
Result	-	Area	13.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#11, \$10	Date	2023/8/10 下午 01:28:25
Segment	1	Camera	1
Pattern	7827	Position[x, y]	94.1 [mm], 5852.8 [m], (213.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:20.0 ,V:58.8 [mm]
Result	-	Area	7.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#11, \$10	Date	2023/8/10 下午 01:28:25
Segment	1	Camera	1
Pattern	7827	Position[x, y]	414.9 [mm], 5852.8 [m], (213.6 [m])
Type	縱向刀絲疵點	Size	H:41.3 ,V:59.2 [mm]
Result	-	Area	7.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#11, \$10	Date	2023/8/10 下午 01:28:25
Segment	1	Camera	1
Pattern	7827	Position[x, y]	869.0 [mm], 5852.9 [m], (213.5 [m])
Type	縱向刀絲疵點	Size	H:12.5 ,V:206.4 [mm]
Result	-	Area	8.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	参照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#11, \$10	Date	2023/8/10 下午 01:28:25
Segment	1	Camera	1
Pattern	7827	Position[x, y]	553.4 [mm], 5852.8 [m], (213.6 [m])
Type	縱向刀絲疵點	Size	H:1.0 ,V:34.8 [mm]
Result	-	Area	9.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#10, \$9	Date	2023/8/10 下午 01:28:24
Segment	1	Camera	1
Pattern	7826	Position[x, y]	736.2 [mm], 5852.1 [m], (214.3 [m])
Type	点状疵点縱向刀絲疵點	Size	H:27.3 ,V:58.8 [mm]
Result	-	Area	6.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	参照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#10, \$9	Date	2023/8/10 下午 01:28:24
Segment	1	Camera	1
Pattern	7826	Position[x, y]	91.7 [mm], 5852.1 [mm], (214.3 [mm])
Type	縱向刀絲疵點	Size	H:8.5 ,V:59.2 [mm]
Result	-	Area	6.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範囲 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	参照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#10, \$9	Date	2023/8/10 下午 01:28:24
Segment	1	Camera	1
Pattern	7826	Position[x, y]	553.4 [mm], 5852.1 [m], (214.3 [m])
Type	縱向刀絲疵點	Size	H:1.0 ,V:22.4 [mm]
Result	-	Area	7.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#10, \$9	Date	2023/8/10 下午 01:28:24
Segment	1	Camera	1
Pattern	7826	Position[x, y]	228.2 [mm], 5852.1 [m], (214.3 [m])
Type	縱向刀絲疵點	Size	H:1.0 ,V:45.2 [mm]
Result	-	Area	7.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#9, \$8	Date	2023/8/10 下午 01:28:24
Segment	1	Camera	1
Pattern	7825	Position[x, y]	88.5 [mm], 5851.3 [m], (215.1 [m])
Type	縱向刀絲疵點	Size	H:15.4 ,V:58.4 [mm]
Result	-	Area	5.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#9, \$8	Date	2023/8/10 下午 01:28:24
Segment	1	Camera	1
Pattern	7825	Position[x, y]	410.8 [mm], 5851.3 [m], (215.1 [m])
Type	縱向刀絲疵點	Size	H:8.8 ,V:58.4 [mm]
Result	-	Area	5.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#9, \$8	Date	2023/8/10 下午 01:28:24
Segment	1	Camera	1
Pattern	7825	Position[x, y]	738.4 [mm], 5851.7 [m], (214.7 [m])
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:9.6 [mm]
Result	-	Area	6.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#9, \$8	Date	2023/8/10 下午 01:28:24
Segment	1	Camera	1
Pattern	7825	Position[x, y]	93.2 [mm], 5851.7 [m], (214.7 [m])
Type	縱向刀絲疵點	Size	H:4.6 ,V:9.6 [mm]
Result	-	Area	6.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#8, \$7	Date	2023/8/10 下午 01:28:23
Segment	1	Camera	1
Pattern	7824	Position[x, y]	88.5 [mm], 5850.5 [m], (215.8 [m])
Type	縱向刀絲疵點	Size	H:15.1 ,V:31.2 [mm]
Result	-	Area	4.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#8, \$7	Date	2023/8/10 下午 01:28:23
Segment	1	Camera	1
Pattern	7824	Position[x, y]	738.9 [mm], 5850.9 [m], (215.5 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.6 [mm]
Result	-	Area	4.7 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#8, \$7	Date	2023/8/10 下午 01:28:23
Segment	1	Camera	1
Pattern	7824	Position[x, y]	95.1 [mm], 5850.9 [m], (215.5 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.6 [mm]
Result	-	Area	4.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#8, \$7	Date	2023/8/10 下午 01:28:23
Segment	1	Camera	1
Pattern	7824	Position[x, y]	733.8 [mm], 5850.6 [m], (215.8 [m])
Type	縱向刀絲疵點	Size	H:8.3 ,V:57.2 [mm]
Result	-	Area	4.7 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#7, \$6	Date	2023/8/10 下午 01:28:22
Segment	1	Camera	1
Pattern	7823	Position[x, y]	723.8 [mm], 5850.2 [m], (216.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.0 [mm]
Result	-	Area	2.6 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#7, \$6	Date	2023/8/10 下午 01:28:22
Segment	1	Camera	1
Pattern	7823	Position[x, y]	95.1 [mm], 5850.2 [m], (216.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	2.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		

Defect information

No.	#7, \$6	Date	2023/8/10 下午 01:28:22
Segment	1	Camera	1
Pattern	7823	Position[x, y]	412.2 [mm], 5849.8 [m], (216.6 [m])
Type	縱向刀絲疵點	Size	H:4.4 ,V:9.2 [mm]
Result	-	Area	3.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#7, \$6	Date	2023/8/10 下午 01:28:22
Segment	1	Camera	1
Pattern	7823	Position[x, y]	738.9 [mm], 5850.2 [m], (216.2 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:9.2 [mm]
Result	-	Area	4.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#6, \$5	Date	2023/8/10 下午 01:28:14
Segment	1	Camera	1
Pattern	7808	Position[x, y]	411.5 [mm], 5838.6 [m], (227.8 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:5.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#6, \$5	Date	2023/8/10 下午 01:28:14
Segment	1	Camera	1
Pattern	7808	Position[x, y]	81.4 [mm], 5838.6 [m], (227.8 [m])
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.4 [mm]
Result	-	Area	2.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#6, \$5	Date	2023/8/10 下午 01:28:14
Segment	1	Camera	1
Pattern	7808	Position[x, y]	874.2 [mm], 5838.6 [m], (227.8 [m])
Type	点状疵点	Size	H:1.7 ,V:16.8 [mm]
Result	-	Area	3.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#6, \$5	Date	2023/8/10 下午 01:28:14
Segment	1	Camera	1
Pattern	7808	Position[x, y]	880.3 [mm], 5838.7 [m], (227.6 [m])
Type	点状疵点縱向刀絲疵點	Size	H:11.2 ,V:318.4 [mm]
Result	-	Area	306.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#5, \$4	Date	2023/8/10 下午 01:28:13
Segment	1	Camera	1
Pattern	7807	Position[x, y]	838.3 [mm], 5838.1 [m], (228.3 [m])
Type	点状疵点	Size	H:19.5 ,V:4.8 [mm]
Result	-	Area	3.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	

Defect information

No.	#5, \$4	Date	2023/8/10 下午 01:28:13
Segment	1	Camera	1
Pattern	7807	Position[x, y]	86.8 [mm], 5838.2 [m], (228.2 [m])
Type	縱向刀絲疵點	Size	H:11.2 ,V:30.0 [mm]
Result	-	Area	5.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#5, \$4	Date	2023/8/10 下午 01:28:13
Segment	1	Camera	1
Pattern	7807	Position[x, y]	883.2 [mm], 5838.2 [m], (228.2 [m])
Type	点状疵点	Size	H:1.5 ,V:58.4 [mm]
Result	-	Area	14.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	檢查範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#5, \$4	Date	2023/8/10 下午 01:28:13
Segment	1	Camera	1
Pattern	7807	Position[x, y]	866.6 [mm], 5837.9 [m], (228.5 [m])
Type	点状疵点縱向刀絲疵點	Size	H:49.6 ,V:216.0 [mm]
Result	-	Area	60.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#4, \$3	Date	2023/8/10 下午 12:43:42
Segment	1	Camera	1
Pattern	3239	Position[x, y]	930.1 [mm], 2425.4 [m], (3641.0 [m])
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm] 寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新
Segments	1 (從左側)	


Defect information

No.	#3, \$2	Date	2023/8/10 下午 12:42:59
Segment	1	Camera	1
Pattern	3166	Position[x, y]	924.2 [mm], 2370.9 [m], (3695.5 [m])
Type	縱向刀絲疵點	Size	H:2.7 ,V:1.6 [mm]
Result	-	Area	2.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/10 下午 12:12:08 ~ 2023/8/10 下午 01:31:18

ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

Coil Information

Total defects	38	検査範圍 : 86.5 ~ 1024.2 [mm]	寬度 : 937.7 [mm]
Web length	6066.4 [m]	參照更新 : 無更新/無更新	
Segments	1 (從左側)		


Defect information

No.	#2, \$1	Date	2023/8/10 下午 12:18:31
Segment	1	Camera	1
Pattern	657	Position[x, y]	624.4 [mm], 496.6 [m], (5569.8 [m])
Type	点状疵点縱向刀絲疵點	Size	H:2.9 ,V:2.4 [mm]
Result	-	Area	5.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image



Reference image



Shape image

