

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#55, \$42	Date	2023/8/9 下午 02:20:00
Segment	1	Camera	1
Pattern	8014	Position[ x, y ]	12.8 [mm], 6025.2 [m], ( 1.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:26.4 ,V:17.2 [mm]
Result	-	Area	342.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#54, \$41	Date	2023/8/9 下午 02:19:59
Segment	1	Camera	1
Pattern	8012	Position[ x, y ]	157.3 [mm], 6023.7 [m], ( 3.5 [m] )
Type	縱向刀絲疵點	Size	H:2.9 ,V:17.6 [mm]
Result	-	Area	23.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#51, \$40	Date	2023/8/9 下午 02:19:31
Segment	1	Camera	1
Pattern	7967	Position[ x, y ]	15.0 [mm], 5989.2 [m], ( 37.9 [m] )
Type	点状疵点	Size	H:28.8 ,V:7.2 [mm]
Result	-	Area	200.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#51, \$40	Date	2023/8/9 下午 02:19:31
Segment	1	Camera	1
Pattern	7967	Position[ x, y ]	65.0 [mm], 5990.0 [m], ( 37.2 [m] )
Type	点状疵点	Size	H:16.1 ,V:33.6 [mm]
Result	-	Area	417.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#51, \$40	Date	2023/8/9 下午 02:19:31
Segment	1	Camera	1
Pattern	7967	Position[ x, y ]	65.5 [mm], 5989.2 [m], ( 37.9 [m] )
Type	点状疵点	Size	H:16.4 ,V:42.0 [mm]
Result	-	Area	554.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#51, \$40	Date	2023/8/9 下午 02:19:31
Segment	1	Camera	1
Pattern	7967	Position[ x, y ]	64.8 [mm], 5989.3 [m], ( 37.8 [m] )
Type	点状疵点	Size	H:16.4 ,V:172.8 [mm]
Result	-	Area	1978.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	42	検査範囲 : 83.6 ~ 1024.2 [mm]    寬度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6027.2 [m]	
Segments	1 ( 從左側 )	

### Defect information

No.	#50, \$39	Date	2023/8/9 下午 02:19:31
Segment	1	Camera	1
Pattern	7966	Position[ x, y ]	65.3 [mm], 5988.5 [m], ( 38.7 [m] )
Type	点状疵点	Size	H:16.1 ,V:17.2 [mm]
Result	—	Area	204.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#50, \$39	Date	2023/8/9 下午 02:19:31
Segment	1	Camera	1
Pattern	7966	Position[ x, y ]	18.2 [mm], 5988.5 [m], ( 38.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:29.8 ,V:9.2 [mm]
Result	-	Area	211.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#50, \$39	Date	2023/8/9 下午 02:19:31
Segment	1	Camera	1
Pattern	7966	Position[ x, y ]	65.5 [mm], 5989.2 [m], ( 37.9 [m] )
Type	点状疵点	Size	H:16.4 ,V:50.0 [mm]
Result	-	Area	668.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#50, \$39	Date	2023/8/9 下午 02:19:31
Segment	1	Camera	1
Pattern	7966	Position[ x, y ]	64.6 [mm], 5988.6 [m], ( 38.6 [m] )
Type	点状疵点	Size	H:16.6 ,V:173.2 [mm]
Result	-	Area	1968.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#49, \$38	Date	2023/8/9 下午 02:19:30
Segment	1	Camera	1
Pattern	7965	Position[ x, y ]	65.0 [mm], 5987.7 [m], ( 39.4 [m] )
Type	面狀重疵点	Size	H:14.2 ,V:34.0 [mm]
Result	-	Area	230.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#49, \$38	Date	2023/8/9 下午 02:19:30
Segment	1	Camera	1
Pattern	7965	Position[ x, y ]	378.3 [mm], 5987.9 [m], ( 39.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.5 ,V:282.4 [mm]
Result	-	Area	324.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#49, \$38	Date	2023/8/9 下午 02:19:30
Segment	1	Camera	1
Pattern	7965	Position[ x, y ]	65.5 [mm], 5987.7 [m], ( 39.4 [m] )
Type	点状疵点	Size	H:16.1 ,V:34.4 [mm]
Result	-	Area	434.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#49, \$38	Date	2023/8/9 下午 02:19:30
Segment	1	Camera	1
Pattern	7965	Position[ x, y ]	64.6 [mm], 5987.8 [m], ( 39.3 [m] )
Type	点状疵点	Size	H:16.6 ,V:173.2 [mm]
Result	-	Area	1976.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#48, \$37	Date	2023/8/9 下午 02:19:30
Segment	1	Camera	1
Pattern	7964	Position[ x, y ]	324.6 [mm], 5987.4 [m], ( 39.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:30.8 ,V:8.0 [mm]
Result	-	Area	206.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#48, \$37	Date	2023/8/9 下午 02:19:30
Segment	1	Camera	1
Pattern	7964	Position[ x, y ]	65.3 [mm], 5987.7 [m], ( 39.4 [m] )
Type	点状疵点	Size	H:16.1 ,V:34.4 [mm]
Result	-	Area	434.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#48, \$37	Date	2023/8/9 下午 02:19:30
Segment	1	Camera	1
Pattern	7964	Position[ x, y ]	65.5 [mm], 5987.0 [m], ( 40.2 [m] )
Type	点状疵点	Size	H:16.4 ,V:42.0 [mm]
Result	-	Area	551.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#48, \$37	Date	2023/8/9 下午 02:19:30
Segment	1	Camera	1
Pattern	7964	Position[ x, y ]	64.6 [mm], 5987.1 [m], ( 40.1 [m] )
Type	点状疵点	Size	H:16.6 ,V:173.6 [mm]
Result	-	Area	1968.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#47, \$36	Date	2023/8/9 下午 02:19:29
Segment	1	Camera	1
Pattern	7963	Position[ x, y ]	18.2 [mm], 5986.2 [m], ( 40.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:29.8 ,V:9.2 [mm]
Result	-	Area	212.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	42	検査範囲 : 83.6 ~ 1024.2 [mm]  宽度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6027.2 [m]	
Segments	1 ( 從左側 )	

### Defect information

No.	#47, \$36	Date	2023/8/9 下午 02:19:29
Segment	1	Camera	1
Pattern	7963	Position[ x, y ]	65.3 [mm], 5986.2 [m], ( 40.9 [m] )
Type	点状疵点	Size	H:16.4 ,V:17.6 [mm]
Result	-	Area	213.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



### Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	42	検査範囲 : 83.6 ~ 1024.2 [mm]  宽度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6027.2 [m]	
Segments	1 ( 從左側 )	

### Defect information

No.	#47, \$36	Date	2023/8/9 下午 02:19:29
Segment	1	Camera	1
Pattern	7963	Position[ x, y ]	65.5 [mm], 5987.0 [m], ( 40.2 [m] )
Type	点状疵点	Size	H:16.4 ,V:50.0 [mm]
Result	—	Area	661.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#47, \$36	Date	2023/8/9 下午 02:19:29
Segment	1	Camera	1
Pattern	7963	Position[ x, y ]	64.8 [mm], 5986.3 [m], ( 40.8 [m] )
Type	点状疵点	Size	H:16.6 ,V:173.2 [mm]
Result	-	Area	1970.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#44, \$35	Date	2023/8/9 下午 02:19:23
Segment	1	Camera	1
Pattern	7953	Position[ x, y ]	77.3 [mm], 5979.0 [m], ( 48.2 [m] )
Type	面状重疵点縱向刀絲疵點	Size	H:23.4 ,V:160.0 [mm]
Result	-	Area	1678.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#44, \$35	Date	2023/8/9 下午 02:19:23
Segment	1	Camera	1
Pattern	7953	Position[ x, y ]	70.2 [mm], 5979.4 [m], ( 47.8 [m] )
Type	面狀重疵點	Size	H:22.5 ,V:99.2 [mm]
Result	-	Area	1814.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#44, \$35	Date	2023/8/9 下午 02:19:23
Segment	1	Camera	1
Pattern	7953	Position[ x, y ]	75.1 [mm], 5978.9 [m], ( 48.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:25.6 ,V:380.0 [mm]
Result	-	Area	4448.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#44, \$35	Date	2023/8/9 下午 02:19:23
Segment	1	Camera	1
Pattern	7953	Position[ x, y ]	74.8 [mm], 5979.3 [m], ( 47.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:24.9 ,V:359.2 [mm]
Result	-	Area	4963.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#43, \$34	Date	2023/8/9 下午 02:19:22
Segment	1	Camera	1
Pattern	7952	Position[ x, y ]	67.0 [mm], 5978.3 [mm], ( 48.9 [mm] )
Type	面狀重疵點	Size	H:17.6 ,V:118.0 [mm]
Result	-	Area	1534.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#43, \$34	Date	2023/8/9 下午 02:19:22
Segment	1	Camera	1
Pattern	7952	Position[ x, y ]	71.4 [mm], 5978.7 [m], ( 48.5 [m] )
Type	点状疵点	Size	H:21.7 ,V:118.0 [mm]
Result	-	Area	1679.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#43, \$34	Date	2023/8/9 下午 02:19:22
Segment	1	Camera	1
Pattern	7952	Position[ x, y ]	67.7 [mm], 5978.1 [m], ( 49.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:18.8 ,V:418.8 [mm]
Result	-	Area	3884.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#43, \$34	Date	2023/8/9 下午 02:19:22
Segment	1	Camera	1
Pattern	7952	Position[ x, y ]	70.7 [mm], 5978.4 [m], ( 48.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:28.1 ,V:706.0 [mm]
Result	-	Area	4490.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#42, \$33	Date	2023/8/9 下午 02:19:22
Segment	1	Camera	1
Pattern	7951	Position[ x, y ]	73.6 [mm], 5977.3 [m], ( 49.9 [m] )
Type	点状疵点	Size	H:34.9 ,V:249.6 [mm]
Result	-	Area	503.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#42, \$33	Date	2023/8/9 下午 02:19:22
Segment	1	Camera	1
Pattern	7951	Position[ x, y ]	67.0 [mm], 5977.9 [m], ( 49.2 [m] )
Type	面狀重疵點	Size	H:16.6 ,V:116.0 [mm]
Result	-	Area	1463.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#42, \$33	Date	2023/8/9 下午 02:19:22
Segment	1	Camera	1
Pattern	7951	Position[ x, y ]	70.9 [mm], 5977.4 [m], ( 49.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:37.1 ,V:436.4 [mm]
Result	-	Area	1722.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#42, \$33	Date	2023/8/9 下午 02:19:22
Segment	1	Camera	1
Pattern	7951	Position[ x, y ]	69.2 [mm], 5977.7 [m], ( 49.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:24.9 ,V:533.2 [mm]
Result	-	Area	4121.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#41, \$32	Date	2023/8/9 下午 02:19:21
Segment	1	Camera	1
Pattern	7950	Position[ x, y ]	12.6 [mm], 5976.5 [m], ( 50.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:16.6 ,V:70.4 [mm]
Result	-	Area	84.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#41, \$32	Date	2023/8/9 下午 02:19:21
Segment	1	Camera	1
Pattern	7950	Position[ x, y ]	15.2 [mm], 5976.9 [m], ( 50.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:28.3 ,V:69.2 [mm]
Result	-	Area	185.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#41, \$32	Date	2023/8/9 下午 02:19:21
Segment	1	Camera	1
Pattern	7950	Position[ x, y ]	62.8 [mm], 5977.1 [m], ( 50.0 [m] )
Type	面状重斑点	Size	H:8.5 ,V:98.8 [mm]
Result	-	Area	327.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#41, \$32	Date	2023/8/9 下午 02:19:21
Segment	1	Camera	1
Pattern	7950	Position[ x, y ]	65.5 [mm], 5977.0 [m], ( 50.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:15.9 ,V:309.6 [mm]
Result	-	Area	1452.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#40, \$31	Date	2023/8/9 下午 02:19:21
Segment	1	Camera	1
Pattern	7949	Position[ x, y ]	10.6 [mm], 5976.1 [m], ( 51.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:14.6 ,V:9.6 [mm]
Result	-	Area	97.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#39, \$30	Date	2023/8/9 下午 02:19:13
Segment	1	Camera	1
Pattern	7937	Position[ x, y ]	451.0 [mm], 5967.1 [m], ( 60.0 [m] )
Type	縱向刀絲疵點	Size	H:2.7 ,V:44.8 [mm]
Result	-	Area	75.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#38, \$29	Date	2023/8/9 下午 02:18:39
Segment	1	Camera	1
Pattern	7880	Position[ x, y ]	128.0 [mm], 5923.9 [m], ( 103.2 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:20.8 [mm]
Result	-	Area	13.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#37, \$28	Date	2023/8/9 下午 02:18:38
Segment	1	Camera	1
Pattern	7879	Position[ x, y ]	132.4 [mm], 5923.2 [m], ( 104.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:5.4 ,V:46.0 [mm]
Result	-	Area	143.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#37, \$28	Date	2023/8/9 下午 02:18:38
Segment	1	Camera	1
Pattern	7879	Position[ x, y ]	450.1 [mm], 5923.2 [m], ( 104.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:8.8 ,V:42.8 [mm]
Result	-	Area	223.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#37, \$28	Date	2023/8/9 下午 02:18:38
Segment	1	Camera	1
Pattern	7879	Position[ x, y ]	448.6 [mm], 5923.6 [m], ( 103.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:10.7 ,V:44.8 [mm]
Result	-	Area	318.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#37, \$28	Date	2023/8/9 下午 02:18:38
Segment	1	Camera	1
Pattern	7879	Position[ x, y ]	127.5 [mm], 5923.6 [m], ( 103.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.5 ,V:153.2 [mm]
Result	-	Area	847.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#36, \$27	Date	2023/8/9 下午 02:18:38
Segment	1	Camera	1
Pattern	7878	Position[ x, y ]	381.5 [mm], 5922.8 [m], ( 104.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:10.3 ,V:26.4 [mm]
Result	-	Area	131.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#36, \$27	Date	2023/8/9 下午 02:18:38
Segment	1	Camera	1
Pattern	7878	Position[ x, y ]	448.3 [mm], 5922.8 [m], ( 104.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:13.7 ,V:64.0 [mm]
Result	-	Area	414.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#36, \$27	Date	2023/8/9 下午 02:18:38
Segment	1	Camera	1
Pattern	7878	Position[ x, y ]	127.8 [mm], 5922.8 [m], ( 104.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:15.4 ,V:160.8 [mm]
Result	-	Area	1037.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#35, \$26	Date	2023/8/9 下午 02:18:18
Segment	1	Camera	1
Pattern	7845	Position[ x, y ]	441.3 [mm], 5897.9 [m], ( 129.2 [m] )
Type	点状疵点	Size	H:5.9 ,V:52.8 [mm]
Result	-	Area	109.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#35, \$26	Date	2023/8/9 下午 02:18:18
Segment	1	Camera	1
Pattern	7845	Position[ x, y ]	374.9 [mm], 5898.1 [m], ( 129.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:11.2 ,V:342.8 [mm]
Result	-	Area	882.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#35, \$26	Date	2023/8/9 下午 02:18:18
Segment	1	Camera	1
Pattern	7845	Position[ x, y ]	441.5 [mm], 5898.0 [m], ( 129.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:14.4 ,V:273.6 [mm]
Result	-	Area	1644.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#35, \$26	Date	2023/8/9 下午 02:18:18
Segment	1	Camera	1
Pattern	7845	Position[ x, y ]	121.7 [mm], 5898.0 [m], ( 129.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:15.1 ,V:274.4 [mm]
Result	-	Area	2315.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#34, \$25	Date	2023/8/9 下午 02:18:17
Segment	1	Camera	1
Pattern	7844	Position[ x, y ]	377.8 [mm], 5897.3 [m], ( 129.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:9.0 ,V:43.2 [mm]
Result	-	Area	245.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#34, \$25	Date	2023/8/9 下午 02:18:17
Segment	1	Camera	1
Pattern	7844	Position[ x, y ]	449.1 [mm], 5896.9 [m], ( 130.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.2 ,V:44.8 [mm]
Result	-	Area	414.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#34, \$25	Date	2023/8/9 下午 02:18:17
Segment	1	Camera	1
Pattern	7844	Position[ x, y ]	444.4 [mm], 5897.3 [m], ( 129.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:13.7 ,V:144.8 [mm]
Result	-	Area	532.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#34, \$25	Date	2023/8/9 下午 02:18:17
Segment	1	Camera	1
Pattern	7844	Position[ x, y ]	124.6 [mm], 5897.3 [m], ( 129.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:14.4 ,V:270.8 [mm]
Result	-	Area	1683.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#33, \$24	Date	2023/8/9 下午 02:18:16
Segment	1	Camera	1
Pattern	7842	Position[ x, y ]	123.9 [mm], 5895.8 [m], ( 131.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.0 ,V:147.6 [mm]
Result	-	Area	739.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#30, \$23	Date	2023/8/9 下午 02:18:08
Segment	1	Camera	1
Pattern	7829	Position[ x, y ]	442.2 [mm], 5886.0 [m], ( 141.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.0 ,V:46.0 [mm]
Result	-	Area	415.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#30, \$23	Date	2023/8/9 下午 02:18:08
Segment	1	Camera	1
Pattern	7829	Position[ x, y ]	374.1 [mm], 5886.0 [m], ( 141.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:10.5 ,V:409.6 [mm]
Result	-	Area	483.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#30, \$23	Date	2023/8/9 下午 02:18:08
Segment	1	Camera	1
Pattern	7829	Position[ x, y ]	125.8 [mm], 5886.3 [m], ( 140.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:11.2 ,V:102.8 [mm]
Result	-	Area	684.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#30, \$23	Date	2023/8/9 下午 02:18:08
Segment	1	Camera	1
Pattern	7829	Position[ x, y ]	123.9 [mm], 5886.1 [m], ( 141.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:18.1 ,V:274.0 [mm]
Result	-	Area	2896.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#29, \$22	Date	2023/8/9 下午 02:18:08
Segment	1	Camera	1
Pattern	7828	Position[ x, y ]	243.0 [mm], 5885.1 [m], ( 142.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:793.2 [mm]
Result	-	Area	126.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#29, \$22	Date	2023/8/9 下午 02:18:08
Segment	1	Camera	1
Pattern	7828	Position[ x, y ]	375.1 [mm], 5885.0 [m], ( 142.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:417.2 [mm]
Result	-	Area	137.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#29, \$22	Date	2023/8/9 下午 02:18:08
Segment	1	Camera	1
Pattern	7828	Position[ x, y ]	568.0 [mm], 5885.1 [m], ( 142.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:793.6 [mm]
Result	-	Area	158.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#29, \$22	Date	2023/8/9 下午 02:18:08
Segment	1	Camera	1
Pattern	7828	Position[ x, y ]	700.1 [mm], 5885.1 [m], ( 142.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:794.0 [mm]
Result	-	Area	160.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#28, \$21	Date	2023/8/9 下午 02:18:07
Segment	1	Camera	1
Pattern	7827	Position[ x, y ]	243.0 [mm], 5884.4 [m], ( 142.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:808.0 [mm]
Result	-	Area	113.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#28, \$21	Date	2023/8/9 下午 02:18:07
Segment	1	Camera	1
Pattern	7827	Position[ x, y ]	883.9 [mm], 5884.4 [m], ( 142.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:657.6 [mm]
Result	-	Area	122.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	42	検査範囲 : 83.6 ~ 1024.2 [mm]  宽度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6027.2 [m]	
Segments	1 ( 從左側 )	

## Defect information

No.	#28, \$21	Date	2023/8/9 下午 02:18:07
Segment	1	Camera	1
Pattern	7827	Position[ x, y ]	568.0 [mm], 5884.4 [m], ( 142.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:808.0 [mm]
Result	—	Area	146.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#28, \$21	Date	2023/8/9 下午 02:18:07
Segment	1	Camera	1
Pattern	7827	Position[ x, y ]	700.1 [mm], 5884.4 [m], ( 142.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:665.6 [mm]
Result	-	Area	149.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	42	検査範囲 : 83.6 ~ 1024.2 [mm]  寬度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6027.2 [m]	
Segments	1 ( 從左側 )	

## Defect information

No.	#27, \$20	Date	2023/8/9 下午 02:18:06
Segment	1	Camera	1
Pattern	7826	Position[ x, y ]	374.9 [mm], 5884.1 [m], ( 143.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:91.2 [mm]
Result	—	Area	34.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#27, \$20	Date	2023/8/9 下午 02:18:06
Segment	1	Camera	1
Pattern	7826	Position[ x, y ]	243.0 [mm], 5884.0 [m], ( 143.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:178.0 [mm]
Result	-	Area	36.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	42	検査範囲 : 83.6 ~ 1024.2 [mm]  宽度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6027.2 [m]	
Segments	1 ( 從左側 )	

## Defect information

No.	#27, \$20	Date	2023/8/9 下午 02:18:06
Segment	1	Camera	1
Pattern	7826	Position[ x, y ]	699.8 [mm], 5883.5 [m], ( 143.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:184.4 [mm]
Result	—	Area	56.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#27, \$20	Date	2023/8/9 下午 02:18:06
Segment	1	Camera	1
Pattern	7826	Position[ x, y ]	568.2 [mm], 5883.7 [m], ( 143.5 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:328.8 [mm]
Result	-	Area	79.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			
		1/40	

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#26, \$19	Date	2023/8/9 下午 02:18:06
Segment	1	Camera	1
Pattern	7825	Position[ x, y ]	567.5 [mm], 5883.4 [m], ( 143.8 [m] )
Type	点状疵点	Size	H:0.5 ,V:3.6 [mm]
Result	-	Area	1.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#26, \$19	Date	2023/8/9 下午 02:18:06
Segment	1	Camera	1
Pattern	7825	Position[ x, y ]	700.1 [mm], 5882.7 [m], ( 144.4 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:122.8 [mm]
Result	-	Area	11.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#26, \$19	Date	2023/8/9 下午 02:18:06
Segment	1	Camera	1
Pattern	7825	Position[ x, y ]	699.8 [mm], 5883.4 [m], ( 143.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:36.0 [mm]
Result	-	Area	17.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#23, \$18	Date	2023/8/9 下午 02:17:46
Segment	1	Camera	1
Pattern	7793	Position[ x, y ]	58.5 [mm], 5859.1 [m], ( 168.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.0 ,V:468.4 [mm]
Result	-	Area	737.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#23, \$18	Date	2023/8/9 下午 02:17:46
Segment	1	Camera	1
Pattern	7793	Position[ x, y ]	392.9 [mm], 5859.3 [m], ( 167.8 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:63.5 ,V:222.0 [mm]
Result	-	Area	749.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#23, \$18	Date	2023/8/9 下午 02:17:46
Segment	1	Camera	1
Pattern	7793	Position[ x, y ]	502.3 [mm], 5859.1 [m], ( 168.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:161.9 ,V:578.4 [mm]
Result	-	Area	786.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#23, \$18	Date	2023/8/9 下午 02:17:46
Segment	1	Camera	1
Pattern	7793	Position[ x, y ]	562.8 [mm], 5858.7 [m], ( 168.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:36.1 ,V:452.0 [mm]
Result	-	Area	1047.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#22, \$17	Date	2023/8/9 下午 02:17:46
Segment	1	Camera	1
Pattern	7792	Position[ x, y ]	376.3 [mm], 5858.1 [m], ( 169.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.2 ,V:384.8 [mm]
Result	-	Area	653.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#22, \$17	Date	2023/8/9 下午 02:17:46
Segment	1	Camera	1
Pattern	7792	Position[ x, y ]	567.2 [mm], 5858.5 [m], ( 168.7 [m] )
Type	面狀重疵點	Size	H:7.1 ,V:357.2 [mm]
Result	-	Area	803.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#22, \$17	Date	2023/8/9 下午 02:17:46
Segment	1	Camera	1
Pattern	7792	Position[ x, y ]	547.7 [mm], 5858.1 [m], ( 169.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:68.4 ,V:795.6 [mm]
Result	-	Area	1522.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#22, \$17	Date	2023/8/9 下午 02:17:46
Segment	1	Camera	1
Pattern	7792	Position[ x, y ]	150.7 [mm], 5858.1 [m], ( 169.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:197.8 ,V:806.4 [mm]
Result	-	Area	3715.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#21, \$16	Date	2023/8/9 下午 02:17:45
Segment	1	Camera	1
Pattern	7791	Position[ x, y ]	229.8 [mm], 5857.8 [m], ( 169.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:58.3 ,V:142.4 [mm]
Result	-	Area	666.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#21, \$16	Date	2023/8/9 下午 02:17:45
Segment	1	Camera	1
Pattern	7791	Position[ x, y ]	486.7 [mm], 5857.8 [m], ( 169.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:46.6 ,V:161.6 [mm]
Result	-	Area	797.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



### Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	42	検査範囲 : 83.6 ~ 1024.2 [mm]    寬度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6027.2 [m]	
Segments	1 ( 從左側 )	

### Defect information

No.	#21, \$16	Date	2023/8/9 下午 02:17:45
Segment	1	Camera	1
Pattern	7791	Position[ x, y ]	401.7 [mm], 5857.5 [m], ( 169.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:205.8 ,V:729.2 [mm]
Result	—	Area	1461.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



### Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

ID information ( No. 2 )



商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

### Coil Information

Total defects	42	検査範囲 : 83.6 ~ 1024.2 [mm]  寬度 : 940.6 [mm] 参照更新 : 週期10<平時>/週期10<平時>
Web length	6027.2 [m]	
Segments	1 ( 從左側 )	

## Defect information




No.	#21, \$16	Date	2023/8/9 下午 02:17:45
Segment	1	Camera	1
Pattern	7791	Position[ x, y ]	459.8 [mm], 5857.6 [m], ( 169.5 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:156.5 ,V:659.2 [mm]
Result	—	Area	1993.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	—
Light	6,6,3/6,6,3		



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#20, \$15	Date	2023/8/9 下午 02:17:45
Segment	1	Camera	1
Pattern	7790	Position[ x, y ]	272.8 [mm], 5856.5 [m], ( 170.7 [m] )
Type	縱向刀絲疵點	Size	H:41.5 ,V:220.0 [mm]
Result	-	Area	230.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#20, \$15	Date	2023/8/9 下午 02:17:45
Segment	1	Camera	1
Pattern	7790	Position[ x, y ]	250.3 [mm], 5856.6 [m], ( 170.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:93.0 ,V:508.0 [mm]
Result	-	Area	437.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#20, \$15	Date	2023/8/9 下午 02:17:45
Segment	1	Camera	1
Pattern	7790	Position[ x, y ]	502.5 [mm], 5857.0 [m], ( 170.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:48.3 ,V:258.4 [mm]
Result	-	Area	1362.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#20, \$15	Date	2023/8/9 下午 02:17:45
Segment	1	Camera	1
Pattern	7790	Position[ x, y ]	529.2 [mm], 5856.8 [m], ( 170.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:72.5 ,V:798.4 [mm]
Result	-	Area	3954.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#19, \$14	Date	2023/8/9 下午 02:17:44
Segment	1	Camera	1
Pattern	7789	Position[ x, y ]	403.9 [mm], 5855.6 [m], ( 171.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:22.9 ,V:153.6 [mm]
Result	-	Area	166.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#19, \$14	Date	2023/8/9 下午 02:17:44
Segment	1	Camera	1
Pattern	7789	Position[ x, y ]	570.2 [mm], 5856.3 [m], ( 170.9 [m] )
Type	点状疵点	Size	H:29.5 ,V:298.8 [mm]
Result	-	Area	233.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#19, \$14	Date	2023/8/9 下午 02:17:44
Segment	1	Camera	1
Pattern	7789	Position[ x, y ]	583.8 [mm], 5856.0 [m], ( 171.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:66.4 ,V:806.4 [mm]
Result	-	Area	432.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#19, \$14	Date	2023/8/9 下午 02:17:44
Segment	1	Camera	1
Pattern	7789	Position[ x, y ]	355.1 [mm], 5856.0 [m], ( 171.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:100.6 ,V:635.6 [mm]
Result	-	Area	1065.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#16, \$13	Date	2023/8/9 下午 02:17:35
Segment	1	Camera	1
Pattern	7775	Position[ x, y ]	95.1 [mm], 5844.8 [m], ( 182.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:240.7 ,V:167.2 [mm]
Result	-	Area	1254.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#16, \$13	Date	2023/8/9 下午 02:17:35
Segment	1	Camera	1
Pattern	7775	Position[ x, y ]	108.7 [mm], 5845.3 [m], ( 181.9 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:197.3 ,V:389.6 [mm]
Result	-	Area	1843.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#16, \$13	Date	2023/8/9 下午 02:17:35
Segment	1	Camera	1
Pattern	7775	Position[ x, y ]	809.4 [mm], 5844.8 [m], ( 182.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.5 ,V:104.4 [mm]
Result	-	Area	1906.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#16, \$13	Date	2023/8/9 下午 02:17:35
Segment	1	Camera	1
Pattern	7775	Position[ x, y ]	769.4 [mm], 5845.2 [m], ( 182.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.3 ,V:109.6 [mm]
Result	-	Area	2142.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#15, \$12	Date	2023/8/9 下午 02:17:35
Segment	1	Camera	1
Pattern	7774	Position[ x, y ]	691.3 [mm], 5844.1 [m], ( 183.1 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:37.1 ,V:180.0 [mm]
Result	-	Area	502.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#15, \$12	Date	2023/8/9 下午 02:17:35
Segment	1	Camera	1
Pattern	7774	Position[ x, y ]	267.0 [mm], 5844.3 [m], ( 182.9 [m] )
Type	縱向刀絲疵點	Size	H:53.7 ,V:530.8 [mm]
Result	-	Area	662.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#15, \$12	Date	2023/8/9 下午 02:17:35
Segment	1	Camera	1
Pattern	7774	Position[ x, y ]	792.6 [mm], 5844.4 [m], ( 182.7 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:208.3 ,V:49.2 [mm]
Result	-	Area	1599.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#15, \$12	Date	2023/8/9 下午 02:17:35
Segment	1	Camera	1
Pattern	7774	Position[ x, y ]	238.9 [mm], 5844.3 [m], ( 182.8 [m] )
Type	点状疵点横向刀絲	Size	H:305.9 ,V:501.6 [mm]
Result	-	Area	1623.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#14, \$11	Date	2023/8/9 下午 02:17:34
Segment	1	Camera	1
Pattern	7773	Position[ x, y ]	704.5 [mm], 5843.8 [m], ( 183.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:15.6 ,V:169.2 [mm]
Result	-	Area	262.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#14, \$11	Date	2023/8/9 下午 02:17:34
Segment	1	Camera	1
Pattern	7773	Position[ x, y ]	879.3 [mm], 5843.8 [m], ( 183.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:448.0 [mm]
Result	-	Area	355.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#14, \$11	Date	2023/8/9 下午 02:17:34
Segment	1	Camera	1
Pattern	7773	Position[ x, y ]	700.3 [mm], 5843.5 [m], ( 183.6 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:12.5 ,V:472.0 [mm]
Result	-	Area	478.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#14, \$11	Date	2023/8/9 下午 02:17:34
Segment	1	Camera	1
Pattern	7773	Position[ x, y ]	625.8 [mm], 5843.4 [m], ( 183.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:24.4 ,V:583.2 [mm]
Result	-	Area	924.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#13, \$10	Date	2023/8/9 下午 02:17:34
Segment	1	Camera	1
Pattern	7772	Position[ x, y ]	879.0 [mm], 5842.8 [m], ( 184.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:526.8 [mm]
Result	-	Area	286.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#13, \$10	Date	2023/8/9 下午 02:17:34
Segment	1	Camera	1
Pattern	7772	Position[ x, y ]	700.3 [mm], 5843.1 [m], ( 184.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:12.7 ,V:315.6 [mm]
Result	-	Area	368.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#13, \$10	Date	2023/8/9 下午 02:17:34
Segment	1	Camera	1
Pattern	7772	Position[ x, y ]	700.1 [mm], 5842.7 [m], ( 184.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:12.7 ,V:588.4 [mm]
Result	-	Area	586.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#13, \$10	Date	2023/8/9 下午 02:17:34
Segment	1	Camera	1
Pattern	7772	Position[ x, y ]	630.7 [mm], 5842.9 [m], ( 184.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:14.6 ,V:542.4 [mm]
Result	-	Area	872.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#12, \$9	Date	2023/8/9 下午 02:17:33
Segment	1	Camera	1
Pattern	7771	Position[ x, y ]	735.7 [mm], 5842.3 [m], ( 184.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:22.5 ,V:158.0 [mm]
Result	-	Area	55.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#12, \$9	Date	2023/8/9 下午 02:17:33
Segment	1	Camera	1
Pattern	7771	Position[ x, y ]	566.3 [mm], 5842.4 [m], ( 184.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:182.4 [mm]
Result	-	Area	102.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#12, \$9	Date	2023/8/9 下午 02:17:33
Segment	1	Camera	1
Pattern	7771	Position[ x, y ]	755.2 [mm], 5842.3 [m], ( 184.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:43.9 ,V:180.4 [mm]
Result	-	Area	160.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#12, \$9	Date	2023/8/9 下午 02:17:33
Segment	1	Camera	1
Pattern	7771	Position[ x, y ]	706.2 [mm], 5842.4 [m], ( 184.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:32.5 ,V:303.2 [mm]
Result	-	Area	334.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#9, \$8	Date	2023/8/9 下午 02:17:26
Segment	1	Camera	1
Pattern	7759	Position[ x, y ]	56.3 [mm], 5833.4 [m], ( 193.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.2 ,V:46.4 [mm]
Result	-	Area	15.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#9, \$8	Date	2023/8/9 下午 02:17:26
Segment	1	Camera	1
Pattern	7759	Position[ x, y ]	371.9 [mm], 5833.4 [m], ( 193.7 [m] )
Type	点状疵点	Size	H:1.5 ,V:46.0 [mm]
Result	-	Area	15.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#9, \$8	Date	2023/8/9 下午 02:17:26
Segment	1	Camera	1
Pattern	7759	Position[ x, y ]	240.1 [mm], 5833.4 [m], ( 193.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:50.4 [mm]
Result	-	Area	18.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#9, \$8	Date	2023/8/9 下午 02:17:26
Segment	1	Camera	1
Pattern	7759	Position[ x, y ]	696.9 [mm], 5833.4 [m], ( 193.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.0 ,V:45.2 [mm]
Result	-	Area	21.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#8, \$7	Date	2023/8/9 下午 02:17:25
Segment	1	Camera	1
Pattern	7758	Position[ x, y ]	240.1 [mm], 5832.6 [m], ( 194.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:54.0 [mm]
Result	-	Area	20.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#8, \$7	Date	2023/8/9 下午 02:17:25
Segment	1	Camera	1
Pattern	7758	Position[ x, y ]	696.9 [mm], 5832.3 [m], ( 194.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:65.2 [mm]
Result	-	Area	26.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#8, \$7	Date	2023/8/9 下午 02:17:25
Segment	1	Camera	1
Pattern	7758	Position[ x, y ]	240.3 [mm], 5832.3 [m], ( 194.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:127.2 [mm]
Result	-	Area	31.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#8, \$7	Date	2023/8/9 下午 02:17:25
Segment	1	Camera	1
Pattern	7758	Position[ x, y ]	564.8 [mm], 5832.3 [m], ( 194.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:152.8 [mm]
Result	-	Area	35.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#7, \$6	Date	2023/8/9 下午 02:17:24
Segment	1	Camera	1
Pattern	7757	Position[ x, y ]	564.8 [mm], 5831.9 [m], ( 195.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:65.2 [mm]
Result	-	Area	29.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	


## Defect information

No.	#7, \$6	Date	2023/8/9 下午 02:17:24
Segment	1	Camera	1
Pattern	7757	Position[ x, y ]	240.1 [mm], 5831.9 [m], ( 195.3 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:56.0 [mm]
Result	-	Area	30.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#7, \$6	Date	2023/8/9 下午 02:17:24
Segment	1	Camera	1
Pattern	7757	Position[ x, y ]	240.1 [mm], 5831.5 [m], ( 195.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:128.0 [mm]
Result	-	Area	45.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#7, \$6	Date	2023/8/9 下午 02:17:24
Segment	1	Camera	1
Pattern	7757	Position[ x, y ]	564.8 [mm], 5831.5 [m], ( 195.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:186.0 [mm]
Result	-	Area	52.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#6, \$5	Date	2023/8/9 下午 02:17:24
Segment	1	Camera	1
Pattern	7756	Position[ x, y ]	56.3 [mm], 5831.2 [m], ( 196.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:48.0 [mm]
Result	-	Area	22.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#6, \$5	Date	2023/8/9 下午 02:17:24
Segment	1	Camera	1
Pattern	7756	Position[ x, y ]	240.1 [mm], 5830.7 [m], ( 196.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:50.4 [mm]
Result	-	Area	24.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#6, \$5	Date	2023/8/9 下午 02:17:24
Segment	1	Camera	1
Pattern	7756	Position[ x, y ]	240.1 [mm], 5831.2 [m], ( 196.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:57.6 [mm]
Result	-	Area	24.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#6, \$5	Date	2023/8/9 下午 02:17:24
Segment	1	Camera	1
Pattern	7756	Position[ x, y ]	371.9 [mm], 5831.2 [m], ( 196.0 [m] )
Type	点状疵点	Size	H:1.5 ,V:48.0 [mm]
Result	-	Area	25.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#5, \$4	Date	2023/8/9 下午 02:17:23
Segment	1	Camera	1
Pattern	7755	Position[ x, y ]	565.0 [mm], 5830.0 [m], ( 197.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:18.8 [mm]
Result	-	Area	5.4 [mm2]
Inspection level	5/5,5/5,5/5,5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#5, \$4	Date	2023/8/9 下午 02:17:23
Segment	1	Camera	1
Pattern	7755	Position[ x, y ]	697.1 [mm], 5830.4 [m], ( 196.7 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:29.2 [mm]
Result	-	Area	13.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#4, \$3	Date	2023/8/9 下午 02:14:45
Segment	1	Camera	1
Pattern	7492	Position[ x, y ]	253.8 [mm], 5632.8 [m], ( 394.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:5.1 ,V:3.6 [mm]
Result	-	Area	12.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#3, \$2	Date	2023/8/9 下午 02:11:56
Segment	1	Camera	1
Pattern	7212	Position[ x, y ]	340.7 [mm], 5422.5 [m], ( 604.7 [m] )
Type	縱向刀絲疵點	Size	H:1.7 ,V:1.6 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 5

Inspected date : 2023/8/9 下午 12:59:28 ~ 2023/8/9 下午 02:20:08

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	42	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	6027.2 [m]	參照更新 : 週期10<平時>/週期10<平時>
Segments	1 ( 從左側 )	

## Defect information

No.	#2, \$1	Date	2023/8/9 下午 01:05:12
Segment	1	Camera	1
Pattern	569	Position[ x, y ]	823.1 [mm], 433.4 [m], ( 5593.7 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:3.7 ,V:3.6 [mm]
Result	-	Area	7.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
