

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#28, \$21	Date	2023/8/9 下午 05:05:08
Segment	1	Camera	1
Pattern	5775	Position[ x, y ]	17.4 [mm], 4341.0 [m], ( 2.0 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:29.5 ,V:17.6 [mm]
Result	-	Area	365.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#27, \$20	Date	2023/8/9 下午 05:04:34
Segment	1	Camera	1
Pattern	5709	Position[ x, y ]	159.3 [mm], 4291.5 [m], ( 51.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:3.9 ,V:3.2 [mm]
Result	-	Area	7.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#26, \$19	Date	2023/8/9 下午 05:04:28
Segment	1	Camera	1
Pattern	5697	Position[ x, y ]	494.0 [mm], 4282.3 [m], ( 60.7 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:3.2 [mm]
Result	-	Area	4.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#25, \$18	Date	2023/8/9 下午 05:04:27
Segment	1	Camera	1
Pattern	5696	Position[ x, y ]	523.8 [mm], 4281.5 [m], ( 61.5 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:1.6 [mm]
Result	-	Area	2.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#25, \$18	Date	2023/8/9 下午 05:04:27
Segment	1	Camera	1
Pattern	5696	Position[ x, y ]	493.0 [mm], 4281.9 [m], ( 61.1 [m] )
Type	縱向刀絲疵點	Size	H:2.2 ,V:2.8 [mm]
Result	-	Area	4.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#24, \$17	Date	2023/8/9 下午 05:04:25
Segment	1	Camera	1
Pattern	5692	Position[ x, y ]	121.9 [mm], 4278.9 [m], ( 64.1 [m] )
Type	縱向刀絲疵點	Size	H:2.0 ,V:1.2 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	檢查範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$16	Date	2023/8/9 下午 05:03:49
Segment	1	Camera	1
Pattern	5622	Position[ x, y ]	205.7 [mm], 4225.9 [m], ( 117.0 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:13.6 [mm]
Result	-	Area	8.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		


Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$16	Date	2023/8/9 下午 05:03:49
Segment	1	Camera	1
Pattern	5622	Position[ x, y ]	772.3 [mm], 4226.2 [m], ( 116.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:66.0 [mm]
Result	-	Area	11.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$16	Date	2023/8/9 下午 05:03:49
Segment	1	Camera	1
Pattern	5622	Position[ x, y ]	129.3 [mm], 4226.2 [m], ( 116.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.8 [mm]
Result	-	Area	17.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#21, \$16	Date	2023/8/9 下午 05:03:49
Segment	1	Camera	1
Pattern	5622	Position[ x, y ]	450.3 [mm], 4226.2 [m], ( 116.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:96.0 [mm]
Result	-	Area	34.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$15	Date	2023/8/9 下午 05:03:48
Segment	1	Camera	1
Pattern	5621	Position[ x, y ]	385.4 [mm], 4225.5 [m], ( 117.4 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:14.0 [mm]
Result	-	Area	6.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$15	Date	2023/8/9 下午 05:03:48
Segment	1	Camera	1
Pattern	5621	Position[ x, y ]	205.7 [mm], 4225.9 [m], ( 117.0 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:13.6 [mm]
Result	-	Area	8.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$15	Date	2023/8/9 下午 05:03:48
Segment	1	Camera	1
Pattern	5621	Position[ x, y ]	450.1 [mm], 4225.8 [m], ( 117.2 [m] )
Type	縱向刀絲疵點	Size	H:0.2 ,V:96.0 [mm]
Result	-	Area	14.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#20, \$15	Date	2023/8/9 下午 05:03:48
Segment	1	Camera	1
Pattern	5621	Position[ x, y ]	129.5 [mm], 4225.8 [m], ( 117.2 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:85.6 [mm]
Result	-	Area	27.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#19, \$14	Date	2023/8/9 下午 05:03:48
Segment	1	Camera	1
Pattern	5620	Position[ x, y ]	229.1 [mm], 4224.8 [m], ( 118.2 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:8.0 [mm]
Result	-	Area	4.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#19, \$14	Date	2023/8/9 下午 05:03:48
Segment	1	Camera	1
Pattern	5620	Position[ x, y ]	385.4 [mm], 4225.2 [m], ( 117.8 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:13.6 [mm]
Result	-	Area	5.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#19, \$14	Date	2023/8/9 下午 05:03:48
Segment	1	Camera	1
Pattern	5620	Position[ x, y ]	68.5 [mm], 4224.8 [m], ( 118.2 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:14.0 [mm]
Result	-	Area	6.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3



## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#19, \$14	Date	2023/8/9 下午 05:03:48
Segment	1	Camera	1
Pattern	5620	Position[ x, y ]	385.4 [mm], 4224.8 [m], ( 118.2 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:13.6 [mm]
Result	-	Area	6.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#18, \$13	Date	2023/8/9 下午 05:03:47
Segment	1	Camera	1
Pattern	5619	Position[ x, y ]	92.1 [mm], 4224.2 [m], ( 118.8 [m] )
Type	縱向刀絲疵點	Size	H:13.9 ,V:26.8 [mm]
Result	-	Area	4.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			
		1/20	

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#18, \$13	Date	2023/8/9 下午 05:03:47
Segment	1	Camera	1
Pattern	5619	Position[ x, y ]	531.1 [mm], 4224.4 [m], ( 118.5 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:14.0 [mm]
Result	-	Area	4.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#18, \$13	Date	2023/8/9 下午 05:03:47
Segment	1	Camera	1
Pattern	5619	Position[ x, y ]	207.6 [mm], 4224.4 [m], ( 118.5 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:13.2 [mm]
Result	-	Area	5.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	21	檢查範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#18, \$13	Date	2023/8/9 下午 05:03:47
Segment	1	Camera	1
Pattern	5619	Position[ x, y ]	386.1 [mm], 4224.4 [m], ( 118.6 [m] )
Type	縱向刀絲疵點	Size	H:5.6 ,V:14.0 [mm]
Result	-	Area	5.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#17, \$12	Date	2023/8/9 下午 05:03:47
Segment	1	Camera	1
Pattern	5618	Position[ x, y ]	709.8 [mm], 4223.7 [m], ( 119.3 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:8.4 [mm]
Result	-	Area	2.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#17, \$12	Date	2023/8/9 下午 05:03:47
Segment	1	Camera	1
Pattern	5618	Position[ x, y ]	95.1 [mm], 4223.1 [m], ( 119.9 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:6.0 [mm]
Result	-	Area	2.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#17, \$12	Date	2023/8/9 下午 05:03:47
Segment	1	Camera	1
Pattern	5618	Position[ x, y ]	229.1 [mm], 4223.7 [m], ( 119.3 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:13.6 [mm]
Result	-	Area	3.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#14, \$11	Date	2023/8/9 下午 05:03:39
Segment	1	Camera	1
Pattern	5602	Position[ x, y ]	773.1 [mm], 4211.6 [m], ( 131.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:98.0 [mm]
Result	-	Area	136.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#14, \$11	Date	2023/8/9 下午 05:03:39
Segment	1	Camera	1
Pattern	5602	Position[ x, y ]	450.5 [mm], 4211.2 [m], ( 131.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:97.6 [mm]
Result	-	Area	140.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

ID information ( No. 2 )




商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3



Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

Defect information

No.	#14, \$11	Date	2023/8/9 下午 05:03:39
Segment	1	Camera	1
Pattern	5602	Position[ x, y ]	450.5 [mm], 4211.6 [m], ( 131.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:98.0 [mm]
Result	-	Area	147.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#14, \$11	Date	2023/8/9 下午 05:03:39
Segment	1	Camera	1
Pattern	5602	Position[ x, y ]	130.0 [mm], 4211.6 [m], ( 131.4 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:98.0 [mm]
Result	-	Area	151.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#13, \$10	Date	2023/8/9 下午 05:03:38
Segment	1	Camera	1
Pattern	5601	Position[ x, y ]	450.5 [mm], 4210.4 [m], ( 132.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	91.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#13, \$10	Date	2023/8/9 下午 05:03:38
Segment	1	Camera	1
Pattern	5601	Position[ x, y ]	772.8 [mm], 4210.8 [m], ( 132.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	105.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#13, \$10	Date	2023/8/9 下午 05:03:38
Segment	1	Camera	1
Pattern	5601	Position[ x, y ]	129.7 [mm], 4210.8 [m], ( 132.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:98.0 [mm]
Result	-	Area	114.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#13, \$10	Date	2023/8/9 下午 05:03:38
Segment	1	Camera	1
Pattern	5601	Position[ x, y ]	450.5 [mm], 4210.8 [m], ( 132.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.2 ,V:98.0 [mm]
Result	-	Area	123.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#12, \$9	Date	2023/8/9 下午 05:03:37
Segment	1	Camera	1
Pattern	5600	Position[ x, y ]	129.7 [mm], 4210.1 [m], ( 132.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	46.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#12, \$9	Date	2023/8/9 下午 05:03:37
Segment	1	Camera	1
Pattern	5600	Position[ x, y ]	773.1 [mm], 4209.7 [m], ( 133.3 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:96.8 [mm]
Result	-	Area	56.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#12, \$9	Date	2023/8/9 下午 05:03:37
Segment	1	Camera	1
Pattern	5600	Position[ x, y ]	450.5 [mm], 4210.1 [m], ( 132.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.0 ,V:98.0 [mm]
Result	-	Area	65.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#12, \$9	Date	2023/8/9 下午 05:03:37
Segment	1	Camera	1
Pattern	5600	Position[ x, y ]	772.8 [mm], 4210.1 [m], ( 132.9 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:1.7 ,V:98.0 [mm]
Result	-	Area	66.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#11, \$8	Date	2023/8/9 下午 05:03:37
Segment	1	Camera	1
Pattern	5599	Position[ x, y ]	748.4 [mm], 4208.9 [m], ( 134.1 [m] )
Type	縱向刀絲疵點	Size	H:0.5 ,V:73.2 [mm]
Result	-	Area	12.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#11, \$8	Date	2023/8/9 下午 05:03:37
Segment	1	Camera	1
Pattern	5599	Position[ x, y ]	702.0 [mm], 4209.3 [m], ( 133.7 [m] )
Type	縱向刀絲疵點	Size	H:0.7 ,V:61.6 [mm]
Result	-	Area	12.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#11, \$8	Date	2023/8/9 下午 05:03:37
Segment	1	Camera	1
Pattern	5599	Position[ x, y ]	871.4 [mm], 4209.4 [m], ( 133.5 [m] )
Type	縱向刀絲疵點	Size	H:1.0 ,V:14.0 [mm]
Result	-	Area	12.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#11, \$8	Date	2023/8/9 下午 05:03:37
Segment	1	Camera	1
Pattern	5599	Position[ x, y ]	130.0 [mm], 4209.3 [m], ( 133.7 [m] )
Type	縱向刀絲疵點	Size	H:0.2 ,V:96.4 [mm]
Result	-	Area	12.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#10, \$7	Date	2023/8/9 下午 05:03:36
Segment	1	Camera	1
Pattern	5598	Position[ x, y ]	409.5 [mm], 4208.7 [m], ( 134.3 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:14.0 [mm]
Result	-	Area	8.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#10, \$7	Date	2023/8/9 下午 05:03:36
Segment	1	Camera	1
Pattern	5598	Position[ x, y ]	553.8 [mm], 4208.3 [m], ( 134.7 [m] )
Type	縱向刀絲疵點	Size	H:5.6 ,V:14.0 [mm]
Result	-	Area	8.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#10, \$7	Date	2023/8/9 下午 05:03:36
Segment	1	Camera	1
Pattern	5598	Position[ x, y ]	733.0 [mm], 4208.7 [m], ( 134.3 [m] )
Type	縱向刀絲疵點	Size	H:5.4 ,V:14.0 [mm]
Result	-	Area	9.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

Defect information

No.	#10, \$7	Date	2023/8/9 下午 05:03:36
Segment	1	Camera	1
Pattern	5598	Position[ x, y ]	733.3 [mm], 4208.3 [m], ( 134.7 [m] )
Type	縱向刀絲疵點	Size	H:5.6 ,V:14.0 [mm]
Result	-	Area	9.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	21	檢查範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#7, \$6	Date	2023/8/9 下午 05:03:15
Segment	1	Camera	1
Pattern	5556	Position[ x, y ]	788.2 [mm], 4176.5 [m], ( 166.4 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:184.6 ,V:102.8 [mm]
Result	-	Area	937.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	



## Coil Information

Total defects	21	檢查範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#7, \$6	Date	2023/8/9 下午 05:03:15
Segment	1	Camera	1
Pattern	5556	Position[ x, y ]	732.8 [mm], 4176.8 [m], ( 166.2 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:255.1 ,V:663.2 [mm]
Result	-	Area	1311.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	檢查範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	

## Defect information

No.	#7, \$6	Date	2023/8/9 下午 05:03:15
Segment	1	Camera	1
Pattern	5556	Position[ x, y ]	125.1 [mm], 4176.9 [m], ( 166.1 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:185.3 ,V:182.8 [mm]
Result	-	Area	1627.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#7, \$6	Date	2023/8/9 下午 05:03:15
Segment	1	Camera	1
Pattern	5556	Position[ x, y ]	116.6 [mm], 4176.6 [m], ( 166.3 [m] )
Type	点状疵点縱向刀絲疵點橫向刀絲	Size	H:242.4 ,V:384.4 [mm]
Result	-	Area	1759.4 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)



商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#6, \$5	Date	2023/8/9 下午 05:03:15
Segment	1	Camera	1
Pattern	5555	Position[ x, y ]	156.6 [mm], 4175.8 [m], ( 167.2 [m] )
Type	面狀重疵点	Size	H:22.9 ,V:40.4 [mm]
Result	-	Area	642.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#6, \$5	Date	2023/8/9 下午 05:03:15
Segment	1	Camera	1
Pattern	5555	Position[ x, y ]	156.1 [mm], 4175.7 [m], ( 167.2 [m] )
Type	淡瑕疵縱向刀絲疵點	Size	H:23.2 ,V:71.2 [mm]
Result	-	Area	683.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#6, \$5	Date	2023/8/9 下午 05:03:15
Segment	1	Camera	1
Pattern	5555	Position[ x, y ]	100.2 [mm], 4175.8 [m], ( 167.2 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:136.7 ,V:202.8 [mm]
Result	-	Area	836.8 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#6, \$5	Date	2023/8/9 下午 05:03:15
Segment	1	Camera	1
Pattern	5555	Position[ x, y ]	143.4 [mm], 4176.2 [m], ( 166.8 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:185.3 ,V:155.2 [mm]
Result	-	Area	1848.3 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)




商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	





## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#5, \$4	Date	2023/8/9 下午 05:03:14
Segment	1	Camera	1
Pattern	5554	Position[ x, y ]	699.1 [mm], 4175.0 [m], ( 168.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:122.4 [mm]
Result	-	Area	83.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image	Reference image	Shape image
		

G	M	G	M
			

# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#5, \$4	Date	2023/8/9 下午 05:03:14
Segment	1	Camera	1
Pattern	5554	Position[ x, y ]	688.3 [mm], 4175.4 [m], ( 167.6 [m] )
Type	面狀重疵點	Size	H:25.6 ,V:185.6 [mm]
Result	-	Area	300.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#5, \$4	Date	2023/8/9 下午 05:03:14
Segment	1	Camera	1
Pattern	5554	Position[ x, y ]	280.6 [mm], 4175.5 [m], ( 167.5 [m] )
Type	面狀重疵點	Size	H:28.6 ,V:450.8 [mm]
Result	-	Area	640.5 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#5, \$4	Date	2023/8/9 下午 05:03:14
Segment	1	Camera	1
Pattern	5554	Position[ x, y ]	273.1 [mm], 4175.4 [m], ( 167.6 [m] )
Type	面狀重疵點縱向刀絲疵點	Size	H:59.8 ,V:575.2 [mm]
Result	-	Area	2723.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/9 下午 05:03:13
Segment	1	Camera	1
Pattern	5553	Position[ x, y ]	760.8 [mm], 4174.4 [m], ( 168.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:39.8 ,V:180.8 [mm]
Result	-	Area	135.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/9 下午 05:03:13
Segment	1	Camera	1
Pattern	5553	Position[ x, y ]	882.4 [mm], 4174.5 [m], ( 168.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:232.4 [mm]
Result	-	Area	160.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/9 下午 05:03:13
Segment	1	Camera	1
Pattern	5553	Position[ x, y ]	704.2 [mm], 4174.4 [m], ( 168.6 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:12.9 ,V:384.0 [mm]
Result	-	Area	314.0 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#4, \$3	Date	2023/8/9 下午 05:03:13
Segment	1	Camera	1
Pattern	5553	Position[ x, y ]	567.2 [mm], 4174.5 [m], ( 168.5 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.7 ,V:330.4 [mm]
Result	-	Area	427.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長
顧客名		Ex1
CODE番号		Ex2
基材		Ex3


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm] 寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新
Segments	1 ( 從左側 )	


## Defect information

No.	#3, \$2	Date	2023/8/9 下午 05:03:13
Segment	1	Camera	1
Pattern	5552	Position[ x, y ]	381.0 [mm], 4174.2 [m], ( 168.8 [m] )
Type	縱向刀絲疵點	Size	H:8.1 ,V:110.0 [mm]
Result	-	Area	26.9 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		


## Defect information

No.	#3, \$2	Date	2023/8/9 下午 05:03:13
Segment	1	Camera	1
Pattern	5552	Position[ x, y ]	568.5 [mm], 4174.2 [m], ( 168.8 [m] )
Type	点状疵点	Size	H:1.5 ,V:71.6 [mm]
Result	-	Area	28.1 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	


## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#3, \$2	Date	2023/8/9 下午 05:03:13
Segment	1	Camera	1
Pattern	5552	Position[ x, y ]	769.4 [mm], 4174.0 [m], ( 169.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:26.4 ,V:179.2 [mm]
Result	-	Area	34.2 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image





# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#3, \$2	Date	2023/8/9 下午 05:03:13
Segment	1	Camera	1
Pattern	5552	Position[ x, y ]	444.4 [mm], 4174.0 [m], ( 169.0 [m] )
Type	縱向刀絲疵點	Size	H:27.3 ,V:129.6 [mm]
Result	-	Area	44.6 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		



Defect image



Reference image



Shape image



# Inspection Result (Individual Data)

Lot number : 8

Inspected date : 2023/8/9 下午 04:15:13 ~ 2023/8/9 下午 05:05:15

## ID information (No. 2)

商品名	標準透明6-6-3	周長	
顧客名		Ex1	
CODE番号		Ex2	
基材		Ex3	

## Coil Information

Total defects	21	検査範圍 : 83.6 ~ 1024.2 [mm]	寬度 : 940.6 [mm]
Web length	4343.0 [m]	參照更新 : 無更新/無更新	
Segments	1 ( 從左側 )		

## Defect information

No.	#2, \$1	Date	2023/8/9 下午 04:19:23
Segment	1	Camera	1
Pattern	481	Position[ x, y ]	880.7 [mm], 367.9 [m], ( 3975.0 [m] )
Type	点状疵点縱向刀絲疵點	Size	H:2.4 ,V:4.0 [mm]
Result	-	Area	4.7 [mm2]
Inspection level	5/5,5/5,5/5,5/5,5/5	Label	-
Light	6,6,3/6,6,3		

Defect image



Reference image



Shape image

