

Informe de Inspección - Tramo: T03

Fecha: 2025-11-10 12:06:58

[00:02:21] Inicio de inspeccion




[00:04:23] Curvatura vertical arriba 0.20M



[00:05:57] Hueco. Tubo colapsado 100%



[00:06:35] Pedazo de tubo incrustado 0.30M



[00:06:53] Fin de inspeccion

