


Kampala City Council Authority Road Report

For A Better City

Area	Paved	Traffic	Traffic_Flow	Pothole
Mawanda Road	Gravel	High	two-way	Potholes Detected
Mpererwe	Gravel	High	two-way	Potholes Detected
Kasangati	Gravel	Low	two-way	Potholes Detected
Nangabo Wetland	Earth	High	two-way	No potholes Detected
Wandegeya	Gravel	High	two-way	No potholes Detected
Kisingiri Street	Earth	High	two-way	Potholes Detected
Kisingiri Street	Earth	Low	two-way	Potholes Detected
Kisingiri Street	Earth	Medium	two-way	Potholes Detected
Mpererwe	Earth	Low	two-way	Potholes Detected
Mawanda Road	Earth	Low	two-way	Potholes Detected
Mawanda Road	Earth	High	two-way	Potholes Detected
Makerere	Gravel	Low	two-way	Potholes Detected

Piechart showing classification of Roads in %



Advisory Report

Areas that are both Gravel and with potholes and high traffic :

- Mawanda Road
- Mpererwe

Recommendation: The road should urgently be maintained in order to handle the current traffic capacity.

Areas with High Traffic, Earth and potholes :

- Kisingiri Street
- Mawanda Road

Recommendation: A road should be constructed in the analyzed areas to improve the traffic capacity

Areas with High Traffic, paved and no potholes :

Wandegeya

Recommendation: The road in the analyzed areas should be widened and maintained to lower the traffic congestion

Areas with no potholes,not paved and Traffic not High :

Recommendation: The road should be noted and monitored for future purposes of road construction

- end of report -