


Kampala City Council Authority Road Report

For A Better City

Area	Paved	Traffic	Traffic_Flow	Pothole
Mawanda Road	Gravel	High	two-way	Potholes Detected
Mpererwe	Gravel	High	two-way	Potholes Detected
Kasangati	Gravel	Low	two-way	Potholes Detected
Nangabo Wetland	Earth	High	two-way	No potholes Detected
Wandegeya	Gravel	High	two-way	No potholes Detected
Kisingiri Street	Earth	High	two-way	Potholes Detected
Kisingiri Street	Earth	Low	two-way	Potholes Detected



Areas that are both Gravel and with potholes :

Mawanda Road

Mpererwe

Kasangati

Areas that are both Earth and with potholes :

Kisingiri Street

Kisingiri Street

Areas with High Traffic, Earth and potholes :

Kisingiri Street

- end of report -