


Kampala City Council Authority Road Report

For A Better City

| Area | Paved | Traffic | Traffic_Flow | Pothole |
|--------------|--------|---------|--------------|-------------------|
| Mpererwe | yes | high | two-way | Potholes Detected |
| Mpererwe | Earth | High | two-way | Potholes Detected |
| kalerwe | Earth | Low | two-way | Potholes Detected |
| mawanda road | Gravel | High | two-way | Potholes Detected |
| Mpererwe | Gravel | High | two-way | Potholes Detected |
| Mpererwe | Gravel | High | two-way | Potholes Detected |



Areas that require attention :

Mpererwe

Mpererwe

kalerwe

mawanda road

Mpererwe

Mpererwe

- end of report -