

---

May 16,2023

From: Angel Cruz

This report is a follow up to the safety inspection completed on May 16,2023. The purpose of the inspection was to identify potential safety hazards and/or OSHA violations. Attached is a list of observations and recommendations based on the conditions present at the time of my visit. Please review the report and verify that all potential hazards are corrected. If you have any questions or require additional information after reviewing this report, please don't hesitate to contact me.

Sincerely,

Angel Cruz  
LF Jennings, Inc.  
Safety Department  
(571) 389-4558  
angel.cruz@lfjennings.net



---

**May 16,2023**

**7000 Carnation**

Reported by: Angel Cruz

On-site Supervisor: Joe Doohan

---

### observation

We found a wire rope in bad condition and no tag on it. We took it out of service.

None



## observation

Fuel tank needs hard barrier around also a spill kit and a fire extinguisher. Also we recommend that we put poles in both entrance with flagging to warn truck drivers about the power lines above.

None



**observation**

Extension cords check out okay today.


None



**observation**

Concrete crew with the proper P. P. E. for the job.

None



observation

Concrete crew with plenty of rebarcaps for the job.

None






**observation**

Concrete. Fire extinguisher on site check out okay.

None





**observation**

Concrete crew good job with the rebar caps on place.

None



<b>observation</b>
We found a wire rope in bad condition and no tag on it. We took it out of service.
<b>observation</b>
Fuel tank needs hard barrier around also a spill kit and a fire extinguisher. Also we recommend that we put poles in both entrance with flagging to warn truck drivers about the power lines above.
<b>observation</b>
Extension cords check out okay today.
<b>observation</b>
Concrete crew with the proper P. P. E. for the job.
<b>observation</b>
Concrete crew with plenty of rebarcaps for the job.
<b>observation</b>
Concrete. Fire extinguisher on site check out okay.
<b>observation</b>
Concrete crew good job with the rebar caps on place.