

---

May 16,2023

From: Alex Granados

This report is a follow up to the safety inspection completed on May 16,2023. The purpose of the inspection was to identify potential safety hazards and/or OSHA violations. Attached is a list of observations and recommendations based on the conditions present at the time of my visit. Please review the report and verify that all potential hazards are corrected. If you have any questions or require additional information after reviewing this report, please don't hesitate to contact me.

Sincerely,

Alex Granados  
LF Jennings, Inc.  
Safety Department  
(703) 929-1626  
[alex.granados@lfjennings.net](mailto:alex.granados@lfjennings.net)



---

**May 16,2023**

**White Oak Town Center**


Reported by: Alex Granados

On-site Supervisor: Torey Mancari

## observation

The scaffold has a warning line on the inside and outside to keep workers away, great job Ramon's crew.

None



## observation

Concrete: Elias is working off a ladder and knowing that he needed to use both hands he's tied-off, the one correction we made was that he needed to use a cross-arm strap instead of the tie-back on the lanyard.

None



**observation**

The guy on the left is not clipped-off, corrected immediately.

None



---

**observation**

Excavation is protected with danger tape all the way around, looks good, thank you.

None



## observation

Excavations: when using rebars to install warning lines, they need to be protected with caps, i found 3 rebars without caps, corrected

None



**observation**

The scaffold has a warning line on the inside and outside to keep workers away, great job Ramon's crew.

**observation**

Concrete: Elias is working off a ladder and knowing that he needed to use both hands he's tied-off, the one correction we made was that he needed to use a cross-arm strap instead of the tie-back on the lanyard.

**observation**

The guy on the left is not clipped-off, corrected immediately.

**observation**

Excavation is protected with danger tape all the way around, looks good, thank you.

**observation**

Excavations: when using rebars to install warning lines, they need to be protected with caps, i found 3 rebars without caps, corrected