



WEEK3

18.Mar-25.Mar

Xingchen MA



I adjusted the problem that occurred last time, re-laser cut, and now it is successful



The printing result is a failure. The reasons are as follows: 1. Due to precision issues, my connection part cannot be inserted into the gap. I can scale my design to solve this problem; 2. Even if the connection part can be inserted, it is not long enough to provide a certain degree of mobility for the entire component.

