

## 2022-05-24 18:16:25 - Validation Report: FAIL

BGP - PASS

DHCPRelay - PASS

LLDP - FAIL

- No LLDP IEEE 802.1 VLAN Name (Subtype 3) Founded
- Incorrect Maximum Frame Size - Input:9214, Found: 9216
- Incorrect ETS Class Bandwidth Configured:  
Input:0:48,1:0,2:0,3:50,4:0,5:2,6:0,7:0  
Found: 0:46,1:1,2:1,3:48,4:1,5:1,6:1,7:1

VLAN - PASS

TimeDate: 2022-04-14T22:38:35.099334Z

ResultSummary:

BGP - PASS: []

DHCPRelay - PASS: []

LLDP - FAIL:

- No LLDP IEEE 802.1 VLAN Name (Subtype 3) Founded
- 'Incorrect Maximum Frame Size - Input:9214, Found: 9216'
- |-

Incorrect ETS Class Bandwidth Configured:

Input:0:48,1:0,2:0,3:50,4:0,5:2,6:0,7:0

Found: 0:46,1:1,2:1,3:48,4:1,5:1,6:1,7:1

VLAN - PASS: []

VLANResult:

vlanids:

- 710
- 711
- 712

LLDPResult:

sysdes: "Dell EMC Networking OS10 Enterprise.\r\nCopyright (c) 1999-2021 by Dell  
Inc. All Rights Reserved.\r\nSystem Description: OS10 Enterprise.\r\nOS Version:  
10.5.3.0.\r\nSystem Type: S5248F-VM"

portname: ethernet1/1/1

chasisid: 0cc23e6c0000

chasisidtype: MAC Address

vlanid: 710

ieee8021subtype3: []

mtu: 9216

ets:

etstotalpg: 8

etsbwbypgid:

- 0: 46
- 1: 1
- 2: 1
- 3: 48
- 4: 1
- 5: 1
- 6: 1
- 7: 1

pfc:

pfcmaxclasses: 8

pfcpriorityenabled:

- 0: 0
- 1: 0
- 2: 0
- 3: 1
- 4: 0
- 5: 0
- 6: 0
- 7: 0

DHCPResult:

dhcppacketdetected: true

relayagentip: 10.10.12.1

BGPResult:

bgptcppacketdetected: true  
switchinterfaceip: 10.10.10.1  
switchinterfacemac: 0c:c2:3e:6c:00:a1  
hostinterfaceip: 10.10.10.100  
hostinterfacemac: 0c:b0:99:4a:00:01