

BDI - PART REQUEST

Tech name: Robert Leeming

Type: Normal      Priority: Quote

Vin #: 1M2AX33C0DM010111

Engine #: 73332986

Comments:

if repair kit only available 6 hrs labour and i will need the rebuild tool kit.

if complete assembly avail - 2.5 hours no special tools

PARTS:

<u>SEG</u>	<u>DESCRIPTION</u>	<u>QTY</u>
5	horton fan hub assmebly - reman ok	1