


REFLEX - GYRO

QUALITY CHECK REPORT

09 Jun 2020



Project ID: dsf
Borehole ID: sdf
Project location: sdf
Client: sdf
Surveyor: sdf
Reporter: sdf
Survey date: 2020-06-09

DRILLING COLLAR PARAMETERS

Easting: 620696.42

Northing: 4631589.19

Elevation: 1378.88

Dip: 43.0 deg

Azimuth: 43.0 deg

Drill diameter: 96.0 mm

SURVEY PARAMETERS

Survey start: 0 m

Survey end: 243 m

Survey interval: 3 m

Number of stations: 82

Survey run on: Wireline

Angular units: Degree

Linear units: Meter

Survey 1

	Dip	Azimuth	Easting	Northing	Elevation
Start of Survey	-71.39	90.0	620696.42	4631589.19	1378.88
End of Survey	-73.88	94.03	620766.45	4631587.12	1146.23

Survey 2

	Dip	Azimuth	Easting	Northing	Elevation
Start of Survey	-71.35	90.0	620696.42	4631589.19	1378.88
End of Survey	-73.88	93.79	620766.53	4631587.39	1146.26


End of Survey Difference

Dip	Azimuth	Easting	Northing	Elevation
-0.0	0.24	-0.08	-0.27	-0.02


End of Survey Misclosure



Depth	Misclosure	Misclosure %	Quality
243	0.28	0.12	Passed




Misclosure





Borehole Path










UP and Down Deviation



Left and Right Deviation

