

Version 4.1 firmware for the 4052/54 can now be ordered from the field. The part number is 050-1282-01. This is not a code 18 upgrade, instruments upgraded that are not on contract, warranty or rental will be charged to the customer at the MAS Board (670-6030-XX) exchange price - refer to the SQI. Refer to Wizards Workshop Issue 10-5, pages 34 & 35 for Version 4.1 firmware checksums.

4052/54 +15 REGULATOR CIRCUIT #M39801

The Mod to solve this problem is as follows: (refer to figure 1)

- [illegible]

--Darrell McGiverin  
63/503, ext. 3786