

Figure 10.19.: Scenario B – Fire origin at 2nd floor Shop space




Figure 10.20.: Stagnant region due to atrium ceiling obstruction