

Once the gauge has initialized and calibrated...

Block up your aircraft so it's stationary and can't move.

Place a sensor on each of the control surfaces parallel with the hinge line.

Open web page showing sensors (ie [192.168.1.1/?c=50](http://192.168.1.1/?c=50) )

Move the control surfaces to their neutral position and press the zero sensor button.

Both sensors should be reading zero degrees & zero mm travel.

You are now ready to measure the movement of the control surfaces from their neutral position.