

## Hylan Datacom &amp; Electrical

## Daily Work Report - Pole Work

Mobilitie ☐Extenet ☒Crown Castle ☐

Date:

9/6/17

Node #

14092

Job#

113 - 0123

## Manpower Information

Name:	Howard Olshewitz	Reg:	1.5	OT:	318
Name:	Chris Dropp	Reg:	1.5	OT:	167
Name:		Reg:		OT:	291
Name:		Reg:		OT:	109

## Description of Work

Qty

Total

REMOVE AND DISPOSE EXISTING POLE (ALL POLE TYPES).		
FURNISH AND INSTALL TYPE 'M' POLE		
REMOVE AND RE-INSTALL TYPE M POLE		
REMOVE AND REINSTALL TYPE OCTOGONAL POLE		
CONSTRUCT FS TYPE FOUNDATION		
CONSTRUCT SPIDER FOUNDATION		
TEMP OUT TRAFFIC SVCS. UP TO 10LF - \$650.00 *OVER 10LF WILL BE \$97.50 EA. LF*		
TEMP PYLON		
REMOVE AND REINSTALL SIGNS ON POLE EA. (Up to 3)		
REMOVE AND DISPOSE DUSKY LIGHT EA		
FURNISH & INSTALL OCTOGONAL POLE		
REPLACE BASE (FS)		
REPLACE BASE (M2)		
FURNISH AND INSTALL 8' ARM AND LUMINAIRE		
F & I (2) RUNS PER NYC DOT 13C/314 TRAFFIC CABLE / PER FOOT		
F & I 2(2) #10 & (1) #8 GROUND TRAFFIC FEED CABLE / PER FOOT		
GROUND 2" PIPE STUBS IN POLE BASE EA.		
SPLICE FEED EA.		
TAP & FUSE		
FURNISH AND INSTALL POWER CABLE (2) #14 IMSA / PER LF		
REMOVE & REPLACE FLOODLIGHT		
TRANSFER EXISTING ARM & LUMINAIRE		
REPLACE CONTROLLER		
FIX EXISTING DOOR		
FURNISH & INSTALL FIRE ALARM PHOTO ELECTRIC CELL		
PAINT POLE, ARM, AND BASE EA		
INSTALL 5' M-2A MAST ARM EXTENSION ASSEMBLY WITH FITTINGS		
FLAGMEN PER DAY *\$25.00 PER HOUR		
GFI RECEPTACLE INSTALL		

## POWER AT LOCATION

Amsterdam Ave + 78th St

SWC

## Job Location:

Edison facility in SWC

## Description of Work:

Arrived at location, the shaft was round  
Base + Anchor Rods Rotted out.Needs new foundation + New shaft. Also  
Twin Arms Needs one offset light arm Adapter  
Plate + U Bolts. Bottom one looks rotted + rusted

Sent Pics Back to Shop