

# Damage Detection Report

Generated on: 2025-05-18 23:00:38

Total Images Processed: 11

## Policy Details:


Policy Types:

- Comprehensive
- Zero Depreciation
- Own Damage
- Third-Party Liability Insurance
- Collision Insurance

Policy Start Date: 2025-05-18

Policy Renewal Date: 2026-05-18

Damage Type	Count	Covered
rear-bumper-dent	4	Yes
bonnet-dent	2	Yes
Headlight-damage	4	Yes
front-bumper-dent	3	Yes
doorrouter-dent	3	Yes
fender-dent	3	Yes
quaterpanel-dent	1	Yes
boot-dent	1	Yes




## Image 1 of 11

Original Image



Detected Image



### Detected Objects:

#### Class

rear-bumper-dent

#### Accuracy

88.57%

## Image 2 of 11

Original Image



Detected Image



### Detected Objects:


Class	Accuracy
bonnet-dent	89.40%
Headlight-damage	86.69%
front-bumper-dent	77.85%

## Image 3 of 11

Original Image



Detected Image



**Detected Objects:**

**Class**

doorrouter-dent

**Accuracy**

90.83%

## Image 4 of 11

Original Image



Detected Image



### Detected Objects:

Class	Accuracy
rear-bumper-dent	53.44%
rear-bumper-dent	38.35%



## Image 5 of 11

Original Image



Detected Image



**Detected Objects:**

**Class**

front-bumper-dent

**Accuracy**


90.55%

## Image 6 of 11

Original Image



Detected Image



### Detected Objects:

Class	Accuracy
bonnet-dent	81.95%
front-bumper-dent	80.60%
Headlight-damage	32.69%



## Image 7 of 11

Original Image



Detected Image



### Detected Objects:

#### Class

Headlight-damage

fender-dent

doorouter-dent

#### Accuracy

94.84%

88.24%


49.02%

## Image 8 of 11

Original Image



Detected Image



### Detected Objects:


Class	Accuracy
Headlight-damage	87.78%
fender-dent	54.69%
fender-dent	31.77%

# Image 9 of 11

Original Image



Detected Image



Detected Objects:

Class	Accuracy
doorrouter-dent	86.74%
quaterpanel-dent	66.85%

## Image 10 of 11

Original Image



Detected Image



Detected Objects:

Class

Accuracy




## Image 11 of 11

Original Image



Detected Image



### Detected Objects:

#### Class

rear-bumper-dent  
boot-dent

#### Accuracy

74.40%  
38.50%