

# Damage Detection Report

Generated on: 2025-05-18 21:27:56

This report presents the results of an advanced AI-driven vehicle damage detection system.

The software is designed to automate the process of identifying vehicle damages by analyzing images of vehicles. It detects various types of visible damage, including dents, scratches, cracks, and other structural imperfections. By using state-of-the-art deep learning models trained on a wide range of vehicle damage data, the system offers highly accurate and reliable damage detection capabilities.

The primary objective of this system is to streamline and accelerate the vehicle inspection process, allowing for faster, more consistent, and more accurate assessments compared to manual inspection methods. This technology can be particularly useful in industries such as insurance, automotive repair, fleet management, and vehicle rental services, where timely damage detection is critical.

The process begins when an image is uploaded to the system, which is then processed by the AI model. The model identifies any damages in the image and highlights them with bounding boxes. These bounding boxes correspond to the location of the detected damage, and each is accompanied by a confidence score, indicating the likelihood of the damage being correctly identified.

The system's AI model is constantly refined and improved to handle a wide variety of vehicle types, damages, and environmental conditions, ensuring accurate results in diverse scenarios.

Total Images Processed: 6

For each image submitted, this report provides the original image on the left and the processed image with detected damages on the right. Below each pair of images, you will find a table listing the detected objects, their class (type of damage), the confidence level for each detection, and the corresponding bounding box coordinates. This detailed information allows for easy inspection and validation of the results.

By automating this process, the system reduces human error, accelerates claim processing times, and enhances the overall efficiency of vehicle inspections.

We hope this report provides valuable insights into the performance and accuracy of the damage detection system, and that it supports the continuous improvement of vehicle assessment operations.

## Image 1 of 6

Original Image



Detected Image



### Detected Objects:


Class	Confidence
bonnet-dent	0.89
Headlight-damage	0.87
front-bumper-dent	0.78

## Image 2 of 6

Original Image



Detected Image



### Detected Objects:

#### Class

doorrouter-dent

#### Confidence

0.91

### Image 3 of 6

Original Image



Detected Image



#### Detected Objects:

Class	Confidence
rear-bumper-dent	0.53
rear-bumper-dent	0.38

## Image 4 of 6

Original Image



Detected Image



### Detected Objects:

#### Class

front-bumper-dent

#### Confidence

0.91




## Image 5 of 6

Original Image



Detected Image



### Detected Objects:

Class	Confidence
bonnet-dent	0.82
front-bumper-dent	0.81
Headlight-damage	0.33

## Image 6 of 6

Original Image




Detected Image



### Detected Objects:

Class	Confidence
Headlight-damage	0.95
fender-dent	0.88
doorouter-dent	0.49





Damage Details

Policy Type: Comprehensive

Policy Start Date: 2024-01-01

Policy Renewal Date: 2025-01-01

Damage Type	Coverage
bonnet-dent	Covered
Headlight-damage	Covered
front-bumper-dent	Covered
doorrouter-dent	Covered
rear-bumper-dent	Covered
fender-dent	Covered